

22/01/2020

ASS. REC. BY:

Surveyor: Tan Aik

REF:

8/SMO20000545/T/sd3er

Special Instruction:

ASSIGNMENT (Office)

From (Person): Gmco Teo

of

SMO

Date/Time: 7/1/2020 @ 4:05pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 7913D

Insured:

SLC 8532X

at Workshop m/s

Kim Kock Motor

Tel:

62650226

of

27A Jurong port Road # 01-19

Policy No:

Claim No:

CM7D1905948/8YH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/12/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:07am @ 8/1/2020

Person Contacted:

chen

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction

Estimate ☒

FBH 7913D - X

SLC 8532X - X

09/01/20

@ 15:37 pm revised PA to Sheng Yig via email.

ASS. REC BY:

Taufik

REF:

SMD

ASSIGNMENT

Form:

Date:

08/01/2020

Veh No:

FBH 7913D

Yr Regn:

2013 / Oct

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To inspect Vehicle No:

FBH 7913D

Make:

Honda 400X

V.C.

399

at Workshop m/s

Kim Kock Motor

Colour:

Maroon

A/C:

Insured / Std / NI / NA

of

27A Junong port Road #01-19

Sp. Reading

-

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

NC471003474

Claims No.

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or


Make of Veh:

After 3pm

Modi: M / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

A 7000

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

8/1/20 C43pm

Survey held at

Kim Kock Motor

Des. of Damages:

Frt

Rear

O/S

N/S

U/C

Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

HS \$ 5,250/- @ 5 days
 (\$ 3,884.00 red - 43%)

(Continued with
 M.S. How)

16/1/2020

RECEIVED 17 JAN 2020

Date/Time, File Pass to?

17/01/20

1)

Typ: 34

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

5

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



West end (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

250

250

Report Format:

Lump Sum / L.R. @

5,250/ HS

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 7 January 2020 4:05 PM
To: kimcockmotor@gmail.com; Hwang, Shiang Yi; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'
Cc: jason@ens.com.sg; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1905948/SYH - LKK/ SLC8532X & FBH7913D ACC ON 21.12.19 - VEH IN
Attachments: 06012020162144-0001.pdf

Without Prejudice

Our Reference: CMTD1905948/SYH

Your Reference: FBH7913D

Hi Ah Zheng,

As spoken and agreed, we will re-assign **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for **FBH7913D** on a without Prejudice and any admission of liability basis and submit with your report upon completion of survey to my colleague, **Ms. Shiang Yi**.

Please note our office will be closed on 24th January 2020 (Friday). Business will resume on 28th January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Teo, Grace

Sent: Tuesday, January 7, 2020 11:12 AM

To: 'kimcockmotor@gmail.com' <kimcockmotor@gmail.com>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: 'jason@ens.com.sg' <jason@ens.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>

Subject: CMTD1905948/SYH - TSL/ SLC8532X & FBH7913D ACC ON 21.12.19

Without Prejudice

Our Reference: CMTD1905948/SYH

Your Reference: FBH7913D

Hi Ah Zheng,

We acknowledged receipt of your claim documents.

As spoken, we have arranged our in-house Mr. Teo (98563133) to conduct the survey today.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg.

Please note our office will be closed on 24th January 2020 (Friday). Business will resume on 28th January 2020 (Tuesday).

Wishing you a happy and prosperous Lunar New Year, filled with wealth, good health and success always!

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Jason Thye <jason@ens.com.sg>

Sent: Monday, January 6, 2020 4:30 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: kimkockmotor@gmail.com

Subject: Arrange Surveyor - Accident inv FBH7913D and SLC8532X

Dear Team,

Please assist to arrange surveyor to Kim Kock Motor Pte Ltd to survey bike FBH7913D.

Enclosed GIA report and estimate cost of repair for your reference.

Thanks & Regards,
Jason Thye

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 872H

Vehicle Details

Vehicle No.: FBH7913D

Vehicle to be Exported: No

Intended Deregistration
Date: 09 Jan 2020

Vehicle Make: HONDA

Vehicle Model: 400X M

Primary Colour: Red

Manufacturing Year: 2013

Engine No.: NC47E1003480

Chassis No.: NC471003474

Maximum Power -

Output:

Open Market Value: \$7,336.00

Original Registration
Date: 03 Oct 2013

Date:

First Registration Date: 03 Oct 2013

Transfer Count: 2

Actual ARF Paid: \$1,101.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry -

Date:

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 02 Oct 2023

COE Category: D - Motorcycle

COE Period(Years): 10

QP Paid: \$1,660.00

COE Rebate Amount: \$619.00

Total Rebate Amount: \$619.00

The information contained herein is correct as at 09 Jan 2020

OK

Shirley Hiew (LKK Auto)

From: Motor Pte Ltd Kim Kock <kimcockmotor@gmail.com>
Sent: Friday, 17 January 2020 11:49 am
To: Shirley Hiew (LKK Auto)
Subject: Re: FBH 7913D DOA - 21/12/2019

Hi Ms Shirley Hiew ,

My Boss agreed and accept your confirm L/S \$ 5,250.00 @5 days .

Kindly assist us for passing up the survey report for this claim to SOMPO Insurance officer In-charge Ms Hwang Shiang Yi
as soon as possible .

Thank You

Mr Gan / Ms How
Kim Kock Motor Pte Ltd
Tel : 6265 0226 / 6265 0358
Fax : 6265 2588

On Fri, Jan 17, 2020 at 9:01 AM Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com> wrote:

Dear Chen,

-

Please confirm L/S \$ 5,250.00/5 days .

-

-

-

"Wishing you a Happy and Prosperous Lunar New Year"



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 9 January 2020 3:37 pm
To: 'Hwang, Shiang Yi'
Cc: 'Ye, Yong Kang Melvin'; 'Henry, Irene James'; SUR; assignments; 'Teo, Grace'
Subject: RE: CMTD1905948/SYH - LKK/ SLC8532X & FBH7913D ACC ON 21.12.19 - VEH IN
Attachments: PRELI ADVISE - FBH 7913D .pdf

Dear Shiang Yi,

Enclosed preliminary revised of vehicle FBH 7913D.

"Wishing you a Happy and Prosperous Lunar New Year"



Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 8 January 2020 10:11 am
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1905948/SYH - LKK/ SLC8532X & FBH7913D ACC ON 21.12.19 - VEH IN

Dear Sir/Mdm,

Thank you for the assignment.

"Wishing you a Happiness and Prosperity New Year"

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD1905948/SYH

Date: 09 January 2020

Our Ref: CS/SMO20000545/T1sd3

The Motor Claims Department
SOMPO INSURANCE SINGAPORE PL

Dear Sir/Madam,


PRELIMINARY ADVISE REPORT OF VEHICLE NO. FBH 7913D .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 08/01/2020 at the premises of M/s Kim Kock Motor Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ 9,134.00 .
Revised Estimate Amount	: S\$ 6,559.60 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the front, o/s front portion & n/s body



Comments/ Present Status:

Damages Consistent.

Repair days: 5 days

Yours faithfully

Mohamad Taufikh
Automotive Assessor

ATTN: claim Department

→ Sompot-Tel-63295170

MSG19171270 / STA INSPECTION PTE LTD - Boon Lay
ENTRY DATE & TIME: 30/12/2019 15:29
SUBMITTED BY: Woodford Richard Vincent

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 30/12/2019 16:24

SINGAPORE ACCIDENT STATEMENT

Fax-62213147
Tel-64616555

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/12/2019 15:29
Date Of Accident 21/12/2019 07:30
Exact Location Of Accident BKE-PIE 1KM MARK
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number FBH7913D
Insured/Policyholder
Name Of Registered Owner LOKMAN BIN ABDUL
NRIC No SXXXX872H
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-96371730
Alternative Phone No OTHERS-96371730

Vehicle Particulars

Manufacturer HONDA
Model 400X
Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category MOTORCYCLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage THIRD PARTY
Fleet Policy NO
Policy Number 5074841076-04
Cover Note Number

Driver

Name of Driver LOKMAN BIN ABDUL
NRIC No SXXXX872H
Date Of Birth 02/06/1959
Occupation OUTDOOR
Date Of Driving Pass 17/04/1979
Driving Experience 40 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-96371730
Fax Number
Contact Number OTHERS-96371730
Email Address NOEMAIL

金国摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Address BLK 678 CHOA CHU KANG CRESCENT
#04-624
Postcode 680678
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
-
-
Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident CHAIN COLLISION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 3
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name 20 CHAO CHU KANG STREET 52 #01-02 SINGAPORE 689286
Police Station Address ROAD: 20 CHAO CHU KANG STREET 52 #01-02 SINGAPORE 689286 ,
POSTCODE: 689286 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: - FAX NO:
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLC8532X
Vehicle Make/Model/Colour MAZDA
Details Of Properties RIGHT FRONT
Vehicle Category PRIVATE CAR
Name of Driver NA
NRIC/Passport Number
Contact Number NA
Address
Postcode
Insurance Company Name

金国摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SBY7873Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LOKMAN BIN ABDUL
Approximate Age	
Injuries Sustain	REFER REPORT
Injured person in which vehicle?	FBH7913D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

金国摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)


Reporting Centre Personnel's Signature
Name:

金国摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

[Signature]

金国摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20191227/2076

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999

1 of 3

Report No. T/20191227/2076

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 27/12/2019 13:57		Vide Report No.: J/20191221/0072		Station Diary No.: 87	
Informants Particulars:					
Name of Informant: LOKMAN BIN ABDUL			Address: APT BLK 678 CHOA CHU KANG CRESCENT #04-624 SINGAPORE 680678		
ID Type / ID No.: NRIC NO / S1355872H			Contact No.: Home/Office: Mobile: 96371730		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 60	Date of Birth: 02/06/1959	Type of Informant: Rider		
Race: Malay			Language: English		Institution / School Name:
Occupation: CRANE OPERATOR			Driving Licence Information: Class: 2B,2A,2,3,4,5 Date of Expiry:		

General Information of the Accident:				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 21/12/2019 07:30	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 BUKIT TIMAH EXPRESSWAY PAN ISLAND EXPRESSWAY BKE > PIE 1 KM mark				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passengers
FBH7913D	Motorcycle	HONDA	400X M	Red	Slightly Damaged	0
SBY3873Y	Car				Slightly Damaged	0
SLC8532X	Car				Slightly Damaged	0

Details of Vehicle Insurance:

金国摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999



T/20191227/2076

2 of 3

Report No. T/20191227/2076

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
FBH7913D	NTUC Income Insurance Co-Operative Limited	5074841076-04	03/10/2019	02/10/2020

Details of Person Involved				
Any Pedestrian Involved: No			Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL				
Rider				
Name	LOKMAN BIN ABDUL		ID No.	S1355872H
Related Vehicle	FBH7913D (Motorcycle)		Contact No.	96371730
Hospital/Clinic	NG TENG FONG GENERAL HOSPITAL		Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL
Date Treatment	21/12/2019		Date Discharge	24/12/2019
No. of Days granted Medical Leave	13		Degree of Injury	Serious

Brief Details.

On 21/12/2019 at about 0730hrs, I was travelling along BKE towards PIE, when after the eco-bridge, a vehicle, bearing the registration plate number SLC8532X, suddenly swerved right, wanting to change lane from lane 2 to lane 1. I was unable to react in time and collided onto the front right side of SLC8532X, and fell on the left side of my body right in front of SLC8532X. My motorcycle had broken windshield, broken side mirrors, fork alignment out-bended and handle bar bended. The front right bumper of SLC8532X was damaged as well.

TP and Ambulance attended to the scene. I was conveyed to Ng Teng Fong Hospital and was hospitalized from 21/12/19 to 24/12/19. I was diagnosed to have suffered closed fracture of shaft on the left humerus and required surgery on 02/01/2020, as well as minor injuries like abrasions on my left knee and ankle, bruises on my left rear shoulder area. I was given 13 days of MC from 21/12/19 - 02/01/2020, ref 63506188.

金國摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Choa Chu Kang N.P.C
20 Choa Chu Kang Street 52 #01-02
SINGAPORE 689286
Tel No: 1800-7659999



T/20191227/2076

3 of 3

Report No. T/20191227/2076

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 3 LAM



Signature Of Interpreter:

Not applicable

SIGNATURE

Officer In Charge Of Case:

TP / GIT /

Sgt 3 RASHIDAH BINTE AZMAN

Contact No.: 65476216

Signature Of Informant:

Date/Time:

27/12/2019 13:57

Classification Of Case:

Authentication Stamp

NID:CG

金國摩哆私人有限公司

KIM KOCK MOTOR PTE LTD

Blk 27A, Jurong Port Road, #01-19,

Singapore 619101

Tel: 6265 0226 Fax: 6265 2588

FBH 7913D

TO wing — \$45 / mi. ⁶⁷
~~\$49~~

(L) Front Fork Assy — \$895 R & SN \$120.

Handle BAR Assy — \$280 bt ✓

MIRRR R/L — \$290 car ✓
balancer

R/L Handle BAR Balancer — \$130 dd ✓

Front Mudguard — \$195 cut ✓

Front ^{lower spokes} ~~spoiling~~ Assy — \$595 cut ✓

(L) Front signal — \$125 car ✓

(R) Front signal — \$125 xols ✓

Head light Assy — \$485 car ✓

Head light Bracket ^{bracket} — \$295 bt ✓

Head light Cowling ^{Cowling.} — \$195 car ✓

Front wiskim ^{windscreen} — \$195 car ✓

Front wiskim Bracket Assy — \$180 bt ✓

Front No plate — \$78 car ✓

Meter Assy — \$495 this ✓

R/L Front Side ^{fairing} Fairing — \$595 car ✓

Head light Low cover — \$125 cut ✓

Meter side cover — \$98 de ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Front Body ^{bar} KAR Assy — \$290 bt ✓
 Engin ^{bar} KAR Assy — \$280 bt ✓
 R/L Seat Front Side Cover — \$280 ¹⁴⁰ LH-cut ✓
 RH-xmm ✓
 clutch lever 1pc — \$78 cut ✓
 ERP unit & Bracket — \$250 ¹²⁰ cut ✓

R/L Front Side AIR idex cover \$96 de ✓

Gear ^{pedal} Pedal Assy — \$125 bt ✓

Fuel tank Assy — \$890 R+ ✓

(L) Rear ^{foot rest} Pull less — \$98 cut ✓

(L) Rear ^{foot rest bracket} Pull less Bracket \$195 de ✓

(L) ^{Front Foot rest} ~~Rear~~ Pull less — \$98 de ✓

chain ^{cover} KAR Assy — \$98 de ✓

Rear Box Assy — \$480 ³⁸⁰ cut ✓

(L) Rear signal Assy — \$125 cut ✓

Tanji 97495749/abu — \$380 250

8/1/20 @ 4:15pm 'wp' Spray paint — \$450 300

Lum Bm

Resurvey after repair

05 days
 sure/Manito.com

\$9134

Parts - 6544
 10% - 5889.60
 Labor - 550
 SN - 120
 6554.60
 4595200*

9524



BIKEBULANCE

9D, Yuan Ching Road #03-38 S(16646)
Tel: 6425-5333 95880922
Email: bikebulance@yahoo.com
MOTORCYCLE / SCOOTER Haulage Company

☐ DELIVERY ORDER
☒ CASH SALE
☐ INVOICE

City: _____

NO : 19258

RE : _____

DATE: 28.12.19

ITEM	QTY	DESCRIPTION	UNIT PRICE	AMOUNT
1			\$	\$
2		FBT 7913 (400x)	\$	\$ 45
3			\$	\$
4		Turk City	\$	\$
5		- KK	\$	\$
6			\$	\$
7			\$	\$
8			\$	\$
9			\$	\$
10			\$	\$
11			\$	\$
12			\$	\$
13			\$	\$

50% of quoted Price or min \$20 (whichever is higher) is liable for cancellation of booking (Not For Contract Terms)

Total \$ 45

E & OE

注意: 本公司對所租的電單車, 在拖運中如有任何損壞, 一概由車主自行負責

NOTE: Vehicle is hired at owner's risk. This Company accepts no responsibility for damages or other misadventure to your vehicle whilst being towed

YM2E ☐ YM3C ☒ OY2E ☐ GBB2K ☐ GZ2320T ☐ GBB4370E ☐ Other ☐

Issued By _____

Customer's Signature & Chop _____

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20000545/T1sd3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 21-01-2020		
Code : SMO				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 8532X	Veh. Inspected	FBH 7913D	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1905948/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	07/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA 400X	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	NC471003474	Colour	MAROON	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70 R17	PIRELLI	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	PIRELLI	5 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/12/2019	Inspection Date	08/01/2020	
Survey held at	KIM KOCK MOTOR PTE LTD BLK 27A JURONG PORT ROAD #01-19 SINGAPORE 619101			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 7913D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HANDLE BAR ASSY	BENT	280.00	280.00
2	MIRROR R/L	CRACKED	290.00	290.00
2	R/L HANDLE BAR BALANCER	DENTED	130.00	130.00
1	FRONT MUDGUARD	CUT	195.00	195.00
1	FRONT LOWER SPOILER ASSY	CUT	595.00	595.00
1	(L) FRONT SIGNAL	CRACKED	125.00	125.00
1	(R) FRONT SIGNAL	DISTORTED	125.00	125.00
1	HEAD LIGHT ASSY	CRACKED	485.00	485.00
1	HEAD LIGHT BRACKET	BENT	295.00	295.00
1	HEAD LIGHT COWLING	CRACKED	195.00	195.00
1	FRONT WINDSCREEN	CRACKED	195.00	195.00
1	FRONT WINDSCREEN BRACKET ASSY	BENT	180.00	180.00
1	FRONT NO PLATE	NECESSARY	18.00	18.00
1	METER ASSY	DISTORTED	495.00	495.00
2	R/L FRONT SIDE FAIRING	CRACKED	595.00	595.00
1	HEAD LIGHT LOW COVER	CUT	125.00	125.00
1	METER SIDE COVER	DEFORMED	98.00	98.00
1	FRONT BODY BAR ASSY	BENT	290.00	290.00
1	ENGINE BAR ASSY	BENT	280.00	280.00
2	R/L SEAT FRONT SIDE COVER	N/S CUT / O/S NOT NECESSARY	280.00	140.00
1	CLUTCH LEVER	CUT	78.00	78.00
1	ERP UNIT & BRACKET	CUT	250.00	120.00
2	R/L FRONT SIDE AVE IDEX COVER	DEFORMED	96.00	96.00
1	GEAR PEDAL ASSY	BENT	125.00	125.00
1	FUEL TANK ASSY	TO REPAIR SEE LABOUR	890.00	-
1	(L) REAR FOOT REST	CUT	98.00	98.00
1	(L) REAR FOOT REST BRACKET	DENTED	195.00	195.00
1	(L) FRONT FOOT REST	DENTED	98.00	98.00
1	CHAIN COVER ASSY	DEFORMED	98.00	98.00

Report Ref No. CS/SMO20000545/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BOX ASSY	CUT	480.00	380.00
1	(L) REAR SIGNAL ASSY	CUT	125.00	125.00
	LESS 10% DISCOUNT		-	-654.40
			7,804.00	5,889.60
	<u>SPECIAL NETT ITEMS</u>			
1	(L) FRONT FORK ASSY (SN)	BENT	895.00	120.00
			895.00	120.00
	<u>LABOUR</u>			
	TOWING.		45.00	45.00
	LABOUR. INCLUSIVE OF THE REPAIR OF FUEL TANK ASSY.		380.00	250.00
	SPRAY PAINT.		450.00	300.00
			875.00	595.00
	GRAND TOTAL		9,574.00	6,604.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,250.00

Report Ref No. CS/SMO20000545/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.