

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |   |                                |            |  |
|---|--|---|--------------------------------|------------|--|
| MS FIRST CAPITAL INSURANCE LTD                                    |  |   | Ref : CC4/FCI20000568/Dea3s2   |            |  |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877             |  |   | Date: 01-09-2020<br>Code: FCI2 |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM                        |  |   |                                |            |  |
|   | Insured Veh.   | SHC 8350B   | Veh. Inspected                 | SHA 3083R  |  |
|   | Policy No.   | D-19092580MFSH  | Coverage (\$)                  | 0.00       |  |
|   | Claim No.  | D20000180MFSH   | Excess (\$)                    | 0.00       |  |
|   | Assign From  | MAY CHUA  | Assign Date                    | 08/01/2020 |  |
| 2. Vehicle Particulars & Condition                                |  |   |                                |            |  |
|   | Make & Model   | TOYOTA PRIUS  | c.c                            | 1798       |  |
|   | Engine No.   | HIDDEN  | Year of Reg.                   | 2017       |  |
|   | Chassis No.  | JTDKB3FU103562728   | Colour                         | BLUE       |  |
|   | Odometer   | -   | Steering                       | IN ORDER   |  |
|   | Brakes   | IN ORDER  | Modification                   | SPORTS RIM |  |
|   | General  | GOOD  |                                |            |  |
| 3. Conditions of Tyres  |  |   |                                |            |  |
|   |  | Size  | Make                           | Balance    |  |
|   | R/H Front Tyre   | 195/65 R15  | DAVANTI                        | 5 mm       |  |
|   | L/H Front Tyre   | 195/65 R15  | DAVANTI                        | 5 mm       |  |
|   | R/H Rear Tyre  | 195/65 R15  | DAVANTI                        | 5 mm       |  |
|   | L/H Rear Tyre  | 195/65 R15  | DAVANTI                        | 5 mm       |  |
| 4.  | Description of Damages   |   |                                |            |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.  |   |                                |            |  |
|   | DAMAGES SEE D  | DAMAGES SEE DETAILS.  |                                |            |  |
| 5.  | General Information  |   |                                |            |  |
|   | Accident Date  | 27/12/2019  | Inspection Date                | 06/01/2020 |  |
|   | Survey held at   | CHUNNI MOTOR WORK PTE LTD  BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047. |                                |            |  |
|   |  |   |                                |            |  |
| 5a.   | Remarks  |   |                                |            |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |                                |            |  |
| 5b.   | 5b. Estimate Days of Repair  |   |                                |            |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 15 Working Days  |   |                                |            |  |