

ASS. REC. BY:

REF: (S/MSG 20000574/Hy f302)

Special Instruction:

SURVIVOR: 1766K Am

ASSIGNMENT (Office)

From (Person): KRM Tan Cct Jng

of MS19

Date/Time: 8 Jan 20 16:52p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJK 7474T

Insured: SLN 6382S

at Workshop m/s Z-ONE Automotive

Tel: 6250.2115 / 66342112

of 1 Kaki Bukit Ave 6 #01-87 / 85 Autobay

Policy No: 29114756MKF

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 6.01.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 9.1.2020 10.14a.m

Person Contacted:

Syafiroh

H.O.D. Endorsement:

Vehicle IN/OUT

| Date/Time | Action/Instruction (✓) Estimate                       |
|-----------|-------------------------------------------------------|
|           | SJK 7474T - NA/CTI 20000454/24 DOR - 06/01/2020       |
|           | SLN 6382S - NA/CTI 20000454/24 DOR - 06/01/2020       |
| 15/1/20   | Sent Pict by Meimer                                   |
|           | SJK 7474T Found Ant L/S rep cor \$ 5000               |
|           | DOR 6 days, Agn by workshop margin from (New syf. LK) |

Meimer  
Photo  
O.K

PRS

ASSIGNMENT

From: \_\_\_\_\_ Date: 14 Jan 2020  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SJK 7474T  
at Workshop n/s: I One Automotive  
of: 1 Kaki Bukit Ave 6 B1K0 #01-52 Autobay  
Insured: 01/08/85  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: Ader 11.000.00

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
Lum Surv: \_\_\_\_\_ % 3 Val: Yes or No  
CA / REV / REP. / 24 HRS *mp*  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SJK 7474T Yr Regn: 31/10/2018  
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: Mercedes Benz E200 cc 1796  
Colour: blue A/C: Insured / Std / NI / NA  
Sp. Reading: 164821km T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: WDB2110412353526  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Inorder / Jammed / Leaked / Burnt or  
Brake: Inorder / Jammed / Leaked / Burnt or  
Modi: Nil / SiRim / STD A/Rim or  
Tyre Size: F: \_\_\_\_\_ R: 245/45/R17  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front: R/Bal. 57 mm L/Bal. 57 mm D.O.A. 6/1/20  
Rear: R/Bal. 57 mm L/Bal. 57 mm D.O.A. 14/1/20  
Survey held at: 2 one  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction                                                                                               |
|-------------|--------------------------------------------------------------------------------------------------------------------|
| 4/2         | 4/5 \$5000F (Red \$12864-00, 72%)<br>* workshop strategy to print case<br>* Noted vehicle and Amend name of driver |
|             | mv - 52000<br>pv - 28374<br>nv - 23600                                                                             |

RECEIVED 5 FEB 2020

Date/Time, File Pass to? ☐ : Prelim. Report  
☐ : Final Report

Days Of Repair: 6  
Resurvey No. of Trip: 2

|                 |     |
|-----------------|-----|
| Survey Fee:     | 200 |
| Transportation: |     |
| Photo:          |     |
| Other:          | 11  |
| Wash:           | 211 |

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

1/2/20 Typist  
Flow Form: \$5000/-

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

| Case | Notified             | Est Submitted | Adj Assigned                                   | Adj Rpt | Adj Submitted | Ins Auth'ed | Status                                               |
|------|----------------------|---------------|------------------------------------------------|---------|---------------|-------------|------------------------------------------------------|
| Main | 08 Jan 2020<br>11:28 |               | 08 Jan 2020<br>16:53<br><a href="#">Assign</a> |         |               |             | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

**CLAIM SUBFOLDER DETAILS** [\[Created by insurer\]](#)

|                             |                                                                                                                    |                        |                                                                              |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|
| Insured:                    | GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G                                                                     |                        |                                                                              |
| Main Claimant:              | YONG CHAN CHONG, ID: S7831987                                                                                      |                        |                                                                              |
| Vehicle Reg. No.:           | SJK7474T                                                                                                           | Date of Loss:          | 06/01/2020 00:00 - :59<br>[134 Months and 6 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | TP                                                                                                                 | Policy/Cover Note No.: | 29114756MKF (Comprehensive)<br>Coverage: 01/02/2019 - 31/01/2020             |
| Vehicle Reg. No. (Insured): | SLN6382S                                                                                                           | Policy No. (Claimant): |                                                                              |
|                             |                                                                                                                    | Excess:                |                                                                              |
| Repairer:                   | Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: |                        |                                                                              |
| Handling Insurer:           | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]      |                        |                                                                              |
| Adjuster:                   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/01/2020]                                 |                        |                                                                              |
| Adj Asg. Remarks:           | on WP, OI:Grab, Liab: NR. Agree on SJE, Assign: LKK Auto Consultants Pte Ltd. Contact: Sya @ 6634 2112.            |                        |                                                                              |

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results, |          |      |            |         |         |             |              |            |       |

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 15 Jan 2020

**Preliminary Advice**

|                    |                                                                                                                   |                         |              |
|--------------------|-------------------------------------------------------------------------------------------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SLN6382S                                                                                                        | Accident Date           | : 06/01/2020 |
| TP Vehicle No      | : SJK7474T                                                                                                        | Assignment Date         | : 08/01/2020 |
| Make               | : MERCEDES-BENZ E200K                                                                                             | Est. Duration of Repair | : 6.00       |
| Date of Inspection | : 14/01/2020                                                                                                      |                         |              |
| Inspection At      | : Z-ONE AUTOMOTIVE PTE LTD - KB (HQ)<br>1 KAKI BUKIT AVENUE 6, #01-87/85 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                         |              |

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages.o/s portion and parts claimed are consistent to the accident.

|                             |      |           |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 17,423.00 |
| Revised Amount              | :S\$ | 4,887.92  |
| Check Items (Estimated)     | :S\$ | 680.40    |
| Total                       | :S\$ | 5,568.32  |

Lump Sum Repair :S\$

**Total Loss Consideration**

|                    |      |
|--------------------|------|
| New for Old Value  | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate  | :S\$ |
| Salvage Value      | :S\$ |
| Margin for Repair  | :S\$ |

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

## Hock Ann (LKK Auto)

---

**From:** Hock Ann (LKK Auto)  
**Sent:** Tuesday, 4 February, 2020 11:10 AM  
**To:** Nur Syafirah  
**Cc:** Yvonne Wong (LKK Auto)  
**Subject:** RE: SJK 7474T FINALIZED

'WITHOUT PREJUDICE'  
SAVE AS TO COSTS

Dear nur syafirah ,

Good day, o.k will be process base on finalized total amount COR \$ 5000 L/sump REPAIR and DOR 6 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need send direct MSIG claim dept .

Thanks.

Best Regards,  
Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: [HockAnn@lkkauto.com](mailto:HockAnn@lkkauto.com) | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** Nur Syafirah [<mailto:service@z-one.com.sg>]  
**Sent:** Tuesday, 4 February, 2020 10:54 AM  
**To:** Hock Ann (LKK Auto)  
**Cc:** Yvonne Wong (LKK Auto); Sya Z1  
**Subject:** Re: SJK 7474T FINALIZED

2nd RESEND

Dear Hock Ann,

We confirm to accept the lump sum \$5000.00 with 6 days.

Thank you!

Best Regards,

Nur Syafirah  
Z-One Automotive Pte Ltd  
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883  
Tel: 66342112 Fax: 6634 2122

From: Nur Syafirah  
Sent: Monday, February 3, 2020 10:41 AM  
To: Hock Ann (LKK Auto)  
Cc: Yvonne Wong (LKK Auto) ; Sya Z1  
Subject: Re: SJK 7474T FINALIZED

RESEND

Dear Hock Ann,

We confirm to accept the lump sum \$5000.00 with 6 days.

Thank you!

Best Regards,

Nur Syafirah  
Z-One Automotive Pte Ltd  
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883  
Tel: 66342112 Fax: 6634 2122

From: Nur Syafirah  
Sent: Thursday, January 30, 2020 7:12 PM  
To: Hock Ann (LKK Auto)  
Cc: Yvonne Wong (LKK Auto) ; Sya Z1  
Subject: Re: RE : SJK 7474T FINALIZED

Dear Hock Ann,

We confirm to accept the lump sum \$5000.00 with 6 days.

Thank you!

Best Regards,

Nur Syafirah  
Z-One Automotive Pte Ltd  
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883  
Tel: 66342112 Fax: 6634 2122

From: Hock Ann (LKK Auto)  
Sent: Thursday, January 23, 2020 1:59 PM  
To: Nur Syafirah  
Cc: Yvonne Wong (LKK Auto)  
Subject: RE : SJK 7474T FINALIZED

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear ah xiong / nur syafirah,

Good day , Kindly attached refer SJK 7474T MERCEDES BENZ finalized updated calculate adjustment on 23.1.2020

COR - \$ 5000

DOR – 6 DAYS

Please refer adjustment updated total LUMP/SUMP amount \$ 5000 if agree total LUMP/SUMP amount and repair days, will be to close case.

Please to updated email back asap.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                                      |
|----------------------------|--------------------------------------|
| Date Of Report             | 07/01/2020 17:24                     |
| Date Of Accident           | 06/01/2020 22:20                     |
| Exact Location Of Accident | JUNC TAMPINES AVE 2 & TAMPINES ST 23 |
| Country/State of Loss      | SINGAPORE                            |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SJK7474T             |
| <b>Insured/Policyholder</b> |                      |
| Name Of Registered Owner    | YONG CHAN CHONG      |
| NRIC No                     | SXXXX987I            |
| Email Address               | NOEMAIL              |
| Mobile Phone No             | (LOCAL) +65-96495604 |
| Alternative Phone No        | OFFICE-96495604      |

### Vehicle Particulars

|                                                                              |               |
|------------------------------------------------------------------------------|---------------|
| Manufacturer                                                                 | MERCEDES-BENZ |
| Model                                                                        | E200K         |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE   |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO            |
| If No, Please state action to be taken                                       | THIRD PARTY   |
| Vehicle Category                                                             | PRIVATE CAR   |

### Insurance Company

|                           |                                               |
|---------------------------|-----------------------------------------------|
| Name of Insurance Company | CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. |
| Type Of Coverage          | COMPREHENSIVE                                 |
| Fleet Policy              | NO                                            |
| Policy Number             | DMPCSN3005811901                              |
| Cover Note Number         |                                               |

### Driver

|                      |                                  |
|----------------------|----------------------------------|
| Name of Driver       | YONG CHAN CHONG (YANG ZHANZHANG) |
| NRIC No              | SXXXX987I                        |
| Date Of Birth        | 23/10/1978                       |
| Occupation           | INDOOR                           |
| Date Of Driving Pass | 20/03/1997                       |
| Driving Experience   | 22 YEARS AND 9 MONTHS            |
| Gender               | MALE                             |
| Mobile Number        | (LOCAL) +65-96495604             |
| Fax Number           |                                  |
| Contact Number       | OFFICE-96495604                  |
| Email Address        | NOEMAIL                          |



|                                                     |                                       |
|-----------------------------------------------------|---------------------------------------|
| Address                                             | BLK 474 TAMPINES STREET 43<br>#04-102 |
| Postcode                                            | 520474                                |
| Was driver an employee of the Insured's Company     | NO                                    |
| If No, Relationship of the Driver with the Insured  | OWNER                                 |
| Vehicle Registration Number of Driver's Own Vehicle | -                                     |
|                                                     | -                                     |
|                                                     | -                                     |
| Insurance Company of Driver's Own Vehicle           | -                                     |
|                                                     | -                                     |
|                                                     | -                                     |

#### General Information of the Accident

|                    |                               |
|--------------------|-------------------------------|
| Type Of Accident   | COLLISION - CHANGE/CROSS LANE |
| Weather Conditions | DRIZZLING                     |
| Road Surface       | WET                           |

#### Other Information

|                                                                                             |                                          |
|---------------------------------------------------------------------------------------------|------------------------------------------|
| Was any foreign vehicle involved in this accident?                                          | NO                                       |
| Number of vehicles (including own vehicle) involved in the accident                         | 2                                        |
| Was any body injured in the Accident?                                                       | YES                                      |
| Was any injured conveyed to hospital by ambulance?                                          | NO                                       |
| Was any other material or property damaged?                                                 | YES                                      |
| I have been approached by unknown person(s) soliciting/offering accident claims assistance. | NO                                       |
| Number of Passengers (Including Driver)                                                     | 4                                        |
| Passenger 1                                                                                 | NAME: : WONG IRENE<br>GENDER: : FEMALE   |
| Passenger 2                                                                                 | NAME: : YONG CHONG HEN<br>GENDER: : MALE |
| Passenger 3                                                                                 | NAME: : YONG CHONG LEN<br>GENDER: : MALE |

#### Details of Police Action

|                                           |    |
|-------------------------------------------|----|
| Was the accident reported to the police?  | NO |
| If Yes, Please state which Police Station |    |
| Was notice of intended Prosecution given? | NO |
| If Yes, against whom?                     |    |

#### Circumstances of Accident

REFER TO STATEMENT.

#### Attachment(s)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | YES |
| Was there any video captured by Car Camera?   | NO  |
| Was there any audio recorded?                 | NO  |

#### Details of Witness 1

|               |             |
|---------------|-------------|
| Name          | VIVIAN YONG |
| Phone Number  | 97891687    |
| Email Address |             |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SLN6382S |
| Vehicle Make/Model/Colour   |          |

#### Details Of Properties

|                                     |               |
|-------------------------------------|---------------|
| Vehicle Category                    | PRIVATE CAR   |
| Name of Driver                      | YEONG AIK NGI |
| NRIC/Passport Number                | SXXXX892I     |
| Contact Number                      | 94455938      |
| Address                             |               |
| Postcode                            |               |
| Insurance Company Name              |               |
| Nature Of Damage                    |               |
| No. Of Passenger (Including Driver) | 3             |

#### DETAILS OF INJURED PERSON 1

|                                                     |                                  |
|-----------------------------------------------------|----------------------------------|
| Name                                                | YONG CHAN CHONG (YANG ZHANZHANG) |
| Approximate Age                                     |                                  |
| Injuries Sustain                                    | BODY                             |
| Injured person in which vehicle?                    | SJK7474T                         |
| Were seat belts worn?                               | YES                              |
| Was this injured conveyed to hospital by ambulance? | NO                               |
| Address                                             |                                  |
| Postcode                                            |                                  |

#### DETAILS OF INJURED PERSON 2

|                                                     |                |
|-----------------------------------------------------|----------------|
| Name                                                | YONG CHONG HEN |
| Approximate Age                                     |                |
| Injuries Sustain                                    | BODY           |
| Injured person in which vehicle?                    | SJK7474T       |
| Were seat belts worn?                               | YES            |
| Was this injured conveyed to hospital by ambulance? | NO             |
| Address                                             |                |
| Postcode                                            |                |

#### DETAILS OF INJURED PERSON 3

|                                                     |            |
|-----------------------------------------------------|------------|
| Name                                                | WONG IRENE |
| Approximate Age                                     |            |
| Injuries Sustain                                    | BODY       |
| Injured person in which vehicle?                    | SJK7474T   |
| Were seat belts worn?                               | YES        |
| Was this injured conveyed to hospital by ambulance? | NO         |
| Address                                             |            |
| Postcode                                            |            |

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the SIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in the accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel Signature  
(Name)  
SIA/TH/12/1

# Accident Sketch Plan

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 06.01.2020 at about 10:20pm, I was travelling along Tampines Ave 2. I was on my rightful lane travelling straight, when suddenly, I felt an impact from the right portion of my vehicle. Vehicle B made a sudden change of lane to the left and collided onto my vehicle. I have a video footage of the accident.

After the accident, I felt pain on my neck and back. My passengers, who are my wife and sons were also not feeling well. We will be seeing the doctors to get check up.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Police Officer's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Resolving Centre Personnel's Signature  
Name: Aduhthas  
Date & Time

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|                |                |
|----------------|----------------|
| Owner ID Type: | Singapore NRIC |
| Owner ID:      | 987I           |

### Vehicle Details

|                               |                    |
|-------------------------------|--------------------|
| Vehicle No.:                  | SJK7474T           |
| Vehicle to be Exported:       | No                 |
| Intended Deregistration Date: | 15 Jan 2020        |
| Vehicle Make:                 | MERCEDES BENZ      |
| Vehicle Model:                | E200K              |
| Primary Colour:               | Grey               |
| Manufacturing Year:           | 2008               |
| Engine No.:                   | 27195631044526     |
| Chassis No.:                  | WDB2110412B353526  |
| Maximum Power Output:         | 135.0 kW (181 bhp) |
| Open Market Value:            | \$51,279.00        |
| Original Registration Date:   | 31 Oct 2008        |
| First Registration Date:      | 31 Oct 2008        |
| Transfer Count:               | 1                  |
| Actual ARF Paid:              | \$51,279.00        |

### Intended PARF Rebate Details

|                               |           |
|-------------------------------|-----------|
| PARF Eligibility:             | Forfeited |
| PARF Eligibility Expiry Date: | -         |
| PARF Rebate Amount:           | \$0.00    |

### Intended COE Rebate Details

|                             |                    |
|-----------------------------|--------------------|
| COE Expiry Date:            | 30 Oct 2028        |
| COE Category:               | E - Open Category  |
| COE Period(Years):          | 10                 |
| PQP Paid:                   | \$32,279.00        |
| COE Rebate Amount:          | \$28,374.00        |
| <b>Total Rebate Amount:</b> | <b>\$28,374.00</b> |

### Message

Transfer of ownership or deregistration is not allowed for this vehicle.

The information contained herein is correct as at 15 Jan 2020

OK



## ANNOUNCING Supreme Cars Pte Ltd as sgCarMart Premium Dealer 2020



mercedes-benz e200k

Price Range

Depreciation

Year Reg

Vehicle Type



Home » Used Cars » Mr Benz Traders » Mercedes-Benz E-Class E200K (COE till 06/2028)

### Mercedes-Benz E-Class E200K (COE till 06/2028)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

|                 |                               |               |                                             |
|-----------------|-------------------------------|---------------|---------------------------------------------|
| Price           | \$56,500                      | Reg Date      | 30-Jun-2008<br>(8yrs 5mths 14days COE left) |
| Depreciation    | \$6,680 /yr                   | Manufactured  | 2007                                        |
| Mileage         | 127,000 km (11k /yr)          | Transmission  | Auto                                        |
| Road Tax        | \$1,169 /yr                   | OMV           | \$50,919                                    |
| Dereg Value     | \$32,070 as of today (change) | ARF           | \$50,919                                    |
| COE             | \$37,906                      | Power         | 135.0 kW (181 bhp)                          |
| Engine Cap      | 1,796 cc                      | No. of Owners | 2                                           |
| Curb Weight     | 1,540 kg                      |               |                                             |
| Type of Vehicle | Luxury Sedan                  |               |                                             |

#### Features

1.8L Kompressor Engine, 181Bhp, 8 x Airbags, ABS, ESP, Brake Assist, Multi-Function Steering, Cruise Control, Climate Control Aircon, Keyless Entry. View specs of the Mercedes-Benz E-Class Saloon (2004-2009)

#### Accessories

Factory Fitted Audio System, Full Access Electric/Memory Seats, Reverse Sensors, Reverse Camera, Leather Seats, Sports Rims, Light/Rain Sensors.

#### Description

Elegant Silver Exterior With Luxurious Black Leather Interior. Well Maintained. Worn Parts Replaced At Workshop With Receipts. 6 Months Warranty. Flexible Financing Schemes Available. Trade-In Welcome. Low Depreciation To Own A Luxurious Mercedes Sedan. Call Now To Schedule A Viewing. Thank You.

#### Category

COE Car

#### Status

Available

#### Resources



#### Car Valuation - Free

Find out the market value of your existing car for free. Get started



#### Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Location Map

Shortlist

Compare

Add no

Report Error

More Actions

#### Seller Information

##### Mr Benz Traders

71 vehicles for sale. 53 sold in past 3 mths

210 Turf Club Road Lot A5  
Car Mall @ The Grandstand  
Tel: 63461282  
Search cars nearby

|               |          |
|---------------|----------|
| Richard Tan   | 97711650 |
| Stanley       | 90012123 |
| Chester Lee   | 90676766 |
| Bernard Foong | 96609891 |



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

## ESTIMATE

Yong Chan Chong  
474 Tampines Street 43 #04-102 Singapore  
520474

Contact : 96495604

Code : C101953

Date in : 14/01/2020

Vehicle Num. : SJK7474T

Model : MERCEDES BENZ E200K

Chassis/Eng# : WDB2110412B353526/27195631044526

### Parts and Labour Assesment

| Description of part                         | Qty | Unit Price | Amount                   |
|---------------------------------------------|-----|------------|--------------------------|
| Front door bottom hinge RH X                | 1   | 125.00     | 125.00                   |
| Front door bottom seal RH X                 | 1   | 86.00      | 86.00                    |
| Front door checker RH X                     | 1   | 45.00      | 45.00                    |
| Front door chrome moulding RH ✓ <i>suc</i>  | 1   | 192.00     | 192.00 <i>100.50</i> ✓   |
| Front door glass channel RH X               | 1   | 182.00     | 182.00                   |
| Front door glass outer moulding RH X        | 1   | 195.00     | 195.00                   |
| Front door glass regulator carrier RH X     | 1   | 289.00     | 289.00                   |
| Front door glass regulator motor RH X       | 1   | 566.00     | 566.00                   |
| Front door glass regulator RH X             | 1   | 635.00     | 635.00                   |
| Front door inner lock RH ✓ <i>Im</i>        | 1   | 586.00     | 586.00 <i>395.20</i> ✓   |
| Front door lock striker RH X <i>suc</i>     | 1   | 42.00      | 42.00                    |
| Front door outer handle RH X ( <i>suc</i> ) | 1   | 156.00     | 156.00                   |
| Front door RH ✓ <i>st</i>                   | 1   | 1826.00    | 1826.00 <i>1620.80</i> ✓ |
| Front door top hinge RH X ( <i>suc</i> )    | 1   | 125.00     | 125.00                   |
| Front door top seal RH X ( <i>suc</i> )     | 1   | 122.00     | 122.00                   |
| Front door weather strip RH ✓ <i>new</i>    | 1   | 286.00     | 286.00 <i>230.50</i> ✓   |
| Rear Bumper X ( <i>R</i> )                  | 1   | 1338.00    | 1,338.00                 |



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

|                                         |   |         |                             |   |
|-----------------------------------------|---|---------|-----------------------------|---|
| Rear door bottom hinge RH               | 1 | 125.00  | 125.00                      | ✓ |
| Rear door bottom seal RH                | 1 | 82.00   | 82.00                       |   |
| Rear door checker RH                    | 1 | 45.00   | 45.00                       | ✓ |
| Rear door <sup>chrome</sup> moulding RH | 1 | 183.00  | <del>183.00</del> 100.50    | ✓ |
| Rear door glass channel RH              | 1 | 162.00  | 162.00                      |   |
| Rear door glass outer moulding RH       | 1 | 189.00  | 189.00                      |   |
| Rear door glass regulator carrier RH    | 1 | 284.00  | 284.00                      |   |
| Rear door glass regulator motor RH      | 1 | 566.00  | 566.00                      |   |
| Rear door glass regulator RH            | 1 | 639.00  | 639.00                      |   |
| Rear door inner lock RH                 | 1 | 560.00  | 560.00                      |   |
| Rear door inner trim board RH           | 1 | 1406.00 | 1,406.00                    |   |
| Rear door outer handle inner guide RH   | 1 | 85.00   | 85.00                       |   |
| Rear door outer handle RH               | 1 | 132.00  | 132.00                      |   |
| Rear door RH                            | 1 | 1778.00 | <del>1,778.00</del> 1520.80 | ✓ |
| Rear door top hinge RH                  | 1 | 125.00  | 125.00                      |   |
| Rear door top seal RH                   | 1 | 86.00   | 86.00                       | ✓ |
| Rear door weather strip RH              | 1 | 246.00  | <del>246.00</del> 230.50    |   |
| Rear fender RH                          | 1 | 1886.00 | 1,886.00                    |   |
| RH sill panel skirt                     | 1 | 895.00  | 895.00                      |   |
| Subtotal before discount                |   |         | 16,270.00                   |   |
| Percentage discount 10%                 |   |         | 1,627.00                    |   |
| Sub-total 1                             |   |         | 14,643.00                   |   |
| Parts-total                             |   |         | 14,643.00                   |   |





# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

## LABOUR

| Description                                                                                                                                                                     | Price     |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------|
| To diagnose, replace and/or repair to rectify front door electrical system for proper functioning                                                                               | 200.00    |
| To diagnose, replace and/or repair to rectify rear door electrical system for proper functioning                                                                                | 200.00    |
| To remove, refix / renew reverse sensor assy and rectify for proper functioning.                                                                                                | 180.00    |
| To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.                                                                             | 1,200.00  |
| To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. | 1,000.00  |
| Labour Total                                                                                                                                                                    | 2,780.00  |
| Parts & Labour Total                                                                                                                                                            | 17,423.00 |

*Handwritten notes:*  
22/1/20  
L/S repair  
6 by  
Rearage also put  
inlet pulser  
Hoch Ann  
P5311813  
4:30 pm  
14/1/20  
Hoch ANN @ Kaki Bukit

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



# Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: [service@z-one.com.sg](mailto:service@z-one.com.sg); [enquiry@z-one.com.sg](mailto:enquiry@z-one.com.sg)

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

## ESTIMATE

Yong Chan Chong  
474 Tampines Street 43  
#04-102  
Singapore 520474

Code : C101953  
Date In: 14/1/2020  
Vehicle Num. : SJK7474T  
Model : MERCEDES BENZ E200K  
Chassis/ Eng # : WDB2110412B353526/27195631044526

Contact : 96495604

### Supplementary for Estimate Items

| Description of part              | Qty | Unit Price | Amount |
|----------------------------------|-----|------------|--------|
| Frt door chrome protector ✓ SCR  | 1   | 275.00     | 275.00 |
| Rear door chrome protector ✓ SCR | 1   | 215.00     | 215.00 |

155.30 ✓  
155.30 ✓

|                         |               |
|-------------------------|---------------|
| Subtotal                | 490.00        |
| Percentage discount 10% | 49.00         |
| <b>Sub-total</b>        | <b>441.00</b> |

Resurvey taken  
15/1/20  
11.45 am  
for air gap part  
H-ANN  
LKK A

|             |        |
|-------------|--------|
| Parts total | 441.00 |
|-------------|--------|

|            |           |
|------------|-----------|
| parts      | 4679.40   |
| parts less | 10%       |
|            | 4211.46   |
| labor      | 2050      |
|            | 6261.46   |
| 1/5 less   | 20%       |
|            | 5009.16   |
| Total      |           |
| 1/5 Amt    | \$ 5000 # |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |                      |               |                                                      |                                                      |                                                |            |                                                                 |
|--------------------------|----------------------|---------------|------------------------------------------------------|------------------------------------------------------|------------------------------------------------|------------|-----------------------------------------------------------------|
| Case                     | Notified             | Est Submitted | Adj Assigned                                         | Adj Rpt                                              | Adj Submitted                                  | Ins Auth'd | Status                                                          |
| Main                     | 08 Jan 2020<br>11:28 |               | 08 Jan 2020<br>16:53<br><a href="#">Edit Adj Rpt</a> | <b>\$55,000.00</b><br><a href="#">Edit Estimates</a> | <b>\$55,000.00</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

  

| Main                                                                                                                                                                          | Reference                                                                                                          | Claim Details          | Documents                                                                    | Show All |         |             |              |            |       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|------------------------|------------------------------------------------------------------------------|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>                                                                                        |                                                                                                                    |                        |                                                                              |          |         |             |              |            |       |
| Insured:                                                                                                                                                                      | GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G                                                                     |                        |                                                                              |          |         |             |              |            |       |
| Main Claimant:                                                                                                                                                                | YONG CHAN CHONG, ID: S78319871                                                                                     |                        |                                                                              |          |         |             |              |            |       |
| Vehicle Reg. No.:                                                                                                                                                             | SJK7474T                                                                                                           | Date of Loss:          | 06/01/2020 22:00 - :59<br>[134 Months and 6 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:                                                                                                                                                                   | TP / 616928                                                                                                        | Policy/Cover Note No.: | 29114756 (Comprehensive)<br>Coverage: 01/02/2019 - 31/01/2020                |          |         |             |              |            |       |
| Vehicle Reg. No. (Insured):                                                                                                                                                   | SLN6382S                                                                                                           | Policy No. (Claimant): |                                                                              |          |         |             |              |            |       |
|                                                                                                                                                                               |                                                                                                                    | Excess:                |                                                                              |          |         |             |              |            |       |
| Repairer:                                                                                                                                                                     | Z-one Automotive Pte Ltd - Kb (HQ) 1 Kaki Bukit Avenue 6, #01-87/85 Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: |                        |                                                                              |          |         |             |              |            |       |
| Handling Insurer:                                                                                                                                                             | MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]      |                        |                                                                              |          |         |             |              |            |       |
| Adjuster:                                                                                                                                                                     | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 07/02/2020]    |                        |                                                                              |          |         |             |              |            |       |
| Adj Asg. Remarks:                                                                                                                                                             | on WP. OI:Grab. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Sya @ 6634 2112.            |                        |                                                                              |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>                                                 |                                                                                                                    |                        |                                                                              |          |         |             |              |            |       |
| There are no mail for this case.                                                                                                                                              |                                                                                                                    |                        |                                                                              |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |                                                                                                                    |                        |                                                                              |          |         |             |              |            |       |
| Due Date                                                                                                                                                                      | Priority                                                                                                           | Type                   | Task Group                                                                   | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.                                                                                                                                                                   |                                                                                                                    |                        |                                                                              |          |         |             |              |            |       |

## Claim Documents

\*SJK7474T (616928)  
[SLN63825]  
TP  
YONG CHAN CHONG  
Jan 6 2020 10:00PM  
[GRAB RENTALS PTE LTD]  
Z-one Automotive Pte Ltd - Kb

|                    |                 |                                   |  |                    |  |            |           |                                     |  |
|--------------------|-----------------|-----------------------------------|--|--------------------|--|------------|-----------|-------------------------------------|--|
| Upload Documents   |                 | Upload Photos                     |  | Compose New Letter |  | View       |           | View in Browser                     |  |
| Assessment Reports |                 |                                   |  |                    |  | 1 per page |           | <input checked="" type="checkbox"/> |  |
| No                 | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) |  |                    |  |            | Thumbnail | Print                               |  |
| 1                  | 15/01/20 16:28  | Adjuster Immediate Advice         |  |                    |  |            | Load HTM  |                                     |  |
| Photos/Images      |                 |                                   |  |                    |  | 3 per page |           | <input checked="" type="checkbox"/> |  |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) |  |                    |  |            | Thumbnail | Print                               |  |
| 1                  | 15/01/20 09:34  | Chassis Number                    |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 2                  | 15/01/20 09:35  | Odometer Reading                  |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 3                  | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 4                  | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 5                  | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 6                  | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 7                  | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 8                  | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 9                  | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 10                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 11                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 12                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 13                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 14                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 15                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 16                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 17                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 18                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 19                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 20                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 21                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 22                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 23                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 24                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 25                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 26                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 27                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 28                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 29                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 30                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 31                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 32                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 33                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |
| 34                 | 15/01/20 09:35  | General View                      |  |                    |  |            | Load JPG  | <input checked="" type="checkbox"/> |  |

| Assessment Reports |                |                                   | 1 per page                                                                                     | <input checked="" type="checkbox"/> |
|--------------------|----------------|-----------------------------------|------------------------------------------------------------------------------------------------|-------------------------------------|
| No                 | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail                                                                                      | Print                               |
|                    |                |                                   |                                                                                                | <input checked="" type="checkbox"/> |
| 35                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50                 | 15/01/20 09:35 | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 52                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 53                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 54                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 55                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 56                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 57                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG   | <input checked="" type="checkbox"/> |
| 58                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 59                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 60                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 61                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 62                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 63                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 64                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 65                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 66                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 67                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 68                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 69                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 70                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 71                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 72                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 73                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 74                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 75                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 76                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 77                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 78                 | 17/01/20 09:42 | Reinspection Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 79                 | 04/02/20 11:23 | After Repair Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 80                 | 04/02/20 11:23 | After Repair Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 81                 | 04/02/20 11:23 | After Repair Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 82                 | 04/02/20 11:23 | After Repair Photo                |  Load JPG | <input checked="" type="checkbox"/> |
| 83                 | 04/02/20 11:23 | After Repair Photo                |  Load JPG | <input checked="" type="checkbox"/> |

| Assessment Reports |                 |                                           |   | 1 per page | <input checked="" type="checkbox"/> |
|--------------------|-----------------|-------------------------------------------|---|------------|-------------------------------------|
| No                 | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)         |   | Thumbnail  | Print                               |
| 84                 | 04/02/20 11:23  | After Repair Photo                        | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| 85                 | 04/02/20 11:23  | After Repair Photo                        | 1 | Load JPG   | <input checked="" type="checkbox"/> |
| Documentation      |                 |                                           |   | 1 per page | <input checked="" type="checkbox"/> |
| No                 | Finalized On    | MSIG Insurance (Singapore) Pte. Ltd. (HQ) |   | Thumbnail  | Print                               |
| 1                  | 08/01/20 11:31  | PRI                                       | 1 | Load PDF   |                                     |
| 2                  | 08/01/20 11:32  | TP GIA                                    | 1 | Load PDF   |                                     |
| 3                  | 08/01/20 11:54  | Agree on SJE                              | 1 | Load PDF   |                                     |
| No                 | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)         |   | Thumbnail  | Print                               |
| 1                  | 06/02/20 14:58  | Supplementary                             | 1 | Load PDF   |                                     |

## Documents Checklist

| DOCUMENTS CHECKLIST                                                                                                                                | Reset | Save | Print |
|----------------------------------------------------------------------------------------------------------------------------------------------------|-------|------|-------|
| There are no document checklists configured.                                                                                                       |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>       |       |      |       |
| <b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20000574/HYF3E2

Date: 06/02/2020

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29114756

Claimant Vehicle No : SJK7474T

Insured Vehicle No : SLN6382S

Date of Loss: 06/01/2020

Nature of Claim: TP Claim No: 616928

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJK7474T

Make & Model: MERCEDES-BENZ E200K, 1.8 (A)

Engine No: 27195631044526

Reg. Date: 31/10/2008 (Man. Year: 2008)

Chassis No: WDB2110412B353526

Colour: Brown

Odometer: 164821 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 245/45R17

Rear Tyre Size: 245/45R17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                           | Repairer's       | Adjuster's      | Difference       | Diff %       |
|------------------------------------------|------------------|-----------------|------------------|--------------|
| Parts                                    | 15,084.00        | 4,211.46        | 10,872.54        | 72.08        |
| Miscellaneous Items                      | 0.00             | 0.00            | 0.00             |              |
| Labour                                   | 2,780.00         | 2,050.00        | 730.00           | 26.26        |
| Paintwork Labour                         | 0.00             | 0.00            | 0.00             |              |
| Towing                                   | 0.00             | 0.00            | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>17,864.00</b> | <b>6,261.46</b> | <b>11,602.54</b> | <b>64.95</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                  | <b>5,000.00</b> |                  |              |
| (S\$)                                    | 17,864.00        | 5,000.00        | 12,864.00        | 72.01        |
| <b>+ GST 7.00/7.00% (S\$)</b>            | 1,250.48         | 350.00          | 900.48           | 72.01        |
| <b>Nett Amount (S\$)</b>                 | <b>19,114.48</b> | <b>5,350.00</b> | <b>13,764.48</b> | <b>72.01</b> |

### INSPECTION

Date of Assignment: 08/01/2020

Date Inspected: 14/01/2020 Inspected At:

Z-one Automotive Pte Ltd - Kb (HQ)  
1 Kaki Bukit Avenue 6, #01-87/85 Autobay  
@ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 6.0 days

---

**Adjuster:** LEE HOCK ANN**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

|                                                              |                                                                                                                                                                              |
|--------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Part Source:</b> MRM-SG                                   | Version: 1.0 (Last Synchronised: 06 Feb 2020)                                                                                                                                |
| <b>Parts:</b> 143                                            | MERCEDES-BENZ E200K 1.8 (A) (Catalogue:Merimen Singapore 1.0)                                                                                                                |
| <b>Labour:</b> Repairer's                                    | (Price-denominated Standard List)                                                                                                                                            |
| <b>Print Code:</b> (Unsubmitted, no print-code for SJK7474T) |                                                                                                                                                                              |
| <b>Validity:</b>                                             | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>                                         | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |

## Recommended Parts

| No. | Qty | Part No. | Particulars                            | Condition     | Repairer's  | Amount       |
|-----|-----|----------|----------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT DOOR BOTTOM HINGE RH            | Not Necessary | 125.00 FL   | *- FL        |
| 2   | 1   |          | *FRONT DOOR BOTTOM SEAL RH             | Not Necessary | 86.00 FL    | *- FL        |
| 3   | 1   |          | *FRONT DOOR CHECKER RH                 | Not Necessary | 45.00 FL    | *- FL        |
| 4   | 1   |          | *FRONT DOOR PROTECTOR MOULDING RH      | Scratched     | 192.00 FL   | *100.50 FL   |
| 5   | 1   |          | *FRONT DOOR GLASS CHANNEL RH           | Serviceable   | 182.00 FL   | *- FL        |
| 6   | 1   |          | *FRONT DOOR GLASS OUTER MOULDING RH    | Serviceable   | 195.00 FL   | *- FL        |
| 7   | 1   |          | *FRONT DOOR GLASS REGULATOR CARRIER RH | Serviceable   | 289.00 FL   | *- FL        |
| 8   | 1   |          | *FRONT DOOR GLASS REGULATOR MOTOR RH   | Serviceable   | 566.00 FL   | *- FL        |
| 9   | 1   |          | *FRONT DOOR GLASS REGULATOR RH         | Serviceable   | 635.00 FL   | *- FL        |
| 10  | 1   |          | *FRONT DOOR INNER LOCK RH              | Jammed        | 586.00 FL   | *395.20 FL   |
| 11  | 1   |          | *FRONT DOOR LOCK STRIKER RH            | Serviceable   | 42.00 FL    | *- FL        |
| 12  | 1   |          | *FRONT DOOR OUTER HANDLE RH            | Serviceable   | 156.00 FL   | *- FL        |
| 13  | 1   |          | *FRONT DOOR RH                         | Bent          | 1,826.00 FL | *1,620.80 FL |
| 14  | 1   |          | *FRONT DOOR TOP HINGE RH               | Serviceable   | 125.00 FL   | *- FL        |
| 15  | 1   |          | *FRONT DOOR TOP SEAL RH                | Serviceable   | 122.00 FL   | *- FL        |
| 16  | 1   |          | *FRONT DOOR WEATHER STRIP RH           | Necessary     | 286.00 FL   | *230.50 FL   |
| 17  | 1   |          | *REAR BUMPER                           | Repair        | 1,338.00 FL | *- FL        |
| 18  | 1   |          | *REAR DOOR BOTTOM HINGE RH LOWER       | Bent          | 125.00 FL   | *125.00 FL   |
| 19  | 1   |          | *REAR DOOR BOTTOM SEAL RH              | Serviceable   | 82.00 FL    | *- FL        |
| 20  | 1   |          | *REAR DOOR CHECKER RH                  | Crumpled      | 45.00 FL    | *45.00 FL    |
| 21  | 1   |          | *REAR DOOR PROTECTOR MOULDING RH       | Scratched     | 183.00 FL   | *100.50 FL   |
| 22  | 1   |          | *REAR DOOR GLASS CHANNEL RH            | Serviceable   | 162.00 FL   | *- FL        |
| 23  | 1   |          | *REAR DOOR GLASS OUTER MOULDING RH     | Serviceable   | 189.00 FL   | *- FL        |
| 24  | 1   |          | *REAR DOOR GLASS REGULATOR CARRIER RH  | Serviceable   | 284.00 FL   | *- FL        |
| 25  | 1   |          | *REAR DOOR GLASS REGULATOR MOTOR RH    | Serviceable   | 566.00 FL   | *- FL        |
| 26  | 1   |          | *REAR DOOR GLASS REGULATOR RH          | Serviceable   | 639.00 FL   | *- FL        |
| 27  | 1   |          | *REAR DOOR INNER LOCK RH               | Serviceable   | 560.00 FL   | *- FL        |
| 28  | 1   |          | *REAR DOOR INNER TRIM BOARD RH         | Serviceable   | 1,406.00 FL | *- FL        |
| 29  | 1   |          | *REAR DOOR OUTER HANDLE INNER GUIDE RH | Serviceable   | 85.00 FL    | *- FL        |
| 30  | 1   |          | *REAR DOOR OUTER HANDLE RH             | Serviceable   | 132.00 FL   | *- FL        |
| 31  | 1   |          | *REAR DOOR RH                          | Bent          | 1,778.00 FL | *1,520.80 FL |
| 32  | 1   |          | *REAR DOOR TOP HINGE RH                | Serviceable   | 125.00 FL   | *- FL        |
| 33  | 1   |          | *REAR DOOR TOP SEAL RH                 | Serviceable   | 86.00 FL    | *- FL        |
| 34  | 1   |          | *REAR DOOR WEATHER STRIP RH            | Necessary     | 246.00 FL   | *230.50 FL   |
| 35  | 1   |          | *REAR FENDER RH                        | Repair        | 1,886.00 FL | *- FL        |
| 36  | 1   |          | *RH SILL PANEL SKIRT                   | Repair        | 895.00 FL   | *- FL        |
| 37  | 1   |          | *FRT DOOR CHROME PROTECTOR             | Scratched     | 275.00 FL   | *155.30 FL   |
| 38  | 1   |          | *REAR DOOR CHROME PROTECTOR            | Scratched     | 215.00 FL   | *155.30 FL   |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars | Condition                                          | Repairer's | Amount   |
|-----|-----|----------|-------------|----------------------------------------------------|------------|----------|
|     |     |          |             | Sub Total (S\$)                                    | 16,760.00  | 4,679.40 |
|     |     |          |             | - List Item Discount on L Items 10.00/10.00% (S\$) | 1,676.00   | 467.94   |
|     |     |          |             | Total Parts (S\$)                                  | 15,084.00  | 4,211.46 |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                      | Particulars                                                                                                                                                                | Lab.Type | Repairer's | Amount   |
|-------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|----------|
| <u>Labour Items</u>     |                                                                                                                                                                            |          |            |          |
| 1                       | TO DIAGNOSE,REPLACE AND/OR REPAIR TO RECTIFY FRONT DOOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING                                                                           | New      | 200.00     | 40.00    |
| 2                       | TO DIAGNOSE,REPLACE AND/OR REPAIR TO RECTIFY REAR DOOR ELECTRICAL SYSTEM FOR PROPER FUNCTIONING                                                                            | New      | 200.00     | 160.00   |
| 3                       | TO REMOVE,REFIX/RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING                                                                                               | New      | 180.00     | 50.00    |
| 4                       | TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS,REPAIR PORTION,AND WHERE CONSISTENT TO THE ACCIDENT                                                                           | New      | 1,200.00   | 1,100.00 |
| 5                       | TO PROVIDE LABOUR,WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS,REPAIR,RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE,BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT | New      | 1,000.00   | 700.00   |
| Gross Labour Cost (S\$) |                                                                                                                                                                            |          | 2,780.00   | 2,050.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >