

ASS. REC. BY:

REF:

es/ctt20000581/Hvd302

Special Instruction:

Surveyor: HOCK ANNASSIGNMENT (Office)From (Person): Chong Boon Sen

of

CTIDate/Time: 9/1/2020 @ 8.51am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBL 8109G

Insured:

SLS 9007E

at Workshop m/s

MS car Auto

Tel:

63851838

of

8 kaki Bukit Ave + # 01-07 premier

Policy No:

Claim No:

SNM20D200103/SLS9007E/CBS

Sum Insured:

Excess:

Make of Veh:

D.O.A.

02/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:20am @ 9/1/2020

Person Contacted:

JuneVehicle IN/OUT

Date/Time	Action/Instruction
	<u>Inform (X)</u>
	<u>FBL 8109G - X</u>
	<u>SLS 9007E - X</u>
	<u>9/1/20 - survey taken.</u>
	<u>13/1/20 - survey taken.</u>
	<u>1/1 - iden party involved.</u>
<u>15/1/2020</u>	<u>Submit PRS, Repair Range \$3500 - \$4500</u>

ASS. REC BY: 11- AAN

REF: CTI

ASSIGNMENT

PRS

From: \_\_\_\_\_ Date: 09/01/2020

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: FBL 8109G

at Workshop m/s MS CAR Auto

of 8 kaki Bukit Ave & # 01-07 premier

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: FBL 8109G Yr Regn: 16/03/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: K.T.M 390 04ke c.c. 373

Colour: orange A/C: Insured / Std / NI / NA

Sp.Reading: 162/6 km T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: UBKJGJ 407 FC 268503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110/70/R17

R: 130/60/R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5 mm

L/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 2/1/20

D.O.I. 2/1/20

Survey held at MS CAR Auto

Des. of Damages: Frnt / Rear / O/S / NIS / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Range → 315-4.5h</u>
	<u>npr Days → 4 day</u>
	<u>* FBL 8109G</u>
	<u>l pas case</u>
	<u>* shortage GIA report</u>
	<u>workshop NON given</u>
	<u>10/1/2020</u>
	<u>MV - 11000</u>
	<u>PV - 4883</u>
	<u>NV - 6100</u>

RECEIVED 15 JAN 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 15h -typist

Days Of Repair: 4

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Report Format: PRS

Lump Sum / L&B: \$

Survey Fee:

150

Transportation:

\$ + RS: \$

Photos

Other

TOTAL

150

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Thursday, 9 January 2020 8:51 AM  
**To:** Chia Jia Rong  
**Cc:** 'assignments'  
**Subject:** RE: OUR REF: SNM20D200103/SLS9007E/CBS - FW: Pre Repair Inspection

### WITHOUT PREJUDICE SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

### Chong Boon Sen

Claims Executive  
Department

#### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Chia Jia Rong [mailto:[jjarong@roypartners.com.sg](mailto:jjarong@roypartners.com.sg)]  
**Sent:** Wednesday, January 8, 2020 5:48 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: OUR REF: SNM20D200103/SLS9007E/CBS - FW: Pre Repair Inspection

Dear Sirs,

Our client reject your list of proposed motor surveyors and propose Ms. Tan Ling Ling, Candy of Impact Analysis Consultant and Mr Patrick Ng of AJAX Inspection Services Pte Ltd as the Single Joint Expert.

Pursuant to the new NIMA protocol, kindly let us know within **2 working days** of receipt of our letter whether you agree or has any objections to the motor surveyor proposed by our client, failing which you are deemed to have agreed to the appointment of any of the motor surveyors proposed by our client.

With regards,

**Chia Jia Rong**

M/s Roy & Partners  
133 New Bridge Road  
#08-09  
China Town Point  
Singapore 059413  
Tel : 6536 8466 Fax : 6536 1963  
Email : [jiarong@roypartners.com.sg](mailto:jiarong@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

---

**From:** Chong Boon Sen [<mailto:boonsen.chong@sg.cntaiping.com>]  
**Sent:** Wednesday, 8 January, 2020 5:29 PM  
**To:** [jiarong@roypartners.com.sg](mailto:jiarong@roypartners.com.sg)  
**Subject:** RE: OUR REF: SNM20D200103/SLS9007E/CBS - FW: Pre Repair Inspection

Without prejudice  
Save as to costs

Dear Sir,  
LKK  
LBS  
STA

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** Claims Dept of CTI  
**Sent:** Wednesday, January 8, 2020 5:12 PM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>; Chee So Chow  
<[sochow.chee@sg.cntaiping.com](mailto:sochow.chee@sg.cntaiping.com)>; [jiarong@roypartners.com.sg](mailto:jiarong@roypartners.com.sg)  
**Cc:** Claims Dept of CTI <[claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)>  
**Subject:** OUR REF: SNM20D200103/SLS9007E/CBS - FW: Pre Repair Inspection

Dear Boon Sen,

Please conduct PRS for FBL8109G.

Note : officer in charge – Boon Sen 63896171.

\*\*\* Kindly quote our reference number when replying.

Thank you

Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

**From:** Chia Jia Rong [<mailto:jiarong@roypartners.com.sg>]

**Sent:** Wednesday, January 08, 2020 2:46 PM

**To:** Claims Dept of CTI

**Cc:** 'MS Group Office'

**Subject:** Pre Repair Inspection

Our Ref: MKR/307/9448/2019/as.jr;

Your Ref: Your insured vehicle no. SLS 9007E;

Dear Sirs,

**CLAIMANT: Tan Joon Kang (Owner of FBL 8109G)**

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. FBL 8109G AND SLS 9007E ALONG SLE ON 02.01.2020 AT ABOUT 2020 HOURS.**

We refer to the above matter.

We act for TAN JOON KANG, the owner of motor vehicle No. **FBL 8109G**.

We are instructed by our client to notify you of a road traffic accident on 02.01.2020 at about 2020 hours along SLE involving our client's motor vehicle registration number **FBL 8109G** and motor vehicle registration number **SLS 9007E** driven by your insured at the material time. A copy of the Singapore Accident Statement report is attached.

As a result of the accident, our client's motor car **FBL 8109G** has been damaged. Before our client proceed to repair the damaged motor car, please let us know within two (2) working days of your receipt of this notice whether you would like to conduct a pre-repair survey of our client's motor car **FBL 8109G** at our client's repairer workshop, MS Car Auto Pte Ltd change at **No. 8 Kaki Bukit Ave 4 #01-07 Premier @ Kaki Bukit Singapore 415875**. Your said surveyor may contact **Desmond and June at 6385 1838**. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the motor car without further reference to you.

With regards,

**Chia Jia Rong**

M/s Roy & Partners

133, New Bridge Road  
#08-09  
China Town Point  
Singapore 059413  
Tel : 6536 8466 Fax : 6536 1963  
Email : [jiarong@roypartners.com.sg](mailto:jiarong@roypartners.com.sg)

*IMPORTANT NOTE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please notify the sender immediately. You should also delete and destroy all copies of it. Thank you.*

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	308D
<b>Vehicle Details</b>	
Vehicle No.:	FBL8109G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Jan 2020
Vehicle Make:	K.T.M.
Vehicle Model:	390 DUKE
Primary Colour:	White
Secondary Colour:	Orange
Manufacturing Year:	2016
Engine No.:	590226425
Chassis No.:	VBKJGJ407FC268503
Maximum Power Output:	-
Open Market Value:	\$4,243.00
Original Registration Date:	16 Mar 2017
First Registration Date:	16 Mar 2017
Transfer Count:	2
Actual ARF Paid:	\$637.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	15 Mar 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,801.00
COE Rebate Amount:	\$4,883.00
<b>Total Rebate Amount:</b>	<b>\$4,883.00</b>

The information contained herein is correct as at 10 Jan 2020

OK



(7)

Bike model

Type Of Vehicle

Any

Price From

Any

Price To

Any


Class

Any

MORE SEARCH OPTIONS

Q SEARCH

VIEW ALL (/LISTING/USEDBIKES/LISTING/)



(/listing/usedbike/gallery/ktm-ktm-390-duke/15543/)

REPORT ERROR (/LISTING/LISTING/ERROR/USEDBIKE/15543/)

SHORTLIST

Share It

SHARE (WHATSAPP/SENDTEXT=HTTPS://WWW.SGBIKEMART.COM.SG/LISTING/USEDBIKE/15543/)

## KTM 390 Duke

Listing Type

Free Ad

Brand

KTM (/listing/usedbike/brand/ktm/)

Model

KTM 390 Duke (/listing/usedbike/model/ktm-390-duke/)

Engine Capacity

373cc

Classification

Class 2A (/listing/usedbike/model/motorcycle-for-sale/class/class-2a/)

Registration Date

08/03/2019

COE Expiry Date

07/03/2029 (9 years 1 months left)

Mileage

4000km

No. of owners

1

Type of Vehicle

Street Bikes (/listing/usedbike/model/motorcycle-for-sale/street-bikes/)

Price: SGD\$14000

\$11000

## DETAILS

Selling March 2019 Duke 390, Low Millage Under 4K. Still Under Warranty 2 Years By Dirt Wheel. Always Parked In Covered Carpark. Never Been Outside Singapore. Never Dropped / No Accident. Basically As Good As New. Powerful 2A Bike, Yet Very Light And Easy To Handle. Fun To Ride. Bike Fully Paid. Cash Only. Arrange Your Own Loan If You Need.



Actual €

## SINGAPORE ACCIDENT ST

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation repudiates policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	10/01/2020 09:44
Date Of Accident	02/01/2020 20:20
Exact Location Of Accident	SLE TOWARDS BKE BEFORE LENTOR AVE EXIT 3
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBL8109G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN JOON KANG
NRIC No	SXXXX308D
Email Address	MSGROUPOFFICE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83289159
Alternative Phone No	OFFICE-83289159

## Vehicle Particulars

Manufacturer	KTM
Model	390 DUKE-390CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

## Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	MA005708
Cover Note Number	

## Driver

Name of Driver	TAN JOON KANG
NRIC No	SXXXX308D
Date Of Birth	02/09/1996
Occupation	INDOOR
Date Of Driving Pass	28/02/2018
Driving Experience	1 YEAR AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83289159
Fax Number	
Contact Number	OFFICE-83289159
EMail Address	MSGROUPOFFICE@GMAIL.COM

Address	BLK642 CHOA CHU KANG STREET 64 #12-71
Postcode	680642
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	10 UBI AVENUE 3
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### Details of Witness 1

Name	SAMUEL CHEW
Phone Number	91511036
Email Address	

#### DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number	SLS9007E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

. Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	TAN JOON KANG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	FBL8109G
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	

# Sketch Plan



## SKETCH PLAN

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS A Police Report

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Keylin  
Policyholder's Signature Date  
& Time:

Keylin  
Driver's Signature  
(If driver is not the policyholder) Date  
& Time:

Keylin  
Reporting Centre Personnel's Signature  
Name: MOO WEN ZHENG  
NRIC/FIN No.:

## Common Statement


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time :

  
Driver's Signature  
(If driver is not the policyholder) Date & Time:

  
Reporting Centre Personnel's Signature  
Name : MOO WEN ZHENG  
NRIC / Fin No :



# SINGAPORE POLICE FORCE



T/20200103/7023

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20200103/7023

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 03/01/2020 19:05		Vide Report No.:		Station Diary No.:	
<b>Informant's Particulars</b>					
Name of Informant: TAN JOON KANG		Address: APT BLK 642 CHOA CHU KANG STREET 64 #12-71 SINGAPORE 680642			
ID Type / ID No.: NRIC NO / S9630308D		Contact No.: Home/Office: Mobile: 83289159			
Nationality: SINGAPORE CITIZEN		Email: victorwong18369@gmail.com			
Sex: Male	Age: 23	Date of Birth: 02/09/1996	Type of Informant: Rider		
Race: Chinese		Language: English		Institution / School Name:	
Occupation: Student		Driving Licence Information: Class:		Date of Expiry:	

## General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/01/2020 20:20	Type of Location: Straight Road
Location:  SELETAR EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 80 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction			Anyone conveyed by ambulance: No	

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL8109G	Motorcycle	KTM	390 DUKE	White		0
SLS9007E	Car					0

## Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL8109G	ETIQA INSURANCE BERHAD	MA005708	16/09/2019	15/09/2020



**SINGAPORE  
POLICE FORCE**



T/20200103/7023

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20200103/7023

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	TAN JOON KANG	ID No.	S9630308D
Related Vehicle	FBL8109G (Motorcycle)	Contact No.	83289159
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	02/01/2020	Date Discharge	03/01/2020
No. of Days granted Medical Leave	04	Degree of Injury	Serious

**Brief Details.**

I was travelling on SLE TOWARDS BKE BEFORE LENTOR AVENUE on my own lane, the lane 2 of the expressway. The vehicle (SLS9007E) abruptly cut into my lane. Suddenly I felt a huge impact on the side of my motorbike and I fell and roll away to lane 1 and was seriously injured due to the accident. I was conveyed to KHOO TECK PHUAT hospital by the ambulance to receive treatment and was given 4 days MC.



**SINGAPORE  
POLICE FORCE**



T/20200103/7023

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20200103/7023

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPHQ /  
SHAHRUL NIZAM BIN SAMARRI  
Contact No.: 65476904

Authentication Stamp

NP168

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:  
03/01/2020 19:05

Classification Of Case:





# SINGAPORE POLICE FORCE



T/20200103/7023

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

1 of 3

Report No. T/20200103/7023

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 03/01/2020 19:05	Vide Report No.:	Station Diary No.:
--	------------------	--------------------

**Informant's Particulars**

Name of Informant: TAN JOON KANG			Address: APT BLK 642 CHOA CHU KANG STREET 64 #12-71 SINGAPORE 680642		
ID Type / ID No.: NRIC NO / S9630308D			Contact No.: Home/Office: Mobile: 83289159		
Nationality: SINGAPORE CITIZEN			Email: victorwong18369@gmail.com		
Sex: Male	Age: 23	Date of Birth: 02/09/1996	Type of Informant: Rider		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Student			Driving Licence Information: Class: Date of Expiry:		

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/01/2020 20:20	Type of Location: Straight Road
Location:  SELETAR EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit: 80 Km/h
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FBL8109G	Motorcycle	KTM	390 DUKE	White		0
SLS9007E	Car					0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FBL8109G	ETIQA INSURANCE BERHAD	MA005708	16/09/2019	15/09/2020



**SINGAPORE  
POLICE FORCE**



T/20200103/7023

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20200103/7023

**CONTINUATION OF REPORT**

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	TAN JOON KANG	ID No.	S9630308D
Related Vehicle	FBL8109G (Motorcycle)	Contact No.	83289159
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	02/01/2020	Date Discharge	03/01/2020
No. of Days granted Medical Leave	04	Degree of Injury	Serious

**Brief Details.**

I was travelling on SLE TOWARDS BKE BEFORE LENTOR AVENUE on my own lane, the lane 2 of the expressway. The vehicle (SLS9007E) abruptly cut into my lane. Suddenly I felt a huge impact on the side of my motorbike and I fell and roll away to lane 1 and was seriously injured due to the accident. I was conveyed to KHOO TECK PHUAT hospital by the ambulance to receive treatment and was given 4 days MC.



**SINGAPORE  
POLICE FORCE**



T/20200103/7023

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

3 of 3

Report No. T/20200103/7023

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPHQ /  
SHAHRUL NIZAM BIN SAMARRI  
Contact No.: 65476904

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by SingPass. No signature is  
required.

Date/Time:  
03/01/2020 19:05

Classification Of Case:

Authentication Stamp

NP168

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2020		10 Jan 2020 14:52 <a href="#">Edit Adj Rpt</a>	<b>\$0.00</b> <a href="#">Edit Estimates</a>	<b>\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------












































CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	tan joon kang								
Vehicle Reg. No.:	FBL8109G	Date of Loss: 02/01/2020 00:00 - :59 [33 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type:	TP / SNM20D200103C02	Policy/Cover Note No.: DMHCSNA00000391900							
Vehicle Reg. No. (Insured):	SLS9007E	Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT, 415875 Kaki Bukit - Tel: 63851838								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 21/01/2020]								
<b>ASSOCIATED MAIL RECEIVED</b> <a href="#">View All</a> <a href="#">Compose Case Mail</a>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

























































## Claim Documents













\*FBL8109G (SNM20D200103C02)  
[SLS9007E]  
TP  
tan joon kang  
Jan 2 2020 12:00AM  
[-]  
Ms Car Auto Pte Ltd

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	15/01/20 10:56	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
2	15/01/20 10:57	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
3	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
4	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
5	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
6	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
7	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
8	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
9	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
10	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
11	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
12	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
13	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
14	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
15	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
16	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
17	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
18	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
19	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
20	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
21	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
22	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
23	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
24	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
25	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
26	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
27	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
28	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
29	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
30	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
31	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
32	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
33	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
34	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
35	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
36	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
37	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
38	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
39	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
40	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
41	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
42	15/01/20 10:57	General View	 Load JPG	<input checked="" type="checkbox"/>
43	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
45	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
46	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
47	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
48	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
49	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
50	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
51	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
52	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
53	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
54	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
55	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
56	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
57	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
58	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
59	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
60	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
61	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
62	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
63	15/01/20 10:58	General View	 Load JPG	<input checked="" type="checkbox"/>
64	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	15/01/20 10:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
100	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
101	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
102	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
103	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
104	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
105	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
106	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
107	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
108	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
109	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
110	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
111	15/01/20 10:59	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; width: 100%;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20000581/HVD3E2

Date: 15/01/2020

### REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00000391900
Claimant Vehicle No :	FBL8109G	Insured Vehicle No :	SLS9007E
Date of Loss:	02/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200103C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBL8109G	Engine No:	590226425
Make & Model:	KTM 390 DUKE, 390cc	Chassis No:	VBKJGJ407FC268503
Reg. Date:	16/03/2017 (Man. Year: 2016)	Odometer:	16216 km
Colour:	Orange		
Engine Capacity:	373 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	10/01/2020	
Date Inspected:	09/01/2020 Inspected At:	Ms Car Auto Pte Ltd (HQ) 8 KAKI BUKIT AVE 4 #01-07 PREMIER @ KAKI BUKIT Singapore 415875
Estimated Period of Repair:	4.0 days	

Adjuster: LEE HOCK ANN

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 - \$4,500.00

## REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 15 Jan 2020)
Parts:	N/A	KTM 390 DUKE 390cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL8109G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >