

ASS. REC. BY:

REF: CS/17M1 20000603/ Fyf302

Special Instruction:

Surveyor: RamASSIGNMENT (Office)From (Person): Dillen Scrutlanof TM1Date/Time: 9 Jan 2020 16:04:12

Estimated Cost: _____

Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SHA 4744KInsured: EZ 3368Zat Workshop m/a ComfortdelgroTel: 62148300of 59 Ioyang DrivePolicy No: MJ 001419Claim No: M 2000235

Sum Insured: _____

Excess: _____

Make of Veh: _____

D.O.A. 9.1. 2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 9.1.2020 4:00pmPerson Contacted: Lumai

H.O.D. Endorsement: _____

Vehicle IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SHA 4744K - CS 3/17 17003597 / H/H/m/z - 1 D.O.A. 2/04/2017
	EZ 3368Z - X

written

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

View	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Authred	Status
Main	09 Jan 2020 Sendback Est	09 Jan 2020 14:23 S\$2,291.02	09 Jan 2020 16:04 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ERIC THAM CHEE TUCK, ID: S1228265F		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA4744K	Date of Loss:	09/01/2020 05:00 - :59 [34 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2000235	Policy/Cover Note No.:	MJ001419 (Comprehensive) Coverage: 13/10/2019 - 12/10/2020
Vehicle Reg. No. (Insured):	EZ3368Z	Policy No. (Claimant):	MCOM0015
		Excess:	S\$1,500.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/01/2020 10:43
Date Of Accident	09/01/2020 05:30
Exact Location Of Accident	TQA PAYOH EAST
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4744K
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXXX21R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	PEK POON TOW
NRIC No	SXXXX049C
Date Of Birth	20/07/1957
Occupation	OUTDOOR
Date Of Driving Pass	02/09/1976
Driving Experience	43 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91763044
Fax Number	
Contact Number	
Email Address	PEKPOONTOW@YAHOO.COM.SG

Address	BLK 504 HOUGANG AVENUE 8 #01-718
Postcode	530504
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	EZ3368Z
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	TOKIO MARINE INSURANCE SINGAPORE LTD
Nature Of Damage	FRT

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GI& Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 18930321R

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

A) SHAKTHAK
 B) KZS 3682
 [B] 1/2 A
 Tai Kien East

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 9/1/20 at about 0530hrs when I Veh A gradually
 slowed down with my hazard lights on and stopped
 to assist my passenger. Veh B entered onto the
 view of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE. LTD.
 CO. REG. NO. 199303621H

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/Fin No:

Form 101 (Rev. 1/19)


Team: AEC Repair TP(CLSO)1	JOB CARD	Sales Order:	JC NO.: 305373169
CUSTOMER COMFORT TRANSPORTATION PTE LTD 7010045 CUSTOMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (P)	REGN NO: SHA4744K MAKE: HYUNDAI MODEL: IONIQ YR OF MANU: 24.02.2017 CHASSIS CODE: KMHC851CVHU022703	MILEAGE FUEL E 1/2 F DATE/TIME IN: 09.01.2020 09:00 TARGET DATE COMPLETION DATE/TIME:	
COUNT CARD NO.			

Accident Date: 09.01.2020
NATURE: 3P 09.01.2020

JOB DESCRIPTION

S/O LABOR CODE
TOKIO - Rear
Ltr/Rdm -

DESCRIPTION



CHECKED & PASSED OUT BY:			
SERVICE ADVISOR		CUSTOMER'S SIGNATURE	
Acknowledgement Slip		Exit Pass	
No.: SHA4744K	LARRY	Vehicle No.: SHA4744K	
Signature/Date		Name of Service Advisor	
Date		Date	
Returned to Service Reception upon collection		To be kept by Security Guard	

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
COMFORT TRANSPORTATION PTE LTD

Singapore

Claimant Insurer: India International Insurance Pte Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	09/01/2020
Vehicle Reg. No.:	SHA4744K	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	PEK POON TOW		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	24/02/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEGU327397	Chassis No:	KMHC851CVHU022703
Odometer:	1 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	PLS REFER TO ATTACHED		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,550.02
Miscellaneous Items	11.00
Labour	730.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,291.02

+ GST 7.00% (S\$)	160.37
Nett Amount (S\$)	2,451.39

This claim is handled by: NG NYUK PHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Copy 2/3

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	\$320 350.00
2	SPRAY PAINTING	New \$200	250.00 250.00
3	WIRING CHARGE	New	200 50.00
4	REMOVE/REFIX REVERSE SENSOR	New	\$50 80.00
Gross Labour Cost (S\$)			730.00

ComfortDelGro Engineering Pte Ltd/SHA4744K/09/01/2020 14:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Handwritten notes:
13/1/2020 RQM(LKK)
\$09/01/2020 KAS
Pamela LKK auto...
88622728
2 repair days
P/P
aft paint photo

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Jan 2020)

Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
---------------	-----	--

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA4744K/09/01/2020 14:23

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER Br	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT 1xnn	20.00	0.00	*294.80 FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET - RH/LH 1xnn	20.00	0.00	*276.20 FL
4	1		*REAR BUMPER CENTRE MOLDING ASSY Cra	20.00	0.00	*451.25 FL
5	1		*REAR BUMPER LOWER CENTRE MOLDING ASSY xnn	20.00	0.00	*155.00 FL
6	1		*REAR LICENSE PLATE & CASING chr	0	0.00	*55.00 FS
7	1		*REAR BUMPER RUBBER MAT xnn	0	0.00	*50.00 FS
8	1		*REVERSE SENSOR 1xnn	0	0.00	*135.70 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)

1,877.35

- List Item Discount on L Items (S\$)

327.33

Total Parts (\$\$)

1,550.02

ComfortDelGro Engineering Pte Ltd/SHA4744K/09/01/2020 14:23. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reporter

Signature: _____

Date:

Our Job Ref No : 305373169

Date : 17. Jan. 2020

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHA4744K

Date of Accident: 9. Jan. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO EZ3368Z

2. The finalized amount shall be:

(a) Spare Parts after List discount \$783.52

(b) Labour Charges \$581.00

Total for Part-By-Part Repair Cost \$1,364.52

(c) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Larry Ng

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : Ram

Name : Ram

Date : 17/02/2020

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305373169
 REGN NO : SHA4744K
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ
 DATE OF REGN : 24.02.2017
 DATE/TIME IN : 09.01.2020 09:00
 ACCIDENT DATE : 09.01.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2360-G	IONIQV1 MOULDING ASSY-RR	1	451.25	20.00	361.00	<i>Cra</i>
0002	FNPS	NO PLATE(S)	1 N	55.00	2.00-	55.00	<i>Cra</i>
0003	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	<i>B</i>

SUB-TOTAL : 783.52

JOB NATURE

0000 L	MERIMEN FEE	11.00	<i>/</i>
0001 PB	PANEL BEATING	320.00	<i>/</i>
0002 23-502	SPRAYPAINT ON AFFECTED AREA	200.00	<i>/</i>
0003 L	REMOVE/REFIX REVERSE SENSOR	50.00	<i>/</i>

SUB-TOTAL : 581.00

TOTAL : 1,364.52

MVA NAME & SIGNATURE
 DATE :

 SURVEYOR NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	09 Jan 2020 Sendback Est	09 Jan 2020 14:23 S\$2,291.02	09 Jan 2020 16:04 Edit Adj Rpt	S\$1,364.52 Edit Estimates	S\$1,364.52 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ERIC THAM CHEE TUCK, ID: S1228265F		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA4744K	Date of Loss:	09/01/2020 05:00 - :59 [34 Months and 16 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2000235	Policy/Cover Note No.:	MJ001419 (Comprehensive) Coverage: 13/10/2019 - 12/10/2020
Vehicle Reg. No. (Insured):	EZ3368Z	Policy No. (Claimant):	MCOM0015
		Excess:	S\$1,500.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 20/01/2020]		

ASSOCIATED MAIL RECEIVED
[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA4744K (M2000235)
[EZ3368Z]
TP
COMFORT TRANSPORTATION PTE LTD
Jan 9 2020 5:00AM
[ERIC THAM CHEE TUCK]
ComfortDelGro Engineering Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	09/01/20 10:52	Accident Statement		 Load HTM	
2	09/01/20 14:23	Repairer Estimates		 Load HTM	

Photos/Images

3 per page

No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail	Print
1	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
2	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
3	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
4	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
5	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
6	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
7	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
8	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
9	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒
10	09/01/20 10:48	Accident Photo [Linked Accident Report Documents]		 Load JPG	☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	23/01/20 16:20	Front View		 Load JPG	☒
2	23/01/20 16:20	Front View		 Load JPG	☒
3	23/01/20 16:20	Front View		 Load JPG	☒
4	23/01/20 16:20	Front View		 Load JPG	☒
5	23/01/20 16:20	Front View		 Load JPG	☒
6	23/01/20 16:20	Front View		 Load JPG	☒
7	23/01/20 16:20	Front View		 Load JPG	☒
8	23/01/20 16:20	Front View		 Load JPG	☒
9	23/01/20 16:20	Front View		 Load JPG	☒
10	23/01/20 16:20	Front View		 Load JPG	☒
11	23/01/20 16:20	Front View		 Load JPG	☒
12	23/01/20 16:20	Front View		 Load JPG	☒
13	23/01/20 16:20	Front View		 Load JPG	☒
14	23/01/20 16:20	Front View		 Load JPG	☒
15	23/01/20 16:20	Front View		 Load JPG	☒
16	23/01/20 16:20	Front View		 Load JPG	☒
17	23/01/20 16:20	Front View		 Load JPG	☒
18	23/01/20 16:20	Front View		 Load JPG	☒
19	23/01/20 16:20	Front View		 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
				☒
20	23/01/20 16:20	Front View	 Load JPG	☒
21	23/01/20 16:20	Front View	 Load JPG	☒
22	23/01/20 16:20	Front View	 Load JPG	☒
23	23/01/20 16:20	Front View	 Load JPG	☒
24	23/01/20 16:20	Front View	 Load JPG	☒
25	23/01/20 16:20	Front View	 Load JPG	☒
26	23/01/20 16:20	Front View	 Load JPG	☒
27	23/01/20 16:20	Front View	 Load JPG	☒
28	23/01/20 16:20	Front View	 Load JPG	☒
29	23/01/20 16:20	Front View	 Load JPG	☒
30	23/01/20 16:20	Front View	 Load JPG	☒
31	23/01/20 16:20	Front View	 Load JPG	☒
32	23/01/20 16:20	Front View	 Load JPG	☒
33	23/01/20 16:20	Front View	 Load JPG	☒
34	23/01/20 16:20	Front View	 Load JPG	☒
35	23/01/20 16:20	Front View	 Load JPG	☒
36	23/01/20 16:20	Front View	 Load JPG	☒
37	23/01/20 16:20	Front View	 Load JPG	☒
38	23/01/20 16:20	Front View	 Load JPG	☒
39	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
40	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
41	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
42	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
43	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
44	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
45	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
46	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
47	23/01/20 16:20	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	09/01/20 10:51	Sketch Plan [Linked Accident Report Documents]	 Load TIF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	09/01/20 10:52	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	09/01/20 10:48	Accident Photo	 Load JPG	☒
2	09/01/20 10:48	Accident Photo	 Load JPG	☒
3	09/01/20 10:48	Accident Photo	 Load JPG	☒
4	09/01/20 10:48	Accident Photo	 Load JPG	☒
5	09/01/20 10:48	Accident Photo	 Load JPG	☒
6	09/01/20 10:48	Accident Photo	 Load JPG	☒
7	09/01/20 10:48	Accident Photo	 Load JPG	☒
8	09/01/20 10:48	Accident Photo	 Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
				☒
9	09/01/20 10:48	Accident Photo	 Load JPG	☒
10	09/01/20 10:48	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	09/01/20 10:51	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) ^ v			
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199507198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20000603/FYF3E2

Date: 18/02/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MJ001419

Claimant Vehicle No: SHA4744K

Insured Vehicle No: EZ3368Z

Date of Loss: 09/01/2020

Nature of Claim: TP Claim No: M2000235

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA4744K

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: HM03GBX427GJ

Reg. Date: 24/02/2017 (Man. Year: 2017)

Chassis No: KMHC851CVHU022703

Colour: Blue

Odometer: 385759 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 7 mm	Rear Left Side:	Davanti 8 mm
Front Right Side:	Davanti 7 mm	Rear Right Side:	Davanti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,550.02	783.52	766.50	49.45
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	730.00	570.00	160.00	21.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,291.02	1,364.52	926.50	40.44
+ GST 7.00/7.00% (S\$)	160.37	95.52	64.85	40.44
Nett Amount (S\$)	2,451.39	1,460.04	991.35	40.44

INSPECTION

Date of Assignment: 09/01/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 09/01/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2020)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4744K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Broken	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	-	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET - RH/LH	Not Necessary	276.20 FL	-	*- FL
4	1		*REAR BUMPER CENTRE MOLDING ASSY	Cracked	451.25 FL	-	*451.25 FL
5	1		*REAR BUMPER LOWER CENTRE MOLDING ASSY	Not Necessary	155.00 FL	-	*- FL
6	1		*REAR LICENSE PLATE & CASING	Cracked	55.00 FS	-	*55.00 FS
7	1		*REAR BUMPER RUBBER MAT	Not Necessary	50.00 FS	-	*- FS
8	1		*REVERSE SENSOR	Not Necessary	135.70 FS	-	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	1,877.35	965.65
- List Item Discount on L Items 20.00/20.00% (S\$)	327.33	182.13
Total Parts (S\$)	1,550.02	783.52

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (S\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING	New	250.00	200.00
3	WIRING CHARGE	New	50.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	80.00	50.00
Gross Labour Cost (S\$)			730.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >