

ASS. REC. BY:

REF: CS/CT 20000635/T/yf3

Special Instruction:

excess
\$2000/-

Surveyor

ASSIGNMENT (Office)

From (Person): Chong Ban Seng of CTL

Date/Time: 9 Jan. 2020 16:50 p.m.

~~Estimated Cost:~~

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLW 977T

Insured:

at Workshop m/s Borneo Motors

Tel: 663 11 857 / 9847 6178

of 2 Pandan Crescent

Policy No: DMP/CS/3004/231900

Claim No: SNM 19D 206181C01

Sum Insured:

Excess: \$ 2000.00

Make of Veh:

D.O.A. 28.12.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.1.2020 9.46am

Person Contacted:

wallyVehicle ~~IN~~/OUT

Date/Time

Action/Instruction	(✓) Estimate
--------------------	----------------

SLW 977T - SLW 977T - CS/CTI 19007974/ ASD3n2 D-DA-0570572019

ASS. REC. BY:

Tampubak

REF: CTI

ASSIGNMENT

From:

Date:

14. Jan 2020

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLW 977T

at Workshop m/s

Borneo Motors

of

2 Pandan Crescent

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$2000

(Client's Record)

Make of Veh:

100m - 10.300m owner wally

wally

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

\$290K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA

REV / REP. / 24 HRS

MP'

Vehicle: IN / OUT

Date:

Person Contacted:

wally

Veh No:

SLW977T

Yr Regn:

2018, Jan

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Lexus LS350

c.c

3456

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

43086

T/Radio: Insured / Std / NI / NA

Eng/No:

JTH1346FF705000759

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/50R19

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

15/1/20

Survey held at

Borneo Pandan

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/1

Revert Vja Mericen

17/1

Approved Mandate by Irene Tay

17/1

Sent email to Workshop Authorise

23/7

Confirm PIP \$19,436-40 (Red \$1458.50, 69%)

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

23/7/20 Typist

Report Format:

Lump Sum / F.B.I. /

Days Of Repair:

8

Resurvey No. of Trip:

3

Add Fee:

☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech. Invs (\$)
☐ Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

PIP \$19436-40

View Received Message

This mail is associated with :

***SLW977T (SNM19D206181C01)**

OD

Dec 28 2019 2:00AM

[THL BUILDING CONSTRUCTION PTE LTD]

Borneo Motors (S) Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 17/01/2020 12:59 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$19411.40) - SLW977T - Claim Handler: Chong Boon Sen

Approved:19411.40.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	09 Jan 2020		09 Jan 2020 16:50 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	THL BUILDING CONSTRUCTION PTE LTD, Co. Reg. No.: 200515025R		
Vehicle Reg. No.:	SLW977T	Date of Loss:	28/12/2019 02:00 - :59
Claim Type:	OD / SNM19D206181C01	Policy/Cover Note No.:	DMPCSN3004231900 (Comprehensive)
		Excess:	S\$2,000.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 20/01/2020]		
Driver/Custodian:	TEO HEE LAI (70 / Male) , NRIC: S2075313G, Tel: +6598483188 Email: TEOHEELAI314@GMAIL.COM		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Yvonne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Friday, January 17, 2020 2:44 PM
To: Wally Tan PTCBC
Subject: VEHICLE NO: SLW977T DOA: 28/12/2019

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLW977T (excess \$2000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chong Boon Sen

Date: 16 Jan 2020

Preliminary Advice

Vehicle No	: SLW977T	Accident Date	: 28/12/2019
Make	: LEXUS LS350	Policy No.	: DMPCSN3004231900
Assignment Date	: 09/01/2020	Excess	: S\$2,000.00
Date of Inspection	: 15/01/2020	Est. Duration of Repair	: 8.00
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s. portion and parts claimed are consistent to the accident.

RePAIRER'S Estimate (Gross)	:S\$	11,395.40
Revised Amount	:S\$	16,348.60
Check Items (Estimated)	:S\$	3,062.80
Total	:S\$	19,411.40
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	290,000.00
COE / PARF Rebate	:S\$	146,136.00
Salvage Value	:S\$	
Margin for Repair	:S\$	143,864.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/12/2019 15:22
Date Of Accident	28/12/2019 02:25
Exact Location Of Accident	ALONG SENTOSA GATEWAY (TOWARDS CITY)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW977T
Insured/Policyholder	
Name Of Registered Owner	THL BUILDING CONSTRUCTION PTE LTD
Co Reg No	2XXXXX025R
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-98483188

Vehicle Particulars

Manufacturer	TOYOTA
Model	LEXUS LS350
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPCSN3004231900
Cover Note Number	

Driver

Name of Driver	TEO HEE LAI
NRIC No	SXXXX313G
Date Of Birth	13/02/1949
Occupation	INDOOR
Date Of Driving Pass	03/10/1977
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98483188
Fax Number	
Contact Number	
EEmail Address	TEOHEELAI314@GMAIL.COM

Address	24 LOR J TELOK KURAU
Postcode	425805
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LAU SHE YIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER ATTACHED SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	OVERWRITTEN
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBE4919Z
Vehicle Make/Model/Colour	VOLKSWAGEN VAN WHITE COLOUR
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	ROBERT JAMES
NRIC/Passport Number	
Contact Number	98363023
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



張火來建築工程私人有限公司
THL BUILDING CONSTRUCTION PTE LTD
49 KAKI BUKIT VIEW
SINGAPORE 415973
TEL: 6447 0126
FAX: 6440 6326

30/12/19
2:00 PM


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 28/12/2019 at about 0225 hrs I was driving SLW977T along Sentosa Gateway (towards City) on lane 2 driving at about 40 km/hr. Suddenly I heard a loud bang from my rear. I noticed GBE4919Z driving very fast in front of me. I honk at him and he stopped by the roadside. I took photos and exchanged particulars with the other driver.

DECLARATION
 張大來建築工程私人有限公司
 THE BUILDING CONSTRUCTION PTE LTD
 10 KAKI BUKIT VIEW SINGAPORE 415973
 TEL: 6447 0126
 FAX: 6440 8326
 I declare the foregoing to be true in every respect.

30/12/19
 2:00 PM

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

MX4E
N SN
AN0602A
COMPREHENSIVE

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMPCSH3004231900	Engine No : 80F9508717
		Chassis No: JTHP41FF703000353
1. Index Mark and Registration Number of Vehicle	SLW9777	
2. Name of Policy Holder	K/S THE BUILDING CONSTRUCTION PTE LTD	
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	21 JANUARY 2019	NAMED DRIVERS EX SECT1 :\$81,500.00 IN ADDITION TO NAMED DRIVERS EX.
4. Date of Expiry of Insurance	20 JANUARY 2020	EX SECT. 1 - AGE <= 25\$81,000.00 EX SECT. 1 - AGE >= 26\$8500.00 * AGE AS AT DATE OF ACCIDENT EX ON WINDSCREEN\$8100.00
5. Persons or Classes of Persons entitled to drive *		

ANY PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH THEIR PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT REGARD FROM DRIVING THE MOTOR VEHICLE.

6. Limitations as to use: *

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS.
THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS / THEFT) WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST \$81,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORIZED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO. : DBS BANK LTD AS HP OWNER

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse
For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned By:

Authorized Officer

Authorized Signatory

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Tel: 6389 6111 Fax: 6225 3582 Website: www.sg.cntaiping.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	025R
Vehicle Details	
Vehicle No.:	SLW977T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS LS350 LUXURY MR (AUTO)
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	8GR9508717
Chassis No.:	JTHB4LFF705000959
Maximum Power Output:	232.0 kW (311 bhp)
Open Market Value:	\$98,524.00
Original Registration Date:	30 Jan 2018
First Registration Date:	30 Jan 2018
Transfer Count:	0
Actual ARF Paid:	\$149,344.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Jan 2028
PARF Rebate Amount:	\$112,008.00
Intended COE Rebate Details	
COE Expiry Date:	29 Jan 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,661.00
COE Rebate Amount:	\$34,128.00
Total Rebate Amount:	\$146,136.00

The information contained herein is correct as at 16 Jan 2020

OK

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept <i>Survey on 10-10-30 am 15/1/20</i>	S1000003 / ICCI1 Document No 0 Document Date 09/01/2020 <i>Summer CLK 67418434</i>	M/s Thl Building Construction Pte Ltd 49 Kaki Bukit View Singapore 415973 Attn: Mr Teo Hee Lai Mobile: 98483188

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEUGH	L1	30/01/2018	SLW0977T	0	18103	4UL/SLW0977T/28121!
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB4LFF705000959	8GR9508717	60	Wally Tan G H	30/12/2019	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:DMPCSN3004231900 ACC DATE:28.12.19 TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50. 80.00/
2	B	BP-LAB3 REMOVE/REFIX REAR WINDSHIELD TO ASSIST REPAIR. (NETT)				✓ 866.00/
3	S	BP-SUBLET INSTALLING SOLAR FILM FOR REAR WINDSHIELD. (NETT)				✓ 420.00/
4	B	BP-LAB3 REMOVE/REFIX REAR LUGGAGE COMPARTMENT, INTERIOR TRIM GARNISH TO ASSIST REPAIR. (NETT)				/ 433.00/
5	B	BP-LAB3 REMOVE/REFIX INTERIOR UPHOLSTERY, ROOF LINING, REAR SPEAKER BOARD, TRIMMINGS, GARNISHES, FRONT AND REAR SEATS, SEAT BELTS, FLOOR CARPETS IN ORDER TO FACILITATE REPAIR. (NETT)				✓ 866.00/
6	B	BP-LAB3 CHECK WIRING SYSTEM AND CONDUCT WATER SEEPAGE. (NETT)				✓ 216.50/

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Tanpin 97495749 Not Authorise 15/1/20 @ 10.30. Less Ex \$2000. Resurvey before paint.
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SLW0977T

CUSTOMERDATE 09/01/2020
TIME 12:51SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors*sure lkhanto.com.*
18/3/2020
O.B. days

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR 8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/s Thi Building Construction Pte Ltd 49 Kaki Bukit View Singapore 415973 Attn: Mr Teo Hee Lai Mobile: 98483188
	Document No 0	
	Document Date 09/01/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEUGH	L1	30/01/2018	SLW0977T	0	18103	4UL/SLW0977T/28121

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHB4LFF705000959	8GR9508717	60	Wally Tan G H	30/12/2019 0.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
7	B	BP-LAB3 REMOVE/REFIX REVERSE SENSORS. (NETT)				216.50/
8	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN L/R BODY PANEL, CUT AND WELD PANEL AND FIT NEW PARTS. 866.			3464	4330.00/
9	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR. 742			1484	1855.00/
10	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50/
11	1	L64801-50900 GLASS SUB-ASSY, BACK	1.00	2047.50	nei	2047.50/
12	2	L75571-50080 MOULDING, BACK	1.00	79.10	nei	79.10/
13	3	L56119-50100 SEAL, WINDSHIELD	1.00	37.50	nei	37.50/
14	4	L56117-24070 DAM, WINDOW GLASS	6.00	4.40	nei	26.40/
15	5	L56118-50070 DAM, WINDOW GLASS	1.00	22.50	nei	22.50/
16	6	T04562-12010 W/SCREEN DAM KIT,	1.00	121.00	nei	121.00/
17	7	T21000-20 SIKA 182010 SIKA TACK GO! (BLA	2.00	108.00	nei	216.00/
18	8	T21000-22 SIKA 207. G+P ADHESIVE PRIMER	1.00	200.00	nei	200.00/
19	9	L61602-50110 PANEL SUB-ASSY,	1.00	1596.60	bt	1596.60/
20	0	T62940-12170 L/R QUARTER AIR DUCT,	1.00	136.20	?	136.20/
21	1	L81561-50311 LENS & BODY, RR	1.00	1342.10	Crn	1342.10/
22	2	L81498-50040 COVER, RR	1.00	58.90	nei	58.90/

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 09/01/2020
TIME 12:51

VEHICLE NO SLW0977T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**Page 2 of 4
Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/s Thl Building Construction Pte Ltd 49 Kaki Bukit View Singapore 415973 Attn: Mr Teo Hee Lai Mobile: 98483188
	Document No 0	
	Document Date 09/01/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEUGH	L1	GSF50R	30/01/2018	SLW0977T	0	18103 :4UL/SLW0977T/28121'
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB4LFF705000959	8GR9508717	60	Wally Tan G H	30/12/2019	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
23	3	T81536-52C80 LED, RR COMBINATION	1.00	152.10	?	152.10
24	4	L76817-26040 CLIP, BACK DOOR	1.00	3.50	rec	3.50
25	5	L81496-60010 GUIDE, RR	1.00	3.50	rec	3.50
26	6	L81496-52020 GUIDE, RR	1.00	2.50	rec	2.50
27	7	L52156-50080 SUPPORT, RR BUMPER	1.00	114.90	rec	114.90
28	8	L52563-50060 RETAINER, RR BUMPER,	1.00	115.60	rec	115.60
29	9	L52568-50060 RETAINER, RR BUMPER	1.00	64.60	rec	64.60
30	0	L52566-50080 RETAINER, RR BUMPER,	1.00	302.00	rec	302.00
31	1	L52159-50938 COVER, RR BUMPER	1.00	1108.60	de	1108.60
32	2	L75895-28010 TAPE, MOULDING, NO.1	2.00	50.40	rec	100.80
33	3	L52181-50030 ARM, RR BUMPER	4.00	24.60	?	98.40
34	4	L52162-50907 PIECE, RR BUMPER, LH	1.00	25.90	?	25.90
35	5	L52753-50010 MOULDING, RR BUMPER	1.00	277.40	cut	277.40
36	6	L52169-50070 COVER, RR BUMPER,	1.00	518.50	?	518.50
37	7	L75392-35220 RETAINER OUTSIDE	18.00	3.90	rec	70.20
38	8	S52161-OK040 BUMPER CLIPS	8.00	4.10	rec	32.80
39	9	T90467-07215 CLIP	8.00	2.50	rec	20.00
40	0	L89348-50130 RETAINER, ULTRASONIC	4.00	19.20	rec	76.80
41	1	L89348-58130 CLIP, ULTRASONIC	2.00	12.30	rec	24.60
42	2	L81920-50020 REFLECTOR ASSY,	1.00	48.80	?	48.80

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 09/01/2020
TIME 12:51

VEHICLE NO SLW0977T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motor**


**TAX INVOICE**Co Reg No : 196700086Z
GST R No : MR 8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Page 3 of 4

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	M/s Thi Building Construction Pte Ltd 49 Kaki Bukit View Singapore 415973 Attn: Mr Teo Hee Lai Mobile: 98483188
	Document No 0	
	Document Date 09/01/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	AEUGH	L1	30/01/2018	SLW0977T	0	18103	4UL/SLW0977T/28121!
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHB4LFF705000959	8GR9508717	60	Wally Tan G H	30/12/2019	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
43	3	L88162-50041 SENSOR, BLIND SPOT	1.00	2001.40	?	2001.40
44	4	L88173-50010 COVER, BLIND SPOT	1.00	81.50	?	81.50
45	5	T08826-08115 PANEL BONDING AD	1.00	267.20	NI	267.20
<div style="border: 1px solid black; padding: 10px; margin: 10px;"> <p><u>LKK Auto Consultants</u> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: _____ Date: _____</p> </div> <p>Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.</p>						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 11,395.40	20,894.90
		Labour 9,079.50	GST 7.00% 1,462.64
		Materials 420.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 22,357.54

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 09/01/2020
TIME 12:51

VEHICLE NO SLW0977T

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**