

ASS. REC. BY:

Surveyor: Adrian

REF: es/GAI20000651/Avd302

Special Instruction: ✓

ASSIGNMENT (Office)

From (Person):

Sherry Wong

of

GAI

Date/Time:

10/01/2020 @ 10:23am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLS 5719K

Insured:

SMG 9767X

at Workshop m/s

CAS Garage

Tel:

9791 6119

of

1 Kaki Bukit Ave 6 # 02-22 Autobay

Policy No:

Claim No:

CLMOMVP000001050

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09/01/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:58am @ 10/01/2020

Person Contacted:

Sharon

Vehicle IN/OUT

Date/Time	Action/Instruction
	Estimated ✓
	SLS 5719K - X
	SMG 9767X - X
26/3/20	Adrian confirmed LS \$ 8500 (Red 844.51, 50%)

ASS. REG. BY:

REP:

GAI

ASSIGNMENT

From:

Date:

10/01/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SL85719K

at Workshop m/s

CAS Garage

of

1 Leaki Bukit Ave 6 # 02-22 Autobay

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SL85719K

Yr Regn:

2017 Sept.

Type: ☒ M.Cap / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Kia Cerato K3

c.c 1591

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

37365

T/Radio: Insured / Std / NI / NA

Eng/No:

KNAF X411MJS744607

C/No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modi: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

10/01/20

Survey held at

CAS Garage

Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Grant American

RECEIVED 20 MAR 2020

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

x63 - typist

Days Of Repair:

7

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

3 x RS. \$

Photos

Others

TOTAL

490

490

Report Format:

TP

Lump Sum / L&L:

8500p

Nivitha (LKK Auto)

From: Motor Claims <motorclaims@sg.gaig.com>
Sent: Friday, 10 January 2020 10:23 AM
To: Allan Goh; Nicole Chong; assignments@lkkauto.com; sur@lkkauto.com
Cc: CAS Garage Garage; Ngian, Kelvyna
Subject: Re: Our Ref:CLMOMVP000001050, PRI - ACCIDENT INVOLVING SLS 5719K AND SMG 9767X ALONG BARTLEY RD ON 09.01.2020

Without Prejudice

Dear Sirs,

Noted on your request, our client has yet to report the accident so we will survey on a without prejudice basis.

Dear LKK,

Please accept assignment for TP survey. Thank you.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Allan Goh <allan@casgarage.sg>
Sent: 09 January 2020 8:02 PM
To: Nicole Chong <nicole@casgarage.sg>
Cc: Motor Claims <motorclaims@sg.gaig.com>; CAS Garage Garage <contact@casgarage.sg>; Ngian, Kelvyna <kelvyna.ngian@sg.gaig.com>
Subject: [External] Re: Our Ref:CLMOMVP000001050, PRI - ACCIDENT INVOLVING SLS 5719K AND SMG 9767X ALONG BARTLEY RD ON 09.01.2020

Hi all,

The survey address is as follow:

CAS Garage Pte. Ltd.
No.1 Kaki Bukit Ave 6

#02-22
Singapore 417883

Regards,
Allan Goh
CAS Garage Pte. Ltd.
No.1 Kaki Bukit Ave 6
#02-22
Singapore 417883
UEN: 201828067M
Mobile: 8782 7171

On Thu, 9 Jan 2020 at 17:58, Nicole Chong <nicole@casgarage.sg> wrote:

Dear Sharon,

We request LKK to survey our client's vehicle.

On Thu, 9 Jan 2020 at 17:27, Motor Claims <motorclaims@sg.gaig.com> wrote:

Without Prejudice

Hi Nicole,

Please be reminded to update your records of our email to motorclaims@sg.gaig.com

Our client has not reported accident. Can we have a copy of the SAS report?

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Adjusters & Surveyors Pte. Ltd.
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Nicole Chong <nicole@casgarage.sg>
Sent: 09 January 2020 4:59 PM
To: Motor Claims <motorclaims@sg.gaig.com>
Cc: Allan Goh <allan@casgarage.sg>; CAS Garage Garage <contact@casgarage.sg>
Subject: [External] Re: RE: PRI - ACCIDENT INVOLVING SLS 5719K AND SMG 9767X ALONG BARTLEY RD ON 09.01.2020

Dear Sharon,

your insured vehicle is SMG 9767X

On Thu, 9 Jan 2020 at 16:49, Motor Claims <motorclaims@sg.gaig.com> wrote:

Hi Nicole

We do not seem to have records of insuring either of the vehicles stated in the subject header.

Please confirm our insured vehicle number.

Regards

Sharon
Great American

From: Nicole Chong <nicole@casgarage.sg>
Sent: 09 January 2020 4:46 PM
To: Ng, Sharon <sharon.ng@sg.gaig.com>
Cc: Allan Goh <allan@casgarage.sg>; CAS Garage Garage <contact@casgarage.sg>
Subject: [External] RE: PRI - ACCIDENT INVOLVING SLS 5719K AND SMG 9767X ALONG BARTLEY RD ON 09.01.2020

WITHOUT PREJUDICE

Kindly arrange survey our client's vehicle

Do let us know when is the available date and time for inspection of the vehicle at:

CAS Garage Pte. Ltd.

Addr: 8 Kaki Bukit Ave 4, #08-26

Premier@ Kaki Bukit

Singapore (417883)

Once arranged, please contact Allan Goh at 8782 7171 during the inspection.

Thank you and have a nice day! Hope to hear from you soon

Regards,

Nicole Chong

Admin and Finance Officer

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Hp: 9791 6119

Office: 6484 2220

UEN: 201828067M

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

--

WITHOUT PREJUDICE

Regards,

Nicole Chong

Admin and Finance Officer

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Hp: 9791 6119

Office: 6484 2220

UEN: 201828067M

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

--

WITHOUT PREJUDICE

Regards,
Nicole Chong

Admin and Finance Officer

CAS Garage Pte. Ltd.

Addr: 1 Kaki Bukit Ave 6, #02-22

Autobay. Singapore (417883)

Hp: 9791 6119

Office: 6484 2220

UEN: 201828067M

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 10/01/2020 15:01
 Date Of Accident 09/01/2020 15:25
 Exact Location Of Accident BARTLEY ROAD
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLS5719K
Insured/Policyholder
 Name Of Registered Owner LAI LI YU
 NRIC No SXXXX167J
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-98893645
 Alternative Phone No OFFICE-98893645

Vehicle Particulars

Manufacturer KIA
 Model CERATO K3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number 1700056340-02
 Cover Note Number

Driver

Name of Driver LAI LI YU
 NRIC No SXXXX167J
 Date Of Birth 02/01/1986
 Occupation INDOOR
 Date Of Driving Pass 31/07/2009
 Driving Experience 10 YEARS AND 5 MONTHS
 Gender FEMALE
 Mobile Number (LOCAL) +65-98893645
 Fax Number
 Contact Number OFFICE-98893645
 Email Address NOEMAIL

Address	945 HOUGANG STREET 92 #04-151
Postcode	S530945
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMG9767X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

† Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

LAI LI YU

Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?


Was this injured conveyed to hospital by ambulance?

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please refer to police report T/20200109/2163

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20200109/2163

1 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20200109/2163

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/01/2020 21:24		Vide Report No.:		Station Diary No.: 186	
Informant's Particulars					
Name of Informant: LAI LIYU			Address: APT BLK 945 HOUGANG STREET 92 #04-151 SINGAPORE 530945		
ID Type / ID No.: NRIC NO / S8601167J			Contact No.: Home/Office: Mobile: 98893645		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 34	Date of Birth: 02/01/1986	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Primary school teacher			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/01/2020 15:30	Type of Location: Straight Road
Location: Along Road 1 BARTLEY ROAD EAST				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLS5719K	Car	KIA	CERATO K3 1.6A	Blue	Seriously Damaged	0
SMG9767X	Car				Seriously Damaged	0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLS5719K	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700056340-02	28/09/2019	27/09/2020

POLICE REPORT Pg. 1



SINGAPORE
POLICE FORCE



T/20200109/2163

2 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20200109/2163

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver:			
Name	LAI LIYU	ID No.	S8601167J
Related Vehicle	SLS5719K (Car)	Contact No.	98893645
Hospital/Clinic	PARKWAY EAST HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	09/01/2020	Date Discharge	09/01/2020
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 09/01/2020 at about 1530hrs, while I was driving my vehicle (Registration Number : SLS5719K) along Bartley Road turning into Bartley Road East, I had met with an accident. As I was waiting for the traffic to clear before turning right, I had stopped my vehicle at the slip road when suddenly there is a vehicle (Registration Number: SMG9767X) had hit on the rear of my vehicle. I then went out of my vehicle to make a check on the damages on my vehicle. I then took photos of the accident scene and had exchange particulars with the other party. Both parties then left the accident scene. After the accident, I felt giddy and pain all over my body thus I had went to Parkway East Hospital to make a check. I was given a total of 3 days of Medical Leave from the said hospital.

POLICE REPORT Pg. 1



SINGAPORE
POLICE FORCE



T/20200109/2163

3 of 3

Police Station Of Origin:
Hougang N.P.C
60 Hougang Avenue 9 SINGAPORE 538775
Tel No: 1800-4890999

Report No. T/20200109/2163

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 MUHAMMAD SYAFIQ BIN ROSMANJA

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / AEIT /

SI ANG YI TING, STEPHANIE

Contact No.: 65476414

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

09/01/2020 21:24

Classification Of Case:

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: GREAT AMERICAN

(MOTOR CLAIMS DEPARTMENT)

10500

Address:

NO 3, TEMASEK AVE, #16-01, CENTENNIAL TOWER

S(039190)

Telephone:

68046000

Fax:

62353354

Email sharon.ng@sg.gaig.comshery.wong@sg.gaig.com

Make/ Model :

KIA CERATO K3

Date:

09.01.2020

Chassis No :

KNAFX411MJ5744607

Vehicle No:

SLS5719K

Date/Time of Accide

09.01.2020/1525

DATE OF REG:

28.09.2017

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	BOOTLID <i>Defect</i>	1	\$ 987.50		\$ <i>263</i> 987.50
2	BOOTLID LOGO <i>per</i>	1	\$ 87.60		\$ 87.60
3	BOOTLID HINGE <i>new</i>	2	\$ 78.60		\$ 157.20
4	BOOTLID STOPPER <i>new</i>	2	\$ 40.50		\$ 81.00
5	BOOTLID K3 EMBLEM <i>2 per</i>	1	\$ 82.10		\$ 82.10
6	BOOTLID CERATO EMBLEM	1	\$ 85.60		\$ 85.60
7	BOOTLID CYCLE & CARRIAGE EMBLEM <i>new</i>	1	\$ 83.20		\$ 83.20
8	BOOTLID LAMP <i>could</i>	2	\$ 680.50		\$ <i>1248</i> 1,361.00
9	BOOTLID WEATHERSTRIP <i>lit</i>	1	\$ 192.60		\$ 192.60
10	BOOTLID INNER LOCK <i>2 per</i>	1	\$ 185.90		\$ 185.90
11	BOOTLID LOCK CATCH <i>new</i>	1	\$ 52.30		\$ 52.30
12	BOOTLID INNER TRIM <i>new</i>	1	\$ 285.60		\$ 285.60
13	BOOTLID NUMBER PLATE LAMPS <i>new</i>	2	\$ 58.70		\$ 117.40
14	REAR BUMPER <i>Disbled</i>	1	\$ 698.70		\$ 698.70
15	REAR BUMPER LOWER <i>Disbled</i>	1	\$ 392.50		\$ 392.50
16	REAR BUMPER LOWER COVER <i>could</i>	2	\$ 145.80		\$ <i>1458</i> 291.60
17	REAR BUMPER REFLECTORS <i>could</i>	1	\$ 99.50		\$ 99.50
18	REAR BUMPER STAY <i>Best 2 per 3 per</i>	5	\$ 65.20		\$ <i>540</i> 326.00
19	REAR BUMPER SIDE RETAINERS <i>new</i>	1	\$ 58.70		\$ 58.70
20	REAR BUMPER REINFORCEMENT <i>Disbled</i>	1	\$ 425.30		\$ <i>365</i> 425.30
21	BUMPER REINFORCEMENT BRACKETS <i>Best</i>	2	\$ 148.90		\$ <i>150</i> 297.80
22	REAR END PANEL <i>Disbled</i>	1	\$ 498.20		\$ 498.20
23	REAR END PANEL TOP GARNISH <i>Disbled</i>	1	\$ 158.70		\$ 158.70
24	TAILAMP <i>could</i>	2	\$ 788.90		\$ 1,577.80
25	TAILAMP INNER SEALER <i>new</i>	2	\$ 40.00		\$ 80.00
26	REAR FLOOR PANEL <i>new</i>	1	\$ 894.70		\$ 894.70
27	REAR FLOOR PANEL TOP BOARD <i>Disbled</i>	1	\$ 258.90		\$ 258.90
28	REAR FLOOR PANEL TOOL SPONGE <i>new</i>	1	\$ 198.50		\$ 198.50
29	REAR FENDER INNER COWLING <i>new</i>	2	\$ 125.60		\$ 251.20
30	REAR FENDER INNER TRIMS <i>new</i>	2	\$ 182.60		\$ 365.20
31	REAR SILENCER BOX <i>Best</i>	1	\$ 683.20		\$ 683.20

32	REAR SILENCER BOX MOUNTING <i>per</i>	2	\$ 45.60	\$ 91.20	+
33	REAR SILENCER BOX HEAT SHIELD <i>per</i>	1	\$ 187.20	\$ 187.20	+
Total List Price Cost				\$ 11,593.90	
				PARTS DISCOUNT 10%	
				\$ 10,434.51	

7989
719010

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR BUMPER CLIPS <i>per</i>	1 SET	\$ 30.00	\$ 30.00
3	REAR NUMBER PLATE WITH CASING <i>per</i>	1 SET	\$ 50.00	\$ 50.00
4	REAR FENDER INNER COWLING CLIPS <i>per</i>	2 SET	\$ 30.00	\$ 60.00
5	REAR FENDER INNER TRIM CLIPS <i>per</i>	2 SET	\$ 30.00	\$ 60.00
6	BOOTLID INNER TRIM <i>per</i>	1 SET	\$ 30.00	\$ 30.00
7	END PANEL TOP GARNISH CLIPS <i>per</i>	1 SET	\$ 30.00	\$ 30.00
8	TAILAMP CLIPS <i>per</i>	2 SET	\$ 30.00	\$ 60.00
9	REVERSE SENSORS <i>per</i>	1 SET	\$ 250.00	\$ 250.00
10	END PANEL SEALANTS <i>per</i>	2	\$ 80.00	\$ 80.00
Total Special Nett Items				\$ 650.00

11 Spare Tyre Panel Insulation Pad *per* 1 ~~300~~ 200 590

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 2,200.00
<i>1200</i>	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,200.00
<i>1200</i>	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 150.00
TO CONDUCT WATER LEAKAGE TEST	\$ 120.00
TO APPLY SEALANT TO THE AFFECTED AREAS	\$ 180.00
TO REMOVE/ REFIT WIRING CHECKS ON REAR TAILAMPS	\$ 150.00
TO REMOVE/ REFIT / REPLACE REAR SILENCER BOX	\$ 180.00
TO REMOVE/ REPLACE REVERSE SENSORS	\$ 180.00
TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM	\$ 200.00
Total Others Cost	\$ 1,360.00
GRAND TOTAL	
	\$ 16,844.51

17,144.51

CAS GARAGE PTE LTD
UEN 201828067M
1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allan@casgarage.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian L
1/5 10/01/20 072p

Total: 10610.10

1/5: 8.5K

8.5K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI20000651/Avd3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 02-04-2020



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMG 9767X	Veh. Inspected	SLS 5719K
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVP000001050	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	10/01/2020

2. Vehicle Particulars & Condition

Make & Model	KIA CERATO K3	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFX411MJ5744607	Colour	BLUE
Odometer	37365	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	NEXEN	6 mm
L/H Front Tyre	205/55 R16	NEXEN	6 mm
R/H Rear Tyre	205/55 R16	NEXEN	6 mm
L/H Rear Tyre	205/55 R16	NEXEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/01/2020	Inspection Date	10/01/2020
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 5719K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED	987.50	863.00
1	BOOTLID LOGO	NECESSARY	87.60	87.60
2	BOOTLID HINGE @\$78.60	NOT NECESSARY	157.20	-
2	BOOTLID STOPPER @\$40.50	NOT NECESSARY	81.00	-
1	BOOTLID K3 EMBLEM	NECESSARY	82.10	82.10
1	BOOTLID CERATO EMBLEM	NECESSARY	85.60	85.60
1	BOOTLID CYCLE & CARRIAGE EMBLEM	NECESSARY	83.20	83.20
2	BOOTLID LAMP @\$680.50	CRACKED	1,361.00	1,248.00
1	BOOTLID WEATHERSTRIP	CUT	192.60	192.60
1	BOOTLID INNER LOCK	DAMAGED	185.90	185.90
1	BOOTLID LOCK CATCH	NOT NECESSARY	52.30	-
1	BOOTLID INNER TRIM	NOT NECESSARY	285.60	-
2	BOOTLID NUMBER PLATE LAMPS @\$58.70	NOT NECESSARY	117.40	-
1	REAR BUMPER	DISTORTED	698.70	698.70
1	REAR BUMPER LOWER	DEFORMED	392.50	392.50
2	REAR BUMPER LOWER COVER @\$145.80	N/S DEFORMED	291.60	145.80
1	REAR BUMPER REFLECTORS	CRACKED	99.50	99.50
5	REAR BUMPER STAY @\$65.20	DAMAGED (3PCS ONLY)	326.00	54.00
1	REAR BUMPER SIDE RETAINERS	NECESSARY	58.70	58.70
1	REAR BUMPER REINFORCEMENT	DISTORTED	425.30	365.00
2	BUMPER REINFORCEMENT BRACKETS @\$148.90	BENT	297.80	150.00
1	REAR END PANEL	DENTED	498.20	498.20
1	REAR END PANEL TOP GARNISH	DEFORMED	158.70	158.70
2	TAILLAMP @\$788.90	CRACKED	1,577.80	1,577.80
2	TAILLAMP INNER SEALER @\$40.00	NECESSARY	80.00	40.00
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	894.70	-
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	258.90	258.90
1	REAR FLOOR PANEL TOOL SPONGE	NOT NECESSARY	198.50	-
2	REAR FENDER INNER COWLING @\$125.60	NOT NECESSARY	251.20	-

Report Ref No. CS/GAI20000651/Avd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIMS @\$182.60	NOT NECESSARY	365.20	-
1	REAR SILENCER BOX	BENT	683.20	683.20
2	REAR SILENCER BOX MOUNTING @\$45.60	NOT NECESSARY	91.20	-
1	REAR SILENCER BOX HEAT SHIELD	NOT NECESSARY	187.20	-
	LESS 10% DISCOUNT		-1,159.39	-800.90
			10,434.51	7,208.10
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	DENTED	50.00	50.00
2	SET REAR FENDER INNER COWLING CLIPS @\$30.00 (SN)	NOT NECESSARY	60.00	-
2	SET REAR FENDER INNER TRIM CLIPS @\$30.00 (SN)	NOT NECESSARY	60.00	-
1	SET BOOTLID INNER TRIM (SN)	NOT NECESSARY	30.00	-
1	SET END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
2	SET TAILLAMP CLIPS @\$30.00 (SN)	NECESSARY	60.00	20.00
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
2	END PANEL SEALANTS @\$80.00 (SN)	NECESSARY	80.00	80.00
1	SPARE TYRE PANEL INSULATION PAD (SN)	NECESSARY	300.00	200.00
			950.00	590.00
	LABOUR			
	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS. INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL.		2,200.00	1,200.00
	TO RESPRAY AFFECTED AREAS.		2,200.00	1,200.00
	TO TUFFCOAT AFFECTED AREA.		200.00	60.00
	TO REMOVE / REFIT INTERIOR UPHOLSTERY.		150.00	80.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	120.00	-
	TO APPLY SEALANT TO THE AFFECTED AREAS.		180.00	60.00
	TO REMOVE, REFIT WIRING CHECKS ON REAR TAILLAMPS.		150.00	30.00
	TO REMOVE / REFIT / REPLACE REAR SILENCER BOX.		180.00	80.00
	TO REMOVE / REPLACE REVERSE SENSORS.		180.00	60.00

Report Ref No. CS/GAI20000651/Avd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE / REFIT BOOTLID MECHANISM.		200.00	60.00
			5,760.00	2,830.00
GRAND TOTAL			17,144.51	10,628.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,500.00

Report Ref No. CS/GAI20000651/Avd3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.