

TJ000000

ASS. RE. BY:

REF: CS/IM1 2000733 / Fyf322

Special Instruction:

Surveyor: Ram

ASSIGNMENT (Office)

From (Person): Dillen Swatkin

of TML

Date/Time: 13-Jun-2020 12:50AM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 3854H

Insured: YN 3363M

at Workshop m/n: Comfortable Engineering

Tel: 62148300

of 59 Iyong Drive

Policy No: MK 000809

Claim No: M 2000297

Sum Insured:

Excess:

Make of Veh:

D.O.A. 11.01.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 13.1.2020 12:04 PM

Person Contacted:

Jumari

H.O.P. Endorsement:

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHA 3854H - NS/IN/10021504/419602 Rm 29/11/2019
	YN 3363M - CS/NS/16014451/6002 Rm 01/03/2020

Meimin
OK

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 3854H Yr Regn: 17/07/2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai iony (G2) cc 1580Colour: blue A/C: Insured / Std / NI / NASp. Reading: 88983 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB8S1CVKUL6774

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15 michelinR: 195/65 R15 Dineturn

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Donor

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 11/1/2020D.O.I. 13/1/2020Survey held at confortdelgro (Loyang)

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 30 JAN 2020

P/P: \$4278.96 with 4 repair days (Red \$776-90, 15%)

confirm on 29/1/2020 with LUMT/S

29/01/2020

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

2)

29/1/20 Typist

Rep. Format: _____

Lump Sum / L.R. / :-

P/P \$4278-96

Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$Survey Fee: 240

Transportation: _____

S + RS. \$

Phone

Others

TOTAL

240

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jan 2020 Sendback Est	13 Jan 2020 10:53 S\$2,961.06	13 Jan 2020 11:50 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	PECK TIONG CHOON LEASING PTE LTD, Co. Reg. No.: 199204891W								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHA3854H	Date of Loss:	11/01/2020 18:00 - :59 [5 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2000297	Policy/Cover Note No.:	MK000809 (Third Party Only) Coverage: 12/10/2019 - 11/10/2020						
Vehicle Reg. No. (Insured):	YN3363M	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 22/01/2020]								
Adj Asg. Remarks:	OI HAS NOT RPT THE ACCDT								
ASSOCIATED MAIL RECEIVED									
				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All	Search Tasks	Create New Task	Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2020 09:00
Date Of Accident	11/01/2020 18:00
Exact Location Of Accident	CTE TWDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA3854H
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXXX21R
Email Address	FLEETSAFTY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	IONIQ
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	TAN LIAM MENG
NRIC No	SXXXX052G
Date Of Birth	16/11/1953
Occupation	OUTDOOR
Date Of Driving Pass	01/08/1978
Driving Experience	41 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97608351
Fax Number	
Contact Number	
Email Address	TANLIAMMENG@HOTMAIL.COM

Address	115 12-315 BEDOK NORTH ROAD
Postcode	460115
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN3363M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NOOR RIZAM BIN SAJI
NRIC/Passport Number	SXXXX387H
Contact Number	81591145
Address	

Postcode

Insurance Company Name

Nature Of Damage

FRT

No. Of Passenger (Including Driver)

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO REG NO. 199303621R

[Signature]

12/1/2020
Jackson Lim
GIA


Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 11/1/2020 at about 1800 hrs, I vehicle A was driving my taxi along CTE toward Crty. As a car in front of me emergency brake stop. I also brake in time. Vehicle B from behind bang into my taxi back causing the damage. No one was injured at that time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name:

NRIC/PIN No.

COMFORT TRANSPORTATION PTE LTD


Team: ARC Repair TP(CLSO)1 JOB CARD Sales Order: JC NO.: 305373993

OWNER COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	REGN NO.: SHA3854H MAKE: HYUNDAI MODEL: IONIQ(G2) YR OF MANU: 17.07.2019 CHASSIS CODE: KMH851CVKU164771	MILEAGE FUEL DATE/TIME IN: 13.01.2020 07:55 TARGET DATE COMPLETION DATE/TIME:
--	---	---

Accident Date: 11.01.2020
NATURE: 3P 11.01.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR CUSTOMER'S SIGNATURE

Damage Slip Vehicle No.: SHA3854H LIMTS	Exit Pass Vehicle No.: SHA3854H
Service Advisor Signature/Date	Name of Service Advisor Date
med to Service Reception upon collection	To be kept by Security Guard

ComfortDelGro Engineering Pte Ltd (Co Reg No: 199506048W)
 59 Loyang Drive
 Singapore 508969
 Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

CP/P)

LKF - Ram

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	11/01/2020
Vehicle Reg. No.:	SHA3854H	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	17/07/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU298134	Chassis No:	KMHC851CVKU164771
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	1,380.06
Miscellaneous Items	11.00
Labour	1,570.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,961.06
+ GST 7.00% (S\$)	207.27
Nett Amount (S\$)	3,168.33

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

C 10:54hys.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jan 2020)

Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SHA3854H/13/01/2020 10:53

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER <i>cut</i>	20.00	0.00	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT <i>cut</i>	20.00	0.00	*294.80 FL
3	1		*REAR BUMPER UNDER COVER <i>Br</i>	20.00	0.00	*451.25 FL
4	1		*REAR BUMPER TOW COVER <i>Br</i>	20.00	0.00	*5.40 FL
5	10		*REAR BUMPER CLIPS <i>nee</i>	20.00	0.00	*22.00 FL
6	1		*REAR BUMPER FOG LAMP <i>1 xnn</i>	20.00	0.00	*201.50 FL
7	1		*TAILGATE EMBLEM - H <i>nee</i>	20.00	0.00	*28.00 FL
8	1		*TAILGATE EMBLEM - HYBRID <i>nee</i>	20.00	0.00	*24.30 FL
9	1		*TAILGATE EMBLEM - IONIQ <i>nee</i>	20.00	0.00	*31.30 FL
10	1		*TAILGATE COMFORTDELGRO STICKER <i>nee</i>	0.00	0.00	*30.00 F
11	1		*REVERSE SENSOR <i>1 xnn</i>	0.00	0.00	*135.70 F

F=Franchise part. L=ListItemDisc.

tailgate assy ppr

Sub Total (\$\$)

1,683.65

- List Item Discount on L Items (\$\$)

303.59

Total Parts (\$\$)

1,380.06

ComfortDelGro Engineering Pte Ltd/SHA3854H/13/01/2020 10:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modifications is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING (TAILGATE ETC)	New	700.00 \$640
2	SPRAY PAINTING	New	500.00 \$400
3	R/I REVERSE SENSOR	New	120.00 \$50
4	COMPUTER PROGRAMME FOR BLIND SPOT DEVICE (BSD)	New	250.00 \$xnn
Gross Labour Cost (S\$)			1,570.00

ComfortDelGro Engineering Pte Ltd/SHA3854H/13/01/2020 10:53. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim(s) must be insured and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

14/1/2020
Ran (LKK)
13/1/2020 1230 hrs
Paraburam @ LKK auto
88622778
Repairing #4 P/R
Bel paint pls to

(SUPPLEMENTARY)

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)

PECK TIONG CHOON LEASING PTE LTD

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	
Policy No:	MK000809	Date of Loss:	11/01/2020
Vehicle Reg. No.:	SHA3854H	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	17/07/2019
Vehicle Colour:	Blue	Gen Condition:	Good
Engine No:	4M42A91183	Chassis No:	FE84BEA20290
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	ACCIDENT INVOLVING YN3363M & SHA3854H CTE TWDS CITY @ 18.00		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	2,094.80
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,094.80
+ GST 7.00% (S\$)	146.64
Nett Amount (S\$)	2,241.44
+ Previous Estimates (S\$)	3,168.33
Claim Total (S\$)	5,409.77

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 14 Jan 2020)
Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHA3854H/14/01/2020 17:58
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILGATE ASSY <i>00</i>	20.00	0.00	*2,480.40 FL
2	1		*REAR BUMPER STAY LH <i>8r</i>	20.00	0.00	*138.10 FL
Sub Total (S\$)						2,618.50
- List Item Discount on L Items (S\$)						523.70
Total Parts (S\$)						2,094.80

F=Franchise part. L=ListItemDisc

ComfortDelGro Engineering Pte Ltd/SHA3854H/14/01/2020 17:58. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

ComfortDelGro Engineering Pte Ltd/SHA3854H/14/01/2020 17:58. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our Job Ref No : 305373993

Date : 16/01/20

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : RAM

Vehicle Reg No. : SHA3854H

Date of Accident : 11-Jan-20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE — YN3363M

2. The finalized amount shall be:

(a) Spare Parts after List discount

\$3,177.96

(b) Labour Charges

\$1,101.00

Total for Part-By-Part Repair Cost

\$4,278.96

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: 20%

Final Lumpsum Repair cost

3. Estimated normal period for repairs: 4 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : Signature : 

Name : LIM T S

Name : RAM

Tel : 62148398

Date : 20/1/2020

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees	*****			
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305373993
 REGN NO : SHA3854H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 17.07.2019
 DATE/TIME IN : 13.01.2020 07:55
 ACCIDENT DATE : 11.01.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2288-G	REAR BUMPER REINFORCEMENT	1	294.80	20.00	235.84	cut
0002	04-01-0104-2533-G	REAR BUMPER UNDER COVER	1	451.25	20.00	361.00	Br
0003	04-01-0104-2544-G	REAR BUMPER TOW COVER	1	5.40	20.00	4.32	Br
0004	04-01-0104-2256-G	TAIL GATE ASSY*	1	2,480.40	20.00	1,984.32	DO
0005	04-01-0104-2270-G	TAILGATE EMBLEM-HYBRID	1	24.30	20.00	19.44	new
0006	04-01-0104-2271-G	TAILGATE EMBLEM-IONIQ	1	31.30	20.00	25.04	new
0007	28-01-0103-0005-A	TAILGATE COMFORTDELGRO	1	30.00	2.00-	30.00	new
0008	04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	cut
0009	04-01-0104-3819-G	REAR BUMPER STAY LH*	1	138.10	20.00	110.48	Br
0010	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	new
0011	04-01-0104-2539-G	TAILGATE EMBLEM-H	1	28.00	20.00	22.40	new

SUB-TOTAL : 3,177.96

JOB NATURE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305373993
REGN NO : SHA3854H
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 17.07.2019
DATE/TIME IN : 13.01.2020 07:55
ACCIDENT DATE : 11.01.2020

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB	PANEL BEATING	640.00				
0001 SP	SPRAYPAINT CHARGE	400.00				
0002 L	R/I REVERSE SENSOR	50.00				
0003 L	TP MERIMEN	11.00				

SUB-TOTAL : 1,101.00

TOTAL : 4,278.96


MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Jan 2020 Sendback Est	13 Jan 2020 10:53 S\$2,961.06	13 Jan 2020 11:50 Edit Adj Rpt	S\$4,278.96 Edit Estimates	S\$4,278.96 View Rpt		Pending for Survey Report Cancel Case
Supp #1	14 Jan 2020 17:56	14 Jan 2020 17:58 S\$2,094.80	14 Jan 2020 17:58			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
Insured:	PECK TIONG CHOON LEASING PTE LTD, Co. Reg. No.: 199204891W								
Main Claimant:	CTPL								
Vehicle Reg. No.:	SHA3854H	Date of Loss:	11/01/2020 18:00 - :59 [5 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / M2000297	Policy/Cover Note No.:	MK000809 (Third Party Only) Coverage: 12/10/2019 - 11/10/2020						
Vehicle Reg. No. (Insured):	YN3363M	Policy No. (Claimant):							
		Excess:	S\$1,500.00						
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300								
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Dillen Senthilan so Selvarajoo]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 22/01/2020]								
Adj Asp. Remarks:	OI HAS NOT RPT THE ACCDT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA3854H (M2000297)
[YN3363M]
TP
CTPL
Jan 11 2020 6:00PM
[PECK TIONG CHOON LEASING PTE LTD]
ComfortDelGro Engineering Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page			
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)					Thumbnail	Print	
1	13/01/20 10:53	Repairer Estimates				1	Load HTM		
2	14/01/20 17:58	Repairer Estimates Suppl. #1				1	Load HTM		
Photos/Images						3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
2	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
3	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
4	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
5	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
6	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
7	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
8	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
9	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
10	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
11	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
12	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
13	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
14	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
15	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
16	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
17	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
18	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
19	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
20	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
21	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
22	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
23	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
24	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
25	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
26	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
27	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
28	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
29	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
30	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
31	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
32	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	
33	23/01/20 16:18	Front View				1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
34	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
35	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
36	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
37	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
38	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
39	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
40	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
41	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
42	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
43	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
44	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
45	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
46	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
47	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
48	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
49	23/01/20 16:18	Front View		Load JPG <input checked="" type="checkbox"/>
50	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	23/01/20 16:19	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)		Thumbnail Print
1	22/01/20 12:14	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee		Load PDF <input type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)		Thumbnail Print
1	13/01/20 10:54	E-filed GIA report		Load PDF <input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	03/02/20 13:37	Supplementary		Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Repairer ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/TMI20000733/FYF3E2

Date: 03/02/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd

Policy No: MK000809

Claimant Vehicle No : SHA3854H

Insured Vehicle No : YN3363M

Date of Loss: 11/01/2020

Nature of Claim: TP Claim No: M2000297

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA3854H

Make & Model: HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)

Engine No: G4LEKU298134

Reg. Date: 17/07/2019 (Man. Year: 2019)

Chassis No: KMHC851CVKU164771

Colour: Blue

Odometer: 88983 km

Engine Capacity: 1580 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	DURATURN 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	DURATURN 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,474.86	3,177.96	296.90	8.54
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,570.00	1,090.00	480.00	30.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,055.86	4,278.96	776.90	15.37
+ GST 7.00/7.00% (S\$)	353.91	299.53	54.38	15.37
Nett Amount (S\$)	5,409.77	4,578.49	831.28	15.37

INSPECTION

Date of Assignment: 13/01/2020 Present Location: ComfortDelGro Engineering Pte Ltd (Loyang)

Date Inspected: 13/01/2020 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 4.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2020)
Parts:	192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA3854H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Cut	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Cut	294.80 FL	-	*294.80 FL
3	1		*REAR BUMPER UNDER COVER	Broken	451.25 FL	-	*451.25 FL
4	1		*REAR BUMPER TOW COVER	Broken	5.40 FL	-	*5.40 FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	-	*- FL
7	1		*TAILGATE EMBLEM - H	Necessary	28.00 FL	-	*28.00 FL
8	1		*TAILGATE EMBLEM - HYBRID	Necessary	24.30 FL	-	*24.30 FL
9	1		*TAILGATE EMBLEM - IONIQ	Necessary	31.30 FL	-	*31.30 FL
10	1		*TAILGATE COMFORTDELGRO STICKER	Necessary	30.00 F	-	*30.00 F
11	1		*REVERSE SENSOR	Not Necessary	135.70 F	-	*- F
Supplementary #1							
12	1		*TAILGATE ASSY	Dented	2,480.40 FL	-	*2,480.40 FL
13	1		*REAR BUMPER STAY LH	Broken	138.10 FL	-	*138.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,302.15	3,964.95
- List Item Discount on L Items 20.00/20.00% (\$\$)	827.29	786.99
Total Parts (\$\$)	3,474.86	3,177.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	640.00
2	SPRAY PAINTING	New	500.00	400.00
3	R/I REVERSE SENSOR	New	120.00	50.00
4	COMPUTER PROGRAMME FOR BLIND SPOT DEVICE (BSD)	New	250.00	0.00
Gross Labour Cost (\$\$)			1,570.00	1,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >