

ASS. REC. BY:

REF: 03/CTI20000739/Gyd3⁵²

Special Instructions

Surveyor: Guo Cheng

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of CTI

Date/Time: 10/11/2020 @ 5.24pm

Estimated Cost:

Bill to:

OD TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJM 9844K

Insured: YP 3537T

at Workshop in/s Hiap Lek Automobile

Tel: 9660 1347

of 160 Sin Ming Drive # 05-17

Policy No:

Claim No: SNM 20D 200138 / YP3537T / CBS

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 9.1.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.57am @ 13/11/2020

Person Contacted: Mr. Ong

Vehicle IN OUT

Date/Time	Action/Instruction
	<u>Johnnie X</u>
	<u>SJM 9844K - X</u>
	<u>YP 3537T - X</u>


REC BY: PRs REP: GTI

ASSIGNMENT

(-2024)

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop n/s: Hiap lek Auto
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SJM9844K (r Regn: 22 Jan 2009)
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Suzuki swift ^{1.5} c.c. 1490
 Colour: orange A/C: Insured / Std / NI / NA
 Sp Reading: 208076 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ISAEZC 21S 004 21253
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 185/60 R15
 R: 17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

	
N/S	O/S

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: \$21K
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. _____ D.O.I. B-01-20
 Survey held at w/s 333 ops
 Des. of Damages Frnt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>CoE: 10475</u>
	<u>\$2000 - \$3000</u> <u>14/1/2020</u>
<u>20/1</u>	<u>\$3000 - \$4000</u>

RECEIVED 20 JAN 2020

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) 20/1/20 Typist
 Report Format: _____
 Email: _____

Days Of Repair: 4
 Resurvey No. of Trip: _____
 Add Fee: Site Insp (\$)
 Interview (\$)
 Tech. Insp (\$)
 Meet up (\$)
 Survey Fee: _____
 Transportation: _____
 S + PS _____
 Parking: _____
 Other: _____
 TOTAL: _____

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 10 January 2020 5:24 PM
To: Celeste Ng
Cc: 'assignments'
Subject: RE: OUR REF: SNM20D200138/YP3537T/CBS & YOUR REF 20-A14-10851-VL.jp.cn - SJM9844K [PRI NOTICE]

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Sir,

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Celeste Ng [mailto:celeste@legaloptions.biz]
Sent: Friday, January 10, 2020 4:27 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200138/YP3537T/CBS & YOUR REF 20-A14-10851-VL.jp.cn - SJM9844K [PRI NOTICE]

Dear Boon Seng,

Our client rejected your list of surveyor.

We provide you herewith our client's list of surveyor: -

	SURVEYOR:	CONTACT PERSON:	CONTACT:
1.	PAR AUTOMOTIVE CONSULTANCY	B J LOI	94882266
2.	UNITED APPRAISAL AND MANAGEMENT PTE LTD	MARC	91461186

3.	OH APPRAISAL SERVICES	OH HAN CHEONG	97982959
4.	SK AUTO CONSULTANTS	KUMA (S. KU,AMAN)	90040225
5.	LEE AUTOMOBILE APPRAISERS SERVICES	LEE K W	81882833
6.	CM AUTOMOTIVE CONSULTANCY	NG CHENG MENG	91459178
7.	ISP MANAGEMENT PTE LTD	ZALI SAIDI	96553574
8.	AUTO PERFORMANCE APPRAISAL	LEK BOON HWEE	94301592

Your said surveyor may contact

Mr Ong Han Wei at 9660 1347, M/s Hiap Lek Automobile Trading at
160 Sin Ming Drive #05-17, Sin Ming Autocity, Singapore 575722

*

If we do not hear from you within 2 days of this email, our clients shall deem that you have agreed that the surveyor appointed by our clients shall be our single joint expert for this matter.

Thanks n regards,

Celeste

Junior Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2805 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

On Fri, Jan 10, 2020 at 11:09 AM Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without prejudice

Save as to costs

Dear Sir,

LKK

LBS

STA

Chong Boon Sen

Claims Executive

Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Claims Dept of CTI

Sent: Friday, January 10, 2020 10:42 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; celeste@legaloptions.biz

Subject: OUR REF: SNM20D200138/YP3537T/CBS & YOUR REF [20-A14-10851-VL.jp.cn](#) -SJM9844K [PRI NOTICE]

Dear Boon Sen,

Please conduct PRS -SJM9844K soonest possible and our Insured has not filed SAS Report.

officer in charge. Chong Boon Sen-DID 6389 6171.

Dear Celeste,

***** kindly quote our reference number when replying*****

Regards

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Celeste Ng [<mailto:celeste@legaloptions.biz>]
Sent: Thursday, 9 January, 2020 3:56 PM
To: Claims Dept of CTI
Subject: [PRI NOTICE] Your Ref: YP 3537T; Our Ref: [20-A14-10851-VL.jp.cn](#)

Dear Sirs,

PRI attached for your urgent attention.

Kindly provide us your list of surveyors in the next 2 working days.

Thanks n regards,

Celeste

Junior Secretary

LEGAL OPTIONS LLC

(GST Registration/UEN No. 201203825R)

Tel (65) 6513-2800 DID (65) 6513-2805 Fax (65) 6438-8275

Information in this message is confidential and may be legally privileged. It is intended solely for the person(s) to whom it is addressed. If you are not the intended recipient, please delete the message and any other record of it from your system, and notify the sender immediately.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/01/2020 15:22
Date Of Accident	09/01/2020 13:00
Exact Location Of Accident	OPEN CARPARK OF BLK 628 ANG MO KIO AVE 4
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJM9844K
Insured/Policyholder	
Name Of Registered Owner	SGRENTACAR PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91968902
Alternative Phone No	OFFICE-91968902

Vehicle Particulars

Manufacturer	SUZUKI
Model	SWIFT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	A400000199MCX
Cover Note Number	

Driver

Name of Driver	KUGAN S/O KESAVAN
NRIC No	SXXXX421J
Date Of Birth	03/10/1988
Occupation	OUTDOOR
Date Of Driving Pass	13/01/2011
Driving Experience	8 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91968902
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 350 ANCHORVALE ROAD #15-107
 Postcode 540350
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP3537T
 Vehicle Make/Model/Colour
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver TAN PHEOW CHANG
 NRIC/Passport Number SXXXX227H
 Contact Number 97838044
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

10 JAN 2020



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

NG WING KIN JAMES
 admin.vac@vicom.com.sg

SKETCH PLAN

A: SJM9844K
 B: YP3537T



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/01/2020, @ about 1 PM, I am travelling along Blk 628 Angmokia Ave to open car park. I was waiting for a parking lot to park my vehicle, my vehicle is stationary. I saw ahead of me there is a lorry. He suddenly change into the reverse gear and it started reversing. I press on my horn to alert him but the vehicle still continue and it rear portside collided onto my vehicle front position.

DECLARATION

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

10 JAN 2020


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name: NG WING KIN JAMES
 NRIC/FIN No.: admin.vac@vicom.com.sg

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	402W
Vehicle No.:	SJM9844K
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jan 2020
Vehicle Make:	SUZUKI
Vehicle Model:	SWIFT 1.5 AT ABS AIRBAG 2WD
Primary Colour:	Orange
Manufacturing Year:	2008
Engine No.:	M15A1333796
Chassis No.:	JSAEZC21500421253
Maximum Power Output:	74.0 kW (99 bhp)
Open Market Value:	\$14,047.00
Original Registration Date:	22 Jan 2009
First Registration Date:	22 Jan 2009
Transfer Count:	4
Actual ARF Paid:	\$10,674.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	21 Jan 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$13,024.00
COE Rebate Amount:	\$10,475.00
Total Rebate Amount:	\$10,475.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 13 Jan 2020

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jan 2020		20 Jan 2020 15:34 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	-, Co. Reg. No.: -		
Main Claimant:	sgrentacar pte ltd		
Vehicle Reg. No.:	SJM9844K	Date of Loss:	09/01/2020 00:00 - :59 [131 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D200138C02	Policy/Cover Note No.:	DMCVSN30516119011
Vehicle Reg. No. (Insured):	YP3537T	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Hiap Lek Automobile Trading () Blk 14 #01-19 Sector B, Sin Ming Industrial Est, 575658 Sin Ming - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 30/01/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJM9844K (SNM20D200138C02)
 [YP3537T]
 TP
 sgrentacar pte ltd
 Jan 9 2020 12:00AM
 [-]
 Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼
Photos/Images			3 per page ▼
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	22/01/20 09:22	General View	Load JPG
2	22/01/20 09:22	General View	Load JPG
3	22/01/20 09:22	General View	Load JPG
4	22/01/20 09:22	General View	Load JPG
5	22/01/20 09:22	General View	Load JPG
6	22/01/20 09:22	General View	Load JPG
7	22/01/20 09:22	General View	Load JPG
8	22/01/20 09:22	General View	Load JPG
9	22/01/20 09:22	General View	Load JPG
10	22/01/20 09:22	General View	Load JPG
11	22/01/20 09:22	General View	Load JPG
12	22/01/20 09:22	General View	Load JPG
13	22/01/20 09:22	General View	Load JPG
14	22/01/20 09:22	General View	Load JPG
15	22/01/20 09:22	General View	Load JPG
16	22/01/20 09:22	General View	Load JPG
17	22/01/20 09:22	General View	Load JPG
18	22/01/20 09:22	General View	Load JPG
19	22/01/20 09:22	General View	Load JPG
20	22/01/20 09:22	General View	Load JPG
21	22/01/20 09:22	General View	Load JPG
22	22/01/20 09:22	General View	Load JPG
23	22/01/20 09:22	General View	Load JPG
24	22/01/20 09:22	General View	Load JPG
25	22/01/20 09:22	General View	Load JPG
26	22/01/20 09:22	General View	Load JPG
27	22/01/20 09:22	General View	Load JPG
28	22/01/20 09:22	General View	Load JPG
29	22/01/20 09:22	General View	Load JPG
30	22/01/20 09:22	General View	Load JPG
31	22/01/20 09:22	General View	Load JPG
32	22/01/20 09:22	General View	Load JPG
33	22/01/20 09:41	Reinspection Photo	Load JPG
34	22/01/20 09:41	Reinspection Photo	Load JPG
35	22/01/20 09:41	Reinspection Photo	Load JPG
36	22/01/20 09:41	Reinspection Photo	Load JPG
37	22/01/20 09:41	Reinspection Photo	Load JPG
38	22/01/20 09:41	Reinspection Photo	Load JPG
39	22/01/20 09:41	Reinspection Photo	Load JPG
40	22/01/20 09:41	Reinspection Photo	Load JPG
41	22/01/20 09:41	Reinspection Photo	Load JPG
42	22/01/20 09:41	Reinspection Photo	Load JPG
43	22/01/20 09:41	Reinspection Photo	Load JPG
44	22/01/20 09:41	Reinspection Photo	Load JPG
45	22/01/20 09:41	Reinspection Photo	Load JPG
46	22/01/20 09:41	Reinspection Photo	Load JPG
47	22/01/20 09:41	Reinspection Photo	Load JPG
48	22/01/20 09:41	Reinspection Photo	Load JPG
49	22/01/20 09:41	Reinspection Photo	Load JPG
50	22/01/20 09:41	Reinspection Photo	Load JPG
51	22/01/20 09:41	Reinspection Photo	Load JPG
52	22/01/20 09:41	Reinspection Photo	Load JPG
53	22/01/20 09:41	Reinspection Photo	Load JPG

Photos/Images			3 per page	Thumbnail	Print
No	Re-label/Reorder	LKK Auto Consultants Pte Ltd (HQ)			
54	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
55	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
56	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
57	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
58	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
59	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
60	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
61	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
62	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
63	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
64	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
65	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
66	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
67	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
68	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
69	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
70	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
71	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
72	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
73	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
74	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
75	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
76	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
77	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
78	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
79	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
80	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
81	22/01/20 09:41	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
82	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
83	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
84	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
85	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
86	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
87	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
88	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
89	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
90	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
91	22/01/20 09:45	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
92	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
93	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
94	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
95	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
96	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
97	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
98	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
99	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
100	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
101	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
102	22/01/20 09:46	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	Thumbnail	Print
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)			
1	20/01/20 15:34	PRI CONTACT		Load PDF	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <p>Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20000739/GYD3S2

Date: 22/01/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30516119011
 Claimant Vehicle No: SJM9844K Insured Vehicle No: YP3537T
 Date of Loss: 09/01/2020 Nature of Claim: TP Claim No: SNM20D200138C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJM9844K**
 Make & Model: SUZUKI SWIFT, 1.5 AT ABS AIRBAG 2WD (A) Engine No: M15A1333796
 Reg. Date: 22/01/2009 (Man. Year: 2008) Chassis No: JSAEZC21S00421253
 Colour: Orange Odometer: 208076 km
 Engine Capacity: 1490 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/01/2020
 Date Inspected: 13/01/2020 Inspected At: 160 SIN MING DRIVE# 05-17
 Estimated Period of Repair: 4.0 days Repairer: Hiap Lek Automobile Trading

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Jan 2020)

Parts: 144 SUZUKI SWIFT 1.5 AT ABS AIRBAG 2WD (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJM9844K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >