

22/01/2020

AS/ REC. BY:

REF: 08/MIG20000741 / Ntd3⁵² Special Instruction:

From (Person): NAZ

ASSIGNMENT (Office)

From (Person): Winnie Fan

of AIG

Date/Time: 13/01/2020 @ 9.53am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

FBP 7480T

Insured:

at Workshop in/s

Bike production

Tel: 6392 2555

of

610 Serangoon Road

Policy No:

1900105213

Claim No:

99733 95946SG

Sum Insured:

Excess:

TBA

Make of Veh:

D.O.A. 07/01/2020

(Client's Record)

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.03am @ 13/1/2020

Person Contacted:

Mr. Kwan

Vehicle IN/OUT

Date/Time	Action/Instruction
13/1/2020	- Mr. Kwan arrange on 16/01/2020 as he wants to wait for NAZ FBP 7480T
4/2-	seek mandate via merimen
5/2-	mandate approval
5/2-	inform workshop authorise repair excess TBA

ASS. REC. BY:

Naz

REF:

ALG

ASSIGNMENT

From:

Date: 31/2/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

12.5K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBP 7480 T

Yr Regn: 31 MAY 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

YAMAHA YZF R3

CC 321

Colour:

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading

8,336

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH3R1+12 000000 2343

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

110 / 70 R17

R:

140 / 70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

7/1/2020

D.O.I.

31/2/2020

Survey held at

BIKE PRODUCTION

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

COR Rate: \$3,218.00

Repair Limit: \$8,000.00

Waiting for BP to accept cor

Lump Sum \$2700/- (Red: 3246, 540/0)

RECEIVED 27 FEB 2020

Date/Time, File Pass to?



: Preli. Report

1) 26/2 Typist



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

Report Format:

OD

Lump Sum / L.B.E: \$2700/-

11

Nivitha (LKK Auto)

From: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Sent: Monday, 13 January 2020 9:53 AM
To: Admin A; assignments
Cc: Fong, Andy-SY
Subject: Aigencypt RE: NEW OD CLAIM - FBP7480T
Attachments: FBP7480T GIA.PDF; 20200111_141534.jpg

Hi LKK,

Kindly assist to survey.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

-----Original Message-----

From: Sbk E <sbk5643e@yahoo.com>
Sent: Saturday, January 11, 2020 2:32 PM
To: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Subject: [EXTERNAL] RE: NEW OD CLAIM - FBP7480T

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Please arrange PRI for own damage claim. Thanks.

Regards,

Kwan S. H.
Director
Bike Production Pte Ltd

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 04 Feb 2020

Preliminary Advice

Vehicle No	: FBP7480T	Accident Date	: 07/01/2020
Make	: YAMAHA YZF-R3	Policy No.	: 1900105213
Assignment Date	: 13/01/2020	Excess	: S\$0.00
Date of Inspection	: 03/02/2020	Est. Duration of Repair	: 2.00
Inspection At	: BIKE PRODUCTION PTE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,235.00
Revised Amount	:S\$	2,811.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,811.00
Lump Sum Repair	:S\$	2,250.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	12,500.00
COE / PARF Rebate	:S\$	3,218.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,282.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Wednesday, 5 February 2020 9:06 AM
To: sbk5643e@yahoo.com
Cc: SUR
Subject: OD / 9973395946SG / FBP 7480T / AIG

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **FBP 7480T (Excess \$TBA/-). Lump sum repair.**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights not to pay if there is no valid approval obtained before repair.

*After repair photo need to be taken.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***FBP7480T (9973395946SG)**

OD

Jan 7 2020 1:00PM

[KRISNAN GOVE]

Bike Production Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 05/02/2020 07:09 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$2250.00) - FBP7480T - Claim Handler: Mithoo Singh, Aashweenjeet Kaur

Approved:2250.00:Resurvey for check, supplementary and after repair.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mithoo Singh, Aashweenjeet Kaur

Date: 07 Feb 2020

Preliminary Advice

Vehicle No	: FBP7480T	Accident Date	: 07/01/2020
Make	: YAMAHA YZF-R3	Policy No.	: 1900105213
Assignment Date	: 13/01/2020	Excess	: S\$0.00
Date of Inspection	: 03/02/2020	Est. Duration of Repair	: 2.00
Inspection At	: BIKE PRODUCTION PTE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,946.00 Inclusive of \$711.00
Revised Amount	:S\$	3,522.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,522.00
Lump Sum Repair	:S\$	2,850.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	12,500.00
COE / PARF Rebate	:S\$	3,218.00
Salvage Value	:S\$	
Margin for Repair	:S\$	9,282.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/01/2020 16:10
Date Of Accident	07/01/2020 13:00
Exact Location Of Accident	BELILIOS LANE OPEN SPACE CARPARK (TPBKE9)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP7480T
Insured/Policyholder	
Name Of Registered Owner	KRISNAN GOVE
NRIC No	SXXXX365Z
Email Address	KRISNAN.GOVE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82929511
Alternative Phone No	OTHERS-82929511

Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900105213
Cover Note Number	

Driver

Name of Driver	KRISNAN GOVE
NRIC No	SXXXX365Z
Date Of Birth	02/06/1951
Occupation	INDOOR
Date Of Driving Pass	15/11/1983
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82929511
Fax Number	
Contact Number	OTHERS-82929511

Address	BLK 458 SEGAR ROAD #02-149
Postcode	670458
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ROCHER N.P.C
Police Station Address	ROAD: 11 KAMPONG KAPOR ROAD , POSTCODE: 208678 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2949999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident


PLEASE REFER TO ATTACHED.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	UNKNOWN
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	



No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Report No: T/20 200107/2119.

Please Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/01/2020 16:10
Date Of Accident	07/01/2020 13:00
Exact Location Of Accident	BELILIOS LANE OPEN SPACE CARPARK (TPBKE9)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBP7480T
Insured/Policyholder	
Name Of Registered Owner	KRISNAN GOVE
NRIC No	SXXXX365Z
Email Address	KRISNAN.GOVE@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82929511
Alternative Phone No	OTHERS-82929511

Vehicle Particulars

Manufacturer	YAMAHA
Model	YZF-R3

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	MOTORCYCLE
------------------	------------

Insurance Company


Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900105213
Cover Note Number	

Driver

Name of Driver	KRISNAN GOVE
NRIC No	SXXXX365Z
Date Of Birth	02/06/1951
Occupation	INDOOR
Date Of Driving Pass	15/11/1983
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82929511
Fax Number	
Contact Number	OTHERS-82929511
EEmail Address	KRISNAN.GOVE@GMAIL.COM

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Report No: T/20 200107/2119.

Please Refer to Police Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20200107/2119

2 of 3

Police Station Of Origin:
Rochor N.P.C
11 Kampong Kapur Road SINGAPORE
208678
Tel No: 1800-2949999

Report No. T/20200107/2119

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Rider			
Name	KRISNAN GOVE	ID No.	S0825365Z
Related Vehicle	FBP7480T (Motorcycle)	Contact No.	82929511
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 07/01/2020 at about 12.30pm at the open space cark (TPBKE9) located along Belilios Lane. I had parked my motorcycle "FBP7480T" at parking lot number "10" and left. There was a total of about 8 motorcycle parking lot where I had parked my motorcycle. There were about 4 other motorcycles parked at the said location. When I returned at about 1.00pm, I wanted to move off. However, I was unable to engage the gear. I then make a checked and there was damage on the left side of my motorcycle.

Damage as followed,

- 1) left front side plastic fairing scratches
- 2) left back side plastic fairing scratches
- 3) left foot lever bended
- 4) left plastic signal light assembly damage
- 5) left foot rest lever broken
- 6) left clutch lever broken
- 7) left side mirror cover scratches

This was a small carpark with limited space. Many lorry and cars were using the said carpark. I strongly believed that my motorcycle was hit by another vehicle. Any vehicle will be able to hit my parked motorcycle if reverse at the lot located beside my motorcycle lot. There was cctv install at the carpark and also police camera near to the HDB beside the carpark.

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.
FBP7480T

Make / Model
YAMAHA / YZF-R3

Vehicle Type :
P00 - Passenger Motorcycle/Autocycle/Moped

Vehicle Scheme :
Normal

Propellant :
Petrol

Motor No. :
-

Power Rating :
-

Maximum Laden Weight :
330 kg

Year Of Manufacture :
2019

Lifespan Expiry Date :
-

Quota Premium :
\$3,452.00

Road Tax Expiry Date :
30 May 2020

Inspection Due Date :
30 May 2022

CO2 Emission :
-

CO Emission :
-

NOx Emission :
-

Vehicle Attachment 1 :
No Attachment

Chassis No. :
MH3RH12D000002343

Engine No. :
H405E0021511

Engine Capacity :
321 cc

Maximum Power Output :
-

Unladen Weight :
170 kg

Original Registration Date :
31 May 2019

COE Category :
D - Motorcycle

COE Expiry Date :
30 May 2029

PARF Eligibility Expiry Date :
-

Intended Transfer Date :
03 Feb 2020

CEV/VES Rebate Utilised Amount :
-

HC Emission :
-

PM Emission :
-

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	365Z
Vehicle Details	
Vehicle No.:	FBP7480T
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Feb 2020
Vehicle Make:	YAMAHA
Vehicle Model:	YZF-R3
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	H405E0021511
Chassis No.:	MH3RH12D000002343
Maximum Power Output:	-
Open Market Value:	\$5,083.00
Original Registration Date:	31 May 2019
First Registration Date:	31 May 2019
Transfer Count:	1
Actual ARF Paid:	\$792.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 May 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,452.00
COE Rebate Amount:	\$3,218.00
Total Rebate Amount:	\$3,218.00

The information contained herein is correct as at 03 Feb 2020

OK

Yamaha YZF-R3



SGD\$11999

Reg : 08/12/2017

Type: Sport Bikes

321cc

Trade in/Loan available. Visit Bike Dynamic Centre.

Posted on : 01/02/2020

PAID AD

DEALER AD

DETAILS

COMPARE

Yamaha YZF-R3



SGD\$8800

Reg : 18/01/2017

Type: Sport Bikes

321cc

36038km

Yamaha YZF-R3 For Sale. Trade In/Loan Of Vehicle Available. Interested Buyers Are Welcome To Neg. Come Visit M1 Motoring Changi.

Posted on : 16/01/2020

PAID AD

DEALER AD

DETAILS

COMPARE

Yamaha YZF-R3



SGD\$8000

Reg : 05/05/2016

Type: Sport Bikes

321cc

59359km

Yamaha YZF-R3 For Sale. Extremely Efficient And Low Maintenance Cost. Never Raced Or Tracked. Used To Daily Commuting. Selling As I Am Not Riding Anymore. Due To Scratches, Hence The Affor...

Posted on : 03/01/2020

DIRECT SELLER

DETAILS

COMPARE

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)

Tel: 63922555, 62995177 Fax: 62975400

ROC/ GST Reg No.: 200007407G

Date: 11 Jan 2020

ASSESSMENT FOR REPAIR: YAMAHA YZF-R3 - FBP7480T

Chassis No.: MH3RH12D000002343

Engine No.: H405E0021511

NA2 LK 312/2020
 4/2/2020
 215
 2 DAYS

LKK Auto Consultants send notice
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: 1430

Qty**Description****Estimate**

1 pc	Left fork assy
1 pc	Front cowl
1 pc	Front cowl amblem
1 pc	Left mirror
1 pc	Left black cover
1 pc	Left handle bar
1 pc	Left balancer
1 pc	Clutch lever
1 pc	Left front signal
2 pcs	Steering bearing @ \$45.00
1 pc	Steering stem
1 pc	Left fairing assy
1 pc	Left fairing amblem
1 pc	Left upper blue fairing
1 pc	Left lower cover
1 pc	Left footrest front
1 pc	Left footrest holder front
1 pc	Gear pedal assy
1 pc	Side stand
1 pc	Rear left cover
1 pc	Rear footrest holder left
1 pc	Rear footrest left

\$850.00	XSVL
\$395.00	SCR XSVL
\$55.00	SCR XNN
\$165.00	SCR
\$205.00	SCR
\$185.00	XSVL
\$45.00	SCR
\$75.00	BR
\$95.00	SCR
\$90.00	XSVL
\$335.00	XSVL
\$325.00	SCR
\$55.00	NEC
\$295.00	SCR
\$205.00	SCR
\$95.00	BR
\$195.00	XSVL BT
\$145.00	XSVL BT
\$105.00	XSVL SCR
\$295.00	SCR
\$205.00	SCR
\$85.00	SCR

2500	\$3,650.00
	\$365.00
2,250	\$3,285.00

Special nett items

1 pc	Rear number plate
1)	Towing charges
	Replace, realign and adjust above damaged parts, check wiring and lighting system
2)	To replace and balance front and rear wheel rim
3)	To knock, straighten chassis & body balancing
4)	To remove/refit, replace (if damage) check and straighten front fork tubes.
5)	Spray painting
6)	Reset meter

\$30.00	DEF
\$100.00	X
\$700.00	182 300
\$120.00	XNN
\$450.00	XNN
\$180.00	XNN
\$250.00	150
\$120.00	XNN

Total Estimate**\$5,235.00**

Note: The above estimate is subjected to the prevailing GST of 7%

LIS TOTAL (1,650)
 450

6000
 6214

PARTS LESS 10% 1,568
 SINE 30
 LABOUR 450
 TOTAL 2,046
 LIS TOTAL 1,636 = 1,636

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 4 Feb 2020

ASSESSMENT FOR REPAIR: YAMAHA YZF-R3 - FBP7480T

Chassis No.: MH3RH12D000002343

Engine No.: H405E0021511

Qty

Description

Estimate

1 pc Left lower fairing
1 pc Left lower fairing emblem
1 pc Left rear number plate lamp
1 pc Rear mudguard assy
1 pc Left rear signal

\$280 \$320.00 / SCR
\$45.00 / NCC
\$85.00 / SCR
\$245.00 / SCR
\$70 \$95.00 / SCR

Less discount 10%

725 \$790.00
\$79.00
652.50 \$711.00

Special nett items

Total Estimate

\$711.00

Note: The above estimate is subjected to the prevailing GST of 7%



For Bike Production Pte Ltd

PARTS \$3,225
LESS 10% \$2,902.50
S/NET \$ 30
LABOUR \$ 450
\$3,382.50
LESS LIS 20% \$2,706.00
\$2,700.00 / 2 REPAIR DAYS

UNDERTAKING

I, KRISNAN GOVE, (NRIC No. S0825365Z), hereby confirm that the Singapore Accident Statement lodged by me on 07012020 at 1300 ¹⁶¹⁰ hours pertaining to the accident involving motor car Reg. No: FBP7480T, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature

: 

Name of Insured / Driver

: KRISNAN GOVE


Nric No.

: S0825365Z

Date

: 3/2/2020

Signature

: 

Name of Policyholder

: KRISNAN GOVE

Nric No.

: S0825365Z

Date

: 3/2/2020



AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way
#07-16

MOTOR ACCIDENT INTERVIEW FORM

NAME : KRISNAN GOVE
VEHICLE NUMBER : FB7480T
DATE/ TIME OF ACCIDENT : 07012020 / 1300H
PLACE OF ACCIDENT : BELILIOS LANE OPEN SPACE CARPARK
THIRD PARTY VEHICLE (IF ANY) : N.A.

WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

FROM WORKPLACE TO TEKKA

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?


NO.

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

HIT AND RUN.

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NO.


NAME: KRISNAN GOVE

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	10 Feb 2020		13 Jan 2020 13:02 Edit Adj Rpt	\$2,700.00 Edit Estimates	\$2,700.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	KRISNAN GOVE, ID: S0825365Z, Tel: +6582929511, Email: krisnan.gove@gmail.com			
Vehicle Reg. No.:	FBP7480T	Date of Loss:	07/01/2020 13:00 - :59 [7 Months and 7 Days From LTA Reg Date (Man Yr)]	
Claim Type:	OD / 9973395946SG	Policy/Cover Note No.:	1900105213 (Comprehensive)	
		Excess:	S\$300.00	
Repairer:	Bike Production Pte Ltd (HQ) 610 SERANGOON ROAD, 218216 Serangoon - Tel:			
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mithoo Singh, Aashweenjeet Kaur] Aashweenjeetkaur.Mithoosingh@aig.com			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 22/01/2020]			
Driver/Custodian:	KRISNAN GOVE (68 / Male) , NRIC: S0825365Z, Tel: +6582929511 Email: krisnan.gove@gmail.com			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (11/02/2020): Alert - Adj Mandate Approved (S\$2850.00) - FBP7480T - Claim Handler: Mithoo Sing...
- AIG_SG (10/02/2020): FBP7480T / OD / 07/01/2020 / Coverage & Excess update
- AIG_SG (05/02/2020): Alert - Adj Mandate Approved (S\$2250.00) - FBP7480T - Claim Handler: Mithoo Sing...

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents



































*FBP7480T (9973395946SG)


































OD

Jan 7 2020 1:00PM






[KRISNAN GOVE]

Bike Production Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/02/20 11:19	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>
2	07/02/20 13:57	Adjuster Immediate Advice	 Load HTM	<input checked="" type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
2	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
3	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
4	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
5	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
6	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
7	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
8	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
9	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
10	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
11	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
12	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
13	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
14	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
15	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
16	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
17	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
18	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
19	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
20	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
21	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
30	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
31	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
32	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
34	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
35	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/02/20 11:29	General View	 Load JPG	<input checked="" type="checkbox"/>
42	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	07/02/20 13:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
56	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
57	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
58	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
59	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
60	26/02/20 16:19	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/02/20 10:37	Singapore Accident Statement	 Load PDF	
2	04/02/20 10:40	Driver's Driving License and NRIC	 Load PDF	
3	04/02/20 10:47	ESTIMATE	 Load PDF	
4	07/02/20 08:34	undertaking letter and interview form	 Load PDF	
5	28/02/20 15:08	SUPPLEMENTARY	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	07/01/20 16:37	Accident Statement	 Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
5	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	07/01/20 16:36	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail	Print
1	07/01/20 16:26	Identification Card	 Load TIF	
2	07/01/20 16:26	Driving License	 Load TIF	
3	07/01/20 16:26	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120Our File No: CS/AIG20000741/NTD3S2
Date: 28/02/2020

REFERENCE

Insured/Claimant: KRISNAN GOVE Policy No: 1900105213
Date of Loss: 07/01/2020 Nature of Claim: OD Claim No: 9973395946SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBP7480T Engine No: H405E0021511
Make & Model: YAMAHA YZF-R3, 321cc ABS Chassis No: MH3RH12D000002343
Reg. Date: 31/05/2019 (Man. Year: 2019) Odometer: 8336 km
Colour: Blue
Engine Capacity: 321 cc
Market Value/New Car Price: S\$12,500.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70 R17 Rear Tyre Size: 140/70 R17
Front Left Side: Dunlop 3 mm Rear Left Side: Dunlop 3 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,791.00	2,932.50	1,858.50	38.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	450.00	1,470.00	76.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,711.00	3,382.50	3,328.50	49.60
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	6,711.00	2,700.00	4,011.00	59.77
+ GST 7.00/7.00% (S\$)	469.77	189.00	280.77	59.77
Nett Amount (S\$)	7,180.77	2,889.00	4,291.77	59.77

INSPECTION

Date of Assignment: 13/01/2020
Date Inspected: 03/02/2020 Inspected At: Bike Production Pte Ltd (HQ)
610 SERANGOON ROAD
Singapore 218216
Estimated Period of Repair: 2.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT FORK ASSY	Serviceable	850.00 FL	*- FL
2	1		*FRONT COWLING	Serviceable	395.00 FL	*- FL
3	1		*FRONT COWLING AMBLEM	Not Necessary	55.00 FL	*- FL
4	1		*LEFT MIRROR	Scratched	165.00 FL	*100.00 FL
5	1		*LEFT BLACK COVER	Scratched	205.00 FL	*205.00 FL
6	1		*LEFT HANDLE BAR	Serviceable	185.00 FL	*- FL
7	1		*LEFT BALANCER	Scratched	45.00 FL	*45.00 FL
8	1		*CLUTCH LEVER	Broken	75.00 FL	*75.00 FL
9	1		*LEFT FRONT SIGNAL	Scratched	95.00 FL	*70.00 FL
10	2		*STEERING BEARING	Serviceable	90.00 FL	*- FL
11	1		*STEERING STEM	Serviceable	335.00 FL	*- FL
12	1		*LEFT FAIRING ASSY	Scratched	325.00 FL	*325.00 FL
13	1		*LEFT FAIRING AMBLEM	Necessary	55.00 FL	*55.00 FL
14	1		*LEFT UPPER BLUE FAIRING	Scratched	295.00 FL	*295.00 FL
15	1		*LEFT LOWER COVER	Scratched	205.00 FL	*205.00 FL
16	1		*LEFT FOOTREST FRONT	Broken	95.00 FL	*95.00 FL
17	1		*LEFT FOOTREST HOLDER FRONT	Bent	195.00 FL	*195.00 FL
18	1		*GEAR PEDAL ASSY	Bent	145.00 FL	*145.00 FL
19	1		*SIDE STAND	Scratched	105.00 FL	*105.00 FL
20	1		*REAR LEFT COVER	Scratched	295.00 FL	*295.00 FL
21	1		*REAR FOOTREST HOLDER LEFT	Scratched	205.00 FL	*205.00 FL
22	1		*REAR FOOTREST LEFT	Scratched	85.00 FL	*85.00 FL
23	1		*REAR NUMBER PLATE	Deformed	30.00 FS	*30.00 FS
24	1		*LEFT LOWER FAIRING	Scratched	320.00 FL	*280.00 FL
25	1		*LEFT LOWER FAIRING EMBLEM	Necessary	45.00 FL	*45.00 FL
26	1		*LEFT REAR NUMBER PLATE LAMP	Scratched	85.00 FL	*85.00 FL
27	1		*REAR MUDGUARD ASSY	Scratched	245.00 FL	*245.00 FL
28	1		*LEFT REAR SIGNAL	Scratched	95.00 FL	*70.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,320.00	3,255.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	529.00	322.50
Total Parts (\$\$)	4,791.00	2,932.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES.	New	100.00	0.00
2	REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS, CHECK WIRING AND LIGHTING SYSTEM.	New	700.00	300.00
3	TO REPLACE AND BALANCE FRONT AND REAR WHEEL RIM.	New	120.00	0.00
4	TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING.	New	450.00	0.00
5	TO REMOVE / REFIT, REPLACE (IF DAMAGE) CHECK AND STRAIGHTEN FORK TUBES.	New	180.00	0.00
6	SPRAY PAINTING.	New	250.00	150.00
7	RESET METER.	New	120.00	0.00
Gross Labour Cost (\$\$)			1,920.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >