



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20000755/Kyf3s2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 29-04-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 5992J	Veh. Inspected	SMA 9144A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000176/LOR	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	13/01/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VOXY (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	ZWR800307046	Colour	METALLIC GREY
Odometer	64481	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	9 mm
L/H Front Tyre	195/65 R15	MICHELIN	9 mm
R/H Rear Tyre	195/65 R15	MICHELIN	9 mm
L/H Rear Tyre	195/65 R15	MICHELIN	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR WINDSCREEN SHATTERED.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/01/2020	Inspection Date	14/01/2020
Survey held at	MBM WHEELPOWER PTE LTD 160 SIN MING DRIVE #06-02 SIN MING AUTOCITY, SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	-----------------------