			442.6+
			332•7+
T	Auto Comisso Dto Ltd		15•4+
	ans-cab Auto Services Pte Ltd	11.	576*3+
No. 2 Ang Mo Kio Street 63 Singapore 569111		100.	116.5+
Tel No. : 6287 6666 Fax No. : 6257 1330		Resi	1,147*8+
CO./GST Reg. No. 201019626G SHD 5256E		rusi	650 • 3 +
SHI	D 5256E		123•7+
	Vehicle No.:	SHI	123•7+
	Chassis No.:	JTD	=
	Vehicle Make:	TOY	3,996**
		PRIL	
	Vehicle Model:	9.1.;	3,996 · ×
	Date of Accident :	AIG	75 %
	Third Party Insurer:	17/3	2,997**
	Date of Registration:	21/1-	0 • C
	PART	\$	
1	REAR BUMPER	Š	220 • +
1	REAR BUMPER RE-INFORCEMENT	Š	66 • +
1	REAR BUMPER TOWING COVER	\$	40 • +
1	REAR BUMPER UNDER COVER (BLACK)	\$	100 • +
1	REAR BUMPER SIDE RETAINER LH		30 • +
1	REAR BUMPER SIDE RETAINER RH	\$	47 • +
1	SEAL, REAR BUMPER SIDE, LH	\$ 1	52.9+
1	SEAL, REAR BUMPER SIDE, RH	\$	53.5+
1	REAR TAILGATE	\$	30 · +
1	REAR TAILGATE OUTER GARNISH	\$	30•+
1	ANTENNA, ELECTRICAL KEY	\$	669•4*
1	COVER, REAR COMBINATION LAMP, RH	\$	009*4*
1	COVER, REAR COMBINATION LAMP, LH	\$	0 · c
1	GARNISH, BACK DOOR SIDE, LH	\$	0-0
1	GARNISH, BACK DOOR SIDE, RH	\$	60 • +
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER R	H S	60•+
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER L		600•+
1		4	120•+
1	BOARD ASSY, BACK DOOR TRIM		30 • +
1	REAR TAILGATE WEATHERSTRIP	3	50 • +
1	COVER, BACK DOOR LOCK	2	1,100.+
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	20•=
1	SWITCH ASSY, BACK DOOR OPENER	\$	2,040 *
1	SPOILER, SUB ASSY, REAR	\$	
1	GLASS, BACK WINDOW FIX	\$	0 • c
1	PANEL SUB-ASSY, BODY LOWER BACK	\$	(I) 100 , 101 and
1	TAILLAMP LOWER RH	9	2,997.+
1		,	669•4+
	TAILLAMP UPPER RH	3	2,040 =
1	REAR BUMPER SIDE RH	\$,	P(p)\$ 5,706.4*
			and the state of t

0.0