

ASS. REC. BY: Sam Pin

REF:

INC

NS/INC20000826/Qtd3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SMC 6348MPolicy No. 5110402808 (13/7/2019-12/07/2020)Claims No. MT/1071073-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMB 3601G Yr Regn: 01/Jul/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Alexander Dennis Enviro 500 c.c 8849Colour: silver multi colour A/C: Insured / Std / NI / NASp. Reading 253390 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SFD76CLRSEMTL3438

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: 805 / 70 R22.5R: 805 / 70 R22.5 (P)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Fireenza

Front

Rear

R/Bal. 5 mm R/Bal. 5/5 mmL/Bal. 5 mm L/Bal. 5/5 mmD.O.A. 11/11/2019 D.O.I. 13/01/2020Survey held at SMARTDes. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SMB 3601G - NS/INC/302117 / S/be2 DOA: 9/10/2017

SM 6348M - CS/MSG/18013732 / R/vd3e2 DOA: 23/7/2018

Confirm with Catherine.

Finalize \$650 @ 2 days, (LA) (Red: 588 :49%)

Date/Time, File Pass to? ☐ : Prell. Report1) 13/3 Typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) \$ + RS. \$☐ : Interview (\$ _____) Phone☐ : Tech. Invs (\$ _____) Others☐ : Weekend (\$ _____)

TOTAL

Rep. Formel: TPLump Sum / L.E.I. C: 650

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Thursday, 12 March, 2020 6:25 PM
To: 'Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses)'
Subject: RE: Finalisation - SMB3601G (BUS/11/19/5016) - NTUC

Hi Catherine,

Confirm the finalize amount \$650. Repair day 2 days under lump sum repair.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses) [<mailto:catherineleesc@smrt.com.sg>]
Sent: Thursday, 12 March, 2020 11:13 AM
To: Oi Sun Pin (LKK Auto); SUR; Admin A
Subject: FW: Finalisation - SMB3601G (BUS/11/19/5016) - NTUC

Hi Sunpin,

This case has not finalised yet.
Please expedite.

Thank you

Regards
Catherine Lee

From: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses)
Sent: Tuesday, 25 February 2020 17.38
To: sunpin@lkkauto.com; SUR; Admin A
Cc: Koo Yew Chung (Auto Svcs/ARC/ARC); AutoSvs-ARC (Bus)
Subject: Finalisation - SMB3601G (BUS/11/19/5016) - NTUC

Hi Sun Pin,

Attached herewith our copy of the bus repair estimate for the case.
Our finalised amount is \$650/- @ 2 working days under lump sum repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards

Denise Tay (LKKAUTO)

From: MTCL@income.com.sg
Sent: Friday, 13 March 2020 11:18 AM
To: Denise Tay (LKKAUTO)
Subject: RE: REQUEST CLAIM NUMBER

Dear Sir/Mdm,

We have registered the claim.

Our reference number: MT/1071078-002
Claim Officer: David Phua

Please allow the claim officer 2-3 working days to respond to your case.

We appreciate if you do not respond to this email. Thank you

Best regards,

Diana Tay
Senior Admin Assistant
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at income.com.sg/careers

in wi
yo

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Friday, 13 March 2020 9:04 AM
To: MTCL@income.com.sg
Subject: REQUEST CLAIM NUMBER

Dear Sir/Mdm,

Request claim number

S/No		Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate	Tentative repair cost
1		Comfort Transportation PTE LTD	SMB 3601G	SMC 6348M	11/11/2019	19:05	1238	650

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident
Vehicle No.(For Motor) Certificate Number

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5110402808		ZHOU LEIJUN	S2672929G	GPC	drive PREMIUM	SMC6348M	SMC6348M	13/07/2019	12/07/2020

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/11/2019 08:17
Date Of Accident	11/11/2019 19:05
Exact Location Of Accident	PIE TOWARDS BKE BEF ADAM RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB3601G
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	198202292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	ALEXANDER DENNIS
Model	ENVIRO 500

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	

Driver

Name of Driver	RAMANATHAN PANNIR SELVAM
NRIC No	S1165923C
Date Of Birth	30/11/1955
Occupation	OUTDOOR
Date Of Driving Pass	20/03/1982
Driving Experience	37 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NO ADDRESS

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 70

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

While my bus SMB3601G was travelling along PIE towards BKE before Adam Road Exit, the left front body of the bus was hit by the right rear body of a private car (SMC6348M) suddenly cut in front my lane. There were 70 pax onboard my bus and no injuries reported. That's all.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING DOWNLOAD

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMC6348M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver MR ZHOU

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

IMPORTANT NOTICE

SKETCH PLAN


SWB36019
page 70
05-08-2019
Bus/19/5016

1. Please report strictly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
 - i understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurer's lawyer/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firm, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyer/law firm), which may be used outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:




Reporting Centre for Insurance Services (RCIS)
Name:
NIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Adam Road Exit



PIE towards BRE
before Alam Road Exit

DECLARATION OF THE U.S.

1 We declare the foregoing particulars are true in every respect.



Polycypher's Signature
Noted As True

Driver's Signature
(If driver is not the policyholder)

Reporting Centre Personnel Signature
Name:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

292D

Vehicle Details

Vehicle No.:

SMB3601G

Vehicle to be Exported:

No

Intended Deregistration Date:

13 Jan 2020

Vehicle Make:

ALEXANDER DENNIS

Vehicle Model:

ENVIRO500

Primary Colour:

Silver

Secondary Colour:

Black

Manufacturing Year:

2014

Engine No.:

22145455

Chassis No.:

SFD76CLR5EMTL3938

Maximum Power Output:

-

Open Market Value:

\$507,930.00

Original Registration Date:

01 Jul 2015

First Registration Date:

01 Jul 2015

Transfer Count:

0

Actual ARF Paid:

\$0.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Rebate Amount:

\$0.00

Total Rebate Amount:

\$0.00

The information contained herein is correct as at 13 Jan 2020

OK



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68652623
Accident Reporting Number : 68662672

Date Generated : 25/02/2020

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	\$530.00	\$265.00 /
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$708.00	\$538.00 /
Total Spray Painting & Panel Beating	\$708.00	\$538.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$160.60)
Total Other Costs	\$0.00	(\$160.60)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011051	BODY LH	20594483/2	BUMPER,CORNER L/H,F OR ADL E500 DD BUS	1.00	\$1,190.20	100.00	\$0.00	Repair	Repair XR
Total					\$1,190.20		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

2 days

$$\begin{array}{r} 803 \\ - 209 \\ \hline 642.4 \end{array}$$

415 \$ 650



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 25/02/2020

User ID : CatherineLee

Section A - Accident Details


Registration Number	SMB3601G
Case Reference Number	BUS/11/19/5016
Registration Date	1/7/2015
Company Type	SMRT Buses Ltd
Make	ALEXANDER DENNIS
Model	ENVIRO 500
Name of Driver	RAMANATHAN PANNIR SELVAM
Type of Accident	Side Swipe
Accident Date and Time	11/11/2019 7:05 PM
Accident Reported Date and Time	11/11/2019 9:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105304
Special Instruction to ARC, if any	SMB3601G-LEFT FRONT PORTION SMC6348M (TP) INSURED WITH NTUC
Prepared Date and Time	13/1/2020 10:30 AM
Chassis Number	SFD76CLR5EMTL3938
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$708.00	\$538.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	(\$160.60)
TOTAL COST	\$1,238.00	\$642.40
Lump Sum Total	\$0.00	\$650.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	13/01/2020 10:45 AM	13/01/2020 3:43 PM
Signature		
Remarks		


Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



Front

Front



Left Side



Right Side



Case Details

Case Reference Number : BUS/11/19/5016

Company Type : SMRT Buses Ltd

Insurance Company Name : NTUC Income

Type of Repair : Accident Repair

Estimation ID : EST-10119-ID

Insurance Co-operative Ltd

Accident Date and Time : 11/11/2019 11:05

Vehicle Registration Number : SMB3601G

Assigned By : Claiming Case Owner Team

AM

Vehicle Age(In Months) : 52

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approva		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Re
Standard	Main	BODY LH	6011051	BUMPER,CORNER-L/H,FOR ADL E500 DD BUS	1	1,190.20	1,190.20	100.00	0.00	Repair	1	0.00	Repair X R
Total Spare Part Cost									0.00		Surveyor Total	0.00	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	0	
Final Spare Part Cost									0.00		Final Sur Total	0.00	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR LH FRONT PORTION	530.00	265	
Total:			530.00	265.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	708.00	538	
Total:			708.00	538.00	

2428.208

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	0.00	0.00
Total Labour Cost	0.00	265.00




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20000826/Qtd3s2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 16-03-2020	
Code: INC4			
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMC 6348M	Veh. Inspected	SMB 3601G
Policy No.	5110402808	Coverage (\$)	0.00
Claim No.	MT/1071078-002	Excess (\$)	0.00
Assign From		Assign Date	13/01/2020
2. Vehicle Particulars & Condition			
Make & Model	ALEXANDER DENNIS ENVIRO500	c.c	8849
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	SFD76CLR5EMTL3938	Colour	MULTI-COLOUR
Odometer	253390	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	305/70 R22.5	FIRENZA	5 mm
L/H Front Tyre	305/70 R22.5	FIRENZA	5 mm
R/H Rear Tyre	305/70 R22.5 (D)	FIRENZA	5/5 mm
L/H Rear Tyre	305/70 R22.5 (D)	FIRENZA	5/5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/11/2019	Inspection Date	13/01/2020
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 3601G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REPLACEMENT OF PARTS	TO REPAIR SEE LABOUR		
	BUMPER, CORNER: L/H, FOR ADL E500 DD BUS		1,190.20	-
			1,190.20	-
	LABOUR			
	TO REPAIR LH FRONT PORTION. INCLUSIVE OF THE REPAIR OF BUMPER, CORNER: L/H, FOR ADL E500 DD BUS.		530.00	265.00
1	TO PUTTY & RESPRAY.		708.00	538.00
			1,238.00	803.00
GRAND TOTAL			2,428.20	803.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				650.00

Report Ref No. NS/INC20000826/Qtd3s2

OI SUN PIN

Asst. Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.