

ASS: REC. BY:

REF: CS/LPC 20000840/uyf322

Special Instruction:

EXCESS  
\$500/=

Surveyor MARCUS ASSIGNMENT (Office)

From (Person): ONG Li Li of LPC Date/Time: 14 Jan 2020 11:06am

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJY 5484D Insured: \_\_\_\_\_

at Workshop m/s: SME MOTOR Tel: 6747 6106

of 1 KAKI BUKIT AVI 6 #02-15 MUTOBAY

Policy No: 219VP05022517 Claim No: 19/20/20/VP05/022900

Sum Insured: \_\_\_\_\_ Excess: \$500.00

Make of Veh: \_\_\_\_\_ D.O.A. 9.1.2020

(Client's Benefit)

CA REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 14.1.2020 11:12am Person Contacted: Pei Yim Vehicle IN / OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
|           | SJY 5484D - X                   |

15/1/2020 @1232pm Marcus said repairer agree repair at not exceeding NV

15/1/2020 Revert via merimen

16/1/20 Approval Mandate by Merimen

16/1/20 Sent email to workshop Authorise

ASS. REC. BY: *Marius*

REF:

*LPC/*

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 P / WS / TP RES / OD RES / EVA / INV / MV  
 Inspect Vehicle No: *SJ / 5484D*  
 at Workshop m/s: *Sme*  
 of \_\_\_\_\_  
 insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: *5'00*  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: *SJ45484D* Yr Regn: *13/9/10*  
 Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or *CM/*  
 Make: *Daikatsu Terios* cc *1495*  
 Colour: *Red* A/C:  Insured / Std / NI / NA  
 Sp. Reading: *176913* T/Radio:  Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: *MHKR2 CJ209K000343*  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Free / Jammed / Leaked / Burnt or  
 Brakes:  Free / Jammed / Leaked / Burnt or  
 Mod:  Nil / S/Rim / STD A/Rim or

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

Tyre Size: F: \_\_\_\_\_ R: *215/60R16*  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO /  OKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: *6* mm R/Bal: *6* mm  
 L/Bal: *0* mm L/Bal: *6* mm  
 D.O.A: *9/1/20* D.O.I: *14/1/20*  
 Survey held at: \_\_\_\_\_  
 Des. of Damages:  Fnt /  Rear /  O/S /  N/S /  U/C / Rooftop or  
*RP.*  
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: *17k.*  
 IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No  
 PR Search: *9* Consistent?: Yes or No  
 Est. Repairs: *4* days Res: Yes or No  
 Lum Sum: *20* % 3 Val: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: *Lee 12/9/20* Vehicle: IN / OUT

*21/2/20* *5/8 m/s - LTA 13325 Rep 96.*  
*net \$3675*  
*1/5 #3000 confirmed with AH ying (Red \$4600-50, 56%)*

RECEIVED 24 FEB 2020

Date/Time, File Pass to?  : Prell. Report  
 : Final Report

Days Of Repair: *4*  
 Resurvey No. of Trip: *3*

*21 24/2/20 Typist*

Add Fee:  : Site Insp (\$)  
 : Interview (\$)  
 : Tech. Invs (\$)  
 : Weekend (\$)

|                 |                   |
|-----------------|-------------------|
| Survey Fee:     | <i>290</i>        |
| Transportation: |                   |
| Photos          |                   |
| Others          | <i>11</i>         |
| <b>TOTAL</b>    | <b><i>301</i></b> |

Report Format:  
 Lump Sum / I.B.I: (\$ *\$3600/=*)

## View Received Message

This mail is associated with :

**SJY5484D (19/20/20/VP05/022900)**  
**[SHA4370E]**

OO  
Jan 9 2020 5:00PM  
[RAMO INDUSTRIES PTE LTD]  
SME Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** Lonpac Insurance Bhd (HQ) (LONPAC\_HQ), sent on 16/01/2020 11:55 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$3675.00) - SJY5484D - Claim Handler: Ong Li Li

Approved: 3675.00.

### DOCUMENTS SUMMARY

There are no documents.

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

| Case | Notified  | Est Submitted                           | Adj Assigned                                | Adj Rpt | Adj Submitted | Ins Auth'd | Status   |
|------|---|---|---|---------|---------------|------------|--|
| Main | 14 Jan 2020 10:16<br><a href="#">Sendback Est</a> | 14 Jan 2020 10:28<br><b>S\$8,200.50</b> | 14 Jan 2020 11:06<br><a href="#">Assign</a> |         |               |            | <b>New Assignment</b><br><a href="#">Cancel Case</a> |

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

### CLAIM SUBFOLDER DETAILS

|                        |   |                        |   |
|------------------------|---|------------------------|---|
| Insured:               | RAMO INDUSTRIES PTE LTD, Co. Reg. No.: 200700682N   |                        |   |
| Vehicle Reg. No.:      | SJY5484D  | Date of Loss:          | 09/01/2020 17:00 - :59<br>[111 Months and 27 Days From LTA Reg Date (Man Yr)] |
| Claim Type:            | OD / 19/20/20/VP05/022900   | Policy/Cover Note No.: | Z19VP05022517 (Comprehensive)   |
| Vehicle Reg. No. (TP): | SHA4370E  | Policy No. (TP):       |   |
|                        |   | Excess:                | S\$500.00   |
| Repairer:              | SME Motor Pte Ltd (Kaki Bukit) 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines) |                        |   |
| Handling Insurer:      | Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]                                     |                        |   |
| Adjuster:              | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 23/01/2020]                                       |                        |   |
| Driver/Custodian:      | YU BING (50 / Male), NRIC: F8289718Q, Tel: +6584065342 Email: NOEMAIL   |                        |   |

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date    | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. |          |      |            |         |         |             |              |            |       |

## Yvonne Wong (LKK Auto)

---

**From:** Yvonne Wong (LKK Auto)  
**Sent:** Thursday, January 16, 2020 3:07 PM  
**To:** peiyong@smemotor.com.sg; SUR  
**Cc:** SEBASTIAN@SMEMOTOR.COM.SG  
**Subject:** RE: SJY 5484D-DOA: 9/1/2020 (LONPAC OD)

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SJY5484D (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

### **NOTE: REPAIR NOT EXCEEDING \$3,600.00**

Thank you.

Best Regards,

**Yvonne Wong (Ms) | Case Handler**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [yvonne.wong@lkkauto.com](mailto:yvonne.wong@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, January 15, 2020 11:35 AM  
**To:** Sebastian Kong <[sebastian@smemotor.com.sg](mailto:sebastian@smemotor.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** SJY 5484D-DOA: 9/1/2020 (LONPAC OD)

Dear Sebastian,

Attach marking.

Best Regards,

**Veron Chen | Case Handler on behalf of Yvonne**

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

|  |  |
|--|--|
| <b>To:</b> Lonpac Insurance Bhd<br>300 Beach Road<br>#17-04/07 The Concourse<br>Singapore 199555 | <b>From:</b> LKK Auto Consultants Pte Ltd<br>51 Ubi Ave 1 #01-25<br>Paya Ubi Industrial Park<br>Singapore 408933 |
| <b>Attn:</b> Ong Li Li   |  |
| <b>Date:</b> 15 Jan 2020   |  |
| <h3 style="margin: 0;">Preliminary Advice</h3>   |  |

|                    |   |                         |                 |
|--------------------|---|-------------------------|-----------------|
| Vehicle No         | : SJY5484D  | Accident Date           | : 09/01/2020    |
| Make               | : DAIHATSU TERIOS   | Policy No.              | : Z19VP05022517 |
| Assignment Date    | : 14/01/2020  | Excess                  | : S\$500.00     |
| Date of Inspection | : 14/01/2020  | Est. Duration of Repair | : 4.00          |
| Inspection At      | : SME MOTOR PTE LTD (KAKI BUKIT)<br>1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                         |                 |

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

|                             |             |                 |
|-----------------------------|-------------|-----------------|
| Repairer's Estimate (Gross) | :S\$        | 8,200.50        |
| Revised Amount              | :S\$        | 4,880.25        |
| Check Items (Estimated)     | :S\$        | 690.00          |
| <b>Total</b>                | <b>:S\$</b> | <b>5,570.25</b> |

Lump Sum Repair :S\$

#### Total Loss Consideration

|                          |             |                 |
|--------------------------|-------------|-----------------|
| New for Old Value        | :S\$        |                 |
| Pre-Accident Value       | :S\$        | 17,000.00       |
| COE / PARF Rebate        | :S\$        | 13,325.00       |
| Salvage Value            | :S\$        |                 |
| <b>Margin for Repair</b> | <b>:S\$</b> | <b>3,675.00</b> |

#### Remarks

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer able to repair at Not Exceeding Nett Value \$3,675.00

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                    |
|----------------------------|--------------------|
| Date Of Report             | 10/01/2020 16:25   |
| Date Of Accident           | 09/01/2020 17:50   |
| Exact Location Of Accident | PIE TOWARDS CHANGI |
| Country/State of Loss      | SINGAPORE          |

### DETAILS OF OWN VEHICLE

|                             |                         |
|-----------------------------|-------------------------|
| Vehicle Registration Number | SJY5484D                |
| <b>Insured/Policyholder</b> |                         |
| Name Of Registered Owner    | RAMO INDUSTRIES PTE LTD |
| Co Reg No                   | 2XXXXX682N              |
| Email Address               | NOEMAIL                 |
| Mobile Phone No             |                         |
| Alternative Phone No        | OFFICE-65156690         |

### Vehicle Particulars

|              |                |
|--------------|----------------|
| Manufacturer | DAIHATSU       |
| Model        | TERIOS-1.5 (A) |

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

|                  |             |
|------------------|-------------|
| Vehicle Category | PRIVATE CAR |
|------------------|-------------|

### Insurance Company

|                           |                      |
|---------------------------|----------------------|
| Name of Insurance Company | LONPAC INSURANCE BHD |
| Type Of Coverage          | COMPREHENSIVE        |
| Fleet Policy              | NO                   |
| Policy Number             | Z19VP05022517        |
| Cover Note Number         |                      |

### Driver

|                      |                      |
|----------------------|----------------------|
| Name of Driver       | YU BING              |
| NRIC No              | FXXXX718Q            |
| Date Of Birth        | 15/04/1969           |
| Occupation           | INDOOR               |
| Date Of Driving Pass | 14/07/2011           |
| Driving Experience   | 8 YEARS AND 5 MONTHS |
| Gender               | MALE                 |
| Mobile Number        | (LOCAL) +65-84065342 |
| Fax Number           |                      |
| Contact Number       |                      |
| Email Address        | NOEMAIL              |

Address -  
Postcode -  
Was driver an employee of the Insured's Company YES  
If No, Relationship of the Driver with the Insured -  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station -  
Was notice of intended Prosecution given? NO  
If Yes, against whom? -

#### Circumstances of Accident

VEHICLE B SUDDENLY JAM BRAKE. I COULDN'T STOP IN TIME AND HIT ONTO VEHICLE B REAR.

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SHA4370E  
Vehicle Make/Model/Colour -  
Details Of Properties VEHICLE B  
Vehicle Category TAXI  
Name of Driver -  
NRIC/Passport Number -  
Contact Number -  
Address -  
Postcode -  
Insurance Company Name -  
Nature Of Damage -  
No. Of Passenger (Including Driver) -

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

VEHICLE B SUDDENLY JAM BRAKE, I COULDN'T STOP IN TIME AND HIT ONTO VEHICLE B REAR.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name  
NIC/FIN No.

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

|                |         |
|----------------|---------|
| Owner ID Type: | Company |
| Owner ID:      | 682N    |

### Vehicle Details

|                               |                              |
|-------------------------------|------------------------------|
| Vehicle No.:                  | SJY5484D                     |
| Vehicle to be Exported:       | No                           |
| Intended Deregistration Date: | 15 Jan 2020                  |
| Vehicle Make:                 | DAIHATSU                     |
| Vehicle Model:                | F700RG-GMDF TERIOS SX 1.5 MT |
| Primary Colour:               | Red                          |
| Manufacturing Year:           | 2009                         |
| Engine No.:                   | DBC0432                      |
| Chassis No.:                  | MHKG2CJ209K000343            |
| Maximum Power Output:         | 77.0 kW (103 bhp)            |
| Open Market Value:            | \$22,287.00                  |
| Original Registration Date:   | 13 Sep 2010                  |
| First Registration Date:      | 13 Sep 2010                  |
| Transfer Count:               | 2                            |
| Actual ARF Paid:              | \$22,287.00                  |

### Intended PARF Rebate Details

|                               |             |
|-------------------------------|-------------|
| PARF Eligibility:             | Yes         |
| PARF Eligibility Expiry Date: | 12 Sep 2020 |
| PARF Rebate Amount:           | \$11,143.00 |

### Intended COE Rebate Details

|                             |                          |
|-----------------------------|--------------------------|
| COE Expiry Date:            | 12 Sep 2020              |
| COE Category:               | A - Car (1600cc & below) |
| COE Period(Years):          | 10                       |
| QP Paid:                    | \$33,089.00              |
| COE Rebate Amount:          | \$2,182.00               |
| <b>Total Rebate Amount:</b> | <b>\$13,325.00</b>       |

The information contained herein is correct as at 15 Jan 2020

OK



**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Renewal COE Toyota Wish 2.0A.



2.96% P.A. \$0 Admin, Monthly  
From \$688, 2 Years Warranty  
Engine/Gearbox,  
GV Credit, StarAC



Browse by Category

1 vehicles

daihatsu terios

Sort by Date Posted

Advanced Search

Search Selection

daihatsu terios



**Daihatsu Terios 7**

Free 1 Year Insurance/Warranty.

Euro Performance Asia Pte Ltd

Posted: 11-Jan-2020

Tags: 2011 Daihatsu Terios, 2011 daihatsu terios, Daihatsu Terios, daihatsu terios, Daihatsu, Terios, terios, Used Daihatsu

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh T

For old advertisements, view Expired ads

Follow sgCarMart.com

### SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883  
 Tel: 6747 6106 (6 Lines) Fax: 6744 2368  
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg  
 Co. & GST Reg. No: 201119451E

INSURER: Lonpac Insurance Bhd (HQ)

**PARTICULARS OF CLAIM**

|                     |                         |                       |                   |
|---------------------|-------------------------|-----------------------|-------------------|
| Claim Type:         | OD (OWN DAMAGE)         | Ref. No:              | 20/LP/OD-023 (01) |
| Policy No:          | Z19VP05022517           | Date of Loss:         | 09/01/2020        |
| Vehicle Reg. No.:   | SJY5484D                | Driveable?            |                   |
| Driver Age/Info:    | 50 / MALE               | Party At Fault:       | UNKNOWN           |
| TP Injury Involved? | NO                      | Third Party Involved? | YES               |
| Insured/Claimant:   | RAMO INDUSTRIES PTE LTD |                       |                   |
| Driver:             | YU BING                 |                       |                   |

|                               |                          |                    |                   |
|-------------------------------|--------------------------|--------------------|-------------------|
| Make/Model:                   | DAIHATSU TERIOS, 1.5 (A) | Vehicle Reg. Date: | 13/09/2010        |
| Vehicle Colour:               | MAROON                   | Chassis No:        | MHKG2CJ209K000343 |
| Engine No:                    | DBC0432                  |                    |                   |
| Odometer:                     | 0 KM                     |                    |                   |
| Paint Type:                   |                          |                    |                   |
| Total Loss?                   | NO                       |                    |                   |
| Est. Duration of Repair (day) | 7                        |                    |                   |

*Handwritten notes:*  
 L/S 3600 Not Authorized  
 14/1/20  
 5x1255 + 500  
 H.L.

Description of Accident/Loss: VEHICLE B SUDDENLY JAM BRAKE. I COULDN'T STOP IN TIME AND HIT ONTO VEHICLE B REAR.  
 Remarks: VEHICLE IN.  
 Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

| COST OF CLAIMS           | Amount          |
|--------------------------|-----------------|
| Parts                    | 6,520.50        |
| Miscellaneous Items      | 60.00           |
| Labour                   | 1,620.00        |
| Paintwork Labour         | 0.00            |
| Towing                   | 0.00            |
| <b>Gross Total (S\$)</b> | <b>8,200.50</b> |
| <b>+ GST 7.00% (S\$)</b> | <b>574.04</b>   |
| <b>Nett Amount (S\$)</b> | <b>8,774.54</b> |

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 14 Jan 2020)  
**Parts:** M1-SUV      **DAIHATSU TERIOS 1.5 (A)** (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** SME Motor Pte Ltd/SJY5484D/14/01/2020 10:28  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*

**Estimates on Parts**

| No.                                       | Qty | Part No. | Particulars                           | %Disc | %Depr | Amount                 |
|---|-----|----------|---------------------------------------|-------|-------|------------------------|
| 1   | 1   |          | *FRT BONNET <i>DO/BUC</i>             | 0.00  | 0.00  | *700.00 F ✓            |
| 2   | 1   |          | *FRT BONNET LOCK <i>2/1</i>           | 0.00  | 0.00  | *90.00 F ✓             |
| 3   | 1   |          | *FRT GRILLE <i>CNE</i>                | 0.00  | 0.00  | *380.00 F ✓            |
| 4   | 1   |          | *FRT GRILLE LOGO <i>SCN</i>           | 0.00  | 0.00  | *45.00 F ✓             |
| 5   | 4   |          | *FRT GRILLE CLIP <i>RE</i>            | 0.00  | 0.00  | *10.00 F ✓             |
| 6   | 1   |          | *FRT BUMPER <i>DO</i>                 | 0.00  | 0.00  | *650.00 F ✓            |
| 7   | 2   |          | *FRT BUMPER RETAINER <i>11</i>        | 0.00  | 0.00  | *70.00 F X             |
| 8   | 10  |          | *FRT BUMPER CLIP <i>RE</i>            | 0.00  | 0.00  | *25.00 F ✓             |
| 9   | 1   |          | *FRT BUMPER REINFORCEMENT <i>RET</i>  | 0.00  | 0.00  | *300.00 F ✓            |
| 10  | 2   |          | *FOG LAMP <i>U/S CNE</i>              | 0.00  | 0.00  | *440.00 F <i>220</i> ✓ |
| 11  | 2   |          | *HEADLAMP <i>11</i>                   | 0.00  | 0.00  | *1,200.00 F X          |
| 12  | 1   |          | *HEADLAMP SUPPORT PANEL <i>RE</i>     | 0.00  | 0.00  | *400.00 F X            |
| 13  | 1   |          | *BRACE PANEL <i>1/1</i>               | 0.00  | 0.00  | *70.00 F ✓             |
| 14  | 1   |          | *AIRCON CONDENSER <i>pan/box</i>      | 0.00  | 0.00  | *600.00 F ✓            |
| 15  | 1   |          | *RADIATOR <i>pan/holder CNE</i>       | 0.00  | 0.00  | *600.00 F ✓            |
| 16  | 2   |          | *AIRCON SIDE DEFLECTOR <i>U/S 2/1</i> | 0.00  | 0.00  | *90.00 F <i>45</i> ✓   |
| <b>Sub Total (S\$)</b>                    |     |          |                                       |       |       | <b>5,670.00</b>        |
| <b>+ Margin on L,N Items 15.00% (S\$)</b> |     |          |                                       |       |       | <b>850.50</b>          |
| <b>Total Parts (S\$)</b>                  |     |          |                                       |       |       | <b>6,520.50</b>        |

F=Franchise part

SME Motor Pte Ltd/SJY5484D/14/01/2020 10:28. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

*3735*

### Estimates on Miscellaneous Items

| No                         | Qty | Particulars      | Amount       |
|----------------------------|-----|------------------|--------------|
| <b>Miscellaneous Items</b> |     |                  |              |
| 1                          | 1   | FRT NUMBER PLATE | 35.00 ✓      |
| 2                          | 1   | RADIATOR COOLANT | 25.00 ✓      |
| <b>Sub Total (S\$)</b>     |     |                  | <b>60.00</b> |

### Estimates on Labour

| No                             | Particulars                   | Lab.Type | Amount          |
|--------------------------------|-------------------------------|----------|-----------------|
| <b>Labour Items</b>            |                               |          |                 |
| 1                              | WIRE CHECKING                 | New      | 20.00 ✓         |
| 2                              | REMOVE & REFIX AIRCON AND GAS | New      | 100.00 ✓        |
| 3                              | LABOUR CHARGE                 | New      | 700.00 520      |
| 4                              | SPRAY PAINTING                | New      | 800.00 600      |
| <b>Gross Labour Cost (S\$)</b> |                               |          | <b>1,620.00</b> |

SME Motor Pte Ltd/SJY5484D/14/01/2020 10:28. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

55-95-28  
4476

1,275

Estimates on Miscellaneous Items  
There are no new miscellaneous items selected.

Estimates on Labour

| No                              | Particulars          | Lab.Type | Amount        |
|---------------------------------|----------------------|----------|---------------|
| <b>Labour Items</b>             |                      |          |               |
| 1                               | SPRAY FRT LH CHASIS  | New      | 17 150.00 X   |
| 2                               | REPAIR FRT LH CHASIS | New      | 17 200.00 X   |
| <b>Gross Labour Cost (\$\$)</b> |                      |          | <b>350.00</b> |

Report was unsubmitted during this print-out.  
Generated using **Merimen e-Claims IEAS**  
< END OF ESTIMATES >

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

| CLAIM SUBFOLDER TRACKING |                              |                      |                              |                                |                          |             |                                  |
|--------------------------|------------------------------|----------------------|------------------------------|--------------------------------|--------------------------|-------------|----------------------------------|
| Case                     | Notified                     | Est Submitted        | Adj Assigned                 | Adj Rpt                        | Adj Submitted            | Ins Auth'ed | Status                           |
| Main                     | 14 Jan 2020<br>10:16         | 14 Jan 2020<br>10:28 | 14 Jan 2020<br>11:06         | <b>S\$3,600.00</b>             | <b>S\$3,600.00</b>       |             | <b>Pending for Survey Report</b> |
|                          | <a href="#">Sendback Est</a> | <b>S\$8,200.50</b>   | <a href="#">Edit Adj Rpt</a> | <a href="#">Edit Estimates</a> | <a href="#">View Rpt</a> |             |                                  |
| Supp #1                  | 10 Feb 2020<br>14:14         | 10 Feb 2020<br>14:30 | 10 Feb 2020<br>14:30         |                                |                          | (Combined)  | <b>Combined with Main</b>        |
|                          |                              | <b>S\$350.00</b>     |                              |                                |                          |             | <a href="#">Uncombine Suppl.</a> |

| Main  | Reference  | Claim Details          | Documents   | Show All |         |             |              |            |       |
|---|--|------------------------|---|----------|---------|-------------|--------------|------------|-------|
| <b>CLAIM SUBFOLDER DETAILS</b>  |  |                        |   |          |         |             |              |            |       |
| Insured:  | <b>RAMO INDUSTRIES PTE LTD</b> , Co. Reg. No.: 200700682N  |                        |   |          |         |             |              |            |       |
| Vehicle Reg. No.:   | <b>SJY5484D</b>  | Date of Loss:          | 09/01/2020 17:00 - :59<br>[111 Months and 27 Days From LTA Reg Date (Man Yr)] |          |         |             |              |            |       |
| Claim Type:   | <b>OD / 19/20/20/VP05/022900</b>   | Policy/Cover Note No.: | 219VP05022517 (Comprehensive)   |          |         |             |              |            |       |
| Vehicle Reg. No. (TP):  | <b>SHA4370E</b>  | Policy No. (TP):       |   |          |         |             |              |            |       |
|   |  | Excess:                | S\$500.00   |          |         |             |              |            |       |
| Repairer:   | <b>SME Motor Pte Ltd (Kaki Bukit)</b> 1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, 417883 Eunos - Tel: 6747 6106 (6 Lines) |                        |   |          |         |             |              |            |       |
| Handling Insurer:   | <b>Lonpac Insurance Bhd (HQ)</b> - Tel: +65 62507388 ... [Handled by <b>Ong Li Li</b> - 62799254]                              |                        |   |          |         |             |              |            |       |
| Adjuster:   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 23/01/2020]  |                        |   |          |         |             |              |            |       |
| Driver/Custodian:   | YU BING (50 / Male), NRIC: F828971BQ, Tel: +6584065342 Email: NOEMAIL  |                        |   |          |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |  |                        |   |          |         |             |              |            |       |
| • LONPAC_HQ (16/01/2020): Alert - Adj Mandate Approved (S\$3675.00) - SJY5484D - Claim Handler: Ong Li Li   |  |                        |   |          |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |  |                        |   |          |         |             |              |            |       |
| Due Date  | Priority   | Type                   | Task Group  | Subject  | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |  |                        |   |          |         |             |              |            |       |

## Claim Documents

**SJY5484D (19/20/20/VP05/022900)**  
**[SHA4370E]**  
**OD**  
**Jan 9 2020 5:00PM**  
**[RAMO INDUSTRIES PTE LTD]**  
**SME Motor Pte Ltd**

| <a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a> |                 |   | <b>View</b> <span style="border: 1px solid black; padding: 2px;">View in Browser</span> |                                     |
|---|-----------------|---|---|-------------------------------------|
| <b>Letters/Correspondences</b>  |                 |   | 1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>                 |                                     |
| No  | Finalized On    | Lonpac Insurance Bhd (HQ)                   | Thumbnail   | Print                               |
| 1   | 14/01/20 11:08  | <b>OD Letter</b>                            | Load HTM  | <input type="checkbox"/>            |
| 2   | 14/01/20 12:49  | <b>Letter template to inf Insd TP claim</b> | Load HTM  | <input type="checkbox"/>            |
| <b>Assessment Reports</b>   |                 |   | 1 per page <input type="checkbox"/> <input checked="" type="checkbox"/>                 |                                     |
| No  | Finalized On    | SME Motor Pte Ltd (Kaki Bukit)              | Thumbnail   | Print                               |
| 1   | 14/01/20 10:28  | <b>Repairer Estimates</b>                   | Load HTM  | <input type="checkbox"/>            |
| 2   | 10/02/20 14:30  | <b>Repairer Estimates Suppl. #1</b>         | Load HTM  | <input type="checkbox"/>            |
| No  | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)           | Thumbnail   | Print                               |
| 1   | 15/01/20 12:37  | <b>Adjuster Immediate Advice</b>            | Load HTM  | <input type="checkbox"/>            |
| <b>Photos/Images</b>  |                 |   | 3 per page <input type="checkbox"/> <input checked="" type="checkbox"/>                 |                                     |
| No  | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)           | Thumbnail   | Print                               |
| 1   | 14/01/20 18:16  | <b>Odometer Reading</b>                     | Load JPG  | <input checked="" type="checkbox"/> |
| 2   | 14/01/20 18:16  | <b>Chassis Number</b>                       | Load JPG  | <input checked="" type="checkbox"/> |
| 3   | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 4   | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 5   | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 6   | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 7   | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 8   | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 9   | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 10  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 11  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 12  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 13  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 14  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 15  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 16  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 17  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 18  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 19  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 20  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 21  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 22  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 23  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 24  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 25  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 26  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 27  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |
| 28  | 14/01/20 18:19  | <b>General View</b>                         | Load JPG  | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                |                            | 1 per page   | <input checked="" type="checkbox"/> |
|-------------------------|----------------|----------------------------|--|-------------------------------------|
| No                      | Finalized On   | Longpac Insurance Bhd (HQ) | Thumbnail  | Print                               |
| 29                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 30                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 31                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 32                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 33                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 34                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 35                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 36                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 37                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 38                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 39                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 40                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 41                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 42                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 43                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 44                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 45                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 46                      | 14/01/20 18:19 | General View               |  Load JPG   | <input checked="" type="checkbox"/> |
| 47                      | 14/01/20 18:19 | General View               |  Load JPG  | <input checked="" type="checkbox"/> |
| 48                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 49                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 50                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 51                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 52                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 53                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 54                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 55                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 56                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 57                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 58                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 59                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 60                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 61                      | 14/01/20 18:19 | General View               |  Load JPG | <input checked="" type="checkbox"/> |
| 62                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 63                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 64                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 65                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 66                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 67                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 68                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 69                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 70                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 71                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 72                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 73                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 74                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 75                      | 23/02/20 10:20 | Reinspection Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 76                      | 23/02/20 10:21 | After Repair Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 77                      | 23/02/20 10:21 | After Repair Photo         |  Load JPG | <input checked="" type="checkbox"/> |
| 78                      | 23/02/20 10:21 | After Repair Photo         |  Load JPG | <input checked="" type="checkbox"/> |

| Letters/Correspondences |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
|-------------------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No                      | Finalized On    |                                   | Thumbnail  | Print                               |
|                         |                 | Lonpac Insurance Bhd (HQ)         |            |                                     |
| Documentation           |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
| No                      | Finalized On    | SME Motor Pte Ltd (Kaki Bukit)    | Thumbnail  | Print                               |
| 1                       | 14/01/20 10:28  | E-filed GIA report                |            | Load PDF                            |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 1                       | 15/01/20 11:26  | MARK ESTIMATE                     |            | Load PDF                            |
| 2                       | 26/02/20 14:36  | Supplementary                     |            | Load PDF                            |

### Linked Accident Report Documents

|                    |                |                                | View       | View in Browser                              |
|--------------------|----------------|--------------------------------|------------|--|
| Assessment Reports |                |                                | 1 per page | <input checked="" type="checkbox"/>          |
| No                 | Finalized On   | SME Motor Pte Ltd (Kaki Bukit) | Thumbnail  | Print  |
| 1                  | 10/01/20 16:31 | Accident Statement             |            | Load HTM                                     |
| Photos/Images      |                |                                | 3 per page | <input checked="" type="checkbox"/>          |
| No                 | Finalized On   | SME Motor Pte Ltd (Kaki Bukit) | Thumbnail  | Print  |
| 1                  | 10/01/20 16:31 | Accident Photo                 |            | Load JPG <input checked="" type="checkbox"/> |
| 2                  | 10/01/20 16:31 | Accident Photo                 |            | Load JPG <input checked="" type="checkbox"/> |
| 3                  | 10/01/20 16:31 | Accident Photo                 |            | Load JPG <input checked="" type="checkbox"/> |
| 4                  | 10/01/20 16:31 | Accident Photo                 |            | Load JPG <input checked="" type="checkbox"/> |
| 5                  | 10/01/20 16:31 | Accident Photo                 |            | Load JPG <input checked="" type="checkbox"/> |
| 6                  | 10/01/20 16:31 | Accident Photo                 |            | Load JPG <input checked="" type="checkbox"/> |
| Documentation      |                |                                | 1 per page | <input checked="" type="checkbox"/>          |
| No                 | Finalized On   | SME Motor Pte Ltd (Kaki Bukit) | Thumbnail  | Print  |
| 1                  | 10/01/20 16:31 | Sketch Plan                    |            | Load TIF                                     |
| 2                  | 10/01/20 16:31 | Sketch Plan #2                 |            | Load TIF                                     |
| 3                  | 10/01/20 16:31 | Driving License                |            | Load TIF                                     |
| 4                  | 10/01/20 16:31 | CI                             |            | Load TIF                                     |

### Documents Checklist

| DOCUMENTS CHECKLIST   | Reset | Save | Print |
|---|-------|------|-------|
| There are no document checklists configured.  |       |      |       |
| <b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>  |       |      |       |
|   |       |      |       |
| Show Remarks To: <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer<br><small>Note: Remarks are private unless you show it to other parties.</small> |       |      |       |

## LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse  
Singapore 199555

**Our File No:** CS/LPC20000840/UYF3E2

**Date:** 26/02/2020

#### REFERENCE

Insured/Claimant: RAMO INDUSTRIES PTE LTD Policy No: Z19VP05022517  
Date of Loss: 09/01/2020 Nature of Claim: OD Claim No: 19/20/20/VP05/022900

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY5484D**  
Make & Model: DAIHATSU TERIOS, 1.5 (A) Engine No: DBC0432  
Reg. Date: 13/09/2010 (Man. Year: 2009) Chassis No: MHKG2CJ209K000343  
Colour: Red Odometer: 176913 km  
Engine Capacity: 1495 cc  
Market Value/New Car Price: S\$17,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16  
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm  
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                           | Repairer's      | Adjuster's      | Difference      | Diff %       |
|--|-----------------|-----------------|-----------------|--------------|
| Parts                                    | 6,520.50        | 4,295.25        | 2,225.25        | 34.13        |
| Miscellaneous Items                      | 60.00           | 60.00           | 0.00            | 0.00         |
| Labour                                   | 1,970.00        | 1,240.00        | 730.00          | 37.06        |
| Paintwork Labour                         | 0.00            | 0.00            | 0.00            |              |
| Towing                                   | 0.00            | 0.00            | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b>      | <b>8,550.50</b> | <b>5,595.25</b> | <b>2,955.25</b> | <b>34.56</b> |
| <b>Approved Total (Overridden) (S\$)</b> |                 | <b>3,600.00</b> |                 |              |
| <b>- Excess (S\$)</b>                    | 0.00            | 500.00          | -500.00         |              |
| <b>(S\$)</b>                             | <b>8,550.50</b> | <b>3,100.00</b> | <b>5,450.50</b> | <b>63.74</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>            | <b>598.54</b>   | <b>217.00</b>   | <b>381.54</b>   | <b>63.75</b> |
| <b>Nett Amount (S\$)</b>                 | <b>9,149.04</b> | <b>3,317.00</b> | <b>5,832.04</b> | <b>63.74</b> |

#### INSPECTION

Date of Assignment: 14/01/2020 Present Location: SME Motor Pte Ltd (Kaki Bukit)  
Date Inspected: 14/01/2020 Inspected At: SME Motor Pte Ltd (Kaki Bukit)  
1 Kaki Bukit Ave 6 #02-15, AutoBay @  
Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** YVONNE WONG YIN CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

|   |  |  |
|---|--|--|
| <b>Reference</b>  |  |  |
| <b>Part Source:</b> MRM-SG  | Version: 1.0 (Last Synchronised: 26 Feb 2020)  |  |
| <b>Parts:</b> M1-SUV  | DAIHATSU TERIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)  |  |
| <b>Labour:</b> Repairer's   | (Price-denominated Standard List)  |  |
| <b>Print Code:</b> (Unsubmitted, no print-code for SJY5484D)                                  |  |  |
| <b>Validity:</b>  | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |  |
| <b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *. |  |  |

## Recommended Parts

| No. | Qty | Part No. | Particulars                        | Condition                  | Repairer's | Amount    |
|-----|-----|----------|------------------------------------|----------------------------|------------|-----------|
| 1   | 1   |          | *FRT BONNET<br>(WCP)               | Dented / Buckled           | 700.00 F   | *700.00 F |
| 2   | 1   |          | *FRT BONNET LOCK<br>(WCP)          | Twisted                    | 90.00 F    | *90.00 F  |
| 3   | 1   |          | *FRT GRILLE<br>(WCP)               | Cracked                    | 380.00 F   | *380.00 F |
| 4   | 1   |          | *FRT GRILLE LOGO<br>(WCP)          | Scratched                  | 45.00 F    | *45.00 F  |
| 5   | 4   |          | *FRT GRILLE CLIP<br>(WCP)          | Necessary                  | 10.00 F    | *10.00 F  |
| 6   | 1   |          | *FRT BUMPER<br>(WCP)               | Dented                     | 650.00 F   | *650.00 F |
| 7   | 2   |          | *FRT BUMPER RETAINER<br>(WCP)      | Not Necessary              | 70.00 F    | *- F      |
| 8   | 10  |          | *FRT BUMPER CLIP<br>(WCP)          | Necessary                  | 25.00 F    | *25.00 F  |
| 9   | 1   |          | *FRT BUMPER REINFORCEMENT<br>(WCP) | Bent                       | 300.00 F   | *300.00 F |
| 10  | 1   |          | *FOG LAMP<br>(WCP)                 | O/S Cracked                | 440.00 F   | *220.00 F |
| 11  | 2   |          | *HEADLAMP<br>(WCP)                 | Not Necessary              | 1,200.00 F | *- F      |
| 12  | 1   |          | *HEADLAMP SUPPORT PANEL<br>(WCP)   | Repair                     | 400.00 F   | *- F      |
| 13  | 1   |          | *BRACE PANEL<br>(WCP)              | Twisted                    | 70.00 F    | *70.00 F  |
| 14  | 1   |          | *AIRCON CONDENSER<br>(WCP)         | Punctured / Bent           | 600.00 F   | *600.00 F |
| 15  | 1   |          | *RADIATOR<br>(WCP)                 | Punctured / Holder Cracked | 600.00 F   | *600.00 F |
| 16  | 1   |          | *AIRCON SIDE DEFLECTOR<br>(WCP)    | O/S Torn                   | 90.00 F    | *45.00 F  |

F=Franchise part.

|   |                 |                 |
|---|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                          | <b>5,670.00</b> | <b>3,735.00</b> |
| <b>+ Margin on L,N Items 15.00/15.00% (S\$)</b> | <b>850.50</b>   | <b>560.25</b>   |
| <b>Total Parts (S\$)</b>                        | <b>6,520.50</b> | <b>4,295.25</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

| No                         | Qty | Particulars                     | Repairer's   | Amount       |
|----------------------------|-----|---------------------------------|--------------|--------------|
| <b>Miscellaneous Items</b> |     |                                 |              |              |
| 1                          | 1   | FRT NUMBER PLATE<br>(CRACKED)   | 35.00        | 35.00        |
| 2                          | 1   | RADIATOR COOLANT<br>(NECESSARY) | 25.00        | 25.00        |
| <b>Sub Total (S\$)</b>     |     |                                 | <b>60.00</b> | <b>60.00</b> |

## Recommended Labour

| No                             | Particulars                   | Lab.Type | Repairer's      | Amount          |
|--------------------------------|-------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>            |                               |          |                 |                 |
| 1                              | WIRE CHECKING                 | New      | 20.00           | 20.00           |
| 2                              | REMOVE & REFIX AIRCON AND GAS | New      | 100.00          | 100.00          |
| 3                              | LABOUR CHARGE                 | New      | 700.00          | 520.00          |
| 4                              | SPRAY PAINTING                | New      | 800.00          | 600.00          |
| <b>Supplementary #1</b>        |                               |          |                 |                 |
| <b>Labour Items</b>            |                               |          |                 |                 |
| 5                              | SPRAY FRT LH CHASIS           | New      | 150.00          | 0.00            |
| 6                              | REPAIR FRT LH CHASIS          | New      | 200.00          | 0.00            |
| <b>Gross Labour Cost (S\$)</b> |                               |          | <b>1,970.00</b> | <b>1,240.00</b> |

|   |
|---|
| Report was unsubmitted during this print-out. |
|---|

&lt; END OF ESTIMATES &gt;