

ASS. REC. BY:

REF:

C83/11420000885 / FSD312

Special Instruction:

Signature: RAMASSIGNMENT (Office)From (Person): Wimie Fan

of

AIQDate/Time: 14/01/2020 @ 2:12pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 45E

Insured:

SMJ 5970K

at Workshop m/s

My Car Consultant

Tel:

8866 8832

of

53 ubi Avenue 1. #01-33

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)D.O.A. 11/01/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2:35pm @ 14/1/2020

Person Contacted:

Hui QinVehicle IN OUT

Date/Time	Action/Instruction
	<u>3:45pm (X)</u>
	<u>SKU 45E - NA / NC 20000821 / 24</u>
	<u>SMJ 5970K - NA / NC 2000</u>
<u>17/01/20</u>	<u>@ 09:44 am discussed with Hui Qin, no comment</u>

Pravik

ASSIGNMENT

Veh No: SKU45E Yr Regn: 05/6/2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: mercedes CLA190 cc 1595

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading 107.313 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 173422N244059

Gen. Cond: Good / Fair / Poor / Burnt

Sliding: (noises) Jammed / Leaked / Burnt or

Brake: ☒ Inorder/ ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: NII (S/RIm) / STD A/RIm or

	N/S		O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or 3

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

UBal. 7.3 mm UBal. 7 mm

D.O.A. 11/01/2020 D.O.I. 14/1/2020

Survey held at my car consultant

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	DAR : Completed
	NO. of days : 8 repair days:
	AIG
	MV : \$80824
	PV : \$51816
	NV : \$29000

☐: Prell, Report

Final Report

Days Of Repair: 8 /

Resurvey No. of Trip: /

Survey Fee:	180
-------------	-----

Add Fee: : Site Insp (\$

☐ : Site Insp (\$

Transportation	
----------------	--

☐: Interview (\$

Fructose	
----------	--

Tech. Invs (\$

Others	11
--------	----

☐ : Weekend (*)

[illegible]

TOTAL	191
-------	-----

RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VE...

From: Fan, Winnie-LW
To: Admin A, assignments
Cc: Fong, Andy-SY
Sent: 1/14/2020 2:12:43 PM
Attachments:  SKU45E 11012020.pdf

Hi LKK,

Kindly assist to survey, car in.

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: My Car Consultant <admin@mycar.sg>
Sent: Tuesday, January 14, 2020 10:54 AM
To: AIG SGP, Claims-Survey <AIGSGP_ClaimsSurvey@aig.com>
Subject: [EXTERNAL] OUR REF: SMJ5970K YOUR REF: SKU45E PRE-REPAIR INSPECTION FOR SMJ5970K

This message is from an external sender; be cautious with links and attachments.

WITHOUT PREJUDICE

OUR REF: SKU45E
YOUR REF: SMJ5970K

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SKU45E
ACCIDENT INVOLVING SKU45E AND SMJ5970K

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attention

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd

+65 88668832

Admin@mycar.sg

Mycar.sg

53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Vehicle Details

Vehicle No.:

Vehicle to be Exported:

Intended Deregistration Date:

Vehicle Make:

Vehicle Model:

Primary Colour:

Manufacturing Year:

Engine No.:

Chassis No.:

Maximum Power Output:

Open Market Value:

Original Registration Date:

First Registration Date:

Transfer Count:

Actual ARF Paid:

Intended PARF Rebate Details

PARF Eligibility:

PARF Eligibility Expiry Date:

PARF Rebate Amount:

Intended COE Rebate Details

COE Expiry Date:

COE Category:

COE Period(Years):

QP Paid:

COE Rebate Amount:

Total Rebate Amount:

Company

255C

SKU45E

No

16 Jan 2020

MERCEDES BENZ

CLA180 (R18 BI)

Grey

2015

27091030661141

WDD1173422N214059

90.0 kW (120 bhp)

\$27,462.00

05 Jun 2015

05 Jun 2015

0

\$20,447.00 x 50% = \$10,223.50

Yes

04 Jun 2025

\$15,335.00

04 Jun 2025

A - Car up to 1600cc & 97kW (130bhp)

10

\$67,749.00

\$36,481.00

\$51,816.00

The information contained herein is correct as at 16 Jan 2020

DOA: 11/1/2020 (5y 3m 24d) 63.7m

OK

Depn: \$13300/yearly \$1108.33/monthly

63.7 x \$1108.33 = \$70600.62

\$70600.62 + \$10223.50 = \$80824.12/=

Your pre-loved Volkswagen will be in the best hands.

Discover your exclusive benefits now.

[Find out more](#)



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

View 1 Year's Remains C&C And Carfax For 2 EA



GV Credit

HIN LUNG AUTO
No Fee Car Wash
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Sort by Date Posted

20 results/page

17 vehicles

Mercedes-Benz cla180

Advanced Search

	Model	Price	Depreciation	Reg Price	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz cla180	Any	Any	2015	Any	Any	Any	Available
	Mercedes-Benz CLA-Class CLA180 AMG Line	\$87,500	\$13,190 /yr	13-Aug-2015	1,595 cc	63,644 km	Luxury	Available
Fully Maintained By C&C Since Day 1. Warranty Till Aug 2020. Free 1 Servicing At C&C. Accident Free. No Further Repair Needed. Excellent Condition Very Comfort Drive. Very Spacious And Clean Interior. Owner Consignment Unit. Strictly By Appointment Only.								
Posted: 13-Jan-2020 Tags: 2015 Mercedes-Benz CLA180, 2015 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz CLA180, cla180, Used Mercedes-Benz								
	Mercedes-Benz CLA-Class CLA180	\$83,800	\$13,500 /yr	25-Jun-2015	1,595 cc	59,859 km	Luxury	Available
Here's Your Chance To Own The Sporty Sedan. One Owner Unit. Genuine Mileage. Regularly Maintain And Serviced By C&C. Wear And Tear Replaced. Buy With A Peace Of Mind. Built In 2 Way Car Alarm, Call/WhatsApp Now To Make An Appointment! Full Loan/Trade In...								
Posted: 11-Jan-2020 Tags: 2015 Mercedes-Benz CLA180, 2015 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz CLA180, cla180, Used Mercedes-Benz								
	Mercedes-Benz CLA-Class CLA180	\$86,800	\$13,280 /yr	03-Aug-2015	1,595 cc	58,000 km	Luxury	Available
1 Owner Only! Offer Interest Rate Of Only 2.28%! Super Low Mileage Of Only 58k Done! 100% Accident Free! STA Evaluation Welcome! Comes With 6 Months Free Warranty! High And Flexible Loan Available! High Trade In For Your Used Car! Call Us Now To Make An Appo...								
ST Carz Pte Ltd								
Posted: 17-Jan-2020 Tags: 2015 Mercedes-Benz CLA180, 2015 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz CLA180, cla180, Used Mercedes-Benz								
	Mercedes-Benz CLA-Class CLA180	\$78,800	\$13,670 /yr	22-Jan-2015	1,595 cc	90,000 km	Luxury	Available
1 Owner. Fully Service And Maintained By Agent. Flexible Repayment With In House Financing! Our Vehicle Inspected By Professional Team For Highest Quality! Owning A Car Is So Much Easier With Us! Owning A Car Is So Much Easier With Us! View To Believe! Call Our...								
Car Empire Automobiles Pte Ltd								
Posted: 12-Jan-2020 Tags: 2015 Mercedes-Benz CLA180, 2015 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz CLA180, cla180, Used Mercedes-Benz								
	Mirage Motorwerkz Pte Ltd - Specialty Workshops							
Mirage Motorwerkz Pte Ltd is a one-stop car workshop which to provide friendly, reliable and prices competitive motoring services.								
More info about this shop								
	Mercedes-Benz CLA-Class CLA180 Sunroof	\$92,888	\$13,360 /yr	11-Dec-2015	1,595 cc	35,000 km	Luxury	Available
Dual Electric Memory Seats, Handsfree Auto Parking Assist, Anti Collision System, LED Intelligent, Keyless Push Start, Cruise Control, GPS Navigation System, YouTube, Bluetooth, Spotify, Android/Carplay System, Rare Panoramic Roof, 100% Tip Top Condition, Perfect Inter...								
Posted: 12-Jan-2020 Tags: 2015 Mercedes-Benz CLA180, 2015 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz CLA180, cla180, Used Mercedes-Benz								
	Mercedes-Benz CLA-Class CLA180	\$82,800	\$12,190 /yr	01-Oct-2015	1,595 cc	-	Luxury	Available
Full Agent Maintained. Reasonable Mileage Done. 1 Year Warranty And Servicing Package. Call Now For Viewing.								
Posted: 12-Jan-2020 Tags: 2015 Mercedes-Benz CLA180, 2015 mercedes-benz cla180, Mercedes-Benz CLA180, mercedes-benz cla180, Mercedes-Benz CLA180, cla180, Used Mercedes-Benz								
	Mercedes-Benz CLA-Class A180	\$77,800	\$13,480 /yr	21-Jan-2015	1,595 cc	61,000 km	Luxury	Available

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2020 16:01
Date Of Accident	11/01/2020 10:50
Exact Location Of Accident	CTE TWDS CITY BEFORE BRADDELL RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU45E
Insured/Policyholder	
Name Of Registered Owner	HSC PIPELINE ENGINEERING PTE LTD
Co Reg No	1XXXXX255C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96546461
Alternative Phone No	OFFICE-96546461

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA180 (R18 BI)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080671106-03
Cover Note Number	

Driver

Name of Driver	SHI HONG SHENG (XU HONGSHENG)
NRIC No	SXXXX627F
Date Of Birth	13/10/1986
Occupation	INDOOR
Date Of Driving Pass	12/06/2006
Driving Experience	13 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96546461
Fax Number	
Contact Number	OFFICE-96546461
Email Address	NOEMAIL

Address	BLK 336A ANCHORVALE CRESCENT #15-22
Postcode	541336
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20200111/7020.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMJ5970K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG CHIN KUAY
NRIC/Passport Number	SXXXXX008C
Contact Number	96325873
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLS8531P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAN KUAN HWEE
NRIC/Passport Number SXXXX535C
Contact Number 98367469
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SMK6499T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver ONG BENG LIANG
NRIC/Passport Number SXXXX102Z
Contact Number 96398036
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SHI HONG SHENG (XU HONGSHENG)
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SKU45E
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please record accurately the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any TMC reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Research Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name:
NIC/FIN No.:

Accident Sketch Plan

C16 TOWARDS AYE
BAYLE BRADEN BKT

WITCH PLAN



CAR A : SKU 4512
CAR B : GMS 5940K
CAR C : SLS B531P
CAR D : SMC 6499T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT ATTACHED.

DECLARATION



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel Signature
Name:
RMC/YIN No:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2020 16:01
Date Of Accident	11/01/2020 10:50
Exact Location Of Accident	CTE TWDS CITY BEFORE BRADDELL RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU45E
Insured/Policyholder	
Name Of Registered Owner	HSC PIPELINE ENGINEERING PTE LTD
Co Reg No	1XXXXXX255C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96546461
Alternative Phone No	OFFICE-96546461

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA180 (R18 BI)
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5080671106-03
Cover Note Number	

Driver

Name of Driver	SHI HONG SHENG (XU HONGSHENG)
NRIC No	SXXXX627F
Date Of Birth	13/10/1986
Occupation	INDOOR
Date Of Driving Pass	12/06/2006
Driving Experience	13 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96546461
Fax Number	
Contact Number	OFFICE-96546461
Email Address	NOEMAIL

Address	BLK 336A ANCHORVALE CRESCENT #15-22
Postcode	541336
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20200111/7020.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMJ5970K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG CHIN KUAY
NRIC/Passport Number	SXXXX008C
Contact Number	96325873
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLS8531P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TAN KUAN HWEE
NRIC/Passport Number SXXXX535C
Contact Number 98367469
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SMK6499T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver ONG BENG LIANG
NRIC/Passport Number SXXXX102Z
Contact Number 96398036
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name SHI HONG SHENG (XU HONGSHENG)
Approximate Age
Injuries Sustain BODY
Injured person in which vehicle? SKU45E
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

Accident Sketch Plan

IMPORTANT NOTICE

1. This form is a part of the claims process and is intended to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. All information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material information will constitute an admission of policy liability to regulate policy liability.
4. The policyholder's acceptance of not involving insurance companies is not an admission of policy liability on the part of the insurance company.
5. Any investigation may be referred to the Police for investigations.
6. This form will be stored by the Insurers of the GIA Insured Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by the insured party.
7. By my signature of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available as stated.
8. I hereby consent to the Personal Data Protection Act (PDPA) and I acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/are be disclosed by any of the insurers and/or GIA to their third party service providers or expert (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, prevention and management in present and all future claims;
 - (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature


Name

NRIC/FIN No.

Accident Sketch Plan

Old bridge area
near Broomfield

DATE: 10/10/2014



CAR A : SKW 1512
CAR B : QMS 5910K
CAR C : SL3 B5317
CAR D : SMC 6499T

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT ATTACHED.

DECLARATION



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
HVIC/YIN No:

Police Report



SINGAPORE
POLICE FORCE



1/20200111/7020

1 of 4

Police Station: CR 010201
Traffic Police
10 Dbl Avenue 3 SINGAPORE 408965
Tel No: 604 726500

Report No: 1/20200111/7020

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/01/2020 10:50 Vide Report No: Station Diary No:

Informant's Particulars

Name of Informant: SHI HONG SHI ENO			Address: APT BLK 336A ANCHORVALE CRESCENT #15-22 SINGAPORE 541336	
ID Card No: N/A NRIC No: S8029627F			Contact No: Home/Office	Mobile: 96546461
Nationality: SINGAPORE CITIZEN			Email: shano@hscpe.com	
Sex: Male	Age: 33	Date of Birth: 13/10/1986	Type of Informant: Driver	
Race: Chinese			Language: English	Institution / School Name:
Occupation: Managing director/Chief executive officer			Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury: Others:	Drink Drive: No	Date/Time of Accident: 11/01/2020 10:50	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY				
Weather: Sunny		Road Surface: Dry	Road Speed Limit: 90 Km/h	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No. of Passenger
SKU45E	Car					0
SLS8531P	Car					0
SMJ5970K	Car					0
SMK6499T	Car					0

Police Report



**SINGAPORE
POLICE FORCE**



T/20200111/7020

Police Station: 201/2020
Type: Traffic
10 John Avenue, #01-02/03/04/05 JUBILIS
Tel: 6744 1111

2 of 4

Report No: T/20200111/7020

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SHI HONG SHENG	ID No.	S8629527F
Related Vehicle	SKU45E (Car)	Contact No.	96546461
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	11/01/2020	Date Discharge	11/01/2020
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	TAN KUAN HWEE	ID No.	S1158535C
Related Vehicle	SLS8531P (Car)	Contact No.	98367469
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	NG CHIN KUAY	ID No.	S1795008C
Related Vehicle	SMJ5970K (Car)	Contact No.	96325873
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Police Report



**SINGAPORE
POLICE FORCE**



T/20200111/7020

Police Station (M/Origin)
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No. 65470000

3 of 4

Report No. T/20200111/7020

CONTINUATION OF REPORT

Driver			
Name	ONG BENG LIANG	ID No	S9212102Z
Related Vehicle	SMK6499T (Car)	Contact No.	96398036
Hospital Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details

I, SKU45E, was traveling on the fast lane of CTE towards city. Nearing the braddell exit, the car in front of me, SLS8531P suddenly did a hard brake and I brake immediately as well. Suddenly I felt a very heavy impact from the back of my car and realised that SMJ5970k had drove into the back of my car. The impact from SMJ5970k pushed my car forward and hit SLS8531P. When I alighted from the vehicle, I can see that there is another vehicle in front of SLS8531P. It is SMK6499T.

Police Report



SINGAPORE
POLICE FORCE

Police Station Of Origin:
Traffic Police
10 Upper Avenue 3, SINGAPORE 408865
Tel No. 65477000



T/20200111/7020

4 of 4

Report No. T/20200111/7020

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
YEO GEAK ENG CECILIA
Contact No. 65476404

Authentication Stamp
SP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
11/01/2020 18:53

Classification Of Case:

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	ACQ	QTY
1137	993626	Rear Number Plate	PO	✓	
1138	993627	Rear Number Plate Base	BR	✓	
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp	CRA	✓	
1141	992958	Rear Bumper	BR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	6
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	BIS	✓	2
1149	993045	Rear Bumper Reinforcement	BR	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	BR	✓	
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	BUC	✓	
1160	993339	Rear End Panel Top Garnish	BR	✓	
1161	993333	Rear End Panel Inner Trim	BR	✓	
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	BR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	BUC	✓	
1166	995116	Rear RH Taillamp	SCR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	BUC	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock	LOCK ROUGH	BR	✓
1178	990377	Bootlid Rubber	BR	✓	
1179	990382	Bootlid Hinge	BT	✓	
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SKUASE

NAC	INC	Item	CON	ACQ	QTY
1202	993784	Spare Tyre Board	BR	✓	
1203	994328	Spare Tyre Panel	BUC	✓	
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover	CRA	✓	
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	BR	✓	
1213	993357	Rear Exhaust Chrome Pipe	PO	✓	
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield	BUC	✓	
1216	995223	Rear LH Chassis Member	BUC	✓	R
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	BUC	✓	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim	CRA	✓	
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	CRA	✓	
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender	BUC	✓	R
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim	CRA	✓	
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield	CRA	✓	
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding	NEC	✓	
1247	993955	Rear Windscreen Sealant	NEC	✓	
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: _____

Assessor: _____

MOTOR CAR (Frt)

Front Portion

Vehicle No: **SKV 45F**

NAC	INC	Item	CON	ACQ	QTY
1001	991886	Frt Number Plate	CR		
1002	991887	Frt Number Plate Base	CR		
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	CR		
1005	992341	Frt Bumper Clips	CR		
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement	CR		
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge	CR		
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille	CR		
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler	CR		
1016	991438	Frt Bumper Sensor	CR		
1017	993100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CR		
1022	991328	Frt Grille Emblem	CR		
1023	991799	Frt Grille Chrome Moulding	CR		
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Bree Panel			
1029	995153	Frt LH Headlamp Assy	CR		
1030	991821	Frt RH Headlamp Assy	CR		
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Bell			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	ACQ	QTY
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991320	Frt LH Chassis Member			
1093	991320	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991809	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			
		(LH) Front Reinforcement Bracket			

No of Items:

Accessories:

01/09/06 COPY

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jan 2020 Edit Reg		14 Jan 2020 00:00 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	NG CHIN KUAY, ID: S1796008C								
Main Claimant:	HSC PIPELINE ENGINEERING PTE LTD								
Vehicle Reg. No.:	SKU45E	Date of Loss:	11/01/2020 10:00 - :59 [55 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2146182333SG	Policy/Cover Note No.:	1900045315 (Comprehensive)						
Vehicle Reg. No. (Insured):	SMJ5970K	Policy No. (Claimant):							
		Excess:							
Repairer:	My Car Consultant Pte Ltd (Ubi) S3 Ubi Ave 1, #01-33, Paya Ubi Industrial Park, 408934 Ubi - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by PARASURAM SHANMUGAM] ... [Final Rpt due 23/01/2020]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
AIG_SG (15/01/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKU45E (2146182333SG)
 [SMJ5970K]
 TP
 HSC PIPELINE ENGINEERING PTE LTD
 Jan 11 2020 10:00AM
 [NG CHIN KUAY]
 My Car Consultant Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	15/01/20 10:10	General View													 Load JPG	☒		
2	15/01/20 10:10	General View													 Load JPG	☒		
3	15/01/20 10:10	General View													 Load JPG	☒		
4	15/01/20 10:10	General View													 Load JPG	☒		
5	15/01/20 10:10	General View													 Load JPG	☒		
6	15/01/20 10:10	General View													 Load JPG	☒		
7	15/01/20 10:10	General View													 Load JPG	☒		
8	15/01/20 10:10	General View													 Load JPG	☒		
9	15/01/20 10:10	General View													 Load JPG	☒		
10	15/01/20 10:10	General View													 Load JPG	☒		
11	15/01/20 10:10	General View													 Load JPG	☒		
12	15/01/20 10:10	General View													 Load JPG	☒		
13	15/01/20 10:10	General View													 Load JPG	☒		
14	15/01/20 10:10	General View													 Load JPG	☒		
15	15/01/20 10:10	General View													 Load JPG	☒		
16	15/01/20 10:10	General View													 Load JPG	☒		
17	15/01/20 10:10	General View													 Load JPG	☒		
18	15/01/20 10:10	General View													 Load JPG	☒		
19	15/01/20 10:10	General View													 Load JPG	☒		
20	15/01/20 10:10	General View													 Load JPG	☒		
21	15/01/20 10:10	General View													 Load JPG	☒		
22	15/01/20 10:10	General View													 Load JPG	☒		
23	15/01/20 10:10	General View													 Load JPG	☒		
24	15/01/20 10:10	General View													 Load JPG	☒		
25	15/01/20 10:10	General View													 Load JPG	☒		
26	15/01/20 10:10	General View													 Load JPG	☒		
27	15/01/20 10:10	General View													 Load JPG	☒		
28	15/01/20 10:10	General View													 Load JPG	☒		
29	15/01/20 10:10	General View													 Load JPG	☒		
30	15/01/20 10:10	General View													 Load JPG	☒		
31	15/01/20 10:10	General View													 Load JPG	☒		
32	15/01/20 10:10	General View													 Load JPG	☒		
33	15/01/20 10:10	General View													 Load JPG	☒		
34	15/01/20 10:10	General View													 Load JPG	☒		
35	15/01/20 10:10	General View													 Load JPG	☒		
36	15/01/20 10:10	General View													Load JPG	☒		
37	15/01/20 10:10	General View													Load JPG	☒		

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	15/01/20 10:10	General View		☒
39	15/01/20 10:10	General View		☒
40	15/01/20 10:10	General View		☒
41	15/01/20 10:10	General View		☒
42	15/01/20 10:10	General View		☒
43	15/01/20 10:10	General View		☒
44	15/01/20 10:10	General View		☒
45	15/01/20 10:10	General View		☒
46	15/01/20 10:10	General View		☒
47	15/01/20 10:10	General View		☒
48	15/01/20 10:10	General View		☒
49	15/01/20 10:10	General View		☒
50	15/01/20 10:10	General View		☒
51	15/01/20 10:10	General View		☒
52	15/01/20 10:10	General View		☒
53	15/01/20 10:10	General View		☒
54	15/01/20 10:10	General View		☒
55	15/01/20 10:10	General View		☒
56	15/01/20 10:10	General View		☒
57	15/01/20 10:10	General View		☒
58	15/01/20 10:10	General View		☒
59	15/01/20 10:10	General View		☒
60	15/01/20 10:10	General View		☒
61	15/01/20 10:10	General View		☒
62	15/01/20 10:10	General View		☒
63	15/01/20 10:10	General View		☒
64	15/01/20 10:10	General View		☒
65	15/01/20 10:10	General View		☒
66	15/01/20 10:10	General View		☒
67	15/01/20 10:10	General View		☒
68	15/01/20 10:10	General View		☒
69	15/01/20 10:10	General View		☒
70	15/01/20 10:10	General View		☒
71	15/01/20 10:10	General View		☒
72	15/01/20 10:10	General View		☒
73	15/01/20 10:10	General View		☒
74	15/01/20 10:10	General View		☒
75	15/01/20 10:10	General View		☒
76	15/01/20 10:10	General View		☒
77	15/01/20 10:10	General View		☒
78	15/01/20 10:10	General View		☒
79	22/01/20 09:58	Dismantled Parts		☒
80	22/01/20 09:58	Dismantled Parts		☒
81	22/01/20 09:58	Dismantled Parts		☒
82	22/01/20 09:58	Dismantled Parts		☒
83	22/01/20 09:58	Dismantled Parts		☒
84	22/01/20 09:58	Dismantled Parts		☒
85	22/01/20 09:58	Dismantled Parts		☒
86	22/01/20 09:58	Dismantled Parts		☒
87	22/01/20 09:58	Dismantled Parts		☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	22/01/20 09:58	Dismantled Parts		☒
89	22/01/20 09:58	Dismantled Parts		☒
90	22/01/20 09:58	Dismantled Parts		☒
91	22/01/20 09:58	Dismantled Parts		☒
92	22/01/20 09:58	Dismantled Parts		☒
93	22/01/20 09:58	Dismantled Parts		☒
94	22/01/20 09:58	Dismantled Parts		☒
95	22/01/20 09:58	Dismantled Parts		☒
96	22/01/20 09:58	Dismantled Parts		☒
97	22/01/20 09:58	Dismantled Parts		☒
98	22/01/20 09:58	Dismantled Parts		☒
99	22/01/20 09:58	Dismantled Parts		☒
100	22/01/20 09:58	Dismantled Parts		☒
101	22/01/20 09:58	Dismantled Parts		☒
102	22/01/20 09:58	Dismantled Parts		☒
103	22/01/20 09:58	Dismantled Parts		☒
104	22/01/20 09:58	Dismantled Parts		☒
105	22/01/20 09:58	Dismantled Parts		☒
106	22/01/20 09:58	Dismantled Parts		☒
107	22/01/20 09:58	Dismantled Parts		☒
108	22/01/20 09:58	Dismantled Parts		☒
109	22/01/20 09:58	Dismantled Parts		☒
110	22/01/20 09:58	Dismantled Parts		☒
111	22/01/20 09:58	Dismantled Parts		☒
112	22/01/20 09:58	Dismantled Parts		☒
113	22/01/20 09:58	Dismantled Parts		☒
114	22/01/20 09:58	Dismantled Parts		☒
115	22/01/20 09:58	Dismantled Parts		☒
116	22/01/20 09:58	Dismantled Parts		☒
117	22/01/20 09:58	Dismantled Parts		☒
118	22/01/20 09:58	Dismantled Parts		☒
119	22/01/20 09:58	Dismantled Parts		☒
120	22/01/20 09:58	Dismantled Parts		☒
121	22/01/20 09:58	Dismantled Parts		☒
122	22/01/20 09:58	Dismantled Parts		☒
123	22/01/20 09:58	Dismantled Parts		☒
124	22/01/20 09:58	Dismantled Parts		☒
125	22/01/20 09:58	Dismantled Parts		☒
126	22/01/20 09:58	Dismantled Parts		☒
127	22/01/20 09:58	Dismantled Parts		☒
128	22/01/20 09:58	Dismantled Parts		☒
129	22/01/20 09:58	Dismantled Parts		☒
130	22/01/20 09:58	Dismantled Parts		☒
131	22/01/20 09:58	Dismantled Parts		☒
132	22/01/20 09:58	Dismantled Parts		☒
133	22/01/20 09:58	Dismantled Parts		☒
134	22/01/20 09:58	Dismantled Parts		☒
135	22/01/20 09:58	Dismantled Parts		☒
136	22/01/20 09:58	Dismantled Parts		☒
137	22/01/20 09:58	Dismantled Parts		☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
139	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
140	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
141	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
142	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
143	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
144	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
145	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
146	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
147	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
148	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
149	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
150	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
151	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
152	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
153	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
154	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
155	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
156	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
157	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
158	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
159	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
160	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
161	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
162	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
163	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
164	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
165	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
166	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
167	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
168	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
169	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
170	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
171	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
172	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
173	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
174	22/01/20 09:58	Dismantled Parts	 Load JPG	☒
175	22/01/20 09:58	Dismantled Parts	Load JPG	☒
176	22/01/20 09:58	Dismantled Parts	Load JPG	☒
177	22/01/20 09:58	Dismantled Parts	Load JPG	☒
178	22/01/20 09:58	Dismantled Parts	Load JPG	☒
179	22/01/20 09:58	Dismantled Parts	Load JPG	☒
180	22/01/20 09:58	Dismantled Parts	Load JPG	☒
181	22/01/20 09:58	Dismantled Parts	Load JPG	☒
182	22/01/20 09:58	Dismantled Parts	Load JPG	☒
183	22/01/20 09:58	Dismantled Parts	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 09:59	TP GIA REPORT.pdf	 Load PDF	
2	17/01/20 09:59	POLICE REPORT.pdf	 Load PDF	

Photos/Images			3 per page	☒
No.	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	15/01/20 12:19	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST			Reset	Save	Print
There are no document checklists configured.					

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20000885/FSD3E2

Date: 23/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900045315
Claimant Vehicle No : SKU45E **Insured Vehicle No :** SMJ5970K
 Date of Loss: 11/01/2020 Nature of Claim: TP Claim No: 2146182333SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU45E**
 Make & Model: MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A) Engine No: 27091030661141
 Reg. Date: 05/06/2015 (Man. Year: 2015) Chassis No: WDD1173422N214059
 Colour: Grey Odometer: 107713 km
 Engine Capacity: 1595 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
 Front Left Side: Pirelli 7 mm Rear Left Side: Pirelli 7 mm
 Front Right Side: Pirelli 7 mm Rear Right Side: Pirelli 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 14/01/2020
 Date Inspected: 14/01/2020 Inspected At: My Car Consultant Pte Ltd (Ubi)
 53 Ubi Ave 1, #01-33, Paya Ubi Industrial
 Park
 Singapore 408934

Estimated Period of Repair: 8.0 days

Adjuster: PARASURAM SHANMUGAM

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE	Dented	0.00 F	*- F
2	1		*REAR NUMBER PLATE BASE	Broken	0.00 F	*- F
3	2		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F
4	1		*REAR BUMPER	Broken	0.00 F	*- F
5	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT	Buckled	0.00 F	*- F
8	1		*REAR BUMPER MOULDING	Broken	0.00 F	*- F
9	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
10	1		*REAR END PANEL	Buckled	0.00 F	*- F
11	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
12	1		*REAR END PANEL INNER TRIM	Broken	0.00 F	*- F
13	1		*REAR LH TAILLAMP	Broken	0.00 F	*- F
14	1		*REAR LH TAILLAMP PANEL	Buckled	0.00 F	*- F
15	1		*REAR RH TAILLAMP	Scratched	0.00 F	*- F
16	1		*BOOTLID	Buckled	0.00 F	*- F
17	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
18	1		*BOOTLID LOCK & LOCK CATCH	Bent	0.00 F	*- F
19	1		*BOOTLID RUBBER	Deformed	0.00 F	*- F
20	2		*BOOTLID HINGE	Bent	0.00 F	*- F
21	1		*SPARE TYRE BOARD	Broken	0.00 F	*- F
22	1		*SPARE TYRE PANEL	Buckled	0.00 F	*- F
23	1		*SPARE TYRE COVER	Cracked	0.00 F	*- F
24	1		*REAR EXHAUST PIPE	Bent	0.00 F	*- F
25	1		*REAR EXHAUST CHROME PIPE	Dented	0.00 F	*- F
26	1		*REAR EXHAUST HEAT SHIELD	Buckled	0.00 F	*- F
27	1		*REAR LH CHASSIS MEMBER	Repair	0.00 F	*- F
28	1		*REAR LH FENDER	Buckled	0.00 F	*- F
29	1		*REAR LH FENDER INNER TRIM	Cracked	0.00 F	*- F
30	1		*REAR LH FENDER INNER SHIELD	Cracked	0.00 F	*- F
31	1		*REAR RH FENDER	Repair	0.00 F	*- F
32	1		*REAR RH FENDER INNER TRIM	Cracked	0.00 F	*- F
33	1		*REAR RH FENDER INNER SHIELD	Cracked	0.00 F	*- F
34	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
35	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
36	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
37	1		*FRT NUMBER PLATE BASE	Cracked	0.00 F	*- F
38	1		*FRT BUMPER	Cut	0.00 F	*- F
39	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
40	2		*FRT BUMPER SIDE RETAINER	* Check	0.00 F	*- F
41	1		*FRT BUMPER REINFORCEMENT	Dented	0.00 F	*- F
42	1		*FRT BUMPER SPONGE	Cracked	0.00 F	*- F
43	1		*FRT BUMPER GRILLE	Cracked	0.00 F	*- F
44	1		*FRT BUMPER LOWER SPOILER	Broken	0.00 F	*- F
45	1		*FRT BUMPER SENSOR	Short Circuit	0.00 F	*- F
46	1		*FRT GRILLE	Cracked	0.00 F	*- F
47	1		*FRT GRILLE EMBLEM	Broken	0.00 F	*- F
48	1		*FRT GRILLE CHROME MOULDING	Scratched	0.00 F	*- F
49	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
51	1		*AIR CON CONDENSER	* Check	0.00 F	*- F
52	1		*RADIATOR	* Check	0.00 F	*- F
53	1		*(LH) FRONT REINFORCEMENT BRACKET	Bent	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >