

7/20/2002

ASS. REC. BY:

REF: CS/MSG 20000 886/Kqfzⁿ²

Special Instruction:

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person): Monica Chung Pi zhu of MSG

Date/Time: 4.1.2020 16:30pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJX 8272J

Insured: SJP 9718 B

at Workshop m/s EM Solution N

Tel: 910 1 8302

160 Sh Ming Drive #103-18

Policy No: 29120351

Claim No: 596175

Sum Insured:

Excess:

Make of Veh:

D.O.A. 7.6.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Imp'

Date/Time: 14.1.2020 5:00pm

Person Contacted:

Bernard

H.O.D. Endorsement:

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SJX 8272J - CC4 / A1G / 4017819 / 3m 3xx D.O.A - 17/09/2014

SJP 9718 B - X

15/1/20 @ 11:20am informed Monica Chung, we are pending estimate from repairer.
 17/3/20 @ 1:47pm revised to Monica Chung via Meridian.

18/3 6/1 Pm 81 Fed anal & confirm Cred to 10412.30, 86%.

ASS. REC. BY:

REF:

MSG/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / DWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJX8272J Yr Regn: 07, 10Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mer E200 C61 1798Colour: M. Gold A/C: Insured / Std / NI / NASp. Reading: 75696 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W00 2120482A161463Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD / Rlm or

Tyre Size: F: _____

R: 225/55R6BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal. 7 mmL/Bal. 7 mmD.O.A. 7/6/19

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 24/2/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Est not ready

RECEIVED 19 MAR 2020

18/3/2020

Date/Time, File Pass to?

1) 18/3/2020

Date/Time, File Return to?

2) _____

☐ : Prel. Report☐ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 2

Survey Fee:

Transportation: 200
S + RS. SI 11

Fees

Others

TOTAL

211

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format:

Lump Sum / I.B.A. (\$)

Mer
1700

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 17 Mar 2020

Preliminary Advice

Insured Vehicle No	: SJP9718B	Accident Date	: 07/06/2019
TP Vehicle No	: SJX8272J	Assignment Date	: 14/01/2020
Make	: MERCEDES-BENZ E200	Est. Duration of Repair	: 2.00
Date of Inspection	: 24/02/2020		
Inspection At	: E M SOLUTION PTE LTD (HQ) 160 SIN MING DRIVE., #03-18, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,112.30
Revised Amount	:S\$	2,185.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,185.40

Lump Sum Repair	:S\$	1,700.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2019		14 Jan 2020 16:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHEE YOONG KONG, ID: S7229929I, Tel: +6597426338, Email: cheechris@gmail.com			
Main Claimant:	ONG GAIK CHOO, ID: S2502074Z			
Vehicle Reg. No.:	SJX8272J	Date of Loss:	07/06/2019 17:00 - :59 [106 Months and 23 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 596175	Policy/Cover Note No.:	29120351 (Third Party Only) Coverage: 20/04/2019 - 19/04/2020	
Vehicle Reg. No. (Insured):	SJP9718B	Policy No. (Claimant):		
		Excess:		
Repairer:	E M Solution Pte Ltd (HQ) 160 Sin Ming Drive,, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pel Zhen - 6594 2552]			
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 15/01/2020]			
Driver/Custodian (Insured):	CHEE YOONG KONG (46 / Male) , NRIC: S7229929I, Tel: +6597426338 Email: cheechris@gmail.com			
Adj Asg. Remarks:	on WP. Liab: clear. Agree on SJE. Assign: Kenneth Kong from LKK Auto Consultants Pte Ltd. Contact: Mr Bernard @ 6456 0226 / 9101 8302.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 25 February 2020 11:20 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SJX 8272J (YOUR REF: 596175)

This mail is associated with :

***SJX8272J (596175)**

[SJP9718B]

TP

ONG GAIK CHOO

Jun 7 2019 5:00PM

[CHEE YOONG KONG]

E M Solution Pte Ltd

Dear Monica,

Please be informed that we have inspected the vehicle SJX 8272J on 24/02/2020.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	074Z
Vehicle Details	
Vehicle No.:	SJX8272J
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Mar 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 200CGI
Primary Colour:	Beige
Manufacturing Year:	2009
Engine No.:	27186030031561
Chassis No.:	WDD2120482A161463
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$51,195.00
Original Registration Date:	15 Jul 2010
First Registration Date:	15 Jul 2010
Transfer Count:	0
Actual ARF Paid:	\$51,195.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Jul 2020
PARF Rebate Amount:	\$25,597.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$35,909.00
COE Rebate Amount:	\$1,162.00
Total Rebate Amount:	\$26,759.00

The information contained herein is correct as at 17 Mar 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/06/2019 13:35
Date Of Accident	07/06/2019 17:30
Exact Location Of Accident	T-JCT OF SINARAN DR & MOULMEIN RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX8272J
Insured/Policyholder	
Name Of Registered Owner	ONG GAIK CHOO
NRIC No	SXXXX074Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97878948
Alternative Phone No	OFFICE-97878948

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100217789-08
Cover Note Number	

Driver

Name of Driver	ONG GAIK CHOO
NRIC No	SXXXX074Z
Date Of Birth	16/06/1959
Occupation	INDOOR
Date Of Driving Pass	21/06/1985
Driving Experience	33 YEARS AND 11 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97878948
Fax Number	
Contact Number	OFFICE-97878948
Email Address	NOEMAIL

Address	63A PASIR PANJANG HILL
Postcode	97878948
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TELOK BLANGAH NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 51 TELOK BLANGAH DRIVE , POSTCODE: 100051 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2729999 - FAX NO: 63772526
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER POLICE REPORT NO: T/20190608/2087. TELOK BLANGAH NPP.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJP9718B
Vehicle Make/Model/Colour	HONDA SILVER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHEE YOONG KONG (XU RONGGUANG)
NRIC/Passport Number	SXXXX929I
Contact Number	97426338
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	ONG GAIK CHOO
Approximate Age	
Injuries Sustain	NECK
Injured person in which vehicle?	SJX8272J
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	63A PASIR PANJANG HILL
Postcode	118879

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 10 06 19 11 20AM

Driver's Signature
(If driver is not the policyholder)
Date & Time

Vincent Seah
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4401 HP: 8132 0965 Fax: 6872 1272
Email: vincent.seah@cyclecarriage.com.sg
Reporting Centre
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


REFER POLICE REPORT

DECLARATION

We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)



Policyholder's Signature

Date & Time: 10/06/19 11:20AM

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Person

Name:

NRIC/FIN No.:

Vincent Seah
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Centre
UFD: 6771 4401 HP: 8112 0662 Fax: 6872 1272
Email: vincent.seah@cyclenation.com.sg

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190608/2087

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

1 of 3

Report No. T/20190608/2087

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 08/06/2019 16:13		Vide Report No.: E/20190607/0115		Station Diary No.: 11	
Informant's Particulars					
Name of Informant: ONG GAIK CHOO			Address: 63A PASIR PANJANG HILL SINGAPORE 118879		
ID Type / ID No.: NRIC NO / S2502074Z			Contact No.: Home/Office: Mobile: 97349698		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Female	Age: 59	Date of Birth: 16/06/1959	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Retiree			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 07/06/2019 17:30	Type of Location: T-Junction
Location: Junction of Road 1 and Road 2 SINARAN DRIVE MOULMEIN ROAD T-Junction of Sinaran Drive and Moulmein Road				
Weather: Clear		Road Surface: Dry	Road Speed Limit: 50 Km/h	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SJP9718B	Car	HONDA		Silver	Slightly Damaged	0
SJX8272J	Car	MERCEDES BENZ	E 200CGI	Beige	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJX8272J	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100217789-08	15/07/2018	14/07/2019

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190608/2087

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

2 of 3

Report No. T/20190608/2087

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHEE YOONG KONG(XU RONGGUANG)	ID No.	S7229929I
Related Vehicle	SJP9718B (Car)	Contact No.	97426338
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	ONG GAIK CHOO	ID No.	S2502074Z
Related Vehicle	SJX8272J (Car)	Contact No.	97349698
Hospital/Clinic	TAN TOCK SENG HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	07/06/2019	Date Discharge	07/06/2019
No. of Days granted Medical Leave	04	Degree of Injury	Slight

Brief Details.

I was driving along Sinaran Drive towards Moulmein Road when I was at a T-Junction. During that point of time, I stopped as I was checking for on coming traffic on the right. As there were some high speed on coming vehicles, from the right, I remained stationary. While I was waiting, I felt a bump from the back of my car and my head and neck was jolted strongly back and forth. I felt pain on the back of my neck and I did not know what to do so I called my husband. I came out of my car and the other driver approached me and told me that it was his fault. Shortly after, the police and ambulance arrived. I told the paramedics that I felt pain on my neck and was immediately conveyed to Tan Tock Seng Hospital. I suffered pain on the back of my neck and was given 4 days MC. The other driver did not suffer any visible injury. My car sustained scratches and dent on the rear. The other driver's car had damaged bumper on the front left of his vehicle.

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190608/2087

Police Station Of Origin:
Telok Blangah NPP
51 Telok Blangah Drive #01-116
SINGAPORE 100055
Tel No: 1800-2729999

3 of 3

Report No. T/20190608/2087

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 3 LOW KONG WEE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

08/06/2019 16:13

Officer In Charge Of Case:

TP / GIT /

SI MOHAMMAD ABDILLAH BIN PALIL

Contact No.: 65476246

Classification Of Case:

SN 045

Authentication Stamp

NP168



Singapore Police Force

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax: 64584500

Registration No: 201016308K

24.02.2020

Ong Gaik Choo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

NOT Notified
11 Day & 1700
Resurvey After Pay
2 days

REPAIR ESTIMATE FOR MERCEDES E200 - SJX 8272 J

1 pc	boot lid		R	1,753.00	X
1 pc	boot logo		nn	64.00	X
1 pc	boot rubber		nn	216.00	X
1 pc	boot lock		nn	167.00	X
1 pc	boot "E 200" badge		nn	61.00	X
1 pc	boot "CGI" badge		nn	66.00	X
1 pc	boot chrome moulding		nn	163.00	X
2 pcs	tail lamps	628.00	nn	1,256.00	X
1 pc	rear end panel		nn	865.00	X
1 pc	rear end panel top garnish		nn	182.00	X
1 pc	rear bumper	1314	nn/cm	1,490.00	✓
1 pc	rear bumper center chrome moulding	182	nn	196.00	—
2 pcs	rear bumper side chrome mouldings	130	nn	304.00	—
1 pc	rear bumper tow hood cover		nn	98.00	X
1 pc	rear bumper reinforcement		nn	531.00	X
2 pcs	rear bumper side retainers	41.00	nn	82.00	X
2 pcs	rear bumper lower brackets	33.00	nn	66.00	X
1 pc	rear bumper center bracket		nn	32.00	X
4 pcs	rear parking sensors	382.00	nn	1,528.00	X
1 pc	rear exhaust silencer		nn	1,487.00	X
1 pc	rear exhaust chrome pipe		nn	102.00	X
2 pcs	rear exhaust mountings	44.00	nn	88.00	X
				10,797.00	
Less 10%				1,079.70	
				9,717.30	

1 set	rear bumper clips	nn	45.00	SN	✓
1 set	rear end panel garnish clips	nn	30.00	SN	X
1 pc	rear number plate	nn	70.00	SN	X
1)	Check electrical wirings.	nn	60.00	X	
2)	Renew rear parking sensors	nn	80.00	601	
3)	Remove and refit rear exhaust silencer.	nn	80.00	X	
4)	Repair accident damages and renew above parts.		980.00	2501	
5)	Spray paint on affected portions.		980.00	2501	
6)	Rust proofing on affected portions.	nn	70.00	X	
				\$ 12,112.30	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20000886/KQF3N2
Date: 20/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29120351

Claimant Vehicle No: SJX8272J

Insured Vehicle No: SJP9718B

Date of Loss: 07/06/2019

Nature of Claim: TP Claim No: 596175

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJX8272J**
Make & Model: MERCEDES-BENZ E200, 1.8 CGI (A)
Reg. Date: 15/07/2010 (Man. Year: 2009)
Colour: Metallic Gold
Engine Capacity: 1796 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

Engine No: 27186030031561
Chassis No: WDD2120482A161463
Odometer: 75696 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R16 Rear Tyre Size: 225/55 R16
Front Left Side: Michelin 7 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 7 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,862.30	1,625.40	8,236.90	83.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	560.00	1,690.00	75.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,112.30	2,185.40	9,926.90	81.96
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	12,112.30	1,700.00	10,412.30	85.96
+ GST 7.00/7.00% (S\$)	847.86	119.00	728.86	85.96
Nett Amount (S\$)	12,960.16	1,819.00	11,141.16	85.96

INSPECTION

Date of Assignment: 14/01/2020

Date Inspected: 24/02/2020 Inspected At:

E M Solution Pte Ltd (HQ)
160 Sin Ming Drive., #03-18, Sin Ming Autocity
Singapore 575722

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 20 Mar 2020)

Parts: 143 MERCEDES-BENZ E200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJX8272J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Repair	1,753.00 FL	*- FL
2	1		*BOOT LOGO	Not Necessary	64.00 FL	*- FL
3	1		*BOOT RUBBER	Serviceable	216.00 FL	*- FL
4	1		*BOOT LOCK	Repair	167.00 FL	*- FL
5	1		*BOOT E 200 BADGE	Not Necessary	61.00 FL	*- FL
6	1		*BOOT CGI BADGE	Not Necessary	66.00 FL	*- FL
7	1		*BOOT CHROME MOULDING	Serviceable	163.00 FL	*- FL
8	2		*TAIL LAMPS	Serviceable	1,256.00 FL	*- FL
9	1		*REAR END PANEL	Repair	865.00 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	182.00 FL	*- FL
11	1		*REAR BUMPER	Buckled / Cracked	1,490.00 FL	*1,314.00 FL
12	1		*REAR BUMPER CENTER CHROME MOULDING	Necessary	196.00 FL	*182.00 FL
13	2		*REAR BUMPER SIDE CHROME MOULDINGS	Necessary	304.00 FL	*260.00 FL
14	1		*REAR BUMPER TOW HOOD COVER	Serviceable	98.00 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Repair	531.00 FL	*- FL
16	2		*REAR BUMPER SIDE RETAINERS	Serviceable	82.00 FL	*- FL
17	2		*REAR BUMPER LOWER BRACKETS	Serviceable	66.00 FL	*- FL
18	1		*REAR BUMPER CENTER BRACKET	Serviceable	32.00 FL	*- FL
19	4		*REAR PARKING SENSORS	Serviceable	1,528.00 FL	*- FL
20	1		*REAR EXHAUST SILENCER	Repair	1,487.00 FL	*- FL
21	1		*REAR EXHAUST CHROME PIPE	Serviceable	102.00 FL	*- FL
22	2		*REAR EXHAUST MOUNTINGS	Serviceable	88.00 FL	*- FL
23	1		*SET REAR BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
24	1		*SET REAR END PANEL GARNISH CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*REAR NUMBER PLATE	Serviceable	70.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$) **10,942.00** **1,801.00**

- List Item Discount on L Items 10.00/10.00% (\$\$) **1,079.70** **175.60**

Total Parts (\$\$) **9,862.30** **1,625.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ELECTRICAL WIRINGS	New	60.00	0.00
2	RENEW REAR PARKING SENSORS	New	80.00	60.00
3	REMOVE AND REFIT REAR EXHAUST SILENCER	New	80.00	0.00
4	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS	New	980.00	250.00
5	SPRAY PAINT ON AFFECTED PORTIONS	New	980.00	250.00
6	RUST PROOFING ON AFFECTED PORTIONS	New	70.00	0.00
Gross Labour Cost (\$\$)			2,250.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >