



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/01/2020

User ID : KimBock

### Section A - Accident Details

Registration Number	SMB1521S
Case Reference Number	BUS/01/20/5017
Registration Date	10/29/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Keng Kian Tiong
Type of Accident	Side Swipe
Accident Date and Time	1/11/2020 4:00 PM
Accident Reported Date and Time	1/11/2020 5:45 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1521S-LEFT FRONT PORTION YP7603J ( TP ) INSURED WITH NTUC
Prepared Date and Time	1/14/2020 9:29 AM
Chassis Number	WMAA22ZZ4E7002315
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,120.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$2,422.40	\$0.00
Total Other Cost	\$0.00	\$0.00
<b>TOTAL COST</b>	<b>\$5,250.40</b>	<b>\$0.00</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	4.0	
Prepared / Adjusted By	Kim Bock Sim	
ARC / Surveyor Sign Off Date		
Signature	x	x
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/01/2020

User ID : KimBock

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT LH PORTION	\$2,120.00	1590
Total Labour	\$2,120.00	

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$708.00	538
Total Spray Painting & Panel Beating	\$708.00	

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010159	BODY LH	4001M01-ACCE466	MIRROR,VIEW:FRONT,L H,FOR MAN	1.00	\$1,903.30	0.00	\$1,903.30	Replace	✓ CRU. Zmm
			RUBBER PROFILE	1.00	\$150.00	0.00	\$150.00	Replace	✓ CRU.
6010153	Body	F01001-CW264	COVER,HEADLAMP:FRT LH,FOR MAN A22 BUS	1.00	\$974.70	0.00	\$974.70	Replace	✓ CRU.
Total					\$3,028.00		\$3,028.00		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 3 days.

5856

Lump Sum Repair.  
After paint photo

Sun Pin (LKK)  
14/01/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: