

ASS. REC. BY:

REF: CS3/INC 20000905/Hqd3⁵²

Special Instruction:

Surveyor: Hack Ann

ASSIGNMENT (Office)

From (Person): Theresa Vimalanof INCDate/Time: 14/01/2020 @ 9:50am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJB 7262K

Insured:

SKJ 139 B

at Workshop m/s

My car consultant

Tel:

8866 8832

of

53 ubi Avenue 1 # 01-33

Policy No:

Claim No:

MT/1079811-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

12/1/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9:52am @ 14/01/2020

Person Contacted:

Hui QinVehicle: IN/OUT

Date/Time	Action/Instruction	Estimate/ (X)
	SJB 7262 K - NA/INC 20000813/h4	D.O.A: 12/1/2020
	SKJ 139 B - NA/INC 20000813/h4	D.O.A: 12/01/2020
6/2/2020 @ 10:43am	confirmed with Hui Qin No estimate for this case.	
	Dismantle recovery: 15/01/20	
	after paint = 16/01/20.	

PRS

ASSIGNMENT

From:

Date:

14/01/2020

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SJB 7262K

at Workshop n/s

My Car Consultant

of

53 ubi Ave 1 #01-33

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1 up

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SJB 7262K Yr Regn: 03/04/1997

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

PE460T 508 ALH4RLE cc 1560

Colour:

Grey

AC: Insured / Std / NI / NA

Sp. Reading

065411km

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

UF3PD5H7T 62040701

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40/R18

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

57 mm

R/Bal.

5 mm

L/Bal.

57 mm

L/Bal.

5 mm

D.O.A.

12/1/20

D.O.I.

14/1/20 @ 12.37pm

Survey held at

My car

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/2/20	Range → party range not Repair days → 3 day submit PRS. * SJB 7262K PRS case
	mv - 65000 pv - 47261 nv - 17700
	RECEIVED 10 FEB 2020
	* L/K views system now open Punam, party upheld plan.

Date/Time, File Pass to?



: Preli. Report

1) 10/2/20 turn in



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S+PS: \$

Photos

Others

TOTAL

Arid Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Report Form(s):

PRS

Lump Sum / LBJ: (\$)

Nivitha (LKK Auto)

From: Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Sent: Tuesday, 14 January 2020 5:05 PM
To: Nivitha (LKK Auto); 'assignments'
Cc: 'SUR'
Subject: RE: TP CASES FARMED OUT TO LKK ON 14/1/2020

OIC details

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at income.com.sg/careers

in with you

From: Theresa Vimala D/O Balagangadharan [<mailto:thrsvim.bala@income.com.sg>]
Sent: Tuesday, 14 January 2020 9:50 AM
To: 'assignments' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Theresa Vimala D/O Balagangadharan <thrsvim.bala@income.com.sg>
Subject: TP CASES FARMED OUT TO LKK ON 14/1/2020

Hi LKK

Please assist to survey these vehicles. Thank you.

SN	OIC	Claim No.	Survey Date	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Iared	MT/1079851-002	14/1/2020	SMD9738X	KAH MOTOR CO SDN BHD	15 UBI ROAD 4 SINGAPORE 408610	You Po Soon / 9678 6493		SLZ6733a	12/1/2020	
2	AIRWAN	MT/1075799-002	14/1/2020	SGP3076U	MY CAR CONSULTANT PTE LTD	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Huiqin / 88668832		SLU1768J	14/12	Previously farmed out to LKK
3	HUEY HUEY	MT/1079811-001	14/1/2020	SJB7262K	MY CAR CONSULTANT PTE LTD	53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934	Huiqin / 88668832		SK1139B	12/1/20	
4	CHESTER	MT/1076170-001	14/1/2020	SJC1173T	PROGRESSIVE CAR CARE PTE LTD	BLK 3022A #01- 45/46 UBI ROAD 1 SINGAPORE 408716	Pei Wen NG / 6741 5336	14:00- 16:00	FBI8326G	16/12/19	

Theresa Vimala
Senior Administrator
Operations, Motor & Personal Lines (PL)
T +65 6430 7898
www.income.com.sg

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/01/2020 11:50
Date Of Accident	12/01/2020 04:15
Exact Location Of Accident	RIVER VALLEY RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB7262K
Insured/Policyholder	
Name Of Registered Owner	TEW CHANG YUAN IVAN
NRIC No	SXXXX039I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81210341
Alternative Phone No	OFFICE-81210341

Vehicle Particulars

Manufacturer	PEUGEOT
Model	508 ALLURE 1.6 BLUEHDI EAT6
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00003027-01
Cover Note Number	

Driver

Name of Driver	TEW CHANG YUAN, IVAN (ZHAO ZHANGYAN, IVAN)
NRIC No	SXXXX039I
Date Of Birth	16/08/1983
Occupation	INDOOR
Date Of Driving Pass	09/03/2012
Driving Experience	7 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81210341
Fax Number	
Contact Number	OFFICE-81210341
Email Address	NOEMAIL

Address	31 PUNGGOL FIELD #16-03
Postcode	828816
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20200112/7009.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKJ139B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HONDA STREAM
NRIC/Passport Number	
Contact Number	85009674
Address	
Postcode	

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TEW CHANG YUAN, IVAN (ZHAO ZHANGYAN, IVAN)

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SJB7262K

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(if driver is not the policyholder)
Date & Time:




Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:

GPRA Form 10/2018 ver. 1.0

Accident Sketch Plan

SKETCH PLAN



A) 52B-00K
B) SK 1398

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT:

DECLARATION

(We declare the foregoing particulars are true to the best of our knowledge)

Police Officer's Signature
Date & Time:

Witness: (if applicable)

Driver's Signature
(If driver is not the police officer)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	039I
Vehicle Details	
Vehicle No.:	SJB7262K
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2020
Vehicle Make:	PEUGEOT
Vehicle Model:	508 ALLURE 1.6 BLUEHDI EAT6
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	10JBHX3018999
Chassis No.:	VF38DBHZTGL040701
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$26,539.00
Original Registration Date:	03 Apr 2017
First Registration Date:	03 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$14,155.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Apr 2027
PARF Rebate Amount:	\$10,616.00
Intended COE Rebate Details	
COE Expiry Date:	02 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,789.00
COE Rebate Amount:	\$36,645.00
Total Rebate Amount:	\$47,261.00

The information contained herein is correct as at 15 Jan 2020

OK



ANNOUNCING Supreme Cars Pte Ltd as sgCarMart Premium Dealer 2020



Peugeot 508

Price Range

Depreciation

2017

Vehicle Type



Home » Used Cars » Vantage Pre-Owned » Peugeot 508 Diesel 1.6A BlueHDi EAT6 Allure

Peugeot 508 Diesel 1.6A BlueHDi EAT6 Allure

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

VANTAGE PRE-OWNED

Price	\$74,800	Fuel Type	Diesel (Euro 5 Engine and Above)
Depreciation	\$8,990 /yr View models with similar depre	Reg Date	25-Jul-2017 (7yrs 6mths 9days COE left)
Mileage	51,605 km (20.8k /yr)	Manufactured	2017
Road Tax	\$1,244 /yr	Transmission	Auto
Dereg Value	\$43,846 as of today (change)	OMV	\$26,647
COE	\$44,002	ARF	\$14,306
Engine Cap	1,560 cc	Power	88.0 kW (118 bhp)
Curb Weight	1,445 kg	No. of Owners	1
Type of Vehicle	Mid-Sized Sedan		

Features

Powerful And Fuel Efficient 4 Cylinder 16 Valve DOHC Turbocharged Engine Producing 118Bhp And 300Nm Torque Through A 6 Speed Automatic Transmission. View specs of the Peugeot 508 (2015-2017)

Accessories

Cruise Control, Speed Limiter, Factory Electronic Seats, 3M UV Film, Multi Zone Climatic Aircon, Reverse Camera And Sensors, In Car Recording Camera.

Description

1 Owner, Pristine Condition, Well Suited For City Driving. Own With A Peace Of Mind From Vantage Pre-Owned, A Member Of The Sime Darby Group. Complete With Our 72 Point Technical Inspection. Trade Ins Are Welcomed. Viewing By Appointment Only.

Category

PARF Car

Status

Available

Resource

Compare

tion



Location Map

Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

Vantage Pre-Owned

30 vehicles for sale. 39 sold in past 3 mths

305 Alexandra Road #02-01

Vantage Automotive Centre

Tel: 63762277

Search cars nearby

Louis Chan

Valerie Tan

96965133

98161147

DOA = 12/1/20

MU - 65000

PV - 47261

NV - 17700

Arbitration → 7yr 4mths

MPV → 8000yr

8000 + 44 = 666

56000 + 2664 + 7077

= 65741



PRE-REPAIR INSPECTION REPORT			
NTUC INCOME INSURANCE CO-OPERATIVE LTD 73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556 ATTN: ENG HUEY HUEY		Ref: CS3/INC20000905/Hqd3s2 Date: 11-02-2020  Code: INC	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKJ 139B	Veh. Inspected	SJB 7262K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1079811-001	Excess (\$)	0.00
Assign From	THERESA VIMALA	Assign Date	14/01/2020
2. Vehicle Particulars & Condition			
Make & Model	PEUGEOT 508 ALLURE	c.c	1560
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VF38DBH2TGL040701	Colour	GREY
Odometer	065411 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R18	CONTINENTAL	5 mm
L/H Front Tyre	245/40 R18	CONTINENTAL	5 mm
R/H Rear Tyre	245/40 R18	CONTINENTAL	5 mm
L/H Rear Tyre	245/40 R18	CONTINENTAL	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information			
Accident Date	12/01/2020	Inspect Date / Time	14/01/2020 (12:37 PM)
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/INC20000905/Hqd3s2

Inspected By



LEE HOCK ANN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.