

22/03/2002

A.S.S. REC. BY:

REF: CS/SPR-20000912/Gvf322

Special Instruction:

Survivor: Guo QiangASSIGNMENT (Office)From (Person): Hafzu Farhan Rahmat of SPFDate/Time: 15. Jan. 2020 9.50a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SSH 1419JInsured: QX 1022Cat Workshop m/s Ah Kim MotorTel: 64831244of 10 AMK Ind PK 2A #01-09

Policy No: _____

Claim No: AEMB / 105 / 009 / 2019 / 121

Sum Insured: _____

Excess: _____

Make of Veh: _____

(Client's Record)

D.O.A. 31.12.2019

CA / REV / REP. / REV 24 HRS

"up"

H.O.D. Endorsement: _____

Date/Time: 15.1.2020 9.58a.mPerson Contacted: ZilaVehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SSH 1419J - X
	QX 1022C - X
6/2/20	@4.53pm Zila said pending liability
27/2/20	@4.01pm Zila said vehicle has not send in for repair, pending liability
28/2/20	Submit preli report

Do Not Finalise

Cal.

REF:

SPF

ASSIGNMENT

(2028)

From:

Date:

Veh No:

SJH1419J

rr Regn:

28 Jul 2008

Estimated Cost:

Type: ☒ M/Cas / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Toyota Allion 1.5 c.c 1496

at Workshop m/s

Ah Lim Motor

Colour

white

A/C:

Insured / Std / NI / NA

of

Sp. Reading

130456

T/Radio:

Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

NZ T260 3030 248

Claims No.

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD / ☒ A/Rim or

(Policy Condition)

Tyre Size:

F:

195/60 R15

R:

u

Remark: The veh had commenced its

repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

2

days

Res.:

Yes or No

D.O.A.

w/s

D.O.I.

15-01-20

Lum Sum:

%

3 Val.:

Yes or No

Survey held at

3pm

CA / REV / REP. / 24 HRS

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

frt N/S

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$350 - \$500 (upper range) (EST)

RECEIVED 28 FEB 2020

Do Not Finalise

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 28/2 - typist

Days Of Repair:

Resurvey No. of Trip: 2

Survey Fee:

220

Transportation:

\$ + R\$ \$

Phone:

Other:

TOTAL

220

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Mech. Insp (\$

Report Form:

Lump Sum / M.B.C.

Summer Lee (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Wednesday, 15 January, 2020 9:50 AM
To: Admin-D (LKKAuto); sur@lkkauto.com; assignments
Cc: Cui Fen ENG (SPF); Frankie THAY (SPF)
Subject: Pre-Repair Survey of SJH1419J DOA: 31/12/2019 (vs QX1022C)

Your reference: SJH 1419J

Our reference: AEMD/105/009/2019/121

Hi,

Kindly conduct pre-repair survey of **SJH 1419J** at:

Ah Lim Motor Company
10 Ang Mo Kio Ind Pk 2A
#01-09 AMK AUTOPOINT
Singapore 568047

Contact person: Zila
Contact No: 6483 1244

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat
Assistant Logistics Support Officer
Logistics Support and Services Division
Tel: 6842 8429
Police Logistics Department | Singapore Police Force



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

.> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	373I
Vehicle No.:	SJH1419J
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1N2D138876
Chassis No.:	NZT2603030248
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,863.00
Original Registration Date:	28 Jul 2008
First Registration Date:	28 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$15,863.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	27 Jul 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$37,165.00
COE Rebate Amount:	\$31,710.00
Total Rebate Amount:	\$31,710.00

The information contained herein is correct as at 15 Jan 2020

OK

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	373I

Vehicle Details

Vehicle No.:	SJH1419J
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	ALLION 1.5 A
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	1N2D138876
Chassis No.:	NZT2603030248
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$15,863.00
Original Registration Date:	28 Jul 2008
First Registration Date:	28 Jul 2008
Transfer Count:	1
Actual ARF Paid:	\$15,863.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	27 Jul 2028
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$37,165.00
COE Rebate Amount:	\$31,840.00
Total Rebate Amount:	\$31,840.00

The information contained herein is correct as at 02 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/01/2020 14:39
Date Of Accident	31/12/2019 21:15
Exact Location Of Accident	BAIN STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJH1419J
Insured/Policyholder	
Name Of Registered Owner	PANG CHEE KEONG
NRIC No	SXXXX373I
Email Address	PCKEONG338@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97964208
Alternative Phone No	OTHERS-97964208

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALLION-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P10030710R02
Cover Note Number	28/07/2019 - 27/07/2020

Driver

Name of Driver	PANG CHEE KEONG
NRIC No	SXXXX373I
Date Of Birth	24/10/1969
Occupation	INDOOR
Date Of Driving Pass	18/08/1988
Driving Experience	31 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97964208
Fax Number	
Contact Number	OTHERS-97964208
EMail Address	PCKEONG338@YAHOO.COM.SG

Address	630 JURONG WEST ST 65 #05-416
Postcode	640630
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : KAREN GOH SIEW WAH GENDER: : FEMALE
Passenger 2	NAME: : SHERENE PANG YAN XUAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	JURONG WEST NPC
Police Station Address	ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE POLICE REPORT & SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX1022C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	CANDICE NG CHEE CHUEN

NRIC/Passport Number	SXXXX029E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

2 JAN 2020, 12.15 pm

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

Date of accident: 31 Dec 2019 Time: 9.15 pm Location: Bain Street
 My Vehicle A: SJH1419J Vehicle B: QX1022C Vehicle C: IVA-
 SKETCH PLAN

Refer to the police Report.
 T/20200101/2046

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police Report
 T/20200101/2046

☒ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop:

Email address:

& myself:

Email address: pckeong338@yahoo.com.sg

*Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

2 Jan 2020, 12.15pm

Driver's Signature

(If driver is not the policyholder)


Date & Time:

Reporting Centre/Insurer's Signature

Name:

NRIC/FIN No.:





31 Dec 2019 (Tue)

about 9.15 pm.



**SINGAPORE
POLICE FORCE**



T/20200101/2046

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3

Report No. T/20200101/2046

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 01/01/2020 13:43	Vide Report No.:	Station Diary No.: 75
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: PANG CHEE KEONG		Address: APT BLK 630 JURONG WEST STREET 65 #05-416 SINGAPORE 640630	
ID Type / ID No.: NRIC NO / S6937373I		Contact No.: Home/Office: Mobile: 97964208	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 50	Date of Birth: 24/10/1969	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: ENGINEERING		Driving Licence Information: Class: Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Government Vehicle	Drink Drive: No	Date/Time of Accident: 31/12/2019 21:15	Type of Location: T-Junction
Location: BAIN STREET				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
QX1022C	Car				Slightly Damaged	1
SJH1419J	Car	TOYOTA	ALLION 1.5 A	White	Slightly Damaged	2

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SJH1419J	AUTO & GENERAL INSURANCE (SINGAPORE) PTE. LIMITED	P10030710R02	28/07/2019	27/07/2020



**SINGAPORE
POLICE FORCE**



T/20200101/2046

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20200101/2046

CONTINUATION OF REPORT

Brief Details.

On 31/12/2019 at about 2115hrs I was driving my vehicle (SJH1419J) along bain street and came to a T junction and I came to a stop since there was vehicle driving past. A police car bearing plate number (QX1022C) stopped on our left hand side . At the moment I was not moving and was unable see the traffic from my left since the police car was blocking my view. The police vehicle then started turning right which ended up hitting my front left bumper. My vehicle suffered scratches and lost some of its paint layer on my front left bumper, while the police car suffered some light scratches on its front right door. There was no CCTV in my vehicle. No police or ambulance arrived on scene.

Driver: Candice Ng chee chuen, S7914029E



**SINGAPORE
POLICE FORCE**



T/20200101/2046

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3


Report No. T/20200101/2046

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J / Sgt 1 JERAL THIO YU XIANG <i>Jeral</i>	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 01/01/2020 13:43
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151 SN 126	Classification Of Case:
Authentication Stamp NP168 Signature: <i>Jeral</i> Singapore Police Force	



Certificate of Insurance

Comprehensive Car Policy
Policy Number: P10030710R02

Motor Vehicles (Third-Party Risks And Compensation) Act (Chapter 189) of Singapore, Motor Vehicles (Third-Party Risks And Compensation) Rules of Singapore, Road Transport Act 1987 of Malaysia, Road Transport (Amendment) Act 2019 of Malaysia, Motor Vehicles (Third-Party Risks) Rules, 1959 of Malaysia, or any Amendment, Act or Acts passed in substitution thereof.

Certificate Number P10030710R02 (Comprehensive / Named Driver Plan)

1) Vehicle Registration Number	:	SJH1419J
Chassis Number	:	NZT2603030248
2) Effective Date / Time of Commencement of Insurance for the Purpose of the Act	:	28/07/2019 (00:00)
3) Date / Time of Expiry of Insurance	:	27/07/2020 (23:59)
4) Excess (i) Policy	:	S\$ 600.00
(ii) Windscreen	:	S\$ 100.00
5) Policyholder	:	Pang Chee Keong
6) Persons or Classes of Persons Entitled to Drive*		
Drivers named as a Main / Named Driver in this Certificate of Insurance only.		
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of accident or loss. Please refer to the Product Disclosure Document for full terms and conditions.		
Main Driver / Date of Birth	:	Pang Chee Keong (24/10/1969)
Named Driver(s) / Date of Birth	:	Karen Goh Siew Wah (05/10/1973)
7) Limitation as to use*		
Use only for social, domestic and pleasure purposes. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.		
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) of Singapore and Section 95 of the Road Transport Act 1987 of Malaysia, are not to be included under these headings.		
8) Finance Company	:	NA

I / We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) of Singapore and Part IV of the Road Transport Act 1987 of Malaysia or any Amendment, Act or Acts passed in substitution thereof.

Issued in Singapore on
29/06/2019

Auto & General Insurance (Singapore) Pte. Limited
Trading as Budget Direct Insurance

Simon Birch

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : PANG CHEE KEONG
630 JURONG WEST ST 65
#05-416
SINGAPORE 640630

LKK
12 noon

Estimate No: MC1900933
Date: 03 Jan 2020
Policy No: P10030710R02
Veh Reg No: SJH1419J
Make/Model: TOYOTA ALLION 1.5 A

ATTN:

Your Ref No: SJH1419J
Claim Type: Third Party — SPF
Accident Date: 31/12/2019
TP Veh Reg No: QX1022C

Estimate Repair Cost to Vehicle No :SJH1419J

Description	Quantity	List Price S\$	Amount S\$
LABOUR			
1 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD.TO KNOCK & REPAIR FRONT BUMPER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	200.00	150
2 TO SPRAY FRONT BUMPER.	1 PC	300.00	200
		500.00	500.00
Total			S\$ 500.00
Add GST @ 7%			35.00
Total Amount Payable			S\$ 535.00

TOTAL: SINGAPORE DOLLAR FIVE HUNDRED THIRTY FIVE ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

350.

For AH LIM MOTOR COMPANY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



AUTHORISED SIGNATURE

2 Days.

part by part.

After repair photos.

Gino Qiang
82880282

15/1/2020

Hi,
Pis arrange vehicle for survey
To:
Zila
Ah Lim Motor Company




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF20000912/Gvf3e2		
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE) POLICE LOGISTICS BASE (PLB) 1 HEMMANT ROADSINGAPORE 438675		Date : 04-03-2020		
ATTN : HAFIZUL FARHAN RAHMAT		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 1022C	Veh. Inspected	SJH 1419J	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/121	Excess (\$)	0.00	
Assign From	HAFIZUL FARHAN RAHMAT	Assign Date	15/01/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALLION 1.5	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NZT2603030248	Colour	WHITE	
Odometer	130456	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/60 R15	MICHELIN	6 mm	
L/H Front Tyre	195/60 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/60 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/60 R15	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/12/2019	Inspection Date	15/01/2020	
Survey held at	AH LIM MOTOR COMPANY NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047			
5a. Remarks				
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 1419J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR FRONT BUMPER INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		200.00	150.00
	TO SPRAY FRONT BUMPER.		300.00	200.00
			500.00	350.00
	GRAND TOTAL		500.00	350.00
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)				350.00

Report Ref No. CS/SPF20000912/Gvf3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$350-\$500

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.