

ASS. REC. BY:

REF:

08/CTI 20000926/Und3

n2

Special Instruction:

Surveyor:

Marcus

## ASSIGNMENT (Office)

From (Person):

Adeline chng

of

CTI

Date/Time:

15/01/2020 @ 11:40am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMK 6499T

Insured:

SLS 8531 P

at Workshop m/s

Kaizen Motors

Tel:

9150 0670

of

68 Icaki Bukit Avenue 6 # 02-12

Policy No:

Claim No: SNM 20D200202 / SLS 8531P / IRENG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:44am @ 15/01/2020

Person Contacted:

Shawn

Vehicle:

IN / OUT

Date/Time	Action/Instruction Estimate (✓)	
	SMK 6499T - NW/INC 20000825 / 24	DOA: 11/01/2020
	SLS 8531P - NW/INC 20000825 / 24	DOA: 11/01/2020

C11/

## ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IPAC Accident Report:

GLA / PR Seen:

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type:

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/2/20 *cor 21-9-2024 LTA 13801*  
*4/5 \$5000 confirmed with Shown. (Red 6009.60, 559)*

RECEIVED 21 FEB 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

*21/2 - typist*

Report Format:

Lump Sum / I.B.I. (\$

*Merimen**5000p*

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

210

## Nivitha (LKK Auto)

---

**From:** Adeline Chng <adeline.chng@sg.cntaiping.com>  
**Sent:** Wednesday, 15 January 2020 11:40 AM  
**To:** assignments@lkkauto.com  
**Cc:** Claims Dept of CTI; ct-admin@visionlawllc.com; Tan Kah Leong; Irene Tay; claims@kaizenmotors.com.sg  
**Subject:** RE: OUR REF: SNM20D200202/SLS8531P/IRENE  
**Attachments:** 2480\_001.pdf

Without Prejudice

Dear Lkk

Please refer to the attached letter and liaise with third party workshop accordingly.

Thank you.

**Adeline Chng**  
Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6155 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

**From:** Claims Dept of CTI  
**Sent:** Wednesday, 15 January 2020 10:29 AM  
**To:** Adeline Chng <adeline.chng@sg.cntaiping.com>  
**Subject:** FW: Scan Image

**From:** ct-admin@visionlawllc.com <ct-admin@visionlawllc.com>  
**Sent:** Wednesday, January 15, 2020 10:15 AM  
**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; claims@kaizenmotors.com.sg  
**Subject:** Scan Image

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths

Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI DIO MUNIANDY  
ANG KIM NOI DIANE  
RAVENDRA KRISHNASAMY  
TAN YINGXIAN, SELWYN  
CHEONG YUNHUI, CLARISSA  
SONIA LIM WEI LEI

Unique Entity Number :200721148H  
✓ **HEAD OFFICE:** 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX ✓ : (65) 65356802 (General)  
: (65) 65355905 (Litigation)  
E-mail : jactan@visionlawllc.com

WHEN REPLYING PLEASE QUOTE OUR REFERENCE- KINDLY REPLY TO HEAD OFFICE FOR THIS MATTER

**Our Ref:** AM.jt.Ins.K88.112661.20 (sj)  
**Your Ref:** SNM20D200202C02/IRENE

15 January 2020

**CHINA TAIPING INSURANCE (S'PORE) PTE LTD**  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909  
**Attention: Motor Claims Department**

**BY FAX: 6224 7175**

Email: claimsdept@sg.cntaiping.com  
Email: kahleong.tan@sg.cntaiping.com  
Email: irene.tay@sg.cntaiping.com

Dear Sirs,

**ACCIDENT INVOLVING SMK 6499 T & SLS 8531 P & SKU 45 E & SMJ 5970 K ON 11 JANUARY 2020 ALONG CTE AYE BEFORE BRADDELL ROAD EXIT AT ABOUT 1045 HOURS (NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email 14 January 2020 of even date informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of Marcus Chua as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

Venue: Kaizen Motors Pte Ltd  
68 Kaki Bukit Avenue 6  
#02-12 ARK@KB  
Singapore 417896  
Contact Person: Shawn Yap: 9150-0670

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

ANJALI M  
(HEAD OFFICE)

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection.  
Thank you.

1<sup>st</sup> Survey on \_\_\_\_\_  
Appointed surveyor : \_\_\_\_\_  
(Name & Signature)

2<sup>nd</sup> Survey on \_\_\_\_\_  
Appointed surveyor : \_\_\_\_\_  
(Name & Signature)

3<sup>rd</sup> Survey on \_\_\_\_\_  
Appointed Surveyor : \_\_\_\_\_  
(Name & signature)

cc: SMK 6499 T – by Email: claims@kaizenmotors.com.sg only

**NB.: Any settlement of offer is on the express condition that this settlement is in respect of our client's claim for property-related damages only and shall not preclude our client from claiming injury-related damages arising from this accident.**

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles



Kia Cerato

Price Range ▼

Depreciation ▼

&gt; 10 year(▼)

Vehicle Type ▼



Home » Used Cars » CarQuotz Singapore » Kia Cerato Forte 1.6M EX (COE till 09/2024)

## Kia Cerato Forte 1.6M EX (COE till 09/2024)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

**CARQUOTZ** *Nothing without Solution*

Price	\$26,998		
Depreciation	\$5,740 /yr	Reg Date	30-Sep-2009 (4yrs 8mths 13days COE left)
Mileage	N.A.	Manufactured	2009
Road Tax	\$812 /yr	Transmission	Manual
Dereg Value	\$13,879 as of today (change)	OMV	\$10,224
COE	\$14,743	ARF	\$10,224
Engine Cap	1,591 cc	Power	92.7 kW (124 bhp)
Curb Weight	1,227 kg	No. of Owners	3

Type of Vehicle Mid-Sized Sedan

## Features

1.6L 4 Cylinders 16 Valves Engine, 124Bhp, 4 Speed Manual With Steptronic, ABS, SRS Airbags, Front And Rear Disc Brakes, Knockdown Rear Seats. View specs of the Kia Cerato Forte (2009-2013)

## Accessories

Sports Rims, Leather Seats, Built In Audio System, Retractable Side Mirrors, Reverse Sensors, Solar Films, Fog Lights.

## Description

Drive With Assurance! Genuine And Transparent Deal! Flexible Bank/In House 100% Full Loan Monthly \$608, All Our Quality Consignment Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! 100% Non-Private Hire Car. STA Inspection Welcome! Fully Refurbished! New \$2k Premium Paintwork/Customize Leather Seat! View To Believ

Daily 10AM To 9PM, Visit Us Today!



Shortlist

Compare

Report Error

More

## Seller Information

CarQuotz Singapore

## Customer Review

5.0 ★★★★★

Carquotz recommended

Si Jia

> **Back to OneMotoring**

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	918G

### Vehicle Details

Vehicle No.:	SMK6499T
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2020
Vehicle Make:	KIA
Vehicle Model:	CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR
Primary Colour:	Brown
Manufacturing Year:	2009
Engine No.:	G4FC9H291460
Chassis No.:	KNAFW411MA5124219
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$14,308.00
Original Registration Date:	22 Sep 2009
First Registration Date:	22 Sep 2009
Transfer Count:	5
Actual ARF Paid:	\$14,308.00

### Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	21 Sep 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$14,743.00
COE Rebate Amount:	\$13,801.00
<b>Total Rebate Amount:</b>	<b>\$13,801.00</b>

### Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 16 Jan 2020

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	13/01/2020 14:30
Date Of Accident	11/01/2020 10:45
Exact Location Of Accident	CTE (AYE) BEFORE BRADDELL RD EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK6499T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FAST CAR RENTAL PTE LTD
Co Reg No	2XXXXX918G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92270221
Alternative Phone No	OFFICE-92270221
<b>Vehicle Particulars</b>	
Manufacturer	KIA
Model	CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5109163827
Cover Note Number	
<b>Driver</b>	
Name of Driver	ONG BENG LIANG
NRIC No	SXXXX102Z
Date Of Birth	13/04/1992
Occupation	OUTDOOR
Date Of Driving Pass	05/01/2015
Driving Experience	5 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96398036
Fax Number	
Contact Number	OFFICE-96398036
Email Address	NOEMAIL



Address	BLK 434 HOUGANG AVENUE 8 #07-914
Postcode	530434
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

#### General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE POST
Police Station Address	ROAD: BLK 357 HOUGANG AVENUE 7 #01-805 , POSTCODE: 530357 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2869999 - FAX NO: 63822066
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20200111/2087.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS8531P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAN KUAN HWEE
NRIC/Passport Number	
Contact Number	98367469



Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

3

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SKU45E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

SHI HONG SHENG

NRIC/Passport Number

SXXXX627F

Contact Number

96546461

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SMJ5970K

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NG CHIN KUAY

NRIC/Passport Number

SXXXX008C

Contact Number

96315873

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

#### DETAILS OF INJURED PERSON 1

Name

ONG BENG LIANG

Approximate Age

Injuries Sustain

BODY

Injured person in which vehicle?

SMK6499T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Accident Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1 Please report correctly the details of the accident to speed up the claims process
- 2 This Form must be completed by the Policyholder and/or the Authorised Driver
- 3 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- 6 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7 By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

### Accident Sketch Plan

### SKETCH PLAN

A. IMPULSIVE  
B. SENSITIVE  
C. WHITE  
D. SING SINGING

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Relat to police report - 7/20/2011/387

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature: \_\_\_\_\_  
Date & Time: \_\_\_\_\_

Driver's Signature:  
(if driver is not the policyholder)  
Date & Time

Reporting Centre Personnel's Signature:  
Name: \_\_\_\_\_  
NRIC/FIN No: \_\_\_\_\_

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20200111/2087

1 of 4

Police Station Of Origin  
Hougang N P C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

Report No: T/20200111/2087

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 11/01/2020 16:38	Vide Report No	Station Diary No 92
---	----------------	------------------------

### Informant's Particulars

Name of Informant ONG BENG LIANG			Address APT BLK 434 HOUGANG AVENUE 8 #07-914 SINGAPORE 530434	
ID Type / ID No NRIC NO / S9212102Z			Contact No. Home/Office	Mobile: 96398036
Nationality SINGAPORE CITIZEN			Email	
Sex Male	Age 27	Date of Birth 13/04/1992	Type of Informant Driver	
Race Chinese			Language English	Institution / School Name
Occupation private hirer			Driving Licence Information: Class: 3 Date of Expiry:	

### General Information of the Accident

General Information of the Road				
Type of Accident	Injury Others	Drink Drive No	Date/Time of Accident: 11/01/2020 10:45	Type of Location Straight Road
Location Along Road 1 CENTRAL EXPRESSWAY				
Along CTE towards AYE before Braddel Road Exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow One Way		Traffic Control Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

### Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKU45E	Car	MERCEDES BENZ	CLA180 (R18 BI)	Grey		0
SLS8531P	Car	TOYOTA	COROLLA ALTIS ECO AUTO	White		2
SMJ5970K	Car	MITSUBISHI	OUTLANDE R 2.0 CVT	White		0

# Police Report



**SINGAPORE  
POLICE FORCE**



T/20200111/2087

Police Station Of Origin:  
Hougang N P C  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

2 of 4

Report No: T/20200111/2087

## CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SMK6499T	Car	KIA	CERATO FORTE 1.6 AT SX ABS D/AB 2WD 4DR	Black		1

Details of Person Involved					
Any Pedestrian Involved No					
No. of Pedestrians Injured NIL			Use of Pedestrian Crossing NA		
Driver					
Name	SHI HONG SHENG		ID No.	S8629627F	
Related Vehicle	SKU45E (Car)		Contact No.	96546461	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL	
Driver					
Name	TAN KUAN HWEE		ID No.	NIL	
Related Vehicle	SLS8531P (Car)		Contact No.	98367469	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL	
Driver					
Name	NG CHIN KUAY		ID No.	S1796008C	
Related Vehicle	SMJ5970K (Car)		Contact No.	96315873	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL		Date Discharge	NIL	
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL	

## Police Report



**SINGAPORE  
POLICE FORCE**



T/20200111/2087

3 of 4

Police Station Of Origin

Hougang N P C

60 Hougang Avenue 9 SINGAPORE 536775

Tel No 1800-4890999

Report No T/20200111/2087

### CONTINUATION OF REPORT

Driver			
Name	ONG BENG LIANG	ID No	S9212102Z
Related Vehicle	SMK6499T (Car)	Contact No	96398036
Hospital/Clinic	CENTRAL 24HR CLINIC	Class of Driving Licence & Expiry Date	Class 3 Date of Expiry: NIL
Date Treatment	11/01/2020	Date Discharge	11/01/2020
No. of Days granted Medical Leave	03	Degree of Injury	NIL

#### **Brief Details.**

On 11/01/2020 at about 1045hrs, I was driving my car(Registration No. SMK6499T) along CTE towards AYE before Braddel Road Exit on the 1st lane of the 5lanes road when traffic was congested and I stopped my car due to traffic. Suddenly another car(Registration No. SLS8531P) collided onto my car's rear. I suffered impact on my back and neck area. This resulted in a chain collision followed by the 3rd car(Registration No. SKU45E) and 4th car(Registration No. SMJ5970K). We then alighted from our vehicle to inspect the damages, took photos, agree in Insurance Claim and left the scene. The is dashcamera in my car facing front. I later went to Central 24Hr Clinic and has 3days of MC therefore lodging this Traffic Accident report.

Police Report



SINGAPORE  
POLICE FORCE



T/20200111/2087

Police Station Of Origin:  
Hougang N.P.C.  
60 Hougang Avenue 9 SINGAPORE 538775  
Tel No: 1800-4890999

4 of 4

Report No. T/20200111/2087

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report  
F /  
Sgt 2 BOH YONG SENG

Signature Of Informant

Signature Of Interpreter:  
Not applicable

Date/Time:  
11/01/2020 16:38

Officer In Charge Of Case:  
TP / AEIT /  
SSI 2 YEO GEAK ENG CECILIA  
Contact No: 65476404

Classification Of Case

Authentication Stamp  
NP168



# KAIZEN MOTORS

KAIZEN MOTORS PTE. LTD.

68 Kaki Bukit Avenue 6, #02-12 Ark@KB, Singapore 417896

UEN: 201502816H GST Reg No. 201502816H

Tel: (+65) 6384 1956 Fax: (+65) 6384 1957

Webpage: <https://www.kaizenmotors.com.sg>

 kaizenmotorsingapore

 kaizen\_motors

 kaizenmotors

*Not Authorized  
dealer  
1/5 \$5000  
6 days.*

Date : 14/01/2020  
Vehicle No : SMK6499T  
Model : KIA Cerato Forte  
Mileage :

## Requesting for List Price

No	Job Description	Qty	Price / Unit	Amount
1	BOOTLID ASSY	1	\$ 747.00	\$ 747.00
2	BOOTLID HINGE	2	\$ 69.00	\$ 138.00
3	BOOTLID WEATHERSTRIP	1	\$ 99.00	\$ 99.00
4	BOOTLID EMBLEM KIA	1	\$ 28.00	\$ 28.00
5	BOOTLID EMBLEM (CERATO)	1	\$ 28.00	\$ 28.00
6	BOOTLID EMBLEM (FORTE)	1	\$ 31.00	\$ 31.00
7	BOOTLID OUTER GARNISH	1	\$ 59.00	\$ 59.00
8	BOOTLID OUTER GARNISH CLIP	10	\$ 4.50	\$ 45.00
9	BOOTLID NO. PLATE LAMP	2	\$ 39.00	\$ 78.00
10	BOOTLID INNER LOCK	1	\$ 104.00	\$ 104.00
11	BOOTLID LOCK CATCH	1	\$ 29.00	\$ 29.00
12	BOOTLID INNER TRIM	1	\$ 269.00	\$ 269.00
13	BOOTLID INNER TRIM CLIP	10	\$ 4.50	\$ 45.00
14	TAIL LAMP INNER ASSY	2	\$ 129.90	\$ 259.80
15	TAIL LAMP OUTER ASSY	2	\$ 174.90	\$ 349.80
16	TAIL LAMP INNER SEALER	2	\$ 45.00	\$ 90.00
17	TAIL LAMP CLIP	10	\$ 5.50	\$ 55.00
18	REAR BUMPER ASSY	1	\$ 601.00	\$ 601.00
19	REAR BUMPER REINFORCEMENT ASSY	1	\$ 304.00	\$ 304.00
20	REAR BUMPER FOAM	1	\$ 135.00	\$ 135.00
21	REAR BUMPER SIDE RETAINER	2	\$ 49.00	\$ 98.00
22	REAR BUMPER CLIP	10	\$ 3.50	\$ 35.00
23	END PANEL	1	\$ 282.00	\$ 282.00
24	END PANEL TRIM	1	\$ 59.00	\$ 59.00
25	END PANEL TRIM CLIP	10	\$ 4.50	\$ 45.00
26	REAR FLOOR PANEL	1	\$ 659.00	\$ 659.00
27	REAR FLOOR PANEL TOP BOARD	1	\$ 299.00	\$ 299.00
28	REVERSE CAMERA	1	\$ 269.00	\$ 269.00
29	REVERSE SENSOR	1	\$ 269.00	\$ 269.00
30	Rear lower skirting	1	\$ 499.00	\$ 499.00
31	REAR NO. PLATE WITH COVER	1	\$ 50.00	\$ 50.00
32	BODY PANEL JOINT SEALANT	1	\$ 120.00	\$ 120.00
33	LABOUR FOR CHECKING ON WIRING		\$ 120.00	\$ 120.00
34	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS, INCLUDING WELDING, KNOCKING, REPAIRING, STRAIGHTENING, RESHAPE & ADJUSTMENT OF END PANEL INNER, REAR BUMPER, DIFFUSER, SIDE PANEL, TAIL LAMP, BOOTLID		\$ 2,500.00	\$ 2,500.00

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Copyright © KAIZEN MOTORS PTE. LTD.

Date:

*P. 4116.80  
102  
P. 3705.12  
S. 200.00  
L. 2360.00  
6265.12  
202  
5012*

35	SPRAYPAINTING & PUTTY OF BOOTLID, END PANELS, REAR BUMPER, TAIL LAMP BOTTOM COVERS	\$	2,250.00	\$	2,250.00	1180
36	APPLYING OF RUST-PROOFING	\$	250.00	\$	250.00	60

---

<b>Sub-Total</b>	\$	11,029.60
<b>GST 7%</b>	\$	772.07
<b>Grand Total</b>	\$	11,801.67

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20000926/UVD3N2  
**Date:** 25/02/2020

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No:  
**Claimant Vehicle No :** SMK6499T **Insured Vehicle No :** SLS8531P  
**Date of Loss:** 11/01/2020 **Nature of Claim:** TP **Claim No:** SNM20D200202

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: **SMK6499T**  
 Make & Model: KIA CERATO FORTE, 1.6 A/T ABS AB 2WD 4DR (A) Engine No: G4FC9H291460  
 Reg. Date: 22/09/2009 (Man. Year: 2009) Chassis No: KNAFW411MA5124219  
 Colour: Brown Odometer: 264841 km  
 Engine Capacity: 1591 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 215/50ZR17 Rear Tyre Size: 215/50ZR17  
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm  
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,789.60	3,945.12	1,844.48	31.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,240.00	2,320.00	2,920.00	55.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,029.60</b>	<b>6,265.12</b>	<b>4,764.48</b>	<b>43.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,000.00</b>		
<b>(S\$)</b>	11,029.60	5,000.00	6,029.60	54.67
<b>+ GST 7.00/7.00% (S\$)</b>	772.07	350.00	422.07	54.67
<b>Nett Amount (S\$)</b>	<b>11,801.67</b>	<b>5,350.00</b>	<b>6,451.67</b>	<b>54.67</b>

## INSPECTION

Date of Assignment: 15/01/2020  
 Date Inspected: 15/01/2020 Inspected At: Kaizen Motors Pte Ltd (HQ)  
 68 KAKI BUKIT AVE 6, #02-12 ARK @ KAKI BUKIT  
 Singapore 417896  
 Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2020)

Parts: 143 KIA CERATO FORTE 1.6 A/T ABS AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMK6499T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID ASSY	Dented/Buckled	747.00 F	*747.00 FL
2	2		*BOOTLID HINGE	Not Necessary	138.00 F	*- FL
3	1		*BOOTLID WEATHERSTRIP	Twisted	99.00 F	*99.00 FL
4	1		*BOOTLID EMBLEM KIA	Necessary	28.00 F	*28.00 FL
5	1		*BOOTLID EMBLEM (CERATO)	Necessary	28.00 F	*28.00 FL
6	1		*BOOTLID EMBLEM (FORTE)	Necessary	31.00 F	*31.00 FL
7	1		*BOOTLID OUTER GARNISH	Cracked	59.00 F	*59.00 FL
8	10		*BOOTLID OUTER GARNISH CLIP	Not Necessary	45.00 F	*- FL
9	2		*BOOTLID NO PLATE LAMP	Not Necessary	78.00 F	*- FL
10	1		*BOOTLID INNER LOCK	Twisted	104.00 F	*104.00 FL
11	1		*BOOTLID LOCK CATCH	Not Necessary	29.00 F	*- FL
12	1		*BOOTLID INNER TRIM	Deformed/Torn	269.00 F	*269.00 FL
13	10		*BOOTLID INNER TRIM CLIP	Not Necessary	45.00 F	*- FL
14	2		*TAIL LAMP INNER ASSY	Not Necessary	259.80 F	*- FL
15	2		*TAIL LAMP OUTER ASSY	Cracked	349.80 F	*349.80 FL
16	2		*TAIL LAMP INNER SEALER	Necessary	90.00 F	*90.00 FL
17	10		*TAIL LAMP CLIP	Not Necessary	55.00 F	*- FL
18	1		*REAR BUMPER ASSY	Distorted	601.00 F	*601.00 FL
19	1		*REAR BUMPER REINFORCEMENT ASSY	Cracked	304.00 F	*304.00 FL
20	1		*REAR BUMPER FOAM	Torn	135.00 F	*135.00 FL
21	2		*REAR BUMPER SIDE RETAINER	Bent	98.00 F	*98.00 FL
22	10		*REAR BUMPER CLIP	Necessary	35.00 F	*35.00 FL
23	1		*END PANEL	Dented	282.00 F	*282.00 FL
24	1		*END PANEL TRIM	Twisted	59.00 F	*59.00 FL
25	10		*END PANEL TRIM CLIP	Not Necessary	45.00 F	*- FL
26	1		*REAR FLOOR PANEL	Repair	659.00 F	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Warped	299.00 F	*299.00 FL
28	1		*REVERSE CAMERA (NPA)	Not fitted	0.00 F	*- FL
29	1		*REAR LOWER SKIRTING	Cracked	499.00 F	*499.00 FL
30	1		*SET REVERSE SENSOR	Shorted	269.00 FS	*200.00 FS
31	1		*REAR NO PLATE WITH COVER	Bent	50.00 FS	*40.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	5,789.60	4,356.80
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	411.68
Total Parts (\$\$)	5,789.60	3,945.12

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	BODY PANEL JOINT SEALANT	New	120.00	50.00
2	LABOUR FOR CHECKING ON WIRING	New	120.00	30.00
3	LABOUR FOR DISMANTLING & REPLACING OF ACCIDENT DAMAGED PARTS,INCLUDING WELDING,KNOCKING,REPAIRING,STRAIGHTENING,RESHAPE & ADJUSTMENT OF END PANEL INNER,REAR BUMPER,DIFFUSER,SIDE PANEL,TAIL LAMP,BOOTLID	New	2,500.00	1,000.00
4	SPRAYPAINTING & PUTTY OF BOOTLID,END PANELS,REAR BUMPER,TAIL LAMP BOTTOM COVERS	New	2,250.00	1,180.00
5	APPLYING OF RUST-PROOFING	New	250.00	60.00
Gross Labour Cost (\$\$)			5,240.00	2,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >