

ASS. REC. BY:

REF: CS3/A1G 20000940/GS fsl Special Instruction:

SURVIVOR

GG

## ASSIGNMENT (Office)

From (Person): Winnie Fan of A1G Date/Time: 15.1.2020 2.42p.m.

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKC 7425R Insured: SGF 766J

at Workshop m/s Long Wang motor Tel: 98172032

of Blk 3007 Ubi road 1 # 01-414

Policy No: Claim No:

Sum Insured: Excess:

Make of Vch: D.O.A. 10.1.2020  
(Client's Record)

CA / REV / REP. / REV 24 HRS imp H.O.D. Endorsement:

Date/Time: 15.1.2020 2.51p.m. Person Contacted: Alice Vehicle: IN / OUT

Date/Time	Action/Instruction ( X ) Estimate
	SKC 7425R - x
	SGF 766J - NA / IN ( 08022320/51 ) DON - 20/10/2009
17/01/20	@ 14:53 pm checked with Alice, no estimate.

ISSA REC BY:

REF:

ASG

PRS

## ASSIGNMENT

(2021)

From: \_\_\_\_\_ Date: 16.1.2020

Estimated Cost: \_\_\_\_\_

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKC 7425R

at Workshop m/s Long Wang motor  
of BIK 3007 Ubi Rd 1 #01-414

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: 2pm Owner Wally

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \$51K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKC 7425R Yr Regn: 28 Sep 2011

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: Audi A6 2.8 C.C 2773

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 162818 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZZ4G8BN023912

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In Order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / S/Rim / STD Air / or

Tyre Size: F: 245/40R18

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 16-01-20

Survey held at w/s 2pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

COE: 37367

RECEIVED 16 FEB 2020

Date/Time, File Pass 1/7

18/02/20

Type: SF

Date/Time, File Return 1/7

23

Rep. Form: PRS

Lump Sum / TD 1/7

☐ : Preli. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weigh (\$)

Survey Fee:

Transportation:

3 + RS \$

Probs

Others

TOTAL

180

11

191

## Nivitha (LKK Auto)

---

**From:** Fan, Winnie-LW <Winnie-LW.Fan@aig.com>  
**Sent:** Wednesday, 15 January 2020 2:42 PM  
**To:** Admin A; assignments  
**Cc:** Fong, Andy-SY  
**Subject:** Aigencypt Re: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGF766J AND SKC7425R ON 11/01/2020 (Oref: LCH.lg/UB06-A10031.20)

**Importance:** High

Hi LKK,

Kindly assist to survey.

Winnie Fan  
AIG  
Claims Service Associate  
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

[winnie-lw.fan@aig.com](mailto:winnie-lw.fan@aig.com) | [www.aig.sg](http://www.aig.sg)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

---

**From:** Cheonghoh Law <[mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)>  
**Sent:** Wednesday, January 15, 2020 12:29 PM  
**To:** Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)>; [claimssurvey@aig.com](mailto:claimssurvey@aig.com)  
**Cc:** Fong, Andy-SY <[Andy-SY.Fong@aig.com](mailto:Andy-SY.Fong@aig.com)>; Fan, Winnie-LW <[Winnie-LW.Fan@aig.com](mailto:Winnie-LW.Fan@aig.com)>; Abu Kassim, Noor Mariesa <[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com)>; Azlan, Syazairdina <[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com)>; Chan, Yoke Shi <[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>; Mithoosingh, Aashweenjeetkaur <[Aashweenjeetkaur.Mithoosingh@aig.com](mailto:Aashweenjeetkaur.Mithoosingh@aig.com)>; Parthiban, Theerthan <[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com)>; Subramaniam, Divyashni <[Divyashni.Subramaniam@aig.com](mailto:Divyashni.Subramaniam@aig.com)>  
**Subject:** [EXTERNAL] Re: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGF766J AND SKC7425R ON 11/01/2020 (Oref: LCH.lg/UB06-A10031.20)

This message is from an external sender; be cautious with links and attachments.

Urgent Attention!

Dear Sirs,

Kindly be inform that our client's vehicle SKC 7425 R will be at workshop tomorrow - 16 January 2020 at 2:00 pm (client waiting).

Please do the needful.

Thanks & regards  
Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

**From:** Cheonghoh Law <[mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)>

**Sent:** Tuesday, January 14, 2020 11:19 AM

**To:** Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)>

**Cc:** Fong, Andy-SY <[Andy-SY.Fong@aig.com](mailto:Andy-SY.Fong@aig.com)>; Fan, Winnie-LW <[Winnie-LW.Fan@aig.com](mailto:Winnie-LW.Fan@aig.com)>; Abu Kassim, Noor Mariesa <[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com)>; Azlan, Syazairdina <[Syazairdina.Azlan@aig.com](mailto:Syazairdina.Azlan@aig.com)>; Chan, Yoke Shi <[yokeshi.chan@aig.com](mailto:yokeshi.chan@aig.com)>; Lim, Sheng Yang <[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com)>; Mithoosingh, Aashweenjeetkaur <[Aashweenjeetkaur.Mithoosingh@aig.com](mailto:Aashweenjeetkaur.Mithoosingh@aig.com)>; Parthiban, Theerthan <[Theerthan.Parthiban@aig.com](mailto:Theerthan.Parthiban@aig.com)>; Subramaniam, Divyashni <[Divyashni.Subramaniam@aig.com](mailto:Divyashni.Subramaniam@aig.com)>

**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SGF766J AND SKC7425R ON 11/01/2020 (Oref: LCH.lg/UB06-A10031.20)

This message is from an external sender; be cautious with links and attachments.

Dear Sirs,

We refer to the above matter and to your email of 13 January 2019.

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your 10 appointed surveyors as stated in your aforesaid e-mail.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- (1) Kelvin Teo Hoon Tong
- (2) Chiang Fuh Keong Dave
- (3) Ho Joo Loong Danny
- (4) Lee Kok Weng
- (5) Hong Shiyuan
- (6) Lim Yong Tian Sebastian
- (7) Ong Ah Keng Kent
- (8) Ong Poh Meng
- (9) Philip Foo
- (10) Thor Teck Soon David

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey and please contact our client's workshop, Leng Wang Motor, Blk 3007 Ubi Road 1 #01-414 Singapore 408701 to contact survey of the said vehicle SKC 7425 R.

Contact Person : Ms Alice Yong  
Tel: 6748 2910 / 9817 2032

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: [mail@cheonghoh.sg](mailto:mail@cheonghoh.sg)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	403Z

### Vehicle Details

Vehicle No.:	SKC7425R
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Jan 2020
Vehicle Make:	AUDI
Vehicle Model:	A6 2.8 FSI MU
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	CHV003670
Chassis No.:	WAUZZZ4G8BN023912
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$47,917.00
Original Registration Date:	28 Sep 2011
First Registration Date:	28 Sep 2011
Transfer Count:	0
Actual ARF Paid:	\$47,917.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Sep 2021
PARF Rebate Amount:	\$26,354.00

### Intended COE Rebate Details

COE Expiry Date:	27 Sep 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$64,889.00
COE Rebate Amount:	\$11,013.00
<b>Total Rebate Amount:</b>	<b>\$37,367.00</b>

The information contained herein is correct as at 16 Jan 2020

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/01/2020 12:35
Date Of Accident	11/01/2020 08:30
Exact Location Of Accident	BLK 121 TOA PAYOH LOR 2 MSCP
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC7425R
Insured/Policyholder	
Name Of Registered Owner	VALENCIA DESIGN PTE LTD
Co Reg No	2XXXXX403Z
Email Address	VALHOUSE@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97391292
Alternative Phone No	OFFICE-63457897

### Vehicle Particulars

Manufacturer	AUDI
Model	A6 2.8 FSI MU
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA063424/1
Cover Note Number	

### Driver

Name of Driver	PANG KIM CHING
NRIC No	SXXXX441C
Date Of Birth	25/11/1971
Occupation	INDOOR
Date Of Driving Pass	01/04/2004
Driving Experience	15 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97391292
Fax Number	
Contact Number	
Email Address	KIMCHING_PANG@YAHOO.COM.SG

Address	BLK 121 TOA PAYOH LORONG 2 #21-30
Postcode	310121
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGF766J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE CHENG GUAN CHRISTIAN
NRIC/Passport Number	SXXXX436H
Contact Number	96808885
Address	
Postcode	
Insurance Company Name	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

VEHICLE NO: SKC742SR  
 ACCIDENT DATE: 12/1/20

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.

VALENCIA DESIGN PTE LTD  
 35 Tammy Road  
 #06-05 Ruby Industrial Centre  
 Singapore 347740  
 Tel: 6753 1690 Fax: 6753 1728


Policyholder's Signature  
 Date & Time: 11/1/2020

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 11/1/2020

CHARN'S CUSTOMCRAFT  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:



## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Found a letter on the glass screen a piece of letter indicating that owner of car SGF 766J has scratched the front of my Audi A6 when reversing into the carpark lot.

Contacted owner Lee Meng Guan S1348436H @ HP 96808855 to meet up at carpark @ 8.51am on 11 Jan 2020. Mr Lee agreed to claim 3rd party insurance on his AIG Policy No: 1800039202

I am working for Valencia Design Pte Ltd & using the vehicle for both personal & work purpose at time of accident.

OWN DAMAGE ( )

3RD PARTY CLAIM ☒REPORTING ONLY ☒OWN WORKSHOP ☒

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

VALENCIA DESIGN PTE LTD

Policyholder's Signature: ASAS 1109

Date & Time:

11/1/2020

Driver's Signature  
(If driver is not the policyholder)

Date & Time:

11/1/2020

CHARN'S CUSTOMCRAFT

Reporting Centre Person's Signature

Name:

NRIC/FIN No.:

MCCC20004540-01 / Cham's Customcraft - HQ  
 ENTRY DATE & TIME: 11/01/2020 12:35  
 SUBMITTED BY: Sharon Lee Chia Ling

## SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date Of Report	11/01/2020 12:35
Date Of Accident	10/01/2020 19:30
Exact Location Of Accident	BLK 121 TOA PAYOH LOR 2 MSCP
Country/State of Loss	SINGAPORE

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC7425R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	VALENCIA DESIGN PTE LTD
Co Reg No	2XXXXX403Z
Email Address	VALHOUSE@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-97391292
Alternative Phone No	OFFICE-63457897

## Vehicle Particulars

Manufacturer	AUDI
Model	A6 2.8 FSI MU

Exact Purpose for which vehicle was being used at time of accident	PRIVATE
--	---------

Are you claiming under your own insurance policy for repair to your vehicle?	NO
--	----

If No, Please state action to be taken	THIRD PARTY
--	-------------

Vehicle Category	PRIVATE CAR
------------------	-------------

## Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA063424/1
Cover Note Number	

## Driver

Name of Driver	PANG KIM CHING
NRIC No	SXXXX441C
Date Of Birth	25/11/1971
Occupation	INDOOR
Date Of Driving Pass	01/04/2004
Driving Experience	15 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97391292
Fax Number	
Contact Number	
Email Address	KIMCHING_PANG@YAHOO.COM.SG

Address BLK 121 TOA PAYOH LORONG 2 #21-30  
 Postcode 310121  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Insurance Company of Driver's Own Vehicle -

**General Information of the Accident**

Type Of Accident HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance?  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 0

**Details of Police Action**

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SGF766J  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver LEE CHENG GUAN CHRISTIAN  
 NRIC/Passport Number SXXXX436H  
 Contact Number 96808885  
 Address  
 Postcode  
 Insurance Company Name AIG ASIA PACIFIC INSURANCE PTE. LTD.  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

## Sketch Plan Pg. 1

SKETCH PLANIMPORTANT NOTICE

VEHICLE NO: SKC7425R

ACCIDENT DATE: 12/1/20

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

**NOTE: DO NOTE THAT YOU MAY HAVE A 14-DAYS TIMEFRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE REFER TO YOUR POLICY FOR MORE INFORMATION.**

VALENCIA DESIGN PTF LTD  
35 Tannery Road  
#06-05 Ruby Industrial Cor-  
Singapore 347740  
Tel: 6345 7881 Fax: 6345 1209

Policyholder's Signature

Date &amp; Time:

11/1/2020

Driver's Signature

(If driver is not the policyholder)

Date &amp; Time:

11/1/2020

CHARN'S CUSTOMER


Reporting Centre Personnel's Signature

Name:

NRC/FIN No.:

## Sketch Plan #2 Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Found a letter on the glass screen a piece of letter indicating that owner of car SGF 766J has scratched the front of my Audi A6 when reversing into the carpark lot.

Contacted owner Lee Meng Guan S1348436H @ HP 96808885 to meet up at carpark @ 8.51am on 11 Jan 2020. Mr Lee agreed to claim 3rd party insurance on his AIG Policy No: 1800039202

I am working for Valencia Design Pte Ltd & using the vehicle for both personal & work purpose at time of accident.

OWN DAMAGE ( )

3RD PARTY CLAIM ☒REPORTING ONLY ☒OWN WORKSHOP ☒

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

VALENCIA DESIGN PTE LTD

35 Timor Road

#05-05 Ruby Industrial Complex

Singapore 437710

Policyholder's Signature: 6345 1209

Date &amp; Time:

11/1/2020

Driver's Signature

(if driver is not the policyholder)

Date &amp; Time:

11/1/2020

CHARN'S CUSTOMCRAFT

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

# VAN / LORRY (Frt)

## Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	SCD	✓	
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	CR	✓	
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side clips	NC	✓	
1006	991325	Frt Bumper Bracket			
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover	SC	✓	
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CR	✓	
1022	991328	Frt Grille Emblem	NC	✓	
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding	CR	✓	
2007	991891	Frt Panel			
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem			
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel Garnish			
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel			
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH			
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber			
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)			
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay			
1025	992013	Frt Support Panel			
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990223	Battery Bracket			

Vehicle No: SKC7425R

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			

No of Items: \_\_\_\_\_ Assessor: \_\_\_\_\_



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	20 Jan 2020 <a href="#">Edit Reg</a>		15 Jan 2020 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>






















Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	Lee Cheng Guan Christian (Li Qingyuan), ID: S1348436H, Tel: +6596808885								
Main Claimant:	VALENCIA DESIGN PTE LTD								
Vehicle Reg. No.:	SKC7425R	Date of Loss:	10/01/2020 00:00 - :59 [99 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 9617567881SG	Policy/Cover Note No.:	1800039202 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGF766J	Policy No. (Claimant):							
		Excess:							
Repairer:	Leng Wang Motor (HQ) Blk 3007 Ubi Road 1, #01-414, 408701 Ubi - Tel:								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian Meng] kianmeng.chan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 24/01/2020]								
Driver/Custodian (Insured):	Lee Cheng Guan Christian (Li Qingyuan) ( ), NRIC: S1348436H, Tel: +6596808885 Email:								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>AIG_SG (28/01/2020): Re: Fw: Conflicting DOA</li> <li>AIG_SG (21/01/2020): Fw: Conflicting DOA</li> <li>AIG_SG (15/01/2020): Conflicting DOA</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SKC7425R (9617567881SG)  
[SGF766J]  
TP  
VALENCIA DESIGN PTE LTD  
Jan 10 2020 12:00AM  
[Lee Cheng Guan Christian (Li Qingyuan)]  
Leng Wang Motor

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Photos/Images															3 per page			<input type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail			Print		
1	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
2	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
3	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
4	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
5	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
6	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
7	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
8	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
9	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
10	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
11	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
12	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
13	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
14	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
15	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
16	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
17	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
18	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
19	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
20	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
21	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
22	17/02/20 16:27	General View																Load JPG <input checked="" type="checkbox"/>		
23	17/02/20 16:28	Odometer Reading																Load JPG <input checked="" type="checkbox"/>		
24	17/02/20 16:28	Chassis Number																Load JPG <input checked="" type="checkbox"/>		
25	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
26	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
27	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
28	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
29	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
30	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
31	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
32	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
33	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
34	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
35	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
36	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		
37	17/02/20 16:28	Dismantled Parts																Load JPG <input checked="" type="checkbox"/>		



Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/02/20 16:28	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/02/20 16:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
49	17/02/20 16:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
50	17/02/20 16:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
51	17/02/20 16:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
52	17/02/20 16:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
53	17/02/20 16:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
54	17/02/20 16:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
55	17/02/20 16:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/01/20 15:51	TP GIA REPORT.pdf	 Load PDF	
2	13/02/20 09:01	TP GIA REPORT - ADDENDUM.pdf	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	15/01/20 15:41	OI GIA REPORT	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20000940/GSF3E2

Date: 18/02/2020

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800039202

Claimant Vehicle  
No: SKC7425R

Insured Vehicle No: SGF766J

Date of Loss: 10/01/2020

Nature of Claim:

TP

Claim No: 9617567881SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SKC7425R

Make &amp; Model: AUDI A6, 2.8 FSI MU (A)

Engine No: CHV003670

Reg. Date: 28/09/2011 (Man. Year: 2011)

Chassis No: WAUZZZ4G8BN023912

Colour: Black

Odometer: 162818 km

Engine Capacity: 2773 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size:

245/40Z R18

Front Left Side: Falken 6 mm

Rear Left Side:

Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side:

Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 15/01/2020

Date Inspected: 16/01/2020

Inspected At:

Leng Wang Motor (HQ)

Blk 3007 Ubi Road 1, #01-414

Singapore 408701

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Scratched	0.00 F	*- F
2	1		*FRT BUMPER	Cut	0.00 F	*- F
3	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*FRT RH BUMPER FOG LAMP COVER	Scratched	0.00 F	*- F
5	1		*FRT GRILLE	Cracked	0.00 F	*- F
6	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
7	1		*FRT GRILLE CHROME MOULDING	Cracked	0.00 F	*- F
F=Franchise part.						
				<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >