Esteem Performance Pte Ltd 385 Sin Ming Drive, Vicom Vehicle Inspection Centre (575718)

Insurer Reference:

Repairer Reference: 026843

Date calculated: 14/01/2020 4:24 PM

Full Report Registration: SLG6061E Printed: 14/01/2020 4:24 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

AIG Asia Pacific Insurance

Pte Ltd

Printed by:

Claim Reference:

Estimated Repair Time: Actual Repair Days: Carmen SG

Currency:

Date of Incident:

SGD 11/01/20

Hire Car Start:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

Model:

Sub Model:

Model Sheet Number: Registration:

VIN number: Odometer: Model Specs

TWO COAT METALLIC

TOYOTA

PRIUS IV BASE MODEL


70 P5 01 SLG6061E

Vehicle Condition

Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas



La	bo	ur
Mar 4-4		•

	Time Base 10 WU/h	Pric	e = 50.	00 SGD/h
Code	Description		WU	Price SGD
043233	ALIGN VEHICLE CPL		12.0	60.00
043233F	ADD: ADJUST REAR TOE		2.0	10.00
B010	R + R FRONT BUMPER		6.0	30.00
B040)	R + R RIGHT HEADLAMP (BUMPER REMOVED)		1.0	5.00
NO NUMBER	DOES NOT INCLUDE: ADJUST HEADLAMP		2.0	10.00
NO NUMBER B110	ADJUST HEADLAMPS RENEW R/F WING		7.0	35.00
	(BUMPER AND HEADLAMP REMOVED) INCLUDES: R + R WING, CONVERT ATTACHED PARTS			
B210	RENEW R/F DOOR		30.0	150.00
B210	R + R RIGHT FRONT DOOR WINDOW FRAME SEAL		2.0	10.00
B100	R + R R/SILL TRIM		3.0	15.00
	Labour Cost	Hrs	WU	
	Panel / Mechanical Labour	5.10	51.0	255.00
	Alignment Measuring Work	1.40	14.0	70.00
	Total of Labour			325.00

Paint

Paint Work SYSTEM AZT		Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC	WU Price SGD	
	R/F WING NEW PART PAINTING RIGHT FRONT DOOR NEW PART PAINTING R/SILL PANELLING REPAIR PAINT PLASTIC	10.0 16.0 12.0	

Paint Material Per Part

Code	Description	Price SGD
0742	R/F WING NEW PART PAINTING	21.67
1482	RIGHT FRONT DOOR NEW PART PAINTING	44.89
2186	R/SILL PANELLING REPAIR PAINT PLASTIC	24.30

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	50.00 SGD/h			
Time Paint			38.0	
Preparation Main Work Metal		0.80	8.0	40.00
Preparation Comp. Work Plastic		2.10	21.0	105.00
Total	10 WU/h	6.70	67.0	335.00

Material Cost - Paint	Price SGD
New Part Painting	66.56
Repair Painting Plastic	24.30
Material-constant Metal	12.70
Material-constant Plastic	18.10
Total	121.66

Spare Parts

				prices as at 2015-06-01/01
Code	Description	Part Number	Supplier	Price SGD
0742	R/F WING	53801 47080		868.70
0812	R/F WING BADGE	75374 47140		44.17
0842	R/F WHEELHOUSE COVER	53875 47070		185.64
1482	RIGHT FRONT DOOR	67001 47152		1,226.70
1488	R/UPPER DOOR HINGE	68710 12151		78.34
1496	R/LOWER DOOR HINGE	68730 12120		78.34
1506	R/F DOOR CHECK	68610 47040		156.79
1510	R/F DOOR SEAL	67861 47050		198.49
1578	R/F DOOR LOCK	69030 47100		428.40
1598	R/F WINDOW CHANNEL	68141 47050		122.95
1002	RHF HUP CAP	RHF HUP CAP		195.65
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			3,584.17
u: Used parts	Subtotal Discount(-	+30.00%)		-1,075.25
	Total			2,508.92

Extras

ode Description	Price SGD
700 FENDER SHIELD CLIP RHF UNDERSHIELD	25.00*
701 TUFF COAT TUFF COAT	100.00*
70tal Extras	125.00

Final Calculation

rillal Calculation		
	SGD	SGD
Parts	3,584.17	
Total Discount(+30.00%)	-1,075.25	
Total Parts		2,508.92
Labour Time Base 10 WU/h		
Total 51.0 WU X 50.00 SGD/h Alignment	255.00	
Measuring Work	70.00	
Total of Labour	, 0, 0	325.00
Total Of Extras		125.00
Paint Work Time Base 10 WU/h		
Labour Cost 67.0 WU X 50.00 SGD/h	335.00	
Material Cost	121.66	
Total Paint Including Material		456.66
Repair Cost Excludes GST		3,415.58
GST (+7.0%)		239.09
Repair Cost Included GST		3,654.67

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as irruthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report

13/01/2020 12:50

Date Of Accident

11/01/2020 17:40

Exact Location Of Accident

ALONG ORCHARD LINK

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLG6061E

Insured/Policyholder

Name Of Registered Owner

GRAB RENTALS PTE LTD

Co Reg No

2XXXXX200G

Email Address

NOEMAIL

Mobile Phone No

Alternative Phone No

OFFICE-31388644

Vehicle Particulars

Manufacturer

TOYOTA

Model

PRIUS-1.8 HYBRID CVT (A)

Exact Purpose for which vehicle was being used at

time of accident

NO

Are you claiming under your own insurance policy for repair to your vehicle?

REPORTING ONLY

If No, Please state action to be taken

PRIVATE HIRE

Vehicle Category

Insurance Company Name of Insurance Company

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

YES

Policy Number

A29114756MKF

Cover Note Number

Driver

LIM GEE WAH Name of Driver SXXXX839Z NRIC No 01/02/1959 Date Of Birth OUTDOOR Occupation

Date Of Driving Pass

05/12/1977 42 YEARS AND 1 MONTH

Driving Experience

MALE

Mobile Number

(LOCAL) +65-96996839

Fax Number

Gender

Contact Number

EMail Address

NOEMAIL

Address

BLK 252 JURONG EAST ST 24 #03-157

Postcode

600252

Was driver an employee of the Insured's Company NO OTHER - LESSEE

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

NO Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: NOT APPLICABLE

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON 11/01/2020 AT AROUND 5:40PM, I WAS DRIVING MY CAR ON LANE 4 OF ORCHARD LINK TOWARDS NGEE ANN CITY WHEN VEHICLE B COLLIDED INTO THE RIGHT SIDE OF MY CAR WHILE HE WAS SHIFTING HIS CAR IN THE YELLOW BOX. MY CAR WAS MOVING STRAIGHT AHEAD AS THERE WAS AMPLE SPACE FOR MY CAR AFTER THE YELLOW BOX TO MOVE INTO. MY CAR SUSTAINED RIGHT SIDE DAMAGES. NO ONE WAS INJURED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SMG3251G

Vehicle Make/Model/Colour

ΚIΑ

Details Of Properties

VEH B

Vehicle Category Name of Driver

PRIVATE CAR MR TAN

NRIC/Passport Number

Contact Number

90288823

Address Postcode

Insurance Company Name

Page 2 of 21

Nature Of Damage No. Of Passenger (Including Driver) FRONT LEFT PORTION

1

Sketch Plan SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any folgo reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA flectords Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 8y the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available processed.
- S. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/ore permitted to collect, use, disclose and/or process my personal date/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or ogents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of froud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

18/01/2020 12.25 p.m.

Policyholder's Signature Date & Time: Orliver's Signature (If driver is not the policyholdor) Date & Time: Reporting Centre Personnel's Signature Name:

Näic/Fin No.:

