

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 14.01.2020

Time: 14:29:47

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305374483
REGN NO : SH 6105A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 05.11.2015
DATE/TIME IN : 14.01.2020 10:45
ACCIDENT DATE : 09.01.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1 L	1,052.20	20.00	841.76	cr
0002 04-01-0103-0637-G	I40V2 BRKT ASSY-FR BPR UP	1 L	22.40	20.00	17.92	xnn
0003 04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1 L	24.60	20.00	19.68	xnn
0004 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nel
0005 04-01-0103-2164-A	I40V3 GRILLE ASSY-RADIATO	1 L	1,110.10	20.00	888.08	scr
0006 04-01-0103-0781-A	I40V2 LAMP ASSY-HEAD LH#	1 L	693.80	20.00	555.04	scr
0007 04-01-0103-0574-G	I40VC PANEL-FENDER LH#	1 L	663.00	20.00	530.40	DD

SUB-TOTAL : 2,870.48

JOB NATURE

0000 L	FRT FENDER ADVERTISMENT LOGO LH
0001 L	PANEL BEATING
0002 23-502	SPRAYPAINT ON AFFECTED AREA
0003 17-01	CHECK ALL LIGHTING

100.00

600.00

450.00

50.00

\$400

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 14.01.2020

Time: 14:29:47

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305374483
REGN NO : SH 6105A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 05.11.2015
DATE/TIME IN : 14.01.2020 10:4
ACCIDENT DATE : 09.01.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0004 20-00 TUFF COAT ON AFFECTED PARTS.

50.00 \$30

SUB-TOTAL : 1,250.00

TOTAL : 4,120.48

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RAM (LKK)
14/1/2020 @ 1430WVS
Parasurama@lkkauto.com
88622728 (48)
ag repair photo
(3 repair bays)