

ASS. REC. BY:

REF: CS/CT1 20000980/Hf3ⁿ²

Special Instructions

Surveyor: marcus

ASSIGNMENT (Office)

From (Person): Ben King

of C11

Date/Time: 15.1.2020 6:50 p.m

~~Estimated Cost~~

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMR 951G

Insured: GBF 1432 Y

at Workshop m/s Zoom Auto works

Tel: 94507920

of 1300 Bedot Rosemary Road #08-1329

Policy No: DMCVSN30486719027

Claim No: SN M 20200021

Sum insured:

Process

Make of Veh

D.O.A. 4.1.2029

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endowment

Date/Time: 16-1-2020

9.08.04.14

Person Contacted: Eliw

Vehicle IN / OFF

Date/Time	Action/Instruction (✓) Estimate Inspection: BIK 15 karki Bukit Road 4 of 01-53
	SMR 95161-X
	GBF 14334-X

DEPT: WAF

ASS. REC. BY: *Morris*

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: *SMR 9516*
at Workshop mile *200m*

of
insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Ven:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *PO*

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: *5* days Res: Yes or No

Lum Sum: *20* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

LT A 49147

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: *SMR 9516* Yr Regn: *J 17*

Type: M/Cycle / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA /*

Make: *Audi Q2* C.C. *999*

Colour: *Red* A/C Insured / Std / NI / NA

Sp. Reading: *34105* T/Radio: Insured / Std / NI / NA

Eng No:

C/Nr: *WAUZZZGA 5JA 003887*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: *8* Jammed / Leaked / Burnt or

Brake: *8* Jammed / Leaked / Burnt or

Mod: *8* Nil / STD A/Rim or

Tyre Size: F:

R: *215/60R18*

SS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: *7* mm R/Bal: *7* mm

L/Bal: *7* mm L/Bal: *7* mm

D.O.A. D.O.A. *15/1/20*

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/2/20 4/5 \$6000 Confirmed with Elin (Rld: 9194.89: 60%)

RECEIVED 26 FEB 2020

Date/Time: File Pass to?

☐ : Prell. Report

1) *26/2 Typst*

☒ : Final Report

Date/Time: File Return to?

2)

Days Of Repair: *5*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

\$ - RS - \$

Photos

Other

Add Fee:

☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: *TP*

Lump Sum *6000* / I.B.I. (\$

TOTAL

220

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Wednesday, 15 January 2020 6:50 PM
To: assignments@lkkauto.com
Subject: FW: OUR REF: SNM20D200081/GBF1433Y/BEN - PRS SMR 951 G // Accident on 04/01/2020 @ 11:30HR at along Liang Seah Street involving Vehicle Number SMR 951 G & GBF 1433 Y

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SMR951G.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Zoom Autowerks <zoomautowerks@gmail.com>
Sent: Monday, January 13, 2020 10:59 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200081/GBF1433Y/BEN - PRS SMR 951 G // Accident on 04/01/2020 @ 11:30HR at along Liang Seah Street involving Vehicle Number SMR 951 G & GBF 1433 Y

Dear All,

Kindly arrange Marcus Chua for the survey.

Warmest Regards,
Elin Cai

Zoom Autowerks Pte Ltd
130 Bedok Reservoir Road
#08-1339 Singapore 470130
☎9450 7920
✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

On Mon, Jan 13, 2020 at 5:27 PM Ben Tang <Ben.Tang@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 12 January 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, January 13, 2020 5:15 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; zoomautowerks@gmail.com
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: SNM20D200081/GBF1433Y/BEN - PRS SMR 951 G // Accident on 04/01/2020 @ 11:30HR at along Liang Seah Street involving Vehicle Number SMR 951 G & GBF 1433 Y

Dear Ben,

Please conduct PRS for SMR951G.

Note : officer in charge – Ben Tang 63896175.

**** Kindly quote our reference number when replying.*

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID (65) 63896116 | F (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Zoom Autowerks <zoomautowerks@gmail.com>

Sent: Sunday, January 12, 2020 10:18 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Pre-Repair Inspection for SMR 951 G // Accident on 04/01/2020 @ 11:30HR at along Liang Seah Street involving Vehicle Number SMR 951 G & GBF 1433 Y

Dear Sir/Madam,

We are instructed by Foo Lily to notify you of a road traffic accident on 04
/01/2020

at about 11:30HR at along Liang Seah Street involving our client's vehicle registration number SMR 951 G and vehicle registration number GBF 1433 Y driven by your insured at the material time.

A copy of the Singapore Accident Statement/Traffic Police Report filed is enclosed. As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated time, our client shall proceed to repair the vehicle without further reference to you.

Please contact me @ 9450 7920, should you require more information.

Kindly arrange survey at Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 4178

08.

Warmest Regards,

Elin Cai

Zoom Autowerks Pte Ltd

130 Bedok Reservoir Road

#08-1339 Singapore 470130

☎9450 7920

✉zoomautowerks@gmail.com

- Please note our change in mailing/registered address with effect from 1st July 2018 -

CITROËN
WAREHOUSE SALE



FROM \$85,000*
BOOK NOW

Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an AdAdvertiser LoginWays of Selling

New 5 Years Renewal COE Toyota Wish 2.0A.



2.000L P&A 5 Doors Monthly \$588. 7 Years Warranty Engine And Gearbox. GV Credit

PRIME MOTOR & 

JOHNSON YONG CREDIT ENTERPRISES PTE LTD. GRC

With over 200 units of vehicles to choose from, ranging from all European to Japanese Makes.

Sort by Date Posted

Choose by Category

3 vehicles

q2

Advanced Search

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	q2	Any	Any	2017	Any	Any	Any
	Audi Q2 1.0A TFSI S-tronic	\$81,800	\$9,940 /yr	29-May-2017	999 cc	85,000 km	SUV
Fully Agent Service Since Day 1, No Repairs Needed. 100% Accident Free, High Trade In, Lowest Interest Rate, Call Our Sales Person Now.							
Hua Yang Credit Pte Ltd							
Posted: 06-Feb-2020 Tags: 2017 Audi Q2, 2017 audi q2, Audi Q2, audi q2, Audi, Q2, q2, Used Audi							
	Audi Q2 1.0A TFSI S-tronic	\$88,800	\$10,160 /yr	28-Nov-2017	999 cc	28,000 km	SUV
Only One Owner. Almost New Audi Q2 Fully Maintained By Premium Automobiles With 5 Years Warranty And 5 Years Free Servicing. Interior And Exterior All Well Maintained And Like New, 100% Accident-Free. 95% In House And Bank Loan Of The Car Price Available...							
Posted: 01-Feb-2020 Tags: 2017 Audi Q2, 2017 audi q2, Audi Q2, audi q2, Audi, Q2, q2, Used Audi							
	Audi Q2 1.0A TFSI S-tronic	\$96,000	\$11,240 /yr	25-Oct-2017	999 cc	37,000 km	SUV
First Owner, Interest Rate 2.48% Only! Agent Unit 5 Years Warranty 3 Years Servicing, Secured And Well Maintained By Fussy Owner. Immaculate Condition Inside And Outside. Give Yourself A Peace Of Mind! Buy It From Us! A Company With Professional Sales Serviced...							
Car Search							
Posted: 10-Jan-2020 Tags: 2017 Audi Q2, 2017 audi q2, Audi Q2, audi q2, Audi, Q2, q2, Used Audi							

Save this search criteria, to get email alerts whenever a match is found.

MakeModelPriceDepreciationReg DateEng CapMileageVeh Type

20

For old advertisements, view Expired ads

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	122A
Vehicle Details	
Vehicle No.:	SMR951G
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2020
Vehicle Make:	AUDI
Vehicle Model:	Q2 1.0 TFSI S TRONIC
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	CHZ501621
Chassis No.:	WAUZZZGA5JA003887
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$26,192.00
Original Registration Date:	16 Aug 2017
First Registration Date:	16 Aug 2017
Transfer Count:	1
Actual ARF Paid:	\$18,669.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Aug 2027
PARF Rebate Amount:	\$14,001.00
Intended COE Rebate Details	
COE Expiry Date:	15 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,778.00
COE Rebate Amount:	\$35,146.00
Total Rebate Amount:	\$49,147.00

The information contained herein is correct as at 10 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	06/01/2020 08:59
Date Of Accident	04/01/2020 11:30
Exact Location Of Accident	25 LIANG SEAH STREET
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SMR951G
Insured/Policyholder	
Name Of Registered Owner	FOO LILY
NRIC No	SXXXX122A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88221319
Alternative Phone No	OTHERS-88221319
Vehicle Particulars	
Manufacturer	AUDI
Model	Q2 1.0 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA520771/1
Cover Note Number	
Driver	
Name of Driver	FOO JAMIE
NRIC No	SXXXX487E
Date Of Birth	01/12/1998
Occupation	INDOOR
Date Of Driving Pass	10/09/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88221319
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	2 MARGATE ROAD #06-00 SPORE 438042
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	RELATIVE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF1433Y
Vehicle Make/Model/Colour	TOYOTA / HIACE DX 3.0 M
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may cause insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIC Records Management Centre established by the Criminal Injuries Compensation Authority (CICA) for Archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report at the centre and for copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
 - a. I, the Insured, do hereby acknowledge, agree and consent that:
 - (i) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and manage such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (a) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (b) investigating the accident and/or my claims;
 - (c) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (d) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me for the above delivery of the same as well as to the external cover of envelopes/mail packages); and/or
 - (e) complying with applicable law in administering, processing, handling and/or dealing with my claims to achieve the "Purposes".
 - (ii) My insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes and;
 - (iii) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or subcontracting their lawyers/law firms, which may be used outside of Singapore, for one or more of the above Purposes;
 - (iv) my Personal Information will not be collected and used to compile claims history for the purpose of fraud detection, monitoring and management in present and all future claims;
 - (v) the information so collected under (i) above may be shared / disclosed:
 - (a) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulation, law enforcement and government agencies as reasonably required for the purposes stated, or;
 - (b) for complying with requirements under any regulations, laws or court orders.

Insured's Signature

Date & Time

Driver's Signature

OR (to be filled in by the policyholder)

Date & Time

Representing Insurer's Lawyer/Law Firm's Signature

Name: *S. Lim*


NRIC: *9901 1111 1111*

Sketch Plan #2

SKETCH PLAN

Vehicle A: SMR9516

Vehicle B: GBF1433Y



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date & time, I, vehicle 'A', SMR9516 was travelling straight along the stated venue. Vehicle 'B', GBF1433Y, suddenly reversed and hit into my vehicle's rear left portion.

DECLARATION

I declare that the foregoing particulars are true in every respect.

Witness's Signature
(not to fill)

Driver's Signature
(If driver is not the police officer)
(date & time)

Reporting Officer's Signature
Name: J. L. M.
(date & time)



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SMR951G

Model: AUDI Q2 1.0 TFSI S Tronic

Date: 16/01/2020

Damaged Area: (Rear Left Portion Damaged)

Repairer Estimation Cost of Repair: WAU XXXX GAS

Supplementary may be included during the cost of repair:

Parts / Material :

- 1 Rear Bumper 1245
- 2 Rear Bumper Lower 399
- 3 Rear Bumper Lamp LH
- 4 Rear Bumper Left Retainer
- 5 Rear Bumper Left Bracket
- 6 Rear Bumper Sponge
- 7 Rear Bumper Reinforcement
- 8 Rear Bumper Clips
- 9 Rear Left Taillamp
- 10 Rear Left Fender
- 11 Rear Left Fender Inner Shield
- 12 Rear Left Fender Inner Shield Clips
- 13 Rear Left Fender Arc-Garnish
- 14 Rear Left Fender Arc-Garnish Clips
- 15 Left Rocker Garnish
- 16 Left Rocker Garnish Clips
- 17 Rear Left Door
- 18 Rear Left Door Outer Handle Garnish
- 19 Rear Left Door Weather Strip
- 20 Rear Left Door Tape
- 21 Rear Left Door Inner Trimboard Garnish Clips
- 22 Rear Left Wheel

Quantity

Qty	\$ 70.1	1,620.30	
	\$ 50.0	455.30	
	\$ 11	245.30	X
	\$ 11	114.00	X
	\$ 11	44.00	X
	\$ 11	368.20	X
	\$ 11	547.00	X
	\$ 11	60.00	
	\$ 11	733.30	X
	\$ 11	1,208.30	
	\$ 11	425.30	X
	\$ 11	60.00	X
	\$ 11	316.20	
	\$ 11	60.00	X
	\$ 11	786.20	X
	\$ 11	60.00	X
	\$ 11	1,602.30	
	\$ 11	480.00	X
	\$ 11	222.30	
	\$ 11	198.20	X
	\$ 11	60.00	X
	\$ 11	1,160.00	

Parts : \$ 10,826.20

Less 5% \$ 541.31

Total Parts : \$ 10,284.89

Special Net Items :

- Rear Left Tyre
Rear Quarter Glass Sealant

\$ 11 480.00 X
\$ 11 80.00 X

Total S/N Parts : \$ 560.00

- To Remove & Renew Affected Accident Areas
To Putty, Spray Paint on Affected Accident Areas
To Check & Re-Connect all electrical wiring
To Remove & Install Rear Left Quarter Glass
To Remove Seat, Carpet, Trims to assist Repairs
To Re-position & Install Reverse Sensor
To Conduct All Wheel Computerised Alignment
To Re-Programme & Reset Diagnostic
To Rust Proof Affected Areas

\$ 1,600.00 800
\$ 1,400.00 800
\$ 50.00 20
\$ 11 150.00 X
\$ 200.00 80
\$ 150.00 50
\$ 250.00 60
\$ 11 450.00 X
\$ 100.00 60

Total Labour : \$ 4,350.00

P-5053.10
57
4800.44
7500.44

TOTAL \$ 15,194.89

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20000980/UTF3N2
Date: 27/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30486719022
Claimant Vehicle No: SMR951G Insured Vehicle No: GBF1433Y
Date of Loss: 04/01/2020 Nature of Claim: TP Claim No: SNM20D200081

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMR951G
Make & Model: AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) Engine No: CHZ501621
Reg. Date: 16/08/2017 (Man. Year: 2017) Chassis No: WAUZZZGA5JA003887
Colour: Red Odometer: 34105 km
Engine Capacity: 999 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm
Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,844.89	5,680.44	5,164.45	47.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,350.00	1,870.00	2,480.00	57.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,194.89	7,550.44	7,644.45	50.31
Approved Total (Overridden) (S\$)		6,000.00		
Nett Amount (S\$)	15,194.89	6,000.00	9,194.89	60.51

INSPECTION

Date of Assignment: 26/02/2020
Date Inspected: 15/01/2020 Inspected At: BLK 15 KAKI BUKIT BROAD 4 ,
REPAIRER: ZOOM AUTOWERKS PTE LTD
Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 27 Feb 2020)		
Parts:	N/A	AUDI Q2 999cc 1.0 TFSI S TRONIC (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMR951G)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cut/Torn	1,620.30 FL	*1,245.00 FL
2	1		*REAR BUMPER LOWER	Grazed	455.30 FL	*399.00 FL
3	1		*REAR BUMPER LAMP LH	Not Necessary	245.30 FL	*- FL
4	1		*REAR BUMPER LEFT RETAINER	Not Necessary	114.00 FL	*- FL
5	1		*REAR BUMPER LEFT BRACKET	Not Necessary	44.00 FL	*- FL
6	1		*REAR BUMPER SPONGE	Not Necessary	368.20 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Not Necessary	547.00 FL	*- FL
8	1		*REAR BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
9	1		*REAR LEFT TAILLAMP	Not Necessary	733.30 FL	*- FL
10	1		*REAR LEFT FENDER	Badly Dented	1,208.30 FL	*1,208.30 FL
11	1		*REAR LEFT FENDER INNER SHIELD	Not Necessary	425.30 FL	*- FL
12	1		*REAR LEFT FENDER INNER SHIELD CLIPS	Not Necessary	60.00 FL	*- FL
13	1		*REAR LEFT FENDER ARC-GARNISH	Grazed	316.20 FL	*316.20 FL
14	1		*REAR LEFT FENDER ARC-GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
15	1		*LEFT ROCKER GARNISH	Not Necessary	786.20 FL	*- FL
16	1		*LEFT ROCKER GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
17	1		*REAR LEFT DOOR	Dented/Bent	1,602.30 FL	*1,602.30 FL
18	1		*REAR LEFT DOOR OUTER HANDLE GARNISH	Not Necessary	480.00 FL	*- FL
19	1		*REAR LEFT DOOR WEATHER STRIP	Necessary	222.30 FL	*222.30 FL
20	1		*REAR LEFT DOOR TAPE	Not Necessary	198.20 FL	*- FL
21	1		*REAR LEFT DOOR INNER TRIMBOARD GARNISH CLIPS	Not Necessary	60.00 FL	*- FL
22	1		*REAR LEFT WHEEL	Dented/Bent	1,102.00 FS	*880.00 FS
23	1		*REAR LEFT TYRE	Not Necessary	480.00 FS	*- FS
24	1		*REAR QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpchNett. L=ListItemDisc.

Sub Total (\$\$)	11,328.20	5,933.10
- List Item Discount on L Items 5.00/5.00% (\$\$)	483.31	252.66
Total Parts (\$\$)	10,844.89	5,680.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & RENEW AFFECTED ACCIDENT AREAS	New	1,600.00	800.00
2	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS	New	1,400.00	800.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	20.00
4	TO REMOVE & INSTALL REAR LEFT QUARTER GLASS	New	150.00	0.00
5	TO REMOVE SEAT,CARPET,TRIMS TO ASSIST REPAIRS	New	200.00	80.00
6	TO RE-POSITION & INSTALL REVERSE SENSOR	New	150.00	50.00
7	TO CONDUCT ALL WHEEL COMPUTERISED ALIGNMENT	New	250.00	60.00
8	TO RE-PROGRAMME & RESET DIAGNOSTIC	New	450.00	0.00
9	TO RUST PROOF AFFECTED AREAS	New	100.00	60.00
Gross Labour Cost (\$\$)			4,350.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >