

Surveyor

REF: CS1/SPF20000994/^FVf332

Special Instruction:

4Sum: \$4350.00

From (Person): Hafizul Farhan of SPF
Estimated Cost: Bill to: Date/Time: 16.1.2020 10:55AM

ASSIGNMENT (Office)

Third Parties:

Claimant:

Surveyor: Vicom Assessment Centre

Workshop: Comfortdelgro

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SHA 6558T

Insured: GBF 2758D

at Workshop m/s Comfortdelgro
of 59 Layang Drive

Tel:

Policy No:

Claim No: AEMD/105/009/2019/085

Sum Insured:

Excess:

Make of Veh:

D.O.A. 08/08/2019


(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig , days (Red \$ / %; Original 3 days)

Date/Time: 17/1/2020 Submit Final Fig LS 4250 , 3 days (Red \$ 100 / 2 %; Original days)

Date/Time	Action/Instruction
	SHA 6558T - CS / PCT 17005/62/1216m2 D.O.A - 11/07/2017
	GBF 2758D - X
	upper range: \$4200-\$4500
	③ repair days
	 20/1/2020

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 20 JAN 2020

Do Not Finalise

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

200

1) Date/Time 20.1.2020 File Pass to

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to

Nivitha (LKK Auto)

From: Hafizul Farhan RAHMAT (SPF) <Hafizul_Farhan_RAHMAT@spf.gov.sg>
Sent: Thursday, 16 January 2020 10:55 AM
To: Admin-D (LKKAuto); assignments
Cc: Cui Fen ENG (SPF); Frankie THAY (SPF); Olivia Lau (LKKAuto)
Subject: Post Survey for SHA6558T (vs GBF2758D)
Attachments: VICOM 2019-085.pdf

Our ref: AEMD/105/009/2019/085

Hi,

Kindly do a paper survey on **SHA6558T** (vs GBF2758D).

Thank you.

Best Regards,

Hafizul Farhan Bin Rahmat

AEMD / PLD

Singapore Police Force

DID: (65) 6478 4840 | FAX: (65) 6478 4850



HOME TEAM
TRANSFORMATION 2025
One Home, One Team
Building Our Future Together

WARNING: This e-mail contains confidential information and may be monitored in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance on the contents. Communication of any information in this e-mail to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender if you receive this in error.



VICOM LTD

385 Sin Ming Drive Singapore 575718

Marline (65) 6458 4555
Facsimile (65) 6458 1040

www.vicom.com.sg
Company Registration No. 108100206

TAX INVOICE

COMFORTDELGRO ENGINEERING PTE LTD
#205 Braddell Road
Blk C Ext 1 3rd Level
Singapore 579701

ATTN : MOTOR CLAIMS DEPT.

VEHICLE No. : SHA6558T
ACCIDENT DATE : 08/08/2019
CLAIM No. : 305323749
INSURED VEH No: GBF2758D

GST REG No. : M9-0000652-A
CUSTOMER ID : VACC0013
INVOICE No. : CL021796
INVOICE DATE : 16/08/2019
PAYMENT TERM : 30 Days Credit

DESCRIPTION	QTY	UNIT PRICE (SG\$)	AMOUNT (SG\$)
Photographs	15	1.00	\$ 15.00
Transportation	1	50.00	\$ 50.00
VAC Assessment Fee	1	185.00	\$ 185.00

REMARKS	GROSS AMOUNT	\$	250.00
CTPL	GST @ 7%	\$	17.50
	INVOICE AMOUNT	\$	267.50

This is a computer generated TAX INVOICE

No signature required

Cheque should be made payable to 'VICOM LTD'.

Sin Ming

385 Sin Ming Drive Singapore 575718
Tel: (65) 6458 4555 Fax: (65) 6458 1040

Bukit Batok

511 Bukit Batok St 21 Singapore 659545
Tel: (65) 6560 3312 Fax: (65) 6569 0722

Kaki Bukit

23 Kaki Bukit Ave 4 Singapore 415933
Tel: (65) 6741 6697 Fax: (65) 6749 2305

COMFORTDELGRO ENGINEERING PTE LTD
 #205 Braddell Road
 Blk C Ext 1 3rd Level
 Singapore 579701



VICOM LTD
 385 Sin Ming Drive Singapore 575718

Marline (65) 6458 4555
 Facsimile (65) 6458 1040

www.vicom.com.sg
 Company Registration No: 198100320K

SURVEY REPORT

GENERAL INFORMATION			
VAC Ref. No.	: 547706	Claim No.	: 305323749
Accident Date	: 08/08/2019	Claim Type	: THIRD PARTY
Assignment Date	: 14/08/2019	Policy No.	:
Survey Date	: 14/08/2019	Finalised Dt.	: 16/08/2019
Survey Report Date	: 16/08/2019		
VEHICLE PARTICULARS			
Vehicle No.	: SHA6558T	Chassis No.	: WDD2120022A758311
Registration Date	: 04/07/2013	Engine No.	: 65192431515661
Make	: MERCEDES BENZ	Engine Cap.	: 2143 CC
Model	: E 220 CDI BLUEEFFICI	Transmission	: AUTOMATIC
		Colour	: WHITE
CONDITION OF VEHICLE DURING SURVEY (VISUAL and STATIC TEST ONLY)			
Foot Brake	: SERVICEABLE	Steering	: SERVICEABLE
Hand Brake	: SERVICEABLE	Modification	: NONE
Mileage	: 940295		
<u>TYRES</u>	<u>SIZE</u>	<u>MAKE</u>	<u>BALANCE (mm)</u>
FRONT RH	205/60R16	WESTLAKE	6
FRONT LH	205/60R16	WESTLAKE	6
REAR RH	205/60R16	WESTLAKE	6
REAR LH	205/60R16	WESTLAKE	6
SURVEY CONDUCTED AT			
59 Loyang Drive Singapore 508969			
REMARKS			
[1] Workshop Estimate : S\$ 6,188.00			
[2] Our Adjustment : S\$ 4,350.00			
[3] Repair Period : 3 days			
[4] We have not authorised repairs. This survey was carried out on without prejudice basis.			

SURVEY REPORT

Annex A: Adjustment on Spare Parts

#	Qty	Vehicle Parts Description	Condition	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	1	Door Sheel.Frt/Lh 00 ✓	Dent	2970.00	2970.00
2	1	Mirror Glass.Frt/Lh Br ✓	Broken	380.00	380.00
3	1	Mirror Cover Frt/Lh m15 ✓	Missing	350.00	350.00
4	1	Mirror Housing W/Signal Lamp, Frt/Lh m15 ✓	Missing	890.00	890.00
5	1	Mirror Motor Assy. Frt/Lh 0m ✓	Malfunction	920.00	920.00
			Subtotal	: 5510.00	5510.00
			Less 20 %	1102.00	1102.00
			TOTAL	: 4408.00	4408.00 ✓
NETT ITEM					
1	1	Rear Door Comfortdelgro Limo Cab Logonec ✓	Necessary	60.00	60.00
			Subtotal	: 60.00	60.00
			Less 0 %	0.00	0.00
			TOTAL	: 60.00	60.00 ✓
TOTAL FOR SPARE PARTS				: 4468.00	4468.00

VICOM LTD
SURVEY REPORT

SHA6558T @ 08/08/2019

Annex B: Adjustment on Labour and Spray Painting

#	Job Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
1	Panel beating	800.00	400.00 \$360
2	Spray painting charge	700.00	480.00 \$400
3	Wiring charge	50.00	20.00 ✓
4	Tuff kote	50.00	20.00 ✓
5	Transfer of door	120.00	60.00 ✓
TOTAL FOR LABOUR AND SPRAY PAINTING		1720.00	980.00

Summary

Description	Workshop Estimate (S\$)	VAC Adjustment (S\$)
TOTAL FOR SPARE PARTS	4468.00	4468.00
TOTAL FOR LABOUR AND SPRAY PAINTING	1720.00	980.00
TOTAL REPAIR COST	6188.00	5448.00

\$5328

aft 20% L/S: \$4250/=

③ repair days

VICOM LTD
SURVEY REPORT

SHA6558T @ 08/08/2019

Annex C: Conclusion

ASSESSOR'S REPORT

At the place of inspection, we saw this vehicle sustained left hand side damage.

The damages seen during our survey were frt lh door, rear lh door, frt lh side mirror assy and surrounding areas. A fuller detailed description of the damages is in Annex A of this survey report.

ASSESSOR'S RECOMMENDATION

Comfortdelgro Engineering Pte Ltd (Loyang) estimated a repair cost of S\$6,188.00. We adjusted it to S\$5,448.00.

Accordingly, we recommend repairs to this vehicle be carried out on a lumpsum basis at S\$4,350.00.

The repairs would require a period of 3 working days.



Thanaraj Krishnasamy
for VICOM Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 6558T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOOR SHEEL, FRT/LH	DENTED	2,970.00	2,970.00
1	MIRROR GLASS, FRT/LH	BROKEN	380.00	380.00
1	MIRROR COVER FRT/LH	MISSING	350.00	350.00
1	MIRROR HOUSING W/SIGNAL LAMP, FRT/LH	MISSING	890.00	890.00
1	MIRROR MOTOR ASSY, FRT/LH	DENTED	920.00	920.00
	LESS 20% DISCOUNT		-1,102.00	-1,102.00
			4,408.00	4,408.00
<u>SPECIAL NETT ITEMS</u>				
1	REAR DOOR COMFORTDELGRO (SN)	NECESSARY	60.00	60.00
			60.00	60.00
<u>LABOUR</u>				
	PANEL BEATING.		800.00	360.00
	SPRAY PAINTING CHARGE.		700.00	400.00
	WIRING CHARGE.		50.00	20.00
	TUFF KOTE.		50.00	20.00
	TRANSFER OF DOOR.		120.00	60.00
			1,720.00	860.00
GRAND TOTAL			6,188.00	5,328.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,250.00

Report Ref No. CS1/SPF20000994/Fvf3s2

THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$4,200.00 - \$4,500.00

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.