

ASS. REC. BY:

REF: CS3/AIG2000/018/Ggd302 Special Instruction:

Summary: GUO CHANGASSIGNMENT (Office)From (Person): Winnie Fan of AIG Date/Time: 16/01/2020 @ 9.35am

Estimated Cost: _____ Bill to: _____

OD TP WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBA 8706R Insured: GBJ 6451Rat Workshop in/s Ann Joo Motor Tel: 6455 0747of Blk 176 Sin Ming Drive # 01-17Policy No: 1900114062 Claim No: 1741786738SG

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 10/01/2020
(Client's Record)CA / REV / REP. / REV 24 HRS ^{1wp} H.O.D. Endorsement: _____Date/Time: 9.58am @ 16/1/2020 Person Contacted: Yiwen Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Johny (x)</u>
	<u>GBA 8706R - X</u>
	<u>GBJ 6451R - CS/CTI 190/4634 / A/F302</u>
<u>23/2/20</u>	<u>Submit DAR.</u>
	<u>Dismantle summary: 14/2/20</u>
	<u>After print: 14/2/20</u>

DOA: 20/2/2019

ASSIGNMENT

(-2023)

PRS

From

Date:

10/01/2020

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

GBA 8706R

at Workshop no/s

Ann Joo Motor

at

Blk 176 S in Ming Drive #01-17

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

2:30pm - 3:30pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

\$19k.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Turn Som:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

(up)

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBA 8706R

Vr Regn:

04 Mar 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Nissan cabstar

2953

Colour:

silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

396637

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JNISC 2F2480 800049

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S / Rim / STD A/Rim or

Tyre Size:

F:

195 R 15 (Journey)

R:

165 R 13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

D.O.I.

16-01-20

Survey held at

w/s

3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Cot: 12568

RECEIVED 24 MAR 2020

Date/Time, File Pass to/



Preli. Report

24/3 12:15



Final Report

Date/Time, File Return to/

3

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:



Site Insp (\$



Interview (\$



Tech Insp (\$



Workshop (\$

Survey Fee:

180

Transportation:

S + RS: \$

Phone:

Other:

11

Total:

191

Report Format:

MER-PAP

Long Form / Short Form

Nivitha (LKK Auto)

From: Fan, Winnie-LW <Winnie-LW.Fan@aig.com>
Sent: Thursday, 16 January 2020 9:35 AM
To: Admin A; assignments
Cc: Fong, Andy-SY
Subject: Aigencypt #1741786738SG003#027# FW: Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBJ6451R AND GBA8706R ON 10/01/2020

Hi LKK,

Kindly assist to survey between 2.30 – 3.30pm today, thanks.

Name of Workshop : Ann Joo Motor Pte Ltd
Address : Blk 176 Sin Ming Drive #01-17
Sin Ming Autocare Singapore 575721
Telephone No : 64550747
Contact person : Yiwen

Winnie Fan
AIG
Claims Service Associate
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120

winnie-lw.fan@aig.com | www.aig.sg

IMPORTANT NOTICE

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or retransmissions. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer systems to which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: cindykoh_kkcheng@yahoo.com <cindykoh_kkcheng@yahoo.com>
Sent: Tuesday, January 14, 2020 12:46 PM
To: Hor, Yinrul <Yinrul.Hor@aig.com>
Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Azlan, Syazairdina <Syazairdina.Azlan@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Hor, Yinrul <Yinrul.Hor@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Parthiban, Theerthan <Theerthan.Parthiban@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; singa_annjoo@singnet.com.sg
Subject: [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBJ6451R AND GBA8706R ON 10/01/2020

This message is from an external sender; be cautious with links and attachments.

Our Ref: AJ/GBA 8706R

Your Ref: GBJ 6421R

(Please quote our reference number when replying)

14 January 2020

AIG ASIA PACIFIC
Singapore

Attention: Motor Claims Department

Dear Sirs

NOTICE OF ACCIDENT

Claimant: LIAN YUAN

Pre-action Protocol for Non-injury Motor Accident Cases involving motor accident occurring on or after 1st April 2016 ["Protocol"]

We refer to your letter dated 14 January 2020.

Firstly, we object to the appointment of any of the motor surveyors proposed by in your List as a single joint expert. We have already stated this at para 4 of our Notice of Accident dated 13 January 2020.

Secondly, we have also given you our proposed list of proposed motor surveyors at para 4 of our Notice of Accident dated 13 January 2020.

Thirdly, if you object to our proposed list of proposed motor surveyors, this matter shall proceed on the basis of para 2.9 of the Protocol. Accordingly, our client shall appoint a surveyor of his choice to conduct the pre-repair survey. And our client shall have his motor vehicle repaired after the pre-repair survey had been done by your appointed surveyor.

Fourthly, for the sake of clarity, we do not agree to your appointed surveyor conducting the Pre-Repair Survey as the single joint expert.

If you wish to conduct a post-repair inspection, please instruct your appointed surveyor to inform our client's repairer of the same during the pre-repair survey.

Finally, the location and contact person of the workshop are as follows:-

Name of Workshop : Ann Joo Motor Pte Ltd
Address : Blk 176 Sin Ming Drive #01-17
Sin Ming Autocare Singapore 575721
Telephone No : 64550747
Contact person : Yiwen

REGARDS
CINDY
KK CHENG AND CO
DID :62271272

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Details**

Owner ID Type:	Business
Owner ID:	245E

Vehicle Details

Vehicle No.:	GBA8706R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	ZD30161974K
Chassis No.:	JN15C2F24Z0800049
Maximum Power Output:	-
Open Market Value:	\$24,958.00
Original Registration Date:	04 Mar 2008
First Registration Date:	04 Mar 2008
Transfer Count:	1
Actual ARF Paid:	\$1,248.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	03 Mar 2023
COE Category:	E - Open Category
COE Period(Years):	5
PQP Paid:	\$20,115.00
COE Rebate Amount:	\$12,568.00
Total Rebate Amount:	\$12,568.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 17 Jan 2020

► Cabstar Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Nissan Cabstar (COE till 03/2020) (Diesel)	\$2,300	-	10-Mar-2001	3,153 cc	-		Available
Date Of Registration : 10 March 2001. Lifespan Of Lorry: 9 March 2021. Date Of COE Expired: 31 March 2020, You Got To Renew A 5 Year COE At About \$13000. Use For 1 Year, Scrap The Lorry In In March 20...							
Office No. - - Vito Su - 97999591							
Nissan Cabstar (COE till 10/2024) (Diesel)	\$18,500	\$4,010 /yr	13-May-2005	3,153 cc	-		Available
5 Years COE Till 31 Oct 2024 Seldom Used. Good Condition. Perfect For Delivery! Suitable For ETS (Early Turnover Scheme).							
Office No. - - Alven Lee - 91333979							
Nissan Cabstar (COE till 04/2020) (Diesel)	\$18,800	-	25-May-2005	3,153 cc	-	Thiam Heng Motor	Available
Good Condition, New 5 Year COE. Low Deposit, In House Loan Available.							
Office No. - 64695691 Johnny Yeo - 98558158 Chuan - 81833939 Anthony Toh - 96849282							
Nissan Cabstar (COE till 04/2023) (Diesel)	\$18,800	\$6,070 /yr	28-Apr-2008	2,953 cc	-		Available
Call For Viewing.							
Office No. - - Christina - 96729488							
Nissan Cabstar (COE till 07/2027) (Diesel)	\$44,800	\$6,090 /yr	12-May-2008	2,953 cc	-	Net Link Partners Pte Ltd	Available
Worth Buying In Market! Yearly Depreciation Only \$6k! Engine Gearbox Condition Tip Top! New Paintwork! Full Canopy! 2 Weeks Warranty! High Loan High Trade In! Nice And Clean Interior! Call Us Now To A...							
Office No. - 67531661 Teo - 92967266 Peter - 84898866 Ken - 82227114							
Nissan Cabstar (COE till 08/2023) (Diesel)	\$19,800	\$5,780 /yr	26-Aug-2008	2,953 cc	-	SG Motor Link Pte Ltd	Available
Nice Double Digit Number Plate, Rare With Tailgate With Box, Low Mileage, All Working Condition, Call Fast To Test Drive Before Its Sold.							
Office No. - 62508527 Cs - 86682223 Yk Ong - 90260360 Jay Lee - 88693466							
Nissan Cabstar (COE till 11/2023) (Diesel)	-	-	06-Nov-2008	2,953 cc	-		Available
Standard 10ft High Moving Box Lorry, Selling Due To No Use. Just Passed Inspection! Road Tax Free For 6 Months. Cheapest In The Market.							
Office No. - - Lee - 93844381							
Nissan Cabstar (COE till 03/2024) (Diesel)	\$15,800	\$3,960 /yr	20-Mar-2009	2,953 cc	-	Top Carz	Available
Ideal For Catering Delivery With Close Box And Stainless Steel Interior, Very Well Kept By Owner, No Repair Needed Or Oil Leak, 6 x New Tyres, Welcome Inspection, Selling Near Paper And Body, Low Risk...							
Office No. - 66849979 Sim - 96212987 Kim Hock - 97887307 Thomas Tan - 93839533							
Nissan Cabstar (COE till 05/2029) (Diesel)	\$32,999	\$3,600 /yr	26-May-2009	2,953 cc	267,762 km		Available
-							
Office No. - - Tan Chee Seng - 97950230							
Nissan Cabstar (COE till 05/2024) (Diesel)	\$19,800	\$4,740 /yr	27-May-2009	2,953 cc	-	SG Motor Link Pte Ltd	Available

Cheap And Value For Business, Good Condition, New Paintwork, Come With Full Canopy, High Loan Low Interest, Trade In Welcome, Call Us For More Information.

Office No. - 62508527

Nikki - 83146959 | Jess - 91147113 | Jerry Tan - 90723112 | Ben - 91122958

Nissan Cabstar (COE till 05/2024) (Diesel)	\$26,800	\$6,390 /yr	01-Jun-2009	2,953 cc	-	I-Deal Auto Trading Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	----------	------------------------------------	------------------

Well Maintained By Previous Owner. Engine And Gearbox In Good Condition. Freezer Truck That Your Business Needed, Loan And Trade-In Welcome. Call Us Now For An Appointment. Don't Miss It.

Office No. - 62659969

Calvin Tan - 91339311 | Tan Zhi Ren - 91266111 | Stephen Tan - 91868299

Nissan Cabstar (COE till 05/2024) (Diesel)	\$22,800	\$5,440 /yr	16-Jul-2009	2,953 cc	-	Hui Hua Credit Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	----------	-------------------------------	------------------

Nissan Cabstar With 5 Years COE For Sale. In House Loan Available.

Office No. - 64646611

Weisley - 84888000 | Jevon - 88588388 | Jian Rong - 91830337 | Joey Ng - 88110091

Nissan Cabstar (COE till 04/2024) (Diesel)	\$17,800	\$4,330 /yr	31-Jul-2009	2,953 cc	-	ABWIN Bus Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	----------	--------------------------	------------------

Monthly \$588, 3 Day Delivery, No Need Repairs. \$0 Drive Away, High Loan With Lowest Interest Rate Available, Super High Trade In. What Are You Waiting For? Call Now View And Text Drive!

Office No. - 69339414

KK Tang - 81245503 | Zhiwei - 91055246

Nissan Cabstar (COE till 08/2024) (Diesel)	\$21,800	\$4,940 /yr	21-Aug-2009	2,953 cc	-	Car (S) Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	----------	------------------------	------------------

3 Months Warranty! High Loan Available! Reliable Box Truck With Fully Done Up Interior. Lowest Driveway Plans With Low Monthly Instalments. Look No Further, View To Believe. Offering The Highest Trade...

Office No. - 63863322

Ray - 81281193 | Roy Tan - 97424455

Nissan Cabstar (COE till 09/2024) (Diesel)	\$18,800	\$4,160 /yr	29-Sep-2009	2,953 cc	-	Net Link Partners Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	----------	----------------------------------	------------------

Why Choose Net Link Partners? Pricing Concern Or Piece Of Mind Purchases? Come On In And Allow Me To Justify To You Why? In Net Link Partners, We Prioritize Our Integrity And Sincerity Towards Every C...

Office No. - 67531661

Eugene Ng - 93270298 | Lance - 94561551 | Wilfred - 83803222

Nissan Cabstar (COE till 11/2024) (Diesel)	\$21,800	\$4,720 /yr	03-Nov-2009	2,953 cc	120,650 km	MCT Trader LLP	Available
---	-----------------	--------------------	--------------------	-----------------	-------------------	-----------------------	------------------

Well-Maintained Unit With Retractable Canopy! One Of The Most Trusted Make/Model Trucks On The Market! High In-House Loans And High Trade Ins Are Available, So Call Or Walk In Today To Inquire And To ...

Office No. - 64648880

JJ - 86064693 | Ah Hwee - 86663444 | Kelvin Kang - 90098718

Nissan Cabstar (COE till 12/2024) (Diesel)	\$21,800	\$4,580 /yr	26-Dec-2009	2,953 cc	270,000 km	Bell Auto Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	-------------------	--------------------------	------------------

2009 Built And Known To Be Very Reliable, Well Maintained By Single Owner. Simple To Maintain And Low Cost. High Trade In And Full Loan Available. Condition Ready For Immediate Delivery!

Office No. - 67457076

Eric Lim - 91084406 | Derrick Tan - 94590990

Nissan Cabstar (COE till 12/2024) (Diesel)	\$23,500	\$4,940 /yr	26-Dec-2009	2,953 cc	-		Available
---	-----------------	--------------------	--------------------	-----------------	----------	--	------------------

Well Maintained By Previous Owner Extremely Clean Interior. Engine And Gearbox In Good Condition. Cabin Height Freezer Truck Ideal For HDB Multi-Storey Parking And Basement Carpark Access, Loan And Tr...

Office No. - -

Low - 96711737

Nissan Cabstar (COE till 12/2024) (Diesel)	\$22,800	\$4,770 /yr	31-Dec-2009	2,953 cc	-	ABWIN (1994) Pte Ltd	Available
---	-----------------	--------------------	--------------------	-----------------	----------	-----------------------------	------------------

Dec 09 Super Reliable Nissan Cabstar, New Paintwork, Wear And Tear Replace, Well Maintained By Previous Owner, High Loan And High Trade In Available! Drive Off With No Worries, Doorstep Viewing Can Be...

Office No. - -

Wei Liang - 91816257 | Rosson - 90683033

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/01/2020 11:43
Date Of Accident	10/01/2020 14:15
Exact Location Of Accident	SERANGOON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBA8706R
Insured/Policyholder	
Name Of Registered Owner	LIAN YUAN
Co Reg No	5XXXX245E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96466013

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR 3.0 5M/T ABS 2DR 2WD 3.4T

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5045525974-08
Cover Note Number	

Driver

Name of Driver	CHUNG KIAT HWA
NRIC No	SXXXX265B
Date Of Birth	29/06/1958
Occupation	OUTDOOR
Date Of Driving Pass	18/07/1979
Driving Experience	40 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82386907
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 15 UPPER BOON KENG ROAD #05-1053
Postcode	380015
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : AH LEK GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ6451R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	AN ZHIJUN
NRIC/Passport Number	QXXXX894D
Contact Number	94676616
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Lian Yuan

15, Chander Road (Little India)
Singapore 219530
Tel: 6295 0239 Fax: 6292 0801
Company No: 53135245 E


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 10/1/2020, I was driving along Serangoon Road at 1415pm, my vehicle was stationary on lane 2, vehicle in front made a stop hence I slow down to stop. But of the sudden vehicle B; GBJ6451R bang onto my vehicle.

Lian Yuan

15, Chandler Road (Little India)

Singapore 219530

Tel: 6292 0239 Fax: 6292 0664

DECLARATION

I/We declare that the particulars are true in every respect.

Company No: 53135245 E

GST No: W00362478 A

[Signature]



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

1. Condition of Goods
 (1) Good (2) Damaged (3) Discontinued (4) Cracked (5) Cor. (6) Scratched
 (7) Replaced (8) Reconditioned (9) Broken (10) Broken (11) Necessary
 (12) Missing (13) Free (14) Unconfirmed (15) Not Working

VAN / LORRY (Rear)

1. Description of Goods (2) Quantity (3) Date of Receipt
 (4) Date of Completion (5) No.

Vehicle No: **GBA8706R**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	BT	/	
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel	Refer		
1163	993851	Rear LH Taillamp	cut		
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	GRA	/	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	Part	/	
2054	993700	Rear Rubber Stopper			
2055	993701	Rear Rubber Stopper Bracket			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate			
2063	994225	Rear Sidegate Lock			
2064	993749	Rear Sidegate Hinge			
2065	994226	Sidegate Lower Panel			
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker "13 pax" "70 km/h" "6 C" / 2			

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PR1

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jan 2020 Edit Reg		16 Jan 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	NEW-M PTE LTD, Co. Reg. No.: -		
Main Claimant:	LIAN YUAN		
Vehicle Reg. No.:	GBA8706R	Date of Loss:	10/01/2020 00:00 - :59 [142 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 1741786738SG	Policy/Cover Note No.:	1900114062 (Comprehensive)
Vehicle Reg. No. (Insured):	GBJ6451R	Policy No. (Claimant):	
		Excess:	
Repairer:	Ann Joo Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #02-17, Singapore 575721, 575721 Sin Ming - Tel: 64510747		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 28/01/2020]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)




































- AIG_SG (17/01/2020): TP GIA report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBA8706R (1741786738SG)
[GBJ6451R]
TP
LIAN YUAN
Jan 10 2020 12:00AM
[NEW-M PTE LTD]
Ann Joo Motor Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print		
1	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
2	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
3	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
4	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
5	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
6	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
7	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
8	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
9	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
10	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
11	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
12	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
13	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
14	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
15	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
16	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
17	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
18	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
19	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
20	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
21	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
22	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
23	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
24	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
25	24/02/20 09:30	General View													 Load JPG	<input checked="" type="checkbox"/>		
26	24/02/20 09:31	Odometer Reading													 Load JPG	<input checked="" type="checkbox"/>		
27	24/02/20 09:31	Chassis Number													 Load JPG	<input checked="" type="checkbox"/>		
28	24/02/20 09:31	Dismantled Parts													 Load JPG	<input checked="" type="checkbox"/>		
29	24/02/20 09:31	Dismantled Parts													 Load JPG	<input checked="" type="checkbox"/>		
30	24/02/20 09:31	Dismantled Parts													 Load JPG	<input checked="" type="checkbox"/>		
31	24/02/20 09:31	Dismantled Parts													 Load JPG	<input checked="" type="checkbox"/>		
32	24/02/20 09:31	Dismantled Parts													 Load JPG	<input checked="" type="checkbox"/>		
33	24/02/20 09:31	Dismantled Parts													 Load JPG	<input checked="" type="checkbox"/>		
34	24/02/20 09:32	After Repair Photo													 Load JPG	<input checked="" type="checkbox"/>		
35	24/02/20 09:32	After Repair Photo													 Load JPG	<input checked="" type="checkbox"/>		
36	24/02/20 09:32	After Repair Photo													Load JPG	<input checked="" type="checkbox"/>		
37	24/02/20 09:32	After Repair Photo													Load JPG	<input checked="" type="checkbox"/>		

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
38	24/02/20 09:32	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
39	24/02/20 09:32	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
40	24/02/20 09:32	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
41	24/02/20 09:32	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
42	24/02/20 09:32	After Repair Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	17/01/20 15:35	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20001018/GQD3E2

Date: 24/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900114062
 Claimant Vehicle No: GBA8706R Insured Vehicle No: GBJ6451R
 Date of Loss: 10/01/2020 Nature of Claim: TP Claim No: 1741786738SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBA8706R
 Make & Model: NISSAN CABSTAR, 3.0 (M) Engine No: ZD30161974K
 Reg. Date: 04/03/2008 (Man. Year: 2008) Chassis No: JN1SC2F24Z0800049
 Colour: Silver Odometer: 396637 km
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 165 R13
 Front Left Side: Journey 5 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Journey 5 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 16/01/2020
 Date Inspected: 16/01/2020 Inspected At: Ann Joo Motor Pte Ltd (HQ)
 Blk 176 Sin Ming Drive #02-17, Singapore
 575721
 Singapore 575721
 Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	0.00 F	*- F
2	1		*REAR END PANEL	Repair	0.00 F	*- F
3	1		*REAR LH TAILLAMP	Cut	0.00 F	*- F
4	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
5	1		*TAILGATE	Buckled	0.00 F	*- F
6	2		*STICKER 13 PAX & 70KM/H	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >