

INS. CASE OWNER: **LALITHA**

CC4/III20001058/Dpa3

LKK:

IDAC:

ASSIGNMENT

Surveyor: **BRYAN**

DOI: **17/01/2020**

Date / Time : **16/01/2020**

Registered in Merimen: **17/01/2020**

Pre-assign / CCU / FTE



Insured Vehicle No. : **GBC 7789Y**
 Name of Insured : **DELCO ART INTERIOR PTE LTD**
 Insured Tel No. : _____ HP: _____
Excess Sec II :S\$ _____ D.O.A : **14/01/2020**
 Is driver the owner? (YES / NO) Nature of Accident :

Claim No. : _____ **X**
 Policy No. : **D18MCV0002346**
 Make / Model : **MITSUBISHI CANTER-3.0 D FEA01BR2SDEB**
 Place of Accident : **LOYANG AVENUE**

If NO, Driver Name / Age : **SUBIRAMANI MANIKANDAN**
 Driver Tel No. : **+65-91088139** (V/L: **YES** / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Insured Liability : % **Final ? Yes / No**

SH 7946H



INSRS: **BIFROST**
 WSP: **AUTO**
 Tel : _____
 Liability : _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel : _____
 Liability : _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel : _____
 Liability : _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel : _____
 Liability : _____
 RMKS: _____

Date/ Time	SH 7946H - NS/INC13011114/H1qn; DOA : 14.06.2013 GBC 7789Y - X	STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Towing Invoice	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LTA / GIA :	<input checked="" type="checkbox"/> <input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
		PIR:	<input type="checkbox"/> <input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
		LOD	<input type="checkbox"/> <input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
		Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
 Repair Cost: S\$ _____ (_____ days) Reduction: % _____ Email Call

FINAL SETTLEMENT Date/Time: **12/1/2020** Confirm with **Mr Lee** Email Call

Final Liability: % **100** (Agreed / Assessed) BOLA S/N No. : _____ If NO or B 28, Ass. Lia : _____
 Repair Cost: **W/CAT** S\$ **1128.00**
 Loss of Rental (LOR): S\$ **574.75** (**5** days) **x \$ 114.95**
 Loss of Use (LOU): S\$ **-** (\$ **-** x **-** days)
 Loss of Income (LOI): S\$ **200.00** (\$ **40.00** x **5** days)
 LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
 GIA/LTA Search S\$ **7.45**
 Medical: S\$ **-**
 Disbursement: S\$ **40.00** (e.g **Tow** / Independent)
 Legal Cost S\$ **-**
 1) Claim status: **Normal/Reject/Private Settle**
 2) Report Format: **SP**
 3) Survey fee: **\$ 60.00**

Total: S\$ **11950.20** **Global Sum S\$:** **11950.00**

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: S\$ **11950.00** Name 1: **Bifrost Auto Pte Ltd**

Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____

Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

ASS. REC. BY:

REF:

ASSIGNMENT

CBE 2023 June

From: _____ Date: _____

Veh No: SH 7946H Yr Regn: June 2015

Estimated Cost: _____

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No: _____

Make: Hyundai I40 C.C. 1685

at Workshop m/s _____

Colour: Blue A/C: Insured / Std / NI / NA

of _____

Sp. Reading: 508375 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: D4FDPU528464

Policy No. _____

C/No: KMHLB41UMG075035

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 205/60 R16

R: — 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Henkook

Bal. or Market Value: _____

Front Rear

IDAC Accident Rpt: _____ Consistent? : Yes or No

R/Bal. S mm R/Bal. S mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. S mm L/Bal. S mm

Est. Repairs: 6 days Res.: Yes or No

D.O.A. 14/01/2020 D.O.I. 17/01/2020

Lum Sum: 20 % 3 Val.: Yes or No

Survey held at Bijoyat Sin Ming

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>III GBC 7789Y</u>
<u>01/02/2020</u>	<u>inspect 2/s 10400/- with 6 days from (Red \$14177.68 / 58 %).</u>

Date/Time, File Pass to?

: Preli. Report

Days Of Repair: _____

1)

: Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: : Site Insp (\$)

Transportation:

Rep. Form(s): _____

: Interview (\$)

____ \$ + RS. ____ \$

Lump Sum / L.P. / C:

: Tech. Invs (\$)

Photos

: Weekend (\$)

Others

TOTAL