

INS. CASE OWNER: **LALITHA**

**CC4/III20001058/Dpa3**

LKK:  
IDAC:

**ASSIGNMENT**

Surveyor: **BRYAN**

DOI: **17/01/2020**

Date / Time : **16/01/2020**

Registered in Merimen: **17/01/2020**

**Pre-assign / CCU / FTE**

X



Insured Vehicle No. : **GBC 7789Y**  
 Name of Insured : **DELCO ART INTERIOR PTE LTD**  
 Insured Tel No. : \_\_\_\_\_ HP: \_\_\_\_\_  
**Excess Sec II :S\$** \_\_\_\_\_ D.O.A : **14/01/2020**  
 Is driver the owner? ( YES / NO ) Nature of Accident :

Claim No. : \_\_\_\_\_  
 Policy No. : **D18MCV0002346**  
 Make / Model : **MITSUBISHI CANTER-3.0 D FEA01BR2SDEB**  
 Place of Accident : **LOYANG AVENUE**

If NO, Driver Name / Age : **SUBIRAMANI MANIKANDAN**  
 Driver Tel No. : **+65-91088139** (V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO  
 Insured Liability : % **Final ? Yes / No**

**SH 7946H**



INSRS:  
WSP: **BIFROST**  
Tel : **AUTO**  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:



INSRS:  
WSP:  
Tel :  
Liability :  
RMKS:

Date/ Time	STAGE	DATE / PIC
	SH 7946H - NS/INC13011114/H1qn; DOA : 14.06.2013	
	GBC 7789Y - X	
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	<b>Documentation Check List:</b>	<b>Handler</b> <b>Typist</b>
	Notification ltr (if non-pickup)	<input type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA :	<input type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input type="checkbox"/> <input type="checkbox"/>
	LOD	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>
<b>PRELIMINARY ADVICE</b> Date/Time:	Sent By:	
<b>FINALIZATION</b> Date/Time:	Confirm with:	Confirm by:
Repair Cost: S\$	( days) Reduction: %	Email <input type="checkbox"/> Call <input type="checkbox"/>
<b>FINAL SETTLEMENT</b> Date/Time:	Confirm with	Email <input type="checkbox"/> Call <input type="checkbox"/>
Final Liability: %	(Agreed / Assessed) BOLA S/N No. :	If NO or B 28, Ass. Lia :
Repair Cost: S\$		
Loss of Rental (LOR): S\$	( days)	
Loss of Use (LOU): S\$	(\$ x days)	
Loss of Income (LOI): S\$	(\$ x days)	
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]	
GIA/LTA Search	S\$	
Medical:	S\$	1) Claim status: Normal/Reject/Private Settle
Disbursement:	S\$ (e.g. Tow/ Independent)	2) Report Format:
Legal Cost	S\$	3) Survey fee:
<b>Total:</b> S\$	<b>Global Sum S\$:</b>	
<b>FINAL PAYMENT</b> Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	S\$ Name 1:	
Payee 2: (Strike if N.A.)	S\$ Name 2:	
Payee 3: (Strike if N.A.)	S\$ Name 3:	

ASS. REC. BY:

REF:

ASSIGNMENT

C0E 2023 Sme

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SH 7946H Yr Regn: June 2015  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai I40 c.c. 1685  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 508375 T/Radio: Insured / Std / NI / NA  
 Eng/No: D4FDPU528464  
 C/No: KMHLB41UMGU075035  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_

N/S	O/S

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 6 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Tyre Size: F: 205/60 R16  
 R: — 11 —  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Henkoak  
 Front Rear  
 R/Bal. S mm R/Bal. S mm  
 L/Bal. S mm L/Bal. S mm  
 D.O.A. 14/01/2020 D.O.I. 17/01/2020  
 Survey held at Bijrost Sun Ming  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
Front  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>III GBC 77894</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Rep. Format: \_\_\_\_\_  
 Lump Sum / I.B.I. C\$ \_\_\_\_\_

Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Weekend (\$) \_\_\_\_\_

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS, \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_