

220013902

ASS. REC. BY:

Surveyor:

Hock Am

REF: CS3/LPC 20001081/Hvd3⁵²

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Gerald Poh

of

LPC

Date/Time:

17/01/2020 @ 8.29am

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 22892

Insured:

XE 777G

at Workshop m/s

My Car Consultant

Tel:

8866 8832

of

53 ubi Ave 1 # 01-33

Policy No:

Claim No:

19/20/20 / VC00/022910

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 14.1.2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

9.51am @ 17/1/2020

Person Contacted:

Hui Qin

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (X)

SLA 22892 - NA/FWD 20000972/24

D.O.A. 14/01/20

XE 777G - NA/FWD 20000972/24

D.O.A. 14/01/20

17/1/20 → survey taken

17/1/20 → Repair taken

1/1 →

PRS

ASSIGNMENT

From:

Date:

17/01/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLA 2289Z

at Workshop m/s

My Car Consultant

of

53 ubi Ave 1 # 01-33

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

1wp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 2289Z

Yr Regn:

5/21/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

VOLKSWAGEN JETTA

C.C. 1390

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

85707km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVWZZZ16Z 9M009783

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55/R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

Yoko mm

Rear

R/Bal.

6

Yoko mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/1/20

D.O.I.

7/1/20

11.43km

Survey held at

my car consultant

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/1/2020

repair days → 7 days
Submit PRS report

* SLA 2289Z
PRS case

RECEIVED 21 JAN 2020

MV - 62000

PV - 50611

NV - 11300

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) 20/1 - typist

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ + RS \$

Photos

Other

TOTAL

Report Format:

Lump Sum / L.B. (\$

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Friday, 17 January 2020 8:29 AM
To: 'admin@mycar.sg'
Cc: MT_Claim_SG; 'assignments@lkkauto.com'
Subject: FW: OUR REF: XE777G YOUR REF: SLA2289Z PRE-REPAIR INSPECTION FORXE777G
- Oref: 19/20/20/VC00/022910 [External Confidential]

Lonpac External - Confidential

WITHOUT PREJUDICE


Our Ref : 19/20/20/VC00/022910

Dear Huiqin,

We are objecting to your list of Single Joint Experts and shall appoint LKK Auto Consultants Pte Ltd for the pre-repair survey.

Aside to LKK Auto Consultants Pte Ltd
Attn: Nivitha – kindly proceed accordingly.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: My Car Consultant [mailto:admin@mycar.sg]
Sent: Thursday, 16 January 2020 6:00 pm
To: KENNY LIM CHING GHEE
Cc: MT_Claim_SG
Subject: RE: OUR REF: XE777G YOUR REF: SLA2289Z PRE-REPAIR INSPECTION FORXE777G - Oref: 19/20/20/VC00/022910 [External Confidential]

WITHOUT PREJUDICE

Dear Sirs,

We refer to your email on even date.

We disagree to your list of surveyor and propose the use of one of the motor surveyors named below to conduct the joint pre-repair survey as a single joint expert:

- a. Alan Cheong
- b. TT Rajan
- c. Oh Han Cheong
- d. Andrew How
- e. Dave Ho Joo Koong
- f. Lee Kok Weng
- g. Seah Kwang Boon
- h. Lee K.W.
- i. Nicky Seah
- j. Winson Goh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyor

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd

+65 88668832

Admin@mycar.sg

Mycar.sg

53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, S408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

From: "KENNY LIM CHING GHEE" <kennylim@lonpac.com>

Sent: Thursday, January 16, 2020 5:58 PM

To: "admin@mycar.sg" <admin@mycar.sg>

Cc: "MT_Claim_SG" <mt_claim@lonpac.com>

Subject: RE: OUR REF: XE777G YOUR REF: SLA2289Z PRE-REPAIR INSPECTION FORXE777G - Oref: 19/20/20/VC00/022910 [External Confidential]

Lonpac External - Confidential

Without Prejudice
Save as to Costs

Dear Huiqin

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the following list to conduct the joint pre-repair survey as a single joint expert.


1	Kalvin Ang
2	Xing Guo Qiang
3	Mohamad Taufikh
4	Mohammed Rasul
5	Adrian Ling
6	Marcus Chua
7	Kenneth Kong

8	Bryan Ang
9	Nicholas Tey
10	Jackson Quek

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Best Regards

Kenny Lim
Asst. Claims Manager | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
DID: 6279 9256 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: My Car Consultant <admin@mycar.sg>
Sent: Thursday, 16 January 2020 2:53 pm
To: MT_Claim_SG <mt_claim@lonpac.com>
Subject: OUR REF: XE777G YOUR REF: SLA2289Z PRE-REPAIR INSPECTION FOR XE777G

WITHOUT PREJUDICE

OUR REF: SLA2289Z
YOUR REF: XE777G

Dear Sir/Madam,

PRE-REPAIR INSPECTION FOR SLA2289Z
ACCIDENT INVOLVING SLA2289Z AND XE777G

We refer to the above matter and enclosed herewith our client's GIA report and Notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction - Amendment No. 1 of 2016 of 2016 of Pre-repair Inspection for your attentio

Best Regards,

Huiqin

Claims | My Car Consultant Pte Ltd

+65 88668832

Admin@mycar.sg

Mycar.sg

53 Ubi Ave 1, Paya Ubi Industrial Park, 01-33, 5408934

This Email, including attached files, may contain confidential information and is intended only for the use of the individual and/or entity to which it is addressed. If you have received this message in error, please notify the sender of the error and delete the message. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2020 14:53
Date Of Accident	14/01/2020 14:00
Exact Location Of Accident	ECP TWDS CHANGI BEFORE PIE EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA2289Z
Insured/Policyholder	
Name Of Registered Owner	CHUA KEE WEE
NRIC No	SXXXX434A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98732289
Alternative Phone No	OFFICE-98732289

Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	JETTA GP 1.4 TSI 90 A/T HL HID 1634G5
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNCV2020-00000036
Cover Note Number	

Driver

Name of Driver	CHUA KEE WEE
NRIC No	SXXXX434A
Date Of Birth	31/05/1957
Occupation	OUTDOOR
Date Of Driving Pass	25/04/1977
Driving Experience	42 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98732289
Fax Number	
Contact Number	OFFICE-98732289
EMail Address	NOEMAIL

Address	BLK 286B TOH GUAN ROAD #21-32
Postcode	602286
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM MOOI KUAN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE777G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	PEH SOON KEONG
NRIC/Passport Number	SXXXX014D
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	


No. Of Passenger (Including Driver)


Accident Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Drivers.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan

SKETCH PLAN ELP Towards Changai before PSE exit.

Vehicle A:
SLA 2284 Z

Vehicle B:
XE 777G




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON the stated time and date
I was travelling my vehicle bearing car plate SLA 2284 Z along Eep Changai before PSE exit. I was driving grab with my passenger aboard on my way to Tagore Lane. As the passenger was a malaysian, he was unsure about his destination. Thus he insisted me to stop by the Road shoulder to clarify. While we were still discussing about the location, I felt an impact from the right side. I was shocked and realised a truck bearing car plate XE 777G had collided onto me and stopped about 50 meters ahead. He then aligned his truck and walk towards me. We exchange particulars and agree that we do not require to lodge a police report, but we still lodge a Accident Report with our Respective Insurance Company for claiming purposes. I wish to state that my vehicle was stop Stationary within the Road Shoulder during the point of collision which my passenger is willing to be the witness.

Passenger: Lim Mui Kuan (MALE)
+ 60 012 4321 388


DECLARATION

We declare the foregoing particulars are true in every respect.



Policyholder's Signature

Date & Time:

WATER SIGNATURE


Driver's Signature
(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	434A
Vehicle Details	
Vehicle No.:	SLA2289Z
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jan 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	JETTA GP 1.4 TSI 90 A/T HL HID 1634G5
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	CAXF82987
Chassis No.:	WVWZZZ16ZGM009283
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$21,584.00
Original Registration Date:	05 Jan 2016
First Registration Date:	05 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$22,218.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jan 2026
PARF Rebate Amount:	\$16,663.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$33,948.00
Total Rebate Amount:	\$50,611.00

The information contained herein is correct as at 20 Jan 2020

OK

Volkswagen Jetta

Price Range

Depreciation

2016

Vehicle Type

Home » Used Cars » Munich Alpina Pte Ltd » Volkswagen Jetta GP 1.4A TSI Highline

Volkswagen Jetta GP 1.4A TSI Highline

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREM

Price \$70,000**Depreciation** ⓘ

\$8,650 /yr

View models with similar depre

Reg Date

30-Nov-2016

(6yrs 10mths 9days COE left)

Mileage

54,000 km (17.2k /yr)

Manufactured ⓘ

2016

Road Tax ⓘ

\$620 /yr

Transmission

Auto

Dereg Value ⓘ

\$50,878 as of today (change)

OMV ⓘ

\$20,867

COE ⓘ

\$50,951

ARF ⓘ

\$21,214

Engine Cap

1,390 cc

Power

90.0 kW (120 bhp)

Curb Weight ⓘ

1,417 kg

No. of Owners ⓘ

1

Type of Vehicle

Mid-Sized Sedan

Features

Responsive 1.4L 4 Cylinder Inline TSI Turbocharger Engine, 120Bhp, 7-Speed (A) DSG Transmission. Fog Lamps. Airbags. Traction Control. View specs of the Volkswagen Jetta (2011-2017)

Accessories

Factory Fitted Leather Seats, Navigation, 3M Solar Film, Reverse Camera/Sensors. Include Factory Fitted BlackVue Full HD Dashboard Camera.

Description

Promo Loan Interest At 2.28%. Extremely Well Maintained And In Prestine Condition, This Beast Does Not Just Look Beautiful. It's 100% Accident-Free. View To Believe! Up To 80% Financing Of Car Price Possible! Trade-In Welcome Call/SMS To Arrange A Viewing Today! Viewing Strictly By Appointment Only!

Category

PARF Car, Premium Ad Car

Status

Available

Resources



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free

Find out the market value of your existing car for free. Get started


Postec Compare

ited on: 03-Jan-2020

https://www.sgcarMart.com/used_cars/info.php?ID=852295&DL=3137


Price Chart

Summary



Click on the point to view the vehicle

Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information

Munich Alpina Pte Ltd

76 vehicles for sale. 26 sold in past 3 mths

1 Bukit Batok Crescent #06-57





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC20001081/Hvd3s2 Date: 22-01-2020 Code: LPC2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	XE 777G	Veh. Inspected	SLA 2289Z
Policy No.		Coverage (\$)	0.00
Claim No.	19/20/20/VC00/022910	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	17/01/2020
2. Vehicle Particulars & Condition			
Make & Model	VOLKSWAGEN JETTA	c.c	1390
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WWWZZZ16ZGM009283	Colour	BLUE
Odometer	85707 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.			
5. General Information			
Accident Date	14/01/2020	Inspect Date / Time	17/01/2020 (11:43 AM)
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Report Ref No. CS3/LPC20001081/Hvd3s2

Inspected By



LEE HOCK ANN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever in contact or form is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.