

INS. CASE OWNER:

CC6/CTI20001135/Dha3

LKK:

IDAC:

Surveyor:

BRYAN

DOI: 15/01/2020

Date / Time : 15/01/2020

Registered in Merimen: _____

Pre-assign / CCU / FTE



Insured Vehicle No. : SLC 1670B

Claim No. : _____

Name of Insured : _____

Policy No. : _____

Insured Tel No. : _____ HP: _____

Make / Model : _____

Excess Sec II :S\$

D.O.A : 08/01/2020 12:30

Place of Accident : PIE TWDS AIRPORT

Is driver the owner?

(YES / NO)

Nature of Accident : _____

If NO, Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : _____ %

Final ? Yes / No

SH 7091Z

INSRS:
WSP: BIFROST
Tel : AUTO
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	SH 7091Z - CC3/CTI18007214/K1ja3q2; DOA: 16.4.18 - NS/INC14016699/H1tbk3; DOA: 30.8.14 SLC 1670B - X	STAGE	DATE / PIC
		Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
		Call OI:	
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	☐ ☐
		After call ltr to OI:	☐ ☐
		Authorisation To Act:	☐ ☐
		Release Voucher:	☐ ☐
		Final Repair Bill:	☐ ☐
		Car Rental Invoice:	☐ ☐
		Towing Invoice	☐ ☐
		LTA / GIA :	☐ ☐
		Medical Bill:	☐ ☐
		PIR:	☐ ☐
		Mandate/Reject Instruction:	☐ ☐
		LOD	☐ ☐
		Payment Breakdown Form:	☐ ☐
		Post-Repair Photos:	☐ ☐
		Others:	☐ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

S\$

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF:

COT April 2024

Veh No: SH 7091 Z Yr Regn: 2016 Apr

Type: M.Car / M.Cycle / Bus / Van / Lorry / ~~Taxi~~ / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading 444948 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDFU607403

C/No: KMH LB41UM GU087060

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — 11 —

	
N/S	O/S
	

TOYO / YOKO or

Front

R/Bal.	Σ	mm	R/Bal.	Σ	mm
--------	----------	----	--------	----------	----

L/Bal. Σ mm L/Bal. Σ mm

D.O.A. 08/01/2020 D.O.I. 15/01/2020

Survey held at Biggest Sin Mine

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Hand y Rev

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]☐: Prelim. Report☐ : Final Report

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$) \$ + RS. \$☐ Interview (\$) Photos

	Tech. Invs (\$	)	Others
--	----------------	---	--------

Weekend (\$)	
--------------	--

Transportation:

5)	$S + RS$	SI
----	----------	------

) Photos

b) Others

TOTAL