

ASS. REC. BY:

REF: CS/CT1 20001158/Ky f3 82

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Ben Tang

of

CT1Date/Time: 20.1.2020 10.13am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 9947A

Insured:

GBH 8329J

at Workshop m/s

Mega Auto

Tel:

84689638of 160 Sin ming Prve #02-01 Antoury575722Policy No: DMCVSN 18326 11901

Claim No:

SWM200200129/GBH 8329J/TKL

Sum Insured:

Excess:

Make of Veh:

D.O.A.

8.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 20.1.2020 10.30am

Person Contacted:

SarahVehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GBB 9947A - xGBH 8329J - CC3/CT1 19020752/Fda3 DPA 25/11/2019

ASS. REC. BY:

REF: CTZ/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 87k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Sg/H Vehicle: IN / OUTVeh No: GBB 9947A Yr Regn: 12.10.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)Make: Toy Regius c.c. 2982Colour: White A/C: Insured / Std / NI / NASp. Reading: 339976 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KD14221 000719PGen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: M1 / S/Rim / STD A/Rim orTyre Size: F: 195R15XL

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 8/1/20 D.O.I. 20/1/2020

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

23/3 Sarah said Total Loss no repair the vehicle
 24/3 Submit Uneconomical Total loss

MV = \$7000-00

LTA = \$2769-00

Nett = \$4231-00

RECEIVED 24 MAR 2020

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 29/3/20 Typist

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

F. H. S.

Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Jan 2020		20 Jan 2020 10:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:			
Main Claimant:	FEDERAL EXPRESS (SINGAPORE) PTE LTD, Co. Reg. No.: 198402740W		
Vehicle Reg. No.:	GBB9947A	Date of Loss:	08/01/2020 10:00 - :59
Claim Type:	TP / SNM20D200129/GBH8329J/TKL	Policy/Cover Note No.:	DMCVSN1832611901 (Comprehensive)
Vehicle Reg. No. (Insured):	GBH8329J	Policy No. (Claimant):	100774093
		Excess:	S\$350.00
Repairer:	Mega Auto Pte Ltd (HQ) Blk 10 Sin Ming Ind Est Sector C #01-04, 575645 Sin Ming - Tel: 64555884		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Susan Teo - 6389 6178]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/01/2020]		

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Monday, 20 January, 2020 10:13 AM
To: assignments@lkkauto.com
Subject: FW: OUR REF: SNM20D200129/GBH8329J/TKL - FW: PRS REQUEST - GBB9447A

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle GBB9447A.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: MTC <mtc@mega-auto.com.sg>
Sent: Monday, January 20, 2020 10:03 AM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Subject: FW: OUR REF: SNM20D200129/GBH8329J/TKL - FW: PRS REQUEST - GBB9447A

resend

From: MTC [mailto:mtc@mega-auto.com.sg]
Sent: 17 January 2020 14:49
To: 'MTC'; 'Claims Dept of CTI'; 'Tan Kah Leong'; 'Chee So Chow'
Subject: RE: OUR REF: SNM20D200129/GBH8329J/TKL - FW: PRS REQUEST - GBB9447A

Dear Ben,

Will conduct the survey by today? Please advise.

Thank you

Sarah Chan

Mega Auto Pte Ltd

Tel : 8468 9838 Fax : 6458 5884

From: MTC [mailto:mtc@mega-auto.com.sg]

Sent: 16 January 2020 23:25

To: 'Claims Dept of CTI'; 'Tan Kah Leong'; 'Chee So Chow'

Subject: FW: OUR REF: SNM20D200129/GBH8329J/TKL - FW: PRS REQUEST - GBB9447A

Dear Ben,

We choose Kenneth Kong from LKK .

Thank you

Sarah Chan

Mega Auto Pte Ltd

Tel : 8468 9838 Fax : 6458 5884

From: Ben Tang [mailto:Ben.Tang@sg.cntaiping.com]
Sent: 16 January 2020 17:24
To: MTC
Cc: Claims Dept of CTI; Tan Kah Leong; Chee So Chow
Subject: RE: OUR REF: SNM20D200129/GBH8329J/TKL - FW: PRS REQUEST - GBB9447A

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 16 January 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING

Kelvin Ang

SEE CHEW SENG

MOHD FADHILAH BIN OSMAN

XING QUO QIANG

KENNETH KONG

SIMON HO

CHUA WEIJIE

MARCUS CHUA

HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com <<http://www.sg.cntaiping.com/>> | FB: www.facebook.com/chinataipingsg/
<<http://www.facebook.com/chinataipingsg/>> | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Thursday, January 16, 2020 4:13 PM

To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>; MTC <mtc@mega-auto.com.sg>; Ben Tang <Ben.Tang@sg.cntaiping.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF: SNM20D200129/GBH8329J/TKL - FW: PRS REQUEST - GBB9447A

Dear Kah Leong/Ben,

Please conduct PRS for SGX3969B.

Note : officer in charge – Kah Leong 63896193.

*** Kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com <<http://www.sg.cntaiping.com/>> | FB: www.facebook.com/chinataipingsg/
<<http://www.facebook.com/chinataipingsg/>> | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: MTC [mailto:mtc@mega-auto.com.sg]
Sent: Thursday, January 16, 2020 11:34 AM
To: Claims Dept of CTI
Subject: PRS REQUEST - GBB9447A

Dear Sirs ,

Attached herewith estimate report & GIA report for your kind attention.

Kindly arrange a pre repair inspection for Third party Clam against your insured GBH 8329J.

Please feel free to call us at 9758 2943 / email us : mtc@mega-auto.com.sg <<mailto:mtc@mega-auto.com.sg>>

Thank you

Sarah Chan

Mega Auto Pte Ltd

Tel : 8468 9838 Fax : 6458 5884

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/01/2020 09:13
Date Of Accident	08/01/2020 10:10
Exact Location Of Accident	ECP TOWARDS MCE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB9947A
Insured/Policyholder	
Name Of Registered Owner	FEDERAL EXPRESS (SINGAPORE) PTE LTD
Co Reg No	1XXXXX740W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-69222929

Vehicle Particulars

Manufacturer	TOYOTA
Model	REGIUS ACE-3.0 D DX (A)
Exact Purpose for which vehicle was being used at time of accident	DELIVERY AND PICK-UP
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	100774093
Cover Note Number	

Driver

Name of Driver	NADARAJAN A/L RETHANAM
Passport No/FIN	FXXXX755Q
Date Of Birth	12/11/1977
Occupation	OUTDOOR
Date Of Driving Pass	26/07/2016
Driving Experience	3 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83568238
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	90 ALPS AVE
Postcode	498746
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON 08/01/2020 AT ABOUT 10:08HRS UPON DRIVING ON ECP TOWARDS MCE THE TRAFFIC WAS HEAVY AND SLOW MOVING WHILE I AM SLOWING DOWN, THE LORRY (GBH8329J) DID NOT MANAGE TO STOP AND HIT MY BACK OF THE VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH8329J
Vehicle Make/Model/Colour	TOYOTA DYNA/SILVER
Details Of Properties	FRONT PORTION
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

6839947A

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/Fin No:


Sketch Plan #2

SKETCH PLAN

VPL A: QBB 9947A

VPL B: QSH 8329J

ECP Towards MCE



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 02/01/2020 at about 10:08 hrs upon driving on ECP towards MCE the traffic was heavy and slow moving while I am slowing down the lorry (QSH 8329J) did not manage to stop and hit my back of the vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NIC/Fly No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	740W
Vehicle Details	
Vehicle No.:	GBB9947A
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	REGIUS ACE 3.0DX A
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	1KD2051788
Chassis No.:	KDH2210007199
Maximum Power Output:	-
Open Market Value:	\$42,806.00
Original Registration Date:	14 Dec 2010
First Registration Date:	14 Dec 2010
Transfer Count:	0
Actual ARF Paid:	\$2,141.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$31,001.00
COE Rebate Amount:	\$2,769.00
Total Rebate Amount:	\$2,769.00

The information contained herein is correct as at 21 Jan 2020

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No.

GBB9947A

Make / Model

TOYOTA / REGIUS ACE 3.0DX A

Vehicle Type :

A50 - Goods (Closed) Van/Van Panel (Delivery)

Vehicle Attachment 1 :

No Attachment

Vehicle Scheme :

Normal

Chassis No. :

KDH2210007199

Propellant :

Diesel

Engine No. :

1KD2051788

Motor No. :

-

Engine Capacity :

2982 cc

Power Rating :

-

Maximum Power Output :

-

Maximum Laden Weight :

3165 kg

Unladen Weight :

1960 kg

Year Of Manufacture :

2010

Original Registration Date :

14 Dec 2010

Lifespan Expiry Date :

13 Dec 2030

COE Category :

C - Goods Vehicle & Bus

Quota Premium :

\$31,001.00

COE Expiry Date :

13 Dec 2020

Road Tax Expiry Date :

01 Apr 2020

PARF Eligibility Expiry Date :

-

Inspection Due Date :

01 Oct 2020

Intended Transfer Date :

17 Aug 2020

CO2 Emission :

-

CEV/VES Rebate Utilised Amount :

-

CO Emission :

-

HC Emission :

-

NOx Emission :

-

Quotation Details - Quotation No SN-002012-20-20001

Date
Created:12/4/2011

Customer Details:

Fedex
Federal Express (s) Pte Ltd
90 Alps Ave
Singapore 498746
Fax: 69222550

Vehicle Details

Vehicle No : GBB 9947
A
Vehicle Make : Toyota
Vehicle Model : Hiace 2008
Vehicle Engine No :
Engine Chasis No :
Mileage :

Owner's Accident Details

Job No : SN-002012-20-20001
JobCategory : TP - Lump Sum
Date of Accident :
Owner's Insurer :
Location of Accident :

Surveyor's Details

Surveyor Name :
Surveyor Company :
Surveyor ContactNo :
Surveyor FaxNo :
Quotation Submission Date :
Surveyor Approve Date :
Supplementary Date :
Supplementary Approve Date :

View Photo Accident Photo

*Not Notified
61 Png & ?
Running After Pains
8 days*

*Kenroth
96910663*

Item No	Ref No	Description	QTY	Unit List Price	Mark Up / Discount %	Mark Up / Discount Price	Total Price	Rev Qty	Rev Unit Price	Remarks	Final Total Price	Surveyor Approval
Materials												
1	1	Tailgate	1	\$2,290.00	-25.00	\$1,717.50	\$1,717.50	0	0	B	\$0.00	✓
2	2	Tailgate Logo	1	\$72.00	-25.00	\$54.00	\$54.00	0	0	M	\$0.00	✓
3	3	Tailgate Centre Garnish	1	\$155.00	-25.00	\$116.25	\$116.25	0	0	Wap	\$0.00	✓
4	4	Windscreen Rear	1	\$1,236.00	-25.00	\$927.00	\$927.00	0	0	Shattered	\$0.00	✓
5	5	Tailgate Weatherstrip	1	\$474.00	-25.00	\$355.50	\$355.50	0	0	at	\$0.00	50211
6	6	Rear End Panel	1	\$450.00	-25.00	\$337.50	\$337.50	0	0	B	\$0.00	✓
7	7	Rear End Panel Inner	1	\$980.00	-25.00	\$735.00	\$735.00	0	0	B	\$0.00	✓
8	8	Rear Corner Panel LH	1	\$100.00	-25.00	\$75.00	\$75.00	0	0	B	\$0.00	✓
9	9	Rear Corner Panel Retainer LH	1	\$45.00	-25.00	\$33.75	\$33.75	0	0	D/I	\$0.00	✓
10	10	Rear Bumper	1	\$415.00	-25.00	\$311.25	\$311.25	0	0	B	\$0.00	✓
11	11	Rear Bumper Clips	10	\$5.00	-25.00	\$3.75	\$37.50	0	0	M	\$0.00	✓
12	12	Rear Bumper Retainer LH	1	\$45.00	-25.00	\$33.75	\$33.75	0	0	D/I	\$0.00	✓
13	13	Rear Bumper Retainer RH	1	\$45.00	-25.00	\$33.75	\$33.75	0	0	S	\$0.00	X
14	14	Tail Lamp RH	1	\$300.00	-25.00	\$225.00	\$225.00	0	0	S	\$0.00	X
15	15	Tail Lamp LH	1	\$300.00	-25.00	\$225.00	\$225.00	0	0	B	\$0.00	✓
16	16	Rear Fender LH	1	\$1,400.00	-25.00	\$1,050.00	\$1,050.00	0	0	R	\$0.00	X
17	17	Tail Lamp Panel LH	1	\$695.00	-25.00	\$521.25	\$521.25	0	0	B	\$0.00	✓
18	18	Exhaust Pipe	1	\$465.00	-25.00	\$348.75	\$348.75	0	0	R	\$0.00	X
19	19	End Panel Top Garnish	1	\$165.00	-25.00	\$123.75	\$123.75	0	0	D/I	\$0.00	✓
20	20	Tailgate Lock	1	\$265.00	-25.00	\$198.75	\$198.75	0	0	D/I	\$0.00	✓
21	21	Floor Wood	1	\$1,125.00	-25.00	\$843.75	\$843.75	0	0	CNF	\$0.00	✓

Material Total: \$8,304.00 Final Sub-Total : \$0.00

Special Nett Items

1	22	Tailgate FedEx Sticker	1	\$120.00	0.00	\$120.00	\$120.00	0	0	M	\$0.00	✓
2	23	Sticker "70/km"	1	\$6.00	0.00	\$6.00	\$6.00	0	0	M	\$0.00	✓
3	24	Sticker "fedex.com"	1	\$28.00	0.00	\$28.00	\$28.00	0	0	M	\$0.00	✓
4	25	Sticker "1-800-7432626"	1	\$28.00	0.00	\$28.00	\$28.00	0	0	M	\$0.00	✓
5	26	Rear Fender Sticker	1	\$320.00	0.00	\$320.00	\$320.00	0	0	M	\$0.00	✓
6	27	Rear End Panel Sealant	1	\$40.00	0.00	\$40.00	\$40.00	0	0	M	\$0.00	30211
7	28	Windscreen Sealant	1	\$50.00	0.00	\$50.00	\$50.00	0	0	M	\$0.00	40211

8	29	Sticker "HIACE"	1	\$22.00	0.00	\$22.00	\$22.00	0	0	Ne	\$0.00	✓
9	30	Rear Number Plate	1	\$45.00	0.00	\$45.00	\$45.00	0	0	Ne	\$0.00	✓
10	31	Sticker "965700"	1	\$12.00	0.00	\$12.00	\$12.00	0	0	Ne	\$0.00	✓

Special Nett Items Total: \$671.00 Final Sub-Total : \$0.00

<u>Labour</u>												
1	32	R & R Tailgate Components	1	\$120.00	0.00	\$120.00	\$120.00	0	0		\$0.00	600
2	33	R & R Rear Fender Sticker	1	\$180.00	0.00	\$180.00	\$180.00	0	0		\$0.00	1500
3	34	Check & Reconnect Wiring System	1	\$60.00	0.00	\$60.00	\$60.00	0	0		\$0.00	200
4	35	Straighten & Panel Beat Accident Area	1	\$1,800.00	0.00	\$1,800.00	\$1,800.00	0	0		\$0.00	11000
5	36	Respray Accident Area	1	\$1,600.00	0.00	\$1,600.00	\$1,600.00	0	0		\$0.00	10000

Labour Total: \$3,760.00 Final Sub-Total : \$0.00

Others

Others Total: \$0.00 Final Sub-Total : \$0.00

Total Price: \$12,735.00 Final Total Price : \$0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	10 Jan 2020		20 Jan 2020 10:51 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured: -, Co. Reg. No.: -

Main Claimant: **FEDERAL EXPRESS (SINGAPORE) PTE LTD,** Co. Reg. No.: 198402740W

Vehicle Reg. No.: GBB9947A	Date of Loss: 08/01/2020 10:00 - :59 [108 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type: TP / SNM20D200129/GBH8329J/TKL	Policy/Cover Note No.: DMCVSN1832611901 (Comprehensive)
Vehicle Reg. No. (Insured): GBH8329J	Policy No. (Claimant): 100774093
	Excess: S\$350.00

Repairer: **Mega Auto Pte Ltd (HQ)** Blk 10 Sin Ming Ind Est Sector C #01-04, 575645 Sin Ming - Tel: 64555884

Handling Insurer: **China Taiping Insurance (Singapore) Pte. Ltd. (HQ)** - Tel: 6389 6111 ... [Handled by **Susan Teo** - 6389 6178]

Claimant's Insurer: **AIG Asia Pacific Insurance Pte. Ltd. (SG)** - Tel: 65-6419-3000

Adjuster: **LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **KENNETH KONG**] ... **[Final Rpt due 30/01/2020]**

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBB9947A (SNM20D200129/GBH8329J/TKL)**
[GBH8329J]
TP
FEDERAL EXPRESS (SINGAPORE) PTE LTD
Jan 8 2020 10:00AM
[-]
Mega Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼		
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
2	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
3	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
4	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
5	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
6	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
7	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
8	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
9	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
10	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
11	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
12	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
13	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
14	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
15	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
16	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
17	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
18	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
19	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
20	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
21	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
22	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
23	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
24	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
25	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
26	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
27	24/03/20 09:19	General View	Load JPG	<input checked="" type="checkbox"/>	
Documentation			1 per page ▼	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	24/03/20 17:00	LTA REBATE	Load PDF		

Linked Accident Report Documents

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Mega Auto Pte Ltd (HQ)	Thumbnail	Print
1	15/01/20 09:28	Accident Statement	1 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Mega Auto Pte Ltd (HQ)	Thumbnail	Print
1	15/01/20 09:24	Accident Photo	1 Load JPG	✓
2	15/01/20 09:24	Accident Photo	1 Load JPG	✓
3	15/01/20 09:24	Accident Photo	1 Load JPG	✓
4	15/01/20 09:24	Accident Photo-At The Scene	1 Load JPG	✓
5	15/01/20 09:24	Accident Photo-TP Vehicle	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Mega Auto Pte Ltd (HQ)	Thumbnail	Print
1	15/01/20 09:22	Sketch Plan	1 Load JPG	✓
2	15/01/20 09:22	Sketch Plan #2	1 Load JPG	✓
3	15/01/20 09:25	Certificate Of Insurance	1 Load JPG	✓
4	15/01/20 09:25	Driving License/Work Permit-FF	1 Load JPG	✓
5	15/01/20 09:25	Driving License/Work Permit-Back	1 Load JPG	✓

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20001158/KYF3S2
Date: 24/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN1832611901
Claimant Vehicle No: GBB9947A Insured Vehicle No: GBH8329J
Date of Loss: 08/01/2020 Nature of Claim: TP Claim No: SNM20D200129/GBH8329J/TKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBB9947A Engine No: 1KD2051788
Make & Model: TOYOTA REGIUS ACE, 3.0 D DX (A) Chassis No: KDH2210007199
Reg. Date: 14/12/2010 (Man. Year: 2010) Odometer: 339976 km
Colour: White
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 20/01/2020
Date Inspected: 20/01/2020 Inspected At: 160 SIN MING DRIVE #02-01 Autocity
Estimated Period of Repair: 0.0 days Repairer: Mega Auto Pte Ltd

Adjuster: KENNETH KONG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 24 Mar 2020)	
Parts:	N/A	TOYOTA REGIUS ACE 3.0 D DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB9947A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >