

ISSUE

ASS. REC. BY:

REF: CSLAGI20001164/Dyd3n2

Special Instructions:

Surveyor: Brayan

ASSIGNMENT (Office)

From (Person): Ivy Rati Ila

of AGI

Date/Time: 20/01/2020 @ 12:58pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / IVA / INV / MV / CS

To Inspect Vehicle No:

SKT 6237J

Insured:

SMEISSIP

at Workshop name:

Teamwork Garage

Tel:

6844 2875

of

53 ubi Avenue 1 # 01-24

Policy No:

Claim No:

C10005310

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 1:05pm @ 20/01/2020

Person Contacted:

Damen

Vehicle IN OUT

Date/Time	Action/Instruction	Initials
	SKT 6237J - INV/INC 20001156/24	✓
	SMEISSIP - HA/INC 20001156/24	

D.O.A: 18/01/2020

D.O.A: 18/01/2020

ASS. REQ. BY:

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop-m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? Yes or No

GIA / PR Seen: _____ Consistent? Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKT 6237 J yr Regn: 2015 June

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Nissan Sylphy c.c. 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp Reading: 280150 T/Radio: Insured / Std / NI / NA

Eng/No: HR 169 68992 B

C/No: MHTBBAB17Z0023712

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Yokohama

Front

Rear

R/Bal. 5 mm R/Bal. 8 mm

L/Bal. 5 mm L/Bal. 8 mm

D.O.A. _____ D.O.I. 20/1/2020

Survey held at Teamwork Paya Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AGI SME 1551P

18/02/20 found 4/5 39501 - with 4 days of rep
(Red \$4549-71, 53%)

RECEIVED 19 FEB 2020

Date/Time, File Pass In?

: Preli. Report

Days Of Repair: 4

1)

: Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return In?

18/2/20 typist

Add Fee: Site Insp (\$)

Transportation:

Interview (\$)

S + RS \$

Tech. Inv (\$)

Photo

Wheel std (\$)

Other

Repair Estimate:

Estimate \$3950/

250

TOTAL

Nivitha (LKK Auto)

From: Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Sent: Monday, 20 January 2020 12:58 PM
To: Nivitha (LKK Auto)
Cc: 'SUR'; Julie Mangubat
Subject: FW: OUR REF : 2001-31 // YOUR REF : SME1551P ACCIDENT INVOLVING SME1551P AND SKT6237J || C10005310
Attachments: OD Report.pdf; TP Report.pdf

Hi Team,

We would like to arrange TP survey for SKT6237J.

Workshop information:
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

From: TEAMWORK <claims@teamworkgarage.com>
Sent: Monday, 20 January 2020 12:09 PM
To: Claims <claims@budgetdirect.com.sg>
Cc: TEAMWORK <claims@teamworkgarage.com>
Subject: OUR REF : 2001-31 // YOUR REF : SME1551P ACCIDENT INVOLVING SME1551P AND SKT6237J

WITHOUT PREJUDICE

OUR REF : 2001-31
YOUR REF : SME1551P

Dear Sir / Madam,
PRE-REPAIR INSPECTION FOR SKT6237J
ACCIDENT INVOLVING SME1551P AND SKT6237J ON 18.01.2020.

We refer to the above matter and enclosed herewith our client's GIA report and notification of Pre-repair inspection for your attention.

We also enclosed herewith the State Court of the Republic of Singapore Practice Direction-Amendment No. 1 of 2016 of Pre-repair Inspection for your attention.

****Please appoint LKK****

Thank you and have a nice day.

Regards,

Shu Shan
Teamwork Garage Pte Ltd
Blk 53 Ubi Avenue 1
#01-24
Paya Ubi Industrial Park
Singapore 408934
Tel: 6844 2475
Fax:6844 2474

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/01/2020 11:47
Date Of Accident	18/01/2020 03:40
Exact Location Of Accident	JUNC CLEMENCEAU AVE & HAVELOCK RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT6237J
Insured/Policyholder	
Name Of Registered Owner	CONNECT4CAR PTE LTD
Co Reg No	2XXXXX459M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-89999999

Vehicle Particulars

Manufacturer	NISSAN
Model	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5114296815
Cover Note Number	

Driver

Name of Driver	MOHD YAZID BIN HASHIM
NRIC No	SXXXX612J
Date Of Birth	15/04/1967
Occupation	OUTDOOR
Date Of Driving Pass	02/11/1987
Driving Experience	32 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97117671
Fax Number	
Contact Number	OFFICE-97117671
EEmail Address	NOEMAIL

Address	BLK 788 WOODLANDS AVENUE 6 #06-627
Postcode	730788
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	WOODLANDS EAST N.P.C
Police Station Address	ROAD: 3 WOODLANDS DRIVE 63 , POSTCODE: 737890 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20200118/2110.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO FOOTAGE WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SME1551P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLG9421E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MOHD YAZID BIN HASHIM
Approximate Age
Injuries Sustain NECK & BACK
Injured person in which vehicle? SKT6237J
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1) Please report **correctly** on the details of the accident to speed up the claims process.
- 2) This form must be **completed by the policy holder and/or the authorised driver.**
- 3) Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) **Any false reporting may be referred to the police for investigation.**
- 6) The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7) By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8) **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
 - (i) Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigations the accident and/or my claims;
 - (iii) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) Complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - (i) To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) For complying with requirements under my regulations, laws or court orders.




Policy holder's signature
Date / time:

Driver's signature
(if driver is not policy holder)
Date / time:

reporting centre personnel's Signature
Date / time:

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policy holder's signature
Date & time:

[Handwritten signature]

Driver's signature
(If driver is not policy holder)
Date & time:

[Handwritten signature]

reporting centre personnel's Signature
NRIC/FIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20200118/2110

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

1 of 3
Report No: T/20200118/2110

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/01/2020 18:35	Video Report No.:	Station Diary No.: 94
--	-------------------	--------------------------

Informant's Particulars			
Name of Informant: MOHD YAZID BIN HASHIM		Address: APT BLK 768 WOODLANDS AVENUE 6 #06-627 SINGAPORE 730768	
ID Type / ID No.: NRIC NO / S1798612J		Contact No.: Home/Office: Mobile: 97117671	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 52	Date of Birth: 15/04/1967	Type of Informant: Driver
Race: Malay		Language:	Institution / School Name:
Occupation: Private Hired Driver		Driving Licence Information: Class: 3	Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 18/01/2020 03:40	Type of Location:
Location: Along Road 1 Traveling Toward Road 2 CLEMENCEAU AVENUE HAVELOCK ROAD Traffic light junction				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKT6237J	Car	NISSAN	Sylphy	Grey	Seriously Damaged	1
SLG9421E	Car	HONDA	Shuttle	Silver	Seriously Damaged	0
SME1551P	Car	SUBARU	Forester	Blue	Seriously Damaged	1

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date

Police Report



**SINGAPORE
POLICE FORCE**



T/20200118/2110

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

2 of 3
Report No. T/20200118/2110

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No	Insurance Company	Insurance No	Effective	Expiry Date
SKT6237J	NTUC Income Insurance Co-Operative Limited	5114296815	04/12/2019	16/12/2020

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	MOHD YAZID BIN HASHIM	ID No.	S1798612J
Related Vehicle	SKT6237J (Car)	Contact No.	97117671
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 18/01/2019 at around 0344hrs, as I was stopping my vehicle at the traffic light junction as it was red light. The car plate SME1551P behind me had bang to my rear due to the car SLG9421E behind him did not manage to stop the car on time. Thus there was a chain collision.

During this incident, I had a passenger sitting at the rear seat however he do not sustained any injury. As for the vehicle SME1551P had passenger sitting beside her and he did not sustained any injury. As for the vehicle SLG9421E, I am not sure whether he had any passenger with him.

My vehicle sustained badly damaged as the bumper was dented and I am not able to closed my bonnet. As for SME1551P sustained badly damaged as the front boot and rear bumper was dented. As for SLG9421E, sustained damaged at the front boot was dented.

There is no police or ambulance at scene. I am not sure whether is there any CCTV at the said location. I have the in car camera inside my vehicle.

Police Report



SINGAPORE
POLICE FORCE



T/20200118/2110

Police Station Of Origin:
Woodlands East N.P.C.
3 Woodlands Drive 63 SINGAPORE 737890
Tel No: 1800-7679999

3 of 3

Report No: T/20200118/2110

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Sgt 3 KHADIJAH BINTE AB SAMAD	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 18/01/2020 16:35
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No: 65476151 SN 130	Classification Of Case:
Authentication Stamp Singapore Police Force	



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC: 201015366H

AUTO & GENERAL

REPAIR PERFORMA INVOICE

Vehicle number	SKT6237J
Make / Model	NISSAN/SYLPHY
Chassis number	MNTBBAB17Z0023712
Accident date	18 January 2020
Reference	2001-31

Qty Particulars

Unit Price - SGD \$

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER <i>distorted / minty crack</i>	720.80 ✓
1	REAR BUMPER LOWER SKIRT <i>distorted</i>	676.20 ✓
1	BOOTLID <i>vt</i>	655.00 ✓
1	END PANEL <i>Distort</i>	552.00 ✓
		2604.00
		2604.00
		Less 30%
		781.20
		1822.80
2	REAR BUMPER SIDE RETAINER <i>o/s broken n/s NN</i>	49.30 ✓
2	REAR BUMPER REFLECTOR <i>nn</i>	92.00 X
1	REAR BUMPER CENTRE SPONGE <i>turn</i>	69.00 ✓
1	REAR BUMPER SIDE SPONGE <i>turn o/s</i>	100.00 ✓
1	BOOTLID EMBLEM LOGO <i>hcc</i>	55.60 ✓
1	BOOTLID EMBLEM SYLPHY <i>hcc</i>	100.00 ✓
1	BOOTLID EMBLEM SIGNATURE <i>hcc</i>	89.20 ✓
1	BOOTLID EMBLEM XTRONIC CVT <i>hcc</i>	45.60 ✓
1	BOOTLID TOP MOULDING <i>hcc</i>	156.60 ✓
1	BOOTLID BOTTOM CHROME MOULDING <i>hcc</i>	120.00 ✓
2	BOOTLID LAMP <i>nn</i>	437.58 X
1	BOOTLID LOCK <i>Down</i>	79.00 ✓
1	BOOTLID LOCK STRIKER <i>vt</i>	69.00 ✓
1	BOOTLID WEATHERSTRIP <i>distorted / hcc</i>	87.00 ✓
2	BOOTLID HINGE <i>nn</i>	178.00 X
1	BOOTLID INNER TRIM <i>nn</i>	178.80 X
2	TAILLAMP <i>nn n/s o/s crack minty</i>	547.30 ✓
1	REAR FENDER INNER TRIM RH <i>vt / turn</i>	235.52 ✓
1	END PANEL TOP GARNISH <i>minty distorted</i>	65.40 ✓
1	SPARE TYRE SPONGE <i>nn</i>	175.00 X
		2929.90
		Less 10 %
		292.99
		Subtotal
		2636.91

24.65

273.65

PARTS REPLACEMENT - SPECIAL NETT ITEMS

	Balance B/F	4459.71
1 SET	REAR REVERSE SENSOR Dem / shunt	400.00 220/-
1 SET	REAR BUMPER CLIP H/W	50.00 20/-
1	JOINT SEALANT H/W	150.00 40/-
1	REAR NUMBER PLATE H/W	80.00 X
	Subtotal	680.00
	Balance C/F	5139.71
	<u>LABOUR AND MISCELLANEOUS CHARGES</u>	
	Balance B/F	5139.71
1	CHECK REAR WIRING AND LIGHTING SYSTEM	60.00 30/-
2	REMOVE AND RENEW REAR REVERSE SENSOR	150.00 40/-
3	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	200.00 80/-
4	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW	200.00 60/-
5	PANEL BEATING ON AFFECTED AREAS	1200.00 600/-
6	SPRAY PAINTING ON AFFECTED AREAS	1400.00 600/-
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 40/-
	Subtotal	3360.00
	Grand total	8499.71

20/01/2020 @ 1102hrs

N/A Auction
2/5mm 4 days.

Ryan

LKK Auto



4975.99

L/S 3950/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI20001164/Dyd3n2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 19-02-2020	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SME 1551P	Veh. Inspected	SKT 6237J
Policy No.		Coverage (\$)	0.00
Claim No.	C10005310	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	20/01/2020
2. Vehicle Particulars & Condition			
Make & Model	NISSAN SYLPHY	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	MNTBBAB17Z0023712	Colour	GREY
Odometer	280150	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	5 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/01/2020	Inspection Date	20/01/2020
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 6237J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED / MOUNTING CRACKED	720.80	720.80
1	REAR BUMPER LOWER SKIRT	DISTORTED	676.20	676.20
1	BOOTLID	BENT	655.00	655.00
1	END PANEL	DENTED	552.00	552.00
	LESS 30% DISCOUNT		-781.20	-781.20
			1,822.80	1,822.80
NETT ITEMS				
2	REAR BUMPER SIDE RETAINER (N)	O/S BROKEN / N/S NOT NECESSARY	49.30	24.65
2	REAR BUMPER REFLECTOR (N)	NOT NECESSARY	92.00	-
1	REAR BUMPER CENTRE SPONGE (N)	TORN	69.00	69.00
1	REAR BUMPER SIDE SPONGE O/S (N)	TORN	100.00	100.00
1	BOOTLID EMBLEM LOGO (N)	NECESSARY	55.60	55.60
1	BOOTLID EMBLEM SLYPHY (N)	NECESSARY	100.00	100.00
1	BOOTLID EMBLEM SIGNATURE (N)	NECESSARY	89.20	89.20
1	BOOTLID EMBLEM XTRONIC CVT (N)	NECESSARY	45.60	45.60
1	BOOTLID TOP MOULDING (N)	NECESSARY	156.60	156.60
1	BOOTLID BOTTOM CHROME MOULDING (N)	NECESSARY	120.00	120.00
2	BOOTLID LAMP (N)	NOT NECESSARY	437.58	-
1	BOOTLID LOCK (N)	DAMAGED	79.00	79.00
1	BOOTLID LOCK STRIKER (N)	BENT	69.00	69.00
1	BOOTLID WEATHERSTRIP (N)	DEFORMED / NECESSARY	87.00	87.00
2	BOOTLID HINGE (N)	NOT NECESSARY	178.00	-
1	BOOTLID INNER TRIM (N)	NOT NECESSARY	178.80	-
2	TAILLAMP (N)	O/S MOUNTING CRACKED / N/S NOT NECESSARY	547.30	273.65
1	REAR FENDER INNER TRIM RH (N)	BENT / TORN	235.52	235.52
1	END PANEL TOP GARNISH (N)	MOUNTING DEFORMED	65.40	65.40

Report Ref No. CS/AGI20001164/Dyd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPARE TYRE SPONGE (N)	NOT NECESSARY	175.00	-
	LESS 10% DISCOUNT		-292.99	-157.02
			2,636.91	1,413.20
	SPECIAL NETT ITEMS			
1	SET REAR REVERSE SENSOR (SN)	DAMAGED / SHORTED	400.00	220.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	JOINT SEALANT (SN)	NECESSARY	150.00	40.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	80.00	-
			680.00	290.00
	LABOUR			
	CHECK REAR WIRING AND LIGHTING SYSTEM.		60.00	30.00
	REMOVE AND RENEW REAR REVERSE SENSOR.		150.00	40.00
	REMOVE AND REFIT REAR LINING, TRIM AND GARNISH.		200.00	80.00
	TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW.		200.00	60.00
	PANEL BEATING ON AFFECTED AREAS.		1,200.00	600.00
	SPRAY PAINTING ON AFFECTED AREAS.		1,400.00	600.00
	APPLY ANTI RUST ON AFFECTED AREAS.		150.00	40.00
			3,360.00	1,450.00
	GRAND TOTAL		8,499.71	4,976.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,950.00

Report Ref No. CS/AGI20001164/Dyd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.