



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20001178/Kka3q2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 15-05-2020



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

|                     |                |                       |            |
|---------------------|----------------|-----------------------|------------|
| <b>Insured Veh.</b> | SHA 2138Z      | <b>Veh. Inspected</b> | SJQ 1960P  |
| <b>Policy No.</b>   | D-20094922MFSH | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | D20000449MFSH  | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | RACHEL WU      | <b>Assign Date</b>    | 20/01/2020 |

### 2. Vehicle Particulars & Condition

|                         |               |                     |            |
|-------------------------|---------------|---------------------|------------|
| <b>Make &amp; Model</b> | HONDA FIT (A) | <b>c.c</b>          | 1339       |
| <b>Engine No.</b>       | HIDDEN        | <b>Year of Reg.</b> | 2009       |
| <b>Chassis No.</b>      | GE61161215    | <b>Colour</b>       | RED        |
| <b>Odometer</b>         | 177           | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER      | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD          |                     |            |

### 3. Conditions of Tyres

|                       | Size       | Make     | Balance |
|-----------------------|------------|----------|---------|
| <b>R/H Front Tyre</b> | 195/50 R15 | GOODYEAR | 5 mm    |
| <b>L/H Front Tyre</b> | 195/50 R15 | GOODYEAR | 5 mm    |
| <b>R/H Rear Tyre</b>  | 195/50 R15 | GOODYEAR | 7 mm    |
| <b>L/H Rear Tyre</b>  | 195/50 R15 | GOODYEAR | 7 mm    |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S DOOR MIRROR.  
DAMAGES SEE DETAILS.

### 5. General Information

|                       |  |                        |            |
|-----------------------|--|------------------------|------------|
| <b>Accident Date</b>  | 14/01/2020   | <b>Inspection Date</b> | 22/01/2020 |
| <b>Survey held at</b> | CITY AUTO PTE LTD<br>BLK 8, SIN MING IND. ESTATE<br>#01-60/62<br>Sector C<br>SINGAPORE 575643. |                        |            |

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **1 Working Days**