

ASS. REC. BY:

REF: CS3/FCI 20001225/Hyf3⁵²

Special Instruction:

Surveyor: Hock Ann

ASSIGNMENT (Office)

From (Person): Jason Tan chee kiat of FCI

Date/Time: 21.1.2020 9.17a.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SKM 504P

Insured: SH 7239 R

at Workshop n/s Gforce Autotechnik

Tel: 97706106

of 10 Kati Bukit Rd 2 # 01-34

Policy No:

Claim No: D20000421 MPBH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.9.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 21.1.2020 10.27a.m

Person Contacted: elle

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (x) Estimate
	SKM 504P - X
	SH 7239 R - CS/FCI 19013891/ E43n2 D.O.A - 21/10/2019

ASS. REC. BY:

REF: PC1

ASSIGNMENT

From:

Date:

21 Jan. 2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: Skm 504P

at Workshop m/s G Force Autotechnik

of 10 kaki Bukit Rd 2 #01-34 First East Centre

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

\$46K

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Skm 504P

Yr Regn:

17/01/2014

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

T. corolla Altis

C.C.

1598

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

288799 km

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MK053REH104500051

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Good / Jammed / Leaked / Burnt or

Brake: Good / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55/R16

R:

17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

8/9/2019

D.O.I.

21/1/20

Survey held at

G Forge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

repair days → 4 days

* Skm 504P
PRS code

RECEIVED 5 MAR 2020

MV - 46000

PV - 38436

NV - 7500

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

5/3/20 Typist

Rep. Format:

PRS

Lump Sum / E.B. / C.

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

MOTOR SURVEY ASSIGNMENT

Date	16-01-2020	Our Ref No.	D20000421MFSH
Accident Date	08-09-2019	Claim Type.	Third Party
Insured Vehicle	SH7239R	Third Party Vehicle.	SKM504P
Survey Location	10 KAKI BUKIT ROAD 2 #01-34 FIRST EAST CENTRE		
Contact Person.	ADRIAN/ DEREK		
Contact No.	0/ 97706106	Fax No.	0
Survey Type	WITHOUT PREJUDICE: SURVEY OR PRI ON WP BASIS		
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD		
Contact Person	NA	Fax No.	68416315
Contact Number.	NA		

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	GFORCE AUTOTECHNIK PTE LTD	Attention.	NIL
Cc : TP Solicitor	ADVANCE LAW LLC	TP Solicitor Fax No.	62585521
Officer Incharge	JASON TEA CHEE KIAT		

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/09/2019 12:52
Date Of Accident	08/09/2019 03:00
Exact Location Of Accident	EU TONG SEN STREET / TEW CHEW STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM504P
Insured/Policyholder	
Name Of Registered Owner	VERMAX CAR LEASING AND MARKETING PTE LTD
Co Reg No	201530285C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97770553

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6L CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5093756378-02
Cover Note Number	

Driver

Name of Driver	EDDIEAIROS BIN ABDULLAH
NRIC No	S7821012E
Date Of Birth	23/07/1978
Occupation	OUTDOOR
Date Of Driving Pass	24/08/2012
Driving Experience	7 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81189973
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

EDDIEAIROS BIN ABDULLAH

Approximate Age

41

Injuries Sustain

Injured person in which vehicle?

SKM504P

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

BLK 306B PUNGGOL PLACE #07-21

Postcode

822306

Accident Sketch Plan

SKETCH PLAN

TEW CHEW
ST

A-SKM504R

B-SH7239R

EU TONG SEN
STREET

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer
To Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Officer's Signature

Phone: 67416697 Fax: 67492305

NSIC/PIN No. Email: vacb@singnet.com.sg

11 SEP 2019

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20190910/2000

2 of 3

Report No: T/20190910/2000

Police Station Of Origin:
Bukit Merah East N.P.C
A 391 New Bridge Road Police Cantonment
Complex SINGAPORE 088762
Tel No: 1800-2369999

CONTINUATION OF REPORT

Driver			
Name	EDDIEFAIROS BIN ABDULLAH		ID No. S7821012E
Related Vehicle	NIL		Contact No. 81189973
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

I was travelling along Eu Tong Sen Street towards Tew Chew Street at about 3am with a female passenger in my car. I am a Grab Driver. I wanted to change to the leftmost lane as I wanted to turn left into Tew Chew Street. I noticed a taxi (SH7239R) stationary along Eu Tong Street picking up a passenger. I cannot recall if his hazard light was on or not. As I was about to change lane and turn left, when I drove past him, he drove forward, resulting in him hitting onto the rear left portion of my car, near the wheel. There are dents and scratches on my car at the aforementioned affected area. I am not aware of any injuries on anyone else but I am experiencing slight lower back pain and it could be because of the accident. I am lodging this report for insurance claims. That is all.

Accident Sketch Plan



Mount Alvernia Hospital
Medical Certificate

24-Hour Walk-in Clinic and
Emergency Department

No. M19000023874

This is to certify that EDDIEFAIROS BIN ABDULLAH, S7821012E, is granted Outpatient Sick Leave for 5 day(s)
from 10-Sep-2019 to 14-Sep-2019.
Remark :

This medical certificate is not valid for absence from Court or judicial proceeding unless specifically stated.

Dr. Lim Jie Sheng

MCR : 197110

A&E / 24-HOUR WALK-IN CLINIC
Mount Alvernia Hospital
820 Thomson Road
Singapore 574623
Tel: 63476210

10/09/2019

Date

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	285C
Vehicle Details	
Vehicle No.:	SKM504P
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jan 2020
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA COROLLA ALTIS 1.6L CVT
Primary Colour:	Silver
Manufacturing Year:	2013
Engine No.:	1ZRX357526
Chassis No.:	MR053REH104500051
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$18,777.00
Original Registration Date:	17 Jan 2014
First Registration Date:	17 Jan 2014
Transfer Count:	①
Actual ARF Paid:	\$13,777.00 — 6888
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Jan 2024
PARF Rebate Amount:	\$8,955.00
Intended COE Rebate Details	
COE Expiry Date:	16 Jan 2024
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$74,002.00
COE Rebate Amount:	\$29,481.00
Total Rebate Amount:	\$38,436.00

The information contained herein is correct as at 22 Jan 2020

OK

Millionaires hate Zhang

Millionaires hate Zhang - Small Investments made too many Singaporeans ri

Toyota Corolla

Price Range

Depreciation

2014

Vehicle Type

Home » Used Cars » Just Paper Motoring » Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

PREM

Price \$51,800

Depreciation ⑦ \$9,660 /yr
View models with similar depre

Reg Date 18-Sep-2014
(4yrs 7mths 26days COE left)

Mileage 51,650 km (9.7k /yr)

Manufactured ⑦ 2014

Road Tax ⑦ \$742 /yr

Transmission Auto

Dereg Value ⑦ \$38,846 as of today (change)

OMV ⑦ \$18,650

COE ⑦ \$62,890

ARF ⑦ \$13,650

Engine Cap 1,598 cc

Power 90.0 kW (120 bhp)

Curb Weight ⑦ 1,205 kg

No. of Owners ⑦ 1

Type of Vehicle Mid-Sized Sedan

Features

1.6L 4 Cylinders Dual VVT-I Engine, 120Bhp, CVT Automatic With Steptronic, ABS, Airbags, Auto Headlights/Rain Sensors, Keyless Entry/Start/Stop. View specs of the Toyota Corolla Altis (2014-2019)

Accessories

Xenon Light, Sports Rims, Electric Leather Seats, Touch Screen Bluetooth/Steering Controls/GPS, Reverse Sensors/Camera, Retractable Side Mirrors.

Description

Price Negotiable And Yet Selling The Cheapest In The Market, Lowest Genuine Mileage Clocked By Previous Owner, Excellent Condition Taken Care Of, Original Paintwork, Accident Free And Hassle Free, Drive With A Peace Of Mind, Flexible Loan Can Be Arranged With Lowest Interest Rate Of 1.98%, Hurry Contact Us Now For More Information Or Drop By For A Test Drive!

Category

PARF Car, Premium Ad Car, Low Mileage Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

? Request to have this car evaluated professionally. Find out more

Compare



Location Map

Price Chart



Shortlist

Compare

Add nc

Report Error

More Actions

Seller Information



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Ref: CS3/FCI20001225/Hyf3s2 Date: 06-03-2020 Code: FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SH 7239R	Veh. Inspected	SKM 504P
Policy No.		Coverage (\$)	0.00
Claim No.	D20000421MFSH	Excess (\$)	0.00
Assign From	JASON TEO CHEE KIAT	Assign Date	21/01/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MR053REH104500051	Colour	SILVER
Odometer	288799 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	5 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	5 mm
R/H Rear Tyre	205/55 R16	MICHELIN	5 mm
L/H Rear Tyre	205/55 R16	MICHELIN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.			
5. General Information			
Accident Date	08/09/2019	Inspect Date / Time	21/01/2020 (01:07 PM)
Survey held at	GFORCE AUTOTECH PTD LTD 10 KAKI BUKIT ROAD 2 #01-34 FIRST EAST CENTRE SINGAPORE 417868		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) MARKET VALUE: \$46,000.00			

Report Ref No. CS3/FCI20001225/Hyf3s2

Inspected By



LEE HOCK ANN

Asst. Automotive Assessor



K.K. LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.