The second of th	1111	Date & Time	Completed	Done b	120
Date In: 11/10-12:38	Jeb description	Date & time	Compresed	201100	
Res No: Na al hours	SAS e-filing				
Veh No: Smy 7160T	E-mail (within Shrs, Al	C 2hrs)	-		
D.O.A: 11/10-17:10	i-Motor Claim For	m e			
	i-Motor W/O (Withi	n: OD 2hrs, TP 4hrs)			
OD . (7) ! Reporting Only	i-Photo Uploaded				
	Assessment/Survey I	Report			
TP Insurer:	Ass't Report by Fax	/ Hand to Owner/Wksr			
Preferred Wksp / INC Assign Wksp / QW: (Tel:	Fax:	54 005 T THU VIEW)
TP Particulars: Veh No: 6V	164x	INC()/Non-IN	C().		
Owner / Driver: (Tel:)	
Policy No: () Per	riod: () Cover Type:	()	
Confirmed by : (Dat	e: Tin	ne:)	1024 (1007 1007)
Insured/Driver Liability: (%) []	Note-Est. Status (WO):	N: 0-20%; P: 21-79	%. F: 80-100%]	+
Year of Registration: ()	Warranty: YES ()/1	40()			
Excess: (S) Loading: \$1,0	00()/\$2,000()			
General Remarks;-			es est à Bar	Silve	
() Walk-In Customer: Customer's info	rmation strictly Confiden	tial & Strictly NO refer	of repairer.		
() Total Luss Case : to e-mail Insure	er URGENTLY.				
Drive-In ()/ Towed-In (); Invoice	:: YES() / NO(); Towing Co: ()
Remarks: (INC horline: 6788 6616)		- Date&Time	Completed "	Done	by -
Tremating.	POT COLUMN SERVICE ALBORDO EN ACTUAL DE LA COLUMN SERVICE DE LA COLUMN S	THE RESIDENCE MANAGEMENT AND THE		Article of the State of	A STATE OF THE STA
1) Apply for Transport Allowance ()/(Courtesy Car ()	00000			
1) Apply for Transport Allowance ()/C	Courtesy Car ()				
2) QC Check / Post Repair Inspection	()				
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$3	()				
2) QC Check / Post Repair Inspection	()				
QC Check / Post Repair Inspection Upload Resurvey Photo [Repair Cost > \$3	()			South	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()			SCHOOL ST	Y 12 P 1
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()			SOADAF.	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()			SOAD NE.	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions	() 3000] ()			Ant (5)	Amt(\$)
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions	() 3000] ()	pice Preparation Che	cklist		Amt (1)
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions	() 5000] () 1ny 1 AF 2 DA	: Accident Reporting (530 : Damage Assessment (510	cklist); o); INC (\$80)	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Raimant's Particulars:-	() 3000] () Inv	: Accident Reporting (530 : Damage Assessment (510 : Towing Fee	cklist	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions laimant's Particulars:- river/Owner:	() 3000] () 3000] () 3000] () 3000] () 4) FT	: Accident Reporting (530 : Damage Assessment (510 : Towing Fee : Follow-Through Survey : Follow-Through Survey (R	Cklist:); 0); INC (\$80)	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Raimant's Particulars:- river/Owner: ontact No:	() 3000] () 3000] () 3000] () 4 Inv	: Accident Reporting (530 : Damage Assessment (510 : Towing Fee : Follow-Through Survey : Follow-Through Survey (R	cklist:); 0); INC (\$80) \$40/\$45 \$120 esurvey) \$30 (wef 10 Jan 2005) \$75	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Injury: I	() 3000] () 3000] () 3000] () 4 Inv	: Accident Reporting (530) : Damage Assessment (510) : Towing Fee : Follow-Through Survey (Reclaiming against INC Only 1: Re-inspection : Idae DA + SMRT Survey	cklist:); 0); INC (\$80) \$40/\$45 \$120 eaurvey) \$30 (wef 10 Jan 2005)	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions Injury: I	() 3000] () 3000] () 3000] () 3000] () 4) FT 4) FT 5) FT Fest 6) TF 7) NI 3) NI	: Accident Reporting (530) : Damage Assessment (510) : Towing Fee : Follow-Through Survey (Reclaiming against INC Only 1: Re-inspection : Idae DA + SMRT Survey UC Additional Services.	Ckdist.); 0); INC (\$80) \$40/\$45 \$120 esurvey) \$30 (wef 10 Jan 2005) \$75 \$160	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions laimant's Particulars:- river/Owner: ontact No: amaged Portion:	() 3000] () 3000] () 3000] () 4) FT 5) FT Eq. 6) TF 7) NI 8) NI QI	: Accident Reporting (530 : Damage Assessment (510 : Towing Fee : Follow-Through Survey (R claiming against INC Only : Re-inspection : Idae DA + SMRT Survey UC Additional Services.	Cklist: 0); INC (\$80) \$40/\$45 \$120 caurvey) \$30 (wef 10 Jan 2005) \$75 \$160	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions laimant's Particulars: river/Owner: ontact No: amaged Portion: C Checked by (Engr-In-Charge):	() 3000] () 3000] () 3000] () 4 inv 2 inv 3 inv 4 inv 4 inv 5 inv 6 inv 7 inv 8 inv 9 inv 8 inv 9	: Accident Reporting (530) : Damage Assessment (510) : Towing Fee : Follow-Through Survey (Reclaiming against INC Only) : Re-inspection : Idae DA + SMRT Survey UC Additional Services. 5: Courtesy Car / Tpt Allowa 6: Repair Co-ordination 7: Fost Repair Inspection	Cklist:); 0); INC (\$80) \$40/\$45 \$120 esurvey) \$30 (wef 10 Jan 2005) \$75 \$160 noc \$5 \$10 \$25	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions laimant's Particulars:- river/Owner: ontact No: amaged Portion: C Checked by (Engr-In-Charge):	() 3000] () 3000] () 3000] () 4 1) AF 2) DA 3) TF 4) FT 5) FT Feat 6) TF 7) NI 8) NI 90 10 10 10 10 10 10 10 10 10 10 10 10 10	: Accident Reporting (530 : Damage Assessment (510 : Towing Fee : Follow-Through Survey (R claiming against INC Only : Re-inspection : Idae DA + SMRT Survey UC Additional Services. 5: Courtesy Car / Tpt Allowa 6: Repair Co-ordination 7: Fost Repair Inspection 8: DV / Collect Excess Coordination	Cklist (i); (i); (i); (i); (i); (ii); (iii); (iii); (iii); (iiii); (iiii); (iiii); (iiii); (iiii); (iiii); (iiii); (iiii); (iiiii); (iiiiii); (iiiiiii); (iiiiiiii); (iiiiiiiiii	Ant (5)	
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date/Time Actions	() 3000] () 3000] () 3000] () 4) FT 5) FT Eq. 6) TF 7) NI 8) NI • N • N • N • N • N • N • N • N	: Accident Reporting (530) : Damage Assessment (510) : Towing Fee : Follow-Through Survey (Reclaiming against INC Only) : Re-inspection : Idae DA + SMRT Survey UC Additional Services. 5: Courtesy Car / Tpt Allowa 6: Repair Co-ordination 7: Fost Repair Inspection	Cklist (i); (i); (i); (i); (i); (ii); (iii); (iii); (iii); (iiii); (iiii); (iiii); (iiii); (iiii); (iiii); (iiii); (iiii); (iiiii); (iiiiii); (iiiiiii); (iiiiiiii); (iiiiiiiiii	Ant (5)	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available
 aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/01/2020 12:38

Date Of Accident 21/01/2020 17:10

Exact Location Of Accident BLK 742 BEDOK RESERVOIR RD CARPARK

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMJ7160T

Insured/Policyholder

Name Of Registered Owner LEOW ZI XIANG TOMMY

NRIC No SXXXX267F

Email Address NOEMAIL

 Mobile Phone No
 (LOCAL) +65-91592245

 Alternative Phone No
 OFFICE-91592245

Vehicle Particulars

Manufacturer KIA

Model CERATO 1.6(A) EX

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE USE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1900067630

Cover Note Number

Driver

Name of Driver LEOW ZI XIANG, TOMMY

 NRIC No
 SXXXX267F

 Date Of Birth
 06/08/1986

 Occupation
 INDOOR

 Date Of Driving Pass
 15/09/2006

Driving Experience 13 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-91592245

Fax Number

Contact Number OFFICE-91592245

EMail Address NOEMAIL

BLK 805 CHAI CHEE ROAD Address

#06-632

Postcode 460805

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - MAJOR/MINOR RD Type Of Accident

Weather Conditions CLEAR Road Surface DRY

Other Information

NO Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Passenger 1

NO

2

NO

: FEMALE

NAME:

GENDER:

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

YES Are accident photos available for attachment? YES

Was there any video captured by Car Camera?

VIDEO FOOTAGE WITH DRIVER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GV464X

Vehicle Make/Model/Colour

Details Of Properties

Remarks/ Reasons:

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Page 2 of 14

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1) Please report correctly on the details of the accident to speed up the claims process.
- 2) This form must be completed by the policy holder and/or the authorised driver.
- 3) Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4) The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5) Any false reporting may be referred to the police for investigation.
- 6) The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies
 of the report being made available aforesaid.
- 8) Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in the [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as police), for the purpose(s) of:
 - Processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (II) Investigations the accident and/or my claims;
 - (III) Carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (IV) Administering my claims (including the mailing of correspondence, statement, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelops/mail packages); and/or
 - (V) Complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "purposes")
- (b) All insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyer/law firms, may/are permitted to collect, use, disclose and/or process my personal information for one or more of the above purposes; and
- (c) My personal information may/can be disclosed by any of the insurer and/or GIA to their third party service providers or agents (including their lawyer/law firms), which may be sited outside of Singapore, for one or more of the above purposes.
- (d) My personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) The information so collected under (d) above may be shared / disclosed:
 - To all insurers and/or any other third parties that assist in evaluating, investigation, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposed stated, or

(II) For complying with requirements under my regulations, laws or court orders.

Policy holder's signature

Date / time:

Driver's signature (if driver is not policy holder) Date / time: reporting centre personnel's Signature
Date / time:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the Stated date and time, I was travelling Straight

at Blk 742 Bedok Rerservoir Rd (arpark heading towards of the Slip Pd

the gantry. Suddenly, Vehicle B (GV464X) turned ont,

without ensuring that there were oncoming car and

hit onto the left, side portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policy holder's signature Date & time: Driver's signature (if driver is not policy holder) Date & time: reporting centre personnel's Signature NRIC/FIN No.:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Complete and submit this form to the individual insurance authorised reporting centre.
- Please report correctly on the details of the accident to speed up the claim process.
- This form must be filled up by the policy holder and/or authorised driver.
- Information provided must be as fruitful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the traffic police department for investigation.

ACCIDENT DETAILS	
21 / 01 / 2020	(DD/MM/YY)
5: 12 pm	(HH:MM)
BIK 742 Bedok Reservoir Rd	(arpark.
	21 01 2020

在基金的基本方式是1999		DETAILS OF	VEHICLE			
Vehicle registration number	SWI	7160T				
Vehicle make and model	Kia	Cerato		N Tree III		
Type of vehicle	Saloon Z	MPV Bus	CRV □ Motorcy	Van : ⁄cle □	Others:	
Vehicle category	Private a	Comme	ercial 🗆 🔠	Motorcyc	le 🗆	
Purpose of using at said time						
Are you claiming under your own insurance company?	Yes □ Third part	No p	if no, please Reporting o			

	INSURANCE IN	FORMATION	
Insurance company	AIG		
Policy number	1900067630		17.1 (1)12.1
Type of policy	Comprehensive	Third party fire & theft \square	TP only 🗆

INSURED / POLICY HOLDER	
Leow 21 Xiang, Tommy	Male ≠ Female □
58621267F	
91592245	
BIK 805 chai chee Road	#06-632 5(460805)
	Leow Zi Xiang, Tommy 58621267F 91592245

DRIVER	SAME AS INSURED ABOVE (SKIP TO D.O.B)	
Name	Male Female	e 🗆
NRIC / Fin / Passport number		
Contact		
Address		
Email address		
Date of birth	06/08/1986	
Occupation	Indoor D Outdoor D	
Driving date pass	15/09/2006	

1					
	GENERAL	INFORMATION	OF THE ACCIDENT		
Was driver an employee of	Yes 🗆	Not			
the insured's company?	If no, rel	ationship of the	driver and insured: _	owner	
Accident captured by camera?	Yes	No 🗆			
Weather condition	Clear	Raining	Others:		
Road surface	Dry	Wet □			
No of passenger	2			(Inclusive	of driver
	////				
		PASSENGE	R 1		
Name					A PURE L
Gender	Male 🗆	Female o			
Condo	TVIOLE D	remarcy			
The second second second second	A UNIVERSAL	PASSENGE	0.2	Maria Calledon San Tile	- Manual N
Name	Secretaria de la Compansión de la Compan	PASSENGE	.K 2		
Gender	Male 🗆	Female □			
Gender	Iviale 🗆	remaie 🗆			
					SHORING
是是特别的一种的人。 第二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十二十		PASSENGE	R 3		No State
Name		220000000000000000000000000000000000000			
Gender	Male 🗆	Female 🗆			
	- Anna Marian				
世界民族。原於世界中的世	WEST IN	PASSENGE	R 4	是 IN	
Name					
Gender	Male □	Female			
	7. 学品情	PASSENGE	R 5		
Name					
Gender	Male 🗆	Female			
	, 全一要年	PASSENGE	R 6		No.
Name				Market To Second	
Gender	Male 🗆	Female			
Centre	Tividic B	remote E			
	STEWNESS.	OTHER INFORM	MATION	Malking (USIS)	
Was anybody injured?	Yes 🗆	No.	MATION		405.08
Was other vehicle damaged?	Yes	No 🗆			
was other vehicle damaged:	Test	NO			
N. Sen. Makeum Al-Water Bolder				AND THE DESIGNATION	
Carlon LVA No. C. Colonia			ATION ACTION		
Reported to police?	Yes 🗆	No e If y	es, please state which	police station.	
Police station name	er on the state of				
5000000000000000000000000000000000000		WITNESS	1		是是是特色
Name					
在新发展的关系是否是对应		WITNESS	2	10000000000000000000000000000000000000	- 1
Name					

(C) 100 (C) 1	THIRD PARTY VEHICLE 1
Vehicle registration number	GV 464 X
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	
	THIRD PARTY VEHICLE 2
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	
A SALE OF SALES OF SALES	THIRD PARTY VEHICLE 3
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	
以及数据数据的	THIRD PARTY VEHICLE 4
Vehicle registration number	THE STEEL PRODUCTION OF THE SECTION
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	
	THIRD PARTY VEHICLE 5
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	
国民发生的产品的企业的企业	THIRD PARTY VEHICLE 6
Vehicle registration number	
Vehicle make model	
Name	
NRIC / Fin / Passport number	
Contact	
2000年1900年1900年1	THIRD PARTY VEHICLE 7
Vehicle registration number	

Vehicle make model

NRIC / Fin / Passport number

Name

Contact

		WWW.DED DEDCOMA
10000000000000000000000000000000000000	HIS SELECTION	INJURED PERSON 1
Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes 🗆	No 🗆
Was injured conveyed to	Yes 🗆	No 🗆
hospital by ambulance?		
Market Street Service Street		INJURED PERSON 2
Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes 🗆	No 🗆
Was injured conveyed to	Yes 🗆	No 🗆
hospital by ambulance?		
		INJURED PERSON 3
Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes □	No p
Was injured conveyed to	Yes 🗆	No 🗆
hospital by ambulance?		
		INJURED PERSON 4
Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes □	No 🗆
Was injured conveyed to	Yes 🗆	No □
hospital by ambulance?		
《	THE PARTY	INJURED PERSON 5
Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes 🗆	No 🗆
Was injured conveyed to	Yes □	No 🗆
hospital by ambulance?		
/		
是"PERSONAL PROPERTY SERVE	建筑地	INJURED PERSON 6
Name		
Injuries sustained		
Which vehicle person in?		
Were seat belts worn?	Yes 🗆	No 🗆
Was injured conveyed to	Yes 🗆	No □
hospital by ambulance?		



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Leow Zi Xiang Tommy

Period of Insurance : 18 Mar 2019 To 17 Mar 2020

Engine No. : G4FGJH722195

Chassis No. : KNAF3416MK5031186 Vehicle No.

: SMJ7160T : 1900067630

Policy No. Endorsement No.

Issued Date

: 27 Mar 2019

ABOUT THE COVER

Make/Model : KIA Cerato

Engine Capacity/Tonnage : 1,591.00 CC Driver Restriction

Sum Insured : Market Value Off Peak Car : No

First Year of Registration : 2019

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

: NA

b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 3

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business

by does not cover use for hire or reward, dri ng tuiton, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Leow Zi Xiang Tommy - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only). Add: 600 Sin Ming Ave Singapore 575733 69328000

2 Cycle & Carriage Body & Paint Centre: Add: 209 Pandan Gardens Singapore 609339 65684501

Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only). Add: 241 Alexandra Road Singapore 159931 64278800.

4 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only). Add: 330 Ubi Rd 3 Singapore 408650 67461000

or other. Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotine at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg. ir AIG SIG Mobile App. Simply search and download "AIG SIG" from ITuries or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189). Part ty of the Road Transport Act, 1967 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500710050

C&C FULCO-CORP SALES 22 UBI ROAD 4 FULCO BUILDING SINGAPORE 408617 ANSP - MOTOR Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. **AUTHORISED REPRESENTATIVE**