

22/03/2021

ASS. REC. BY:

REL: 093 | CTI 20001387/HS d3^{SP} Special Instruction

Surveyor: Next Ann

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of CTI

Date/Time: 23/1/2020 @ 8.53am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBC 4853P

Insured: GBH 3613X

at Workshop m/s

Hup ley Hwa

Tel: 96773832

of

1 Kaki Bukit Ave 6 # 01-35 Autobay

Policy No: DMCVSN19199619000

Claim No:

SNM20D200435C02

Sum Insured:

Excess:

D.O.A. 19/01/2020

Make of Veh:
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time: 10-04am @ 23/1/2020 Person Contacted:

Mr. Tan

Vehicle IN/OUT

Date/Time	Action/Instruction	Follow up
shiny	GBC 4853P-CC4/ASM/7020290/Kpa3y2	
	GBH 3613X-X	
* 4/2/20	→ survey taken	
# 5/2/20	→ survey taken	
# 10/2/20	→ after paint taken	

D.O.A: 15/10/2017

ASS. REC. BY: H-ANN REF: CT1

PRS

ASSIGNMENT

From: _____ Date: 4.2.2020
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBC 4853P
 at Workshop m/s Hup Lay Huat
 of Blk 1 Kaki Bukit Ave 6 #101-35
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: GBC 4853P Yr Regn: 30/10/2012
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: NISSAN CABSTAR c.c. 2953
 Colour: White A/C: Insured / Std / NI / NA
 Sp.Reading: 192155 km T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN15C 2F.2420850535
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/R/15C
 R: 155/R/17

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

	X	X
N/S		O/S
	X	X

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 67 mm Rear R/Bal. 5x2 mm Yoko
 L/Bal. 6 mm L/Bal. 5x2 mm
 D.O.A. 19/1/20 D.O.I. 4/2/20
 Survey held at Hup Lay
 Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Page 5-6 KL</u>
	<u>Apr Days 6 days</u>
	<u>13/2/2020</u>
	<u>MV - 19000</u>
	<u>PV - 16221</u>
	<u>NV - 2779</u>

Date/Time, File Pass to? 13/02/20
 1) Typist
 Date/Time, File Return to?
 2) _____

Days Of Repair: 5
 Resurvey No. of Trip: 2

Add Fee: Site Insp (\$) Interview (\$) Tech. Invs (\$) Weekend (\$)

Survey Fee:	
Transportation:	
S + RS	
Photos	
Others	
TOTAL	

Report Format: PRS
 Lump Sum / B.B. / ...

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2020		23 Jan 2020 08:53 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:									
Main Claimant: SOON BOON TRADING & TRANSPORT CO, Co. Reg. No.: 53116086J									
Vehicle Reg. No.:		GBC4853P	Date of Loss:	19/01/2020 11:00 - :59					
Claim Type:		TP / SNM20D200435C02	Policy/Cover Note No.:	DMCVSN19199619000					
Vehicle Reg. No. (Insured):		GBH3613X	Policy No. (Claimant):	5108445937					
			Excess:	S\$500.00					
Repairer: Hup Ley Huat Motor Spray Painting Services () BLK 1 KAKI BUKIT AVE 6 #01-35, 409793 Kaki Bukit - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/02/2020]									
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Sent: Thursday, 23 January 2020 8:49 AM
To: Chris Tan; 'assignments'
Subject: RE: OUR REF: SNM20D200435/GBH3613X/TKL - Accident involving GBC 4853 P and GBH 3613 X on 19 January 2020 along CTE towards Changi Airport (before Braddell Road exit) - Our ref: LCH.ct/2KB02-A10052.20
Attachments: A10052.LTR.PDF

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Chris,

We refer to your email of below.

We regret to inform that we are not agreeable to your list of proposed surveyors and will be assigning our panel surveyor, M/s LKK Auto Consultants to conduct the Pre-repair survey.

Please contact our surveyor to conduct the post repair inspection before returning the repaired vehicle to the claimant.

Aside to LKK,

Please refer to the email below and liaise with third party workshop accordingly.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Chris Tan [mailto:mail@cheonghoh.sg]
Sent: Wednesday, January 22, 2020 5:39 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200435/GBH3613X/TKL - Accident involving GBC 4853 P and GBH 3613 X on 19 January 2020 along CTE towards Changi Airport (before Braddell Road exit) - Our ref: LCH.ct/2KB02-A10052.20

Dear Kah Leong

Pls see attached our letter dated 22 January 2020 for your information and reply.

Regards,
Chris Tan
Cheonghoh Law Corporation
Blk 53 Chin Swee Road #03-05
Singapore 160053
Tel: 63378700
Fax: 63373700

On 22 Jan 2020, at 2:00 PM, Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com> wrote:

Without Prejudice

Dear Melody,

We refer to your email below.

Please see attached and let us know if you agree with SJE.

Thank you.

Regards

Tan Kah Leong
Assistant Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6193 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Wednesday, January 22, 2020 1:43 PM
To: Tan Kah Leong <KahLeong.Tan@sg.cntaiping.com>; Melody Yap <mail@cheonghoh.sg>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: SNM20D200435/GBH3613X/TKL - Accident involving GBC 4853 P and GBH 3613 X on 19 January 2020 along CTE towards Changi Airport (before Braddell Road exit) - Our ref: LCH.ct/2KB02-A10052.20

Dear Kah Leong,

Please conduct PRS for GBC4853P.

Note : officer in charge – Kah Leong 63896193.

***** Kindly quote our reference number when replying.**

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Chris Tan <mail@cheonghoh.sg>

Sent: Wednesday, January 22, 2020 10:25 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: hup Ley Huat <hup.ley.huat@gmail.com>

Subject: Re: PRS for GBC 4853 P - Accident involving GBC 4853 P and GBH 3613 X on 19 January 2020 along CTE towards Changi Airport (before Braddell Road exit) - Our ref: LCH.ct/2KB02-A10052.20

Dear Sir/Mdm

Pls see attached our PRS letter dated 22 January 2020 for your information and reply.

Regards,

Chris Tan

Cheonghoh Law Corporation

Blk 53 Chin Swee Road #03-05

Singapore 160053

Tel: 63378700

Fax: 63373700

<PRS.pdf>

Cheonghoh Law Corporation

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 , Singapore 160053
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

In reply, please quote our Reference Number

Our Ref: LCH.ct/2KB02-10052.20
Your Ref: SNM20D200435C02/tkl

22 January 2020

BY EMAIL ONLY
Fax No: 6224 7478

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #15-00
Springleaf Tower
Singapore 079909
Attn: Tan Kah Leong

Dear Sirs

**ACCIDENT INVOLVING VEHICLES NO GBC 4853 P AND GBH 3613 X ON 19 JANUARY 2020
AT/ALONG CTE TOWARDS CHANGI AIRPORT (BEFORE BRADDELL ROAD EXIT) -**

We refer to the above matter and to your email of 22 January 2020..

Pursuant to the NIMA protocol of the Practice Directions Amendment No. 1 of 2016, we have our client's instructions to reject your list of appointed surveyors as stated in your said email.

We are further instructed to append below our client's 10 proposed surveyors as follows:

- 1) Fong Kok Heng
- 2) Danny Yap
- 3) Willy Goh
- 4) Francis Ng
- 5) Dennis Yap
- 6) Louis Ng
- 7) Michael Yap
- 8) LimYong Tian
- 9) Patrick Ng
- 10) Philip Foo

If you are not agreeable to our list of surveyors above, kindly appoint your surveyor to proceed with the pre-repair survey of our client's vehicle GBC 4853 P is at our client's repairer workshop as follows :-

Hup Ley Huat Motor Spray Painting Services
Blk 1 Kaki Bukit Avenue 6 #01-35
Singapore 417883

Person to contact : Mr Tan Boon Seng (contact no. 96773832)

Yours faithfully

CHEONGHOH LAW CORPORATION
Lee Cheong Hoh
CHEONGHOH LAW CORPORATION

cc: client - via fax only (GBC 4853 P)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/01/2020 14:53
Date Of Accident	19/01/2020 11:55
Exact Location Of Accident	CTE TWDS CHANGI AIRPORT (BEFORE BRADDE RD EXIT)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC4853P
Insured/Policyholder	
Name Of Registered Owner	SOON BOON TRADING & TRANSPORT CO
Co Reg No	5XXXX086J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97681606
Alternative Phone No	OFFICE-97681606

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-2.0 (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSES
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5108445937
Cover Note Number	

Driver

Name of Driver	NG YIAN HUAT
NRIC No	SXXXX189E
Date Of Birth	11/06/1947
Occupation	OUTDOOR
Date Of Driving Pass	07/06/1984
Driving Experience	35 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97681606
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	APT BLK 43 CIRCUIT RD #07-675
Postcode	370043
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
POLICE STATION NAME [OTHER]	T/20200120/2087
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED POLICE REPORT T/20200120/2087

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH3613X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HUANG MING
NRIC/Passport Number	GXXXX705Q
Contact Number	88696771
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMQ4839C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LEE EE LENG, ELLEN
NRIC/Passport Number	SXXXX219B
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 SOON BOON TRANSPORT CO.



Policyholder's Signature
 Date & Time:

Manager, Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


IDAC KAKI BUKIT (VAC)
 25 Kaki Bukit Ave 4 #02-02
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: vackb@vicom.com.sg

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

21/01/2020

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Attached
Police Report

DECLARATION

(We declare the foregoing particulars are true in every respect.

順文貿易運輸公司
SOON BOON TRADING & TRANSPORT CO.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (YAC)

25 Kaki Bukit Ave 4 #02-02
Singapore 415953

Tel: 67416697 Fax: 67492305

Email: vackb@idcom.com.sg

Reporting Centre Personnel's Signature

Name:

NRUC/FIN No.:

©ARMC SketchPlanForm_v3

21/01/2020



**SINGAPORE
POLICE FORCE**



T/20200120/2087

2 of 4

Police Station Of Origin:
Kampong Ubi NPP
9 Eunos Crescent #01-2687 SINGAPORE
400009
Tel No: 1800-7479999

Report No. T/20200120/2087

CONTINUATION OF REPORT

Driver			
Name	NG YIAN HUAT	ID No.	S0426189E
Related Vehicle	GBC4853P (Lorry)	Contact No.	97681606
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	HUANG MING	ID No.	G3145705Q
Related Vehicle	GBH3613X (Lorry)	Contact No.	88696771
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	LIM EE LENG, ELLEN	ID No.	S7804219B
Related Vehicle	SMQ4839C (Car)	Contact No.	96564005
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 19/1/20 at about 1135hrs, I was driving my lorry bearing the registration plate number, GBC4853P along CTE towards Changi Airport. I was driving on the extreme left lane and queueing up to exit towards Upper Serangoon Rd. I came to a stop as there is quite a number of cars in front of me that was also queueing up. I was stationary for about a min or more when suddenly, I felt a strong impact from the rear and saw that one lorry bearing the registration plate number, GBH3613X had hit onto my lorry from the back. The impact was quite strong as such my lorry was pushed forward even though I had pressed onto my brakes. I then slightly hit onto the car bearing the registration plate number, SMQ4839C that was in front of me.

My lorry sustained slight damages on the front and damages on the rear area. The car in front of me sustained slight scratches on the rear only. The lorry behind me sustained damages on the front of the

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	086J
Vehicle Details	
Vehicle No.:	GBC4853P
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Feb 2020
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD TURBO
Primary Colour:	White
Manufacturing Year:	2012
Engine No.:	ZD30306879K
Chassis No.:	JN1SC2F24Z0850535
Maximum Power Output:	-
Open Market Value:	\$31,120.00
Original Registration Date:	30 Oct 2012
First Registration Date:	30 Oct 2012
Transfer Count:	1
Actual ARF Paid:	\$1,556.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$59,334.00
COE Rebate Amount:	\$16,221.00
Total Rebate Amount:	\$16,221.00

The information contained herein is correct as at 04 Feb 2020

OK

2-9.3



Performance Michelin PS3 16" Tyre at \$120



Replace Armrest To Have A More Classy Look



Enhance Braking Performance With Force...



Grade Coaxial Speaker priced

Search filters: nissan cabstar, Price Range, Depreciation, Year Reg, Vehicle Type

Home » Used Cars » KSL Automotive Pte Ltd » Nissan Cabstar

Nissan Cabstar

Overview Financial Accessories Similar Research Photos Map




KSL Automotive Your Trusted Partner in Automotive



Table with vehicle specifications: Price (\$28,800), Lifespan (11-Jun-2034), Depreciation (\$6,620/yr), Reg Date (12-Jun-2014), Mileage (N.A.), Manufactured (2014), Road Tax (N.A.), Transmission (Manual), Dereg Value (\$1,968), OMV (\$25,081), COE (\$4,521), ARF (\$1,255), Engine Cap (2,953 cc), No. of Owners (1), Curb Weight (1,800 kg), Type of Vehicle (Truck)

Price Chart Summary



Shortlist Report Error Compare More Actions Add no

Seller Information: KSL Automotive Pte Ltd, 54 vehicles for sale, 23 sold in past 3 mths, 2A Kian Teck Avenue Level 3

Features: Selling Cheap! Nissan Cabstar 10ft Lorry! Full Loan Available! Insurance Quote Available. View specs of the Nissan Cabstar (2008-2009)

Accessories: CD Player

Description: \$0 Drive Away! No Gimmick! All Must Go! Vehicle Selling At It Is! No Repair Needed! Call Our Sales Now!

Category: Premium Ad Car

Status: Available

Resources



Vehicle Evaluation: Afraid of lemons? Request to have this car evaluated professionally. Find out more

Compare - Free: Get started with the market value of your existing car for free.

Handwritten notes: DOA = 19/1/20, MV = 18000, PV = 11221, NV = 1700, Budget 2yr 9 months, Rp -> 6600, 6600/12 = 550, 13200 + 4950 = 18150

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Jan 2020		23 Jan 2020 08:53 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	-, Co. Reg. No.: -								
Main Claimant:	SOON BOON TRADING & TRANSPORT CO, Co. Reg. No.: 53116086J								
Vehicle Reg. No.:	GBC4853P	Date of Loss:	19/01/2020 11:00 - :59 [86 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200435C02	Policy/Cover Note No.:	DMCVSN19199619000						
Vehicle Reg. No. (Insured):	GBH3613X	Policy No. (Claimant):	5108445937						
		Excess:	S\$500.00						
Repairer:	Hup Ley Huat Motor Spray Painting Services () BLK 1 KAKI BUKIT AVE 6 #01-35, 409793 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 04/02/2020]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/>				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBC4853P (SNM20D200435C02)**
[GBH3613X]

TP

SOON BOON TRADING & TRANSPORT CO

Jan 19 2020 11:00AM

[-]

Hup Ley Huat Motor Spray Painting Services

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▾	
Assessment Reports			1 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	21/01/20 15:19	Accident Statement	i	Load HTM	
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>	
No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	21/01/20 15:11	Accident Photo [Linked Accident Report Documents]	i	Load JPG	<input checked="" type="checkbox"/>
2	21/01/20 15:11	Accident Photo [Linked Accident Report Documents]	i	Load JPG	<input checked="" type="checkbox"/>
3	21/01/20 15:11	Accident Photo [Linked Accident Report Documents]	i	Load JPG	<input checked="" type="checkbox"/>
4	21/01/20 15:11	Accident Photo [Linked Accident Report Documents]	i	Load JPG	<input checked="" type="checkbox"/>
5	21/01/20 15:11	Accident Photo [Linked Accident Report Documents]	i	Load JPG	<input checked="" type="checkbox"/>
6	21/01/20 15:11	Accident Photo [Linked Accident Report Documents]	i	Load JPG	<input checked="" type="checkbox"/>
7	21/01/20 15:11	Accident Photo [Linked Accident Report Documents]	i	Load JPG	<input checked="" type="checkbox"/>
8	21/01/20 15:11	Accident Photo [Linked Accident Report Documents]	i	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/02/20 18:42	Chassis Number	i	Load JPG	<input checked="" type="checkbox"/>
2	04/02/20 18:42	Odometer Reading	i	Load JPG	<input checked="" type="checkbox"/>
3	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
4	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
5	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
6	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
7	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
8	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
9	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
10	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
11	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
12	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
13	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
14	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
15	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
16	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
17	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
18	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
19	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>
20	04/02/20 18:43	General View	i	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
21	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
22	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
23	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
24	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
25	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
26	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
27	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
28	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
29	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
30	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
31	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
32	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
33	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
34	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
35	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
36	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
37	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
38	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
39	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
40	04/02/20 18:43	General View	 Load JPG	<input checked="" type="checkbox"/>
41	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
42	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
43	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
44	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
45	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
46	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
47	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
48	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
49	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
50	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
51	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
52	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
53	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
54	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
55	04/02/20 18:44	General View	 Load JPG	<input checked="" type="checkbox"/>
56	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	06/02/20 09:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
69	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	06/02/20 09:39	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
89	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
90	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
91	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
92	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
93	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
94	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
95	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
96	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
97	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
98	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
99	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
100	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
101	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
102	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
103	13/02/20 09:36	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/01/20 08:54	Pre-Repair Survey	 Load PDF	
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	21/01/20 15:18	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	21/01/20 15:18	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
3	21/01/20 15:18	Sketch Plan #3 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
4	21/01/20 15:18	Sketch Plan #4 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
5	21/01/20 15:18	Sketch Plan #5 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
6	21/01/20 15:18	Sketch Plan #6 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

View View in Browser ▼

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	21/01/20 15:19	Accident Statement	Load HTM	

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	21/01/20 15:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	21/01/20 15:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	21/01/20 15:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	21/01/20 15:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	21/01/20 15:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	21/01/20 15:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	21/01/20 15:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	21/01/20 15:11	Accident Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	21/01/20 15:18	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	21/01/20 15:18	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	21/01/20 15:18	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>
4	21/01/20 15:18	Sketch Plan #4	Load JPG	<input checked="" type="checkbox"/>
5	21/01/20 15:18	Sketch Plan #5	Load JPG	<input checked="" type="checkbox"/>
6	21/01/20 15:18	Sketch Plan #6	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST
Reset
Save
Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI20001387/HSD3S2
Date: 14/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN19199619000
Claimant Vehicle No : GBC4853P **Insured Vehicle No :** GBH3613X
 Date of Loss: 19/01/2020 Nature of Claim: TP Claim No: SNM20D200435C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBC4853P**
 Make & Model: NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Turbo (A) Engine No: ZD30306879K
 Reg. Date: 30/10/2012 (Man. Year: 2012) Chassis No: JN1SC2F24Z0850535
 Colour: White Odometer: 192155 km
 Engine Capacity: 2953 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/R15C Rear Tyre Size: 155 R13C
 Front Left Side: Bridgestone 6 mm Rear Left Side: Yokohama 5 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/01/2020
 Date Inspected: 04/02/2020 Inspected At: Hup Ley Huat Motor Spray Painting Services
 BLK 1 KAKI BUKIT AVE 6 #01-35
 Singapore 409793
 Estimated Period of Repair: 6.0 days

Adjuster: LEE HOCK ANN

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/14/2020

Adjuster Report

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 - \$6,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Feb 2020)

Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD Turbo (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBC4853P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >