

22/03/2002

ASS. REC. BY:

REF:

CS/CTI 20001452/CS d3

Special Instruction:

Surveyor: Quo Quing

ASSIGNMENT (Office)

From (Person): Chong Boon Sen

of

CTIDate/Time: 24/01/2020 @ 8:52am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLG 1983C

Insured:

SBT 3335 K

at Workshop m/s

premium Automobile

Tel:

6768 9911

of

55 ubi Road 1

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 21/01/2020

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time: 9:07am @ 24/1/2020

Person Contacted:

TonyVehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SLG 1983C - NA / INC 18000577 / K4	DOA: 10/01/2018
	SBT 3335K - NJA / INC 09020119 / ji	DOA: 7/09/2009

REF. REC. BY: be.

REF: CTI

ASSIGNMENT

From: _____ Date: 31/01/2020

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SLG 1983Cat Workshop m/s Premiumof 281 Alexandra Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

1pm (waiting)
George

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1up

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLG 1983C Yr Regn: 23 Sep 2016Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Civic C.C. 1597Colour: Black A/C: Insured / Std / NI / NASp. Reading: #52606 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR HFC 5650 GT 000 319Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215/55 R16R: 17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 31-01-20Survey held at w/s 1pmDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29.12.2021 9.43am Guo Qiang confirmed final fig \$7,921.92 ; 8 days with Carrine. (Red 4575.00, 56%)
(Red \$19,387.08 ; 70%)

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

TOTAL

Report Format: TPLump Sum LEP \$7,921.92