

ASS. REC. BY: Marcus

REF:

MS16/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMJ1993X

at Workshop m/s

Rf.

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

65k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

131

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SMJ1993X

Yr Regn:

219

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(A)

Make:

Hyundai Avante cc 1591

Colour:

Red

A/C:

Insured / Std / NI / NA

Sp. Reading

10442

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KMHD841CM KU865717

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-216

R:

BS (DUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

21/1/20

D.O.I.

28/1/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1. TA 3484 CNY 25,26

20/2/20 P/P # 6035-76 Confirmed w. the ALA
(\$ 8,599.64 Red - 59%)

21/2/2020

RECEIVED 24 FEB 2020

Date/Time, File Pass to?

24/2/20

1)

Type 44

Date/Time, File Return to?

2)

☐

Prel. Report

☒

Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

TOTAL

200

11

211

Report Format:

Lump Sum / I.B. (\$ 6,035.76 P/P)

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Wednesday, 29 January 2020 1:26 pm
To: motorsurvey@sg.msig-asia.com
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 21/01/2020 , SMJ 1993X (TP VEHICLE), GBG 6027Z (OI VEHICLE)
Attachments: TP GIA REPORT.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SMJ 1993X at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 28/01/2020.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Wishing you a Happy and Prosperous Lunar New Year



Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | 5(408933)

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



**MCF
HANGOUT**

DasWeltAuto.

Exclusive pre-owned car guide session.
Child seat tutorial. Kids activities.
15 February 2020 | 11 am

REGISTER NOW!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Iconic VW Beetle Daily Driver Vintage Plate New COE.



Inmaculate Fully Restored,
Premium Quality Parts, No
Expense Spared Totally New,
Direct Owner - StarKid.

ABWIN

ONE-STOP
AUTOCARE



Browse by Category		Sort by Date Posted		20 results/page				
10 vehicles		avante		Advanced Search		Submit		
Search Selection		avante	Any	Any	2019	Any	Any	
	Hyundai Avante 1.6A GLS S (OPC)	\$59,800	\$5,670 /yr	30-Apr-2019	1,591 cc	5,000 km	Sedan	
	Interest Rates Starting From 2.28%, Flexible Bank/In House Loan Available. 100% Loan Available. 5 Years Warranty Unlimited Mileage....						Available	
Autobrust Traders Pte Ltd		Posted: 26-Jan-2020 Tags: 2019 Hyundai Avante, 2019 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai						
	Hyundai Avante 1.6A GLS	\$73,800	\$7,100 /yr	01-Aug-2019	1,591 cc	2,338 km	Sedan	
	Full Loan Available. 1 Owner Unit, Flexible Loan From Bank/In House Curated To Your Financing Needs, With Attractive Interest Rates! S...						Available	
Posted: 25-Jan-2020 Tags: 2019 Hyundai Avante, 2019 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai								
	Hyundai Avante 1.6A GLS S	\$73,800	\$7,220 /yr	15-Apr-2019	1,591 cc	7,100 km	Sedan	
	100% Loan Available, 1 Owner! Super Low Mileage! Still Under Agent Warranty! Come And View Now!						Available	
Taxi		Posted: 21-Jan-2020 Tags: 2019 Hyundai Avante, 2019 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai						
	Hyundai Avante 1.6A GLS	\$67,800	\$6,900 /yr	05-Jan-2019	1,591 cc	11,302 km	Sedan	
	100% Loan Available, 1 Owner! Super Low Mileage! Still Under Agent Warranty! Come And View Now!						Available	
Taxi		Posted: 19-Jan-2020 Tags: 2019 Hyundai Avante, 2019 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai						
	Throttle Controller For Hyundai Avante 1.6 A	SBA special R&D Cable Throttle Controller & SBA Intake Manifold Decarbonizing - 2008 HYUNDAI / HD AVANTE 1.6 A.						
	More info about this product							
	Hyundai Avante 1.6A GLS S	\$74,888	\$7,380 /yr	23-Mar-2019	1,591 cc	10,833 km	Sedan	
	Komoco Unit With First 5 Years Warranty, 1 Owner With Low Mileage Clocked. Current Owner Only Use For Sending Kids To School And...						Available	
Posted: 12-Jan-2020 Tags: 2019 Hyundai Avante, 2019 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai								
	Hyundai Avante 1.6A GLS	\$73,800	\$7,040 /yr	27-Aug-2019	1,591 cc	50 km	Sedan	
	5 Years Comprehensive Warranty. A Few Color Options. High Trade In Available, In House Finance Available, Attractive Bank Interest Ra...						Available	
Tan Wei Auto Pte Ltd		Posted: 03-Jan-2020 Tags: 2019 Hyundai Avante, 2019 hyundai avante, Hyundai Avante, hyundai avante, Hyundai, Avante, avante, Used Hyundai						
Compare		Hyundai Avante 1.6A GLS S	\$72,800	\$7,290 /yr	30-Jan-2019	1,591 cc	12,684 km	Sedan
							Available	

https://www.sgcarmart.com/used_cars/listing.php?MOD=avante&PRC=0&DEP=0&RGD=2019&VEH=... 28-Jan-20

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	813F

Vehicle Details

Vehicle No.:	SMJ1993X
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jan 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	AD AVANTE 1.6 GLS (A) S
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	G4FGKU094567
Chassis No.:	KMHD841CMKU865717
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$14,623.00
Original Registration Date:	26 Feb 2019
First Registration Date:	26 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$14,623.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2029
PARF Rebate Amount:	\$10,967.00

Intended COE Rebate Details

COE Expiry Date:	25 Feb 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$26,301.00
COE Rebate Amount:	\$23,887.00
Total Rebate Amount:	\$34,854.00

The information contained herein is correct as at 28 Jan 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/01/2020 13:20
Date Of Accident	21/01/2020 08:40
Exact Location Of Accident	PIE TWDS CITY B4 BEDOK NORTH AVE 3 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ1993X
Insured/Policyholder	
Name Of Registered Owner	PANG AI LING JUDY
NRIC No	SXXXX813F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93481414
Alternative Phone No	OTHERS-93481414

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AD AVANTE 1.6 GLS (A) S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P2253351
Cover Note Number	

Driver

Name of Driver	LOO DIP CHEE
NRIC No	SXXXX582F
Date Of Birth	15/01/1969
Occupation	INDOOR
Date Of Driving Pass	27/03/1990
Driving Experience	29 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96775269
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	155 SIMEI ROAD #09-208 SPORE 520155
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	YES
Foreign Vehicle Registration Number	ALC6297 (PRIVATE CAR)
Number of vehicles (including own vehicle) involved in the accident	6
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG6027Z
Vehicle Make/Model/Colour	NISSAN / CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	FBM267E
Vehicle Make/Model/Colour	KAWASAKI / Z1000 ABS MANUAL
Details Of Properties	
Vehicle Category	MOTORCYCLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLG4257X
Vehicle Make/Model/Colour	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	ALC6297
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number	SKX7275X
Vehicle Make/Model/Colour	CITROEN / C4 PICASSO 1.6 BLUEHDI EAT6
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LOO DIP CHEE

Approximate Age

Injuries Sustain

Injured person in which vehicle? SMJ1993X

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

Date of Accident : 21.01.2020 Accident Time: 08:40 (24-HR-Format)
Accident Place : PIE Towards City Before Labot North Ave 3 Exit
Vehicle No. (Car Plate No.) : SMJ 1993 X Make/Model: _____
Insurance Company : AXA Policy No: YPA/P2253351
Owner or Company Name / IC No. : Pang Ai Ling Judy (S1580813F)
Owner or Company Contact No. : - Owner's Hp 9348 1414 Company Tel
DRIVER'S Name / IC No. : luo Dip Chee (S6905582F)
DRIVER'S Date Of Birth : 15 Jan 1969 DRIVER'S License Pass Date 27 Mar 1990
Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: _____
DRIVER'S Address : Blk 155 Simei Road # 09-208 Singapore 520155
DRIVER'S Contact No / Alt No. : 1) 96775269 2) _____
DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)
Email Address : pjloo 208 @ gmail . com
Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET
Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance
Number of Passengers (Including Driver): 1 Driver
Was there any video Captured by car camera: YES \ NO - SD with TP
Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose
Any Injury (If YES, Pls state): Yes

Vehicle B	Other Party Driver's Particular (if any)	Vehicle C
Vehicle No: GBG 6027Z		Vehicle No: FBM 267 E
Vehicle Make/Model: _____		Vehicle Make/Model: _____
Name Driver: _____		Name Driver: _____
IC No. Driver/Contact: _____		IC No. Driver/Contact: _____

* NEW - Passenger's name & gender:

Vehicle D : SLG 4257 X
Vehicle E : ALC 6297
Vehicle F : SKX 7275X

[Signature]

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that: _____

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

2




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21.01.2020 at about 8.40 am. I was travelling along PIE Towards City Before Bedok North Ave 3 Exit. I was travelling straight. Suddenly Vehicle F (SKX 7275X) emergency brake and I also able to brake in time. Out of no where vehicle B (G86 607Z) hit on the rear side RH My Vehicle. My Vehicle SMJ 1993X was not involved with any accident of the stated Vehicle Number in the report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

2

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

N.f. Artholent
28/1/20
P/P 6035.76
6 Lps.

VEHICLE NO : **SMY 1993X**

QTY	PARTICULAR	
1 PCS	REAR DOOR O/S <i>151.20</i>	<i>Sodly AD</i> \$1,455.00
1 PCS	REAR DOOR OUTER HANDLE O/S	<i>11</i> \$245.00 X
1 PCS	REAR DOOR INNER LOCK O/S	<i>22</i> \$299.30 X
1 PCS	REAR DOOR INNER RUBBER O/S <i>133</i>	<i>7W1</i> \$215.00
1 SET	REAR DOOR FRAME BLACK STICKER O/S <i>120</i>	<i>24</i> \$166.00
1 PCS	REAR DOOR INNER TRIM BOARD O/S <i>627.80</i>	<i>Before</i> \$665.00
1 PCS	REAR DOOR GLASS REGULATOR O/S	<i>17</i> \$365.00 X
1 PCS	REAR DOOR GLASS OUTER CHROME MOULDING O/S	<i>17</i> \$182.30 X
1 PCS	REAR DOOR INNER LOWER RUBBER O/S	<i>1F</i> \$66.80 X
1 PCS	REAR FENDER O/S <i>1768.32</i>	<i>Sodly AD</i> \$1,995.00
1 PCS	REAR WINDSCREEN MOULDING <i>88.10</i>	<i>22</i> \$185.00
1 PCS	REAR BUMPER <i>459.00</i>	<i>7m</i> \$885.00
1 PCS	REAR BUMPER SIDE RETAINER O/S <i>36.80</i>	<i>24</i> \$66.50
1 PCS	REAR BUMPER SPLASH SHIELD O/S	<i>70.1</i> \$122.00
1 PCS	REAR BUMPER REFLECTOR O/S	<i>17</i> \$85.50 X
1 PCS	REAR BUMPER MUDFLAP O/S	<i>17</i> \$105.00 X
1 PCS	REAR BUMPER REINFORCEMENT	<i>17</i> \$392.00 X
1 PCS	REAR BUMPER SPONGE	<i>17</i> \$182.00 X
1 SET	REAR BUMPER CLIPS	<i>22</i> \$50.00
1 PCS	TAILLAMP O/S <i>362.00</i>	<i>SAO</i> \$852.00
1 PCS	TAILLAMP HOUSING PANEL O/S	<i>2</i> \$265.00 X
1 PCS	REAR WHEEL HUB BEARING O/S	<i>17</i> \$320.00 X
1 PCS	REAR KNUCKLE ARM O/S	<i>17</i> \$552.00 X
1 PCS	REAR SHOCK ABSORBER O/S	<i>17</i> \$239.00 X
		\$9,955.40
	S.NETT	
1 PCS	REAR WINDSCREEN SEALANT	<i>22</i> \$50.00 <i>40</i>
1 PCS	REAR WINDSCREEN INNER SEAL	<i>22</i> \$50.00 <i>30</i>
1 PCS	REAR SPORT RIM O/S	<i>17</i> \$450.00 X
	LABOUR CHARGES	
	TO CHECK WIRING	\$80.00 <i>20</i>
	TO DISMANTLE & REFIX REVERSE SENSOR	\$80.00 <i>50</i>
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$120.00 <i>80</i>
	TO TRANSFER REAR DOOR MECHANISM	\$100.00 <i>60</i>
	TO CONDUCT WHEEL ALIGNMENT	<i>17</i> \$120.00 X
	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	<i>17</i> \$380.00 X
	TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00 <i>120</i>
	TO SPRAY RUST PROOFING	\$100.00 <i>60</i>
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,500.00 <i>600</i>
	TO PUTTY & SPRAY PAINTING	\$1,500.00 <i>800</i>
	TOTAL	\$14,635.40

20%

Let's Auto Consultants Please notify
the Possessor of the following:
• To notify the owner of the vehicle
• To notify the owner of the vehicle
• To notify the owner of the vehicle
• To notify the owner of the vehicle
• To notify the owner of the vehicle
• To notify the owner of the vehicle
• To notify the owner of the vehicle

Approved by Manager

Signature:

Date:

P-5219.70
20%
475.76
6035.76

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20001485/USD3N2
Date: 27/02/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29022516MKC
Claimant Vehicle No :	SMJ1993X	Insured Vehicle No :	GBG6027Z
Date of Loss:	21/01/2020	Nature of Claim:	TP
		Claim No:	618204

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ1993X	Engine No:	G4FGKU094567
Make & Model:	HYUNDAI AVANTE, 1.6 (A)	Chassis No:	KMHD841CMKU865717
Reg. Date:	26/02/2019 (Man. Year: 2019)	Odometer:	10442 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,505.40	4,245.76	6,259.64	59.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,130.00	1,790.00	2,340.00	56.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,635.40	6,035.76	8,599.64	58.76
+ GST 7.00/7.00% (S\$)	1,024.48	422.50	601.98	58.76
Nett Amount (S\$)	15,659.88	6,458.26	9,201.62	58.76

INSPECTION

Date of Assignment:	29/01/2020	
Date Inspected:	28/01/2020	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Feb 2020)

Parts: 143 HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMJ1993X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR O/S	Badly Dented	1,455.00 F	*1,455.00 FL
2	1		*REAR DOOR OUTER HANDLE O/S	Not Necessary	245.00 F	*- FL
3	1		*REAR DOOR INNER LOCK O/S	Serviceable	299.30 F	*- FL
4	1		*REAR DOOR INNER RUBBER O/S	Twisted	215.00 F	*133.00 FL
5	1		*SET REAR DOOR FRAME BLACK STICKER O/S	Necessary	166.00 F	*120.00 FL
6	1		*REAR DOOR INNER TRIM BOARD O/S	Deformed/Cracked	665.00 F	*627.80 FL
7	1		*REAR DOOR GLASS REGULATOR O/S	Not Necessary	365.00 F	*- FL
8	1		*REAR DOOR GLASS OUTER CHROME MOULDING O/S	Not Necessary	182.30 F	*- FL
9	1		*REAR DOOR INNER LOWER RUBBER O/S	Not fitted	66.80 F	*- FL
10	1		*REAR FENDER O/S	Badly Dented	1,995.00 F	*1,768.30 FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	185.00 F	*86.10 FL
12	1		*REAR BUMPER	Torn	885.00 F	*459.00 FL
13	1		*REAR BUMPER SIDE RETAINER O/S	Bent	66.50 F	*36.50 FL
14	1		*REAR BUMPER SPLASH SHIELD O/S	Torn	122.00 F	*122.00 FL
15	1		*REAR BUMPER REFLECTOR O/S	Not Necessary	85.50 F	*- FL
16	1		*REAR BUMPER MUDFLAP O/S	Not Necessary	105.00 F	*- FL
17	1		*REAR BUMPER REINFORCEMENT	Not Necessary	392.00 F	*- FL
18	1		*REAR BUMPER SPONGE	Not Necessary	182.00 F	*- FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
20	1		*TAILLAMP O/S	Broken	852.00 F	*362.00 FL
21	1		*TAILLAMP HOUSING PANEL O/S	Repair	265.00 F	*- FL
22	1		*REAR WHEEL HUB BEARING O/S	Not Necessary	320.00 F	*- FL
23	1		*REAR KNUCKLE ARM O/S	Not Necessary	552.00 F	*- FL
24	1		*REAR SHOCK ABSORBER O/S	Not Necessary	239.00 F	*- FL
25	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
26	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
27	1		*REAR SPORT RIM O/S	Not Necessary	450.00 FS	*- FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (\$\$)	10,505.40	5,289.70
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,043.94
Total Parts (\$\$)	10,505.40	4,245.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TO DISMANTLE & REFIX REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY	New	120.00	80.00
4	TO TRANSFER REAR DOOR MECHANISM	New	100.00	60.00
5	TO CONDUCT WHEEL ALIGNMENT	New	120.00	0.00
6	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	380.00	0.00
7	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
8	TO SPRAY RUST PROOFING	New	100.00	60.00
9	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,500.00	600.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	800.00
Gross Labour Cost (S\$)			4,130.00	1,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >