

22/03/2002

ASS. REC. BY:

REF: CS/LPC 20001493/Tly d3

Special Instruction:

Supervisor: tan hui ch

ASSIGNMENT (Office)

From (Person): Ong hui

of JPC

Date/Time: 28/01/2020 @ 3:42pm

Estimated Cost:

Bill to:

OL: 1/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

XE 39741

Insured:

at Workshop in/s

Woon Meng Motor

Tel:

63161151

of

50 Bukit Batok St 23 # 01-06

Policy No:

2/19/VCO6/104968

Claim No:

19/20/20/VCO6/022932

Sum Insured:

Excess:

\$1,500.00

Make of Vehicle

(Client's Record)

D.O.A. 15/01/2020

29/11/2020

CA (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3:42pm 28/1/2020

Person Contacted:

MS. Henry

Vehicle IN / OUT

Date/Time

Action/Instruction

Signature

Insp: 42 Singapore Road Ave

XE 39741 - X

$$y = \frac{1}{2} + \frac{1}{2} \cos 2x$$

Log-Conditional PLS

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Jan 2020 Sendback Est	28 Jan 2020 15:37 \$3,815.00	28 Jan 2020 15:42 Assign				New Assignment Cancel Case

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	YLS STEEL PTE LTD, Co. Reg. No.: 198400237R		
Vehicle Reg. No.:	XE3974J	Date of Loss:	15/01/2020 12:00 - :59 [24 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 19/20/20/VC06/022932	Policy/Cover Note No.:	Z/19/VC06/104968 (Comprehensive)
		Excess:	\$1,500.00
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/02/2020]		
Driver/Customer:	DEEN JALIL MOHDEEN (47 / Male), NRIC: S7248624B, Tel: +6593858544 Email: business@ylssteel.com.sg		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)
[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

View Received Message

This mail is associated with :

XE3974J (19/20/20/VC06/022932)

OD

Jan 15 2020 12:00PM

[YLS STEEL PTE LTD]

Woon Meng Motor Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on 19/02/2020 17:37 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$7906.54) - XE3974J - Claim Handler: Ong LI LI

Approved:7906.54.

DOCUMENTS SUMMARY

There are no documents.

View Received Message

This mail is associated with :

XE3974J (19/20/20/VC06/022932)

OD

Jan 15 2020 12:00PM

[YLS STEEL PTE LTD]

Woon Meng Motor Pte Ltd

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on 04/02/2020 15:59 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3315.00) - XE3974J - Claim Handler: Ong Li Li

Approved: 3315.00.

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (In Reg No 199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com, assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 18 Feb 2020

Preliminary Advice

Vehicle No	: XE3974J	Accident Date	: 15/01/2020
Make	: VOLVO FMX410	Policy No.	: Z/19/C06/104968
Assignment Date	: 28/01/2020	Excess	: S\$1,500.00
Date of Inspection	: 29/01/2020	Est. Duration of Repair	: 3.00
Inspection At	: WOON MENG MOTOR PTE LTD (BUKIT BATOK) 50 BUKIT BATOK STREET 23., #01-06 MIDVIEW BUILDING SINGAPORE 659578		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,146.55
Revised Amount	:S\$	7,756.54 (INCL SUPP)
Check Items (Estimated)	:S\$	150.00
Total	:S\$	7,906.54

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	45,617.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,383.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 30 Jan 2020

Preliminary Advice

Vehicle No	: XE3974J	Accident Date	: 15/01/2020
Make	: VOLVO FMX410	Policy No.	: Z/19/VC06/104968
Assignment Date	: 28/01/2020	Excess	: S\$1,500.00
Date of Inspection	: 29/01/2020	Est. Duration of Repair	: 3.00
Inspection At	: WOON MENG MOTOR PTE LTD (BUKIT BATOK) 50 BUKIT BATOK STREET 23,, #01-06 MIDVIEW BUILDING SINGAPORE 659578		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages.o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,815.00
Revised Amount	:S\$	3,165.00
Check Items (Estimated)	:S\$	150.00
Total	:S\$	3,315.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	130,000.00
COE / PARF Rebate	:S\$	45,617.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,383.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Anne Wong (LKK Auto)

From: Yvonne Wong (LKK Auto)
Sent: Tuesday, February 04, 2020 4:28 PM
To: Woon Meng
Cc: SUR
Subject: RE: Estimate for vehicle XE 3974J

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **XE 3974J (excess \$1500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)
Sent: Monday, February 03, 2020 10:16 AM
To: SUR <sur@lkkauto.com>
Subject: FW: Estimate for vehicle XE 3974J

CS/LPC20001493/T1yd3

From: Woon Meng <woonmeng@singnet.com.sg>
Sent: Thursday, 30 January, 2020 12:41 PM
To: Admin A <admin_a@lkkauto.com>; CS A Team <cs_a@lkkauto.com>
Subject: Estimate for vehicle XE 3974J

Dear Sirs/Madam,

Kindly find enclosed estimate for vehicle XE 3974J for your reference as per requested.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 20/01/2020 13:16
Date Of Accident 15/01/2020 12:25
Exact Location Of Accident 25 PIONEER SECTOR 1
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number XE3974J
Insured/Policyholder
Name Of Registered Owner YLS STEEL PTE LTD
Co Reg No 1XXXXX237R
Email Address BUSINESS@YLSSTEEL.COM.SG

Mobile Phone No
Alternative Phone No Office-93858544

Vehicle Particulars

Manufacturer VOLVO
Model FMX410 84RT RAS DC WB4100

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number Z/19/VC06/104968

Cover Note Number

Driver

Name of Driver DEEN JALIL MOHDEEN
NRIC No SXXXX624B
Date Of Birth 22/12/1972
Occupation OUTDOOR
Date Of Driving Pass 24/04/1996
Driving Experience 23 YEARS AND 8 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-93858544

iber
ct Number
ail Address BUSINESS@YLSSTEEL.COM.SG
.dress BLK 501, JURONG WEST ST 51, #04-267
Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-
-

Insurance Company of Driver's Own Vehicle -
-
-

General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 1

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHED SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category NA/UNKNOWN

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

e Company Name

, Of Damage

Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



A 20/1/20

20/1/20

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Please note that you might be able to submit an Own Damage Claim under own policy within 14 days.

☒ Claim Own Damage ☐ Claim TP ☐ Reporting Only ☐ Claim OD/TP at other workshop

Workshop Name : _____

On 19/1/20, @ about 12.25 hrs, I was lifting the bin from the ground to the truck, when suddenly, the load gave way and causing the vehicle to overturn.

I/We declare the foregoing particulars are true in every respect.



4 20/01/20

20/4/20

**LONPAC INSURANCE BHD** (S98FC5635C)

(Incorporated in Malaysia)
 Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555
 Tel: (65) 6250 7388 Fax: (65) 6206 3767 Website: www.lonpac.com.sg
 GST Reg No: F0-0005635-C

MZ300

CERTIFICATE OF INSURANCE*Insured's Copy*

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION ACT (CAP 189) REPUBLIC OF SINGAPORE,
 MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE),
 ROAD TRANSPORT ACT 1987 (MALAYSIA),
 ROAD TRANSPORT (AMENDMENT) ACT 2019 (MALAYSIA),
 THE MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate No. : Z/19/VC06/104968

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

VOLVO FMX410 84RT RAS DC W84100
- XE 3974

2. Name of Policy Holder

YLS STEEL PTE LTD

3. Effective date of the Commencement of Insurance for the purpose of the Act.

30/09/2019

4. Date of Expiry of the Insurance

29/09/2020

5. Persons or Classes of Persons entitled to drive.

(A) THE POLICYHOLDER. (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS. USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS. USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES. THE POLICY DOES NOT COVER: USE FOR HIRE OR REWARD OR FOR RACING, PACEMAKING, RELIABILITY TRIAL OR SPEED TESTING. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

Excess

: S\$1500.00 (SECTION 1)
 S\$2500.00 (SECTION 1) ADDITIONAL EXCESS FOR
 YOUNG &/OR INEXPERIENCED DRIVERS
 S\$100.00 WINDSCREEN EXCESS (EXCESS WILL BE DOUBLED ON SECOND AND
 SUBSEQUENT CLAIM)

Condition

: ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading

We hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore

CHIEF EXECUTIVE
 (Singapore Branch)

User ID : aslinyao_nirwong
 Date Issued : 30-09-2019

19/VC06/104968 - 84RT RAS DC W84100 - XE 3974

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

237R

Vehicle Details

Vehicle No.:

XE3974J

Vehicle to be Exported:

Yes

Intended Deregistration Date:

30 Jan 2020

Vehicle Make:

VOLVO

Vehicle Model:

FMX410 B4RT RAS DC WB4100

Primary Colour:

White

Manufacturing Year:

2017

Engine No.:

D11426557

Chassis No.:

YV2X1F1G0JA817075

Maximum Power Output:

-

Open Market Value:

\$108,903.00

Original Registration Date:

28 Dec 2017

First Registration Date:

28 Dec 2017

Transfer Count:

0

Actual ARF Paid:

\$5,446.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

27 Dec 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$57,701.00

COE Rebate Amount:

\$45,617.00

Total Rebate Amount:

\$45,617.00

The information contained herein is correct as at 30 Jan 2020

OK

Woon Meng Motor Pte Ltd (Co Reg No 200503578M)

50 Bukit Batok Street 23, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg**INSURER:****Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC06/104968	Date of Loss:	15/01/2020
Vehicle Reg. No.:	XE3974J	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YLS STEEL PTE LTD		
Driver:	DEEN JALIL MOHDEEN		

Make/Model:	VOLVO FMX410, 10.8 D 84RT RAS	Vehicle Reg. Date:	28/12/2017
	DC WB5200 (M)		
Vehicle Colour:	WHITE/PEARL		
Engine No:	D11426557	Chassis No:	YV2X1F1G0JA817075
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	28		

Description of Accident/Loss	REFER TO ATTACHED SKETCH PLAN.
Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)

COST OF CLAIMS

Parts	Amount
Miscellaneous Items	2,415.00
Labour	0.00
Paintwork Labour	950.00
Towing	450.00
	0.00
Gross Total (S\$)	3,815.00
+ GST 7.00% (S\$)	267.05
Nett Amount (S\$)	4,082.05

This claim is handled by: **HENG SEW SOW**Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

IR DETAILS

Reference

Part Source: (Last Synchronised: 28 Jan 2020)
Parts: N/A VOLVO FMX410 10.8 D 84RT RAS DC WB5200 (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Woon Meng Motor Pte Ltd/XE3974J/28/01/2020 15:37
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT DOOR O/S	0.00	0.00	dd✓ 2,100.00 F
2	1		*ENGINE UNIT	0.00	0.00	2,100.00 F
F=Franchise part.						
Sub Total (S\$)						2,100.00
+ Margin on L,N Items 15.00% (S\$)						315.00
Total Parts (S\$)						2,415.00

Woon Meng Motor Pte Ltd/XE3974J/28/01/2020 15:37. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

2415

ates on Miscellaneous Items

• no new miscellaneous items selected.

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1 TO PUTTY & SPRAY PAINTING

New

300

450.00

Labour Items

2 TOWING FEE

New

towing receipt

150.00

3 TO REMOVE, REPAIR, REPLACE, INSTALL & WELD FRONT DAMAGED PARTS.

New

300

500.00

4 TO NUMBERING LOGO

New

150

300.00

Gross Labour Cost (\$\$)

900

1,400.00

Woon Meng Motor Pte Ltd/XE3974J/28/01/2020 15:37. Not valid without Reference section.

Generated using Morimen e-Claims IEAS

< END OF ESTIMATES >

Tanjik 97495749

Not Authorise

29/1/20 @ 930am

sur @ khando.com

03 days

Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Woon Meng Motor Pte Ltd (Co.Reg.No.200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

(SUPPLEMENTARY)**INSURER: Lonpac Insurance Bhd (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC06/104968	Date of Loss:	15/01/2020
Vehicle Reg. No.:	XE3974J	Driveable?	
Driver Age/Info:	47 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	YLS STEEL PTE LTD		
Driver:	DEEN JALIL MOHDEEN		
Make/Model:	VOLVO FMX410, 10.8 D 84RT RAS DC WB5200 (M)	Vehicle Reg. Date:	28/12/2017
Vehicle Colour:	WHITE/PEARL	Chassis No:	YV2X1F1G0JA817075
Engine No:	D11426557		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	28		
Description of Accident/Loss	REFER TO ATTACHED SKETCH PLAN.		
Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)		

COST OF CLAIMS	Amount
Parts	3,901.55
Miscellaneous Items	80.00
Labour	1,350.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,331.55
+ GST 7.00% (S\$)	373.21
Nett Amount (S\$)	5,704.76
+ Previous Estimates (S\$)	4,082.05
Claim Total (S\$)	9,786.81

Generated using Merimen e-Claims Internet Estimation & Adjusting System

R DETAILS

Reference

Source: (Last Synchronised: 18 Feb 2020)

Parts: N/A VOLVO FMX410 10.8 D 84RT RAS DC WB5200 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Woon Meng Motor Pte Ltd/XE3974J/18/02/2020 12:39

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*INTER COOLER	0.00	0.00	leak *1,823.40 F/
2	1		*INTER COOLER UPP HOSE	0.00	0.00	leak *252.45 F/
3	1		*INTER COOLER LOWER HOSE	0.00	0.00	leak *224.55 F/
4	1		*FRONT FENDER O/S	0.00	0.00	scr *165.15 F/
5	1		*FRONT SIDE MIRROR TOP ARM O/S	0.00	0.00	cra *180.20 F/
6	1		*FRONT SIDE MIRROR ARM PIN O/S	0.00	0.00	nec *35.30 F/
7	1		*RIM HUB COVER O/S.	0.00	0.00	scr *90.45 F/
8	1		*FRONT SIDE MIRROR LOWER O/S	0.00	0.00	cra *87.30 F/
9	1		*FRONT SIDE MIRROR ARM LOWER COVER O/S	0.00	0.00	cra *17.90 F/
10	10		*NUT COVER	0.00	0.00	scr *15.00 F/
11	1		*FRONT SIDE MIRROR TOP O/S	0.00	0.00	cra *45.10 F/
12	1		*FRONT SIDE MIRROR STAY O/S	0.00	0.00	ht *455.85 F/

F=Franchise part.

Sub Total (S\$)	3,392.65
+ Margin on L,N Items 15.00% (S\$)	508.90
Total Parts (S\$)	3,901.55

Woon Meng Motor Pte Ltd/XE3974J/18/02/2020 12:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

3901.55

Estimates on Miscellaneous Items

Qty Particulars

Amount

Miscellaneous Items

1 COOLANT *Neu*

40/- 80.00

Sub Total (S\$)

80.00

40

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1 TOWING FEE *Neu*

New

X 150.00

2 TO R & R AIR CON SYSTEM AND REFILL & TOP UP AIR CON GAS

New

100/- 250.00

3 TO R & R INTER COOLER

New

100/- 350.00

4 TO R & R FRONT RADIATOR

New

100/- 220.00

5 TO R & R FRONT SIDE MIRROR ASSY AND CHECK FOR FUNCTION.

New

200/- 380.00

Gross Labour Cost (S\$)

500 1,350.00

Woon Meng Motor Pte Ltd/XE3974J/18/02/2020 12:39. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1st est { 2415
900
Supp. { 3901.55
40
500
7756.55

1/s\$ 6200 *

06 days *