### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	ACCIDENT STATEMENT	
Date Of Report	23/01/2020 12:05	
Date Of Accident	22/01/2020 15:00	
Exact Location Of Accident	SENTOSA GANTRY	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	

	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKZ6250M
Insured/Policyholder	
Name Of Registered Owner	PERFORMANCE COATINGS INTERNATIONAL PTE LTD
Co Reg No	1XXXXX877G
Email Address	ZHENGYI@PERFORMANCECOATINGS.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-97545532
Vehicle Particulars	

HONDA
JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Vehicle Category PRIVATE CAR
Insurance Company

Name of Insurance Company QBE INSURANCE (SINGAPORE) PTE LTD

Type Of Coverage COMPREHENSIVE Fleet Policy NO

Policy Number 8-V0014544-MVA-R002

Cover Note Number

Driver

Name of Driver WONG ZHENGYI (HUANG ZHENGYI)

 NRIC No
 SXXXX153C

 Date Of Birth
 22/09/1988

 Occupation
 OUTDOOR

 Date Of Driving Pass
 06/01/2014

Driving Experience 6 YEARS AND 0 MONTHS

Gender FEMALE

Mobile Number (LOCAL) +65-97545532

Fax Number Contact Number

EMail Address ZHENGYI@PERFORMANCECOATINGS.COM.SG

Address

BLK 27, GHIM MOH LINK, #03-258

Postcode

270027

Was driver an employee of the Insured's Company YES

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: AMANDA NEO

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### **Circumstances of Accident**

REFER TO ATTACHED SKETCH PLAN.

# Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Was there any audio recorded?

NO

## DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number Vehicle Make/Model/Colour

GBG5355H

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

MUHAMMAD FARID BIN KORDI

NRIC/Passport Number

SXXXX880E

Contact Number

91044709

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Page 2 of 20

## SKETCH PLAN

Sentosa Gantry

A- SKZ 6250M B- GBG 5355H

# DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Lorry and Honda Jazz were in Stationary position.  Suddenly, Lorry reversed into Honda Jazz  despite repeated Honks and safety  distance between both vehicles.	While 1	vaiting to enter Seutosa	premises, both
despite repeated Honks and sobety	Lorry o	nd Honda Jazz were in	stationary position.
	Sudden	, long reversed into 1	loude Jazz
	despit	e repeated Honks a	and sodety
			•

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

1 3

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder) Date & Time: 25 1 1092

Name: NRIC/FIN No.:

Reporting Centre Personnel's Signature