

ASS. REC. BY:

REF: CS/UOI20001498/Kvd3

Special Instructions:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Feli's of UOI Date/Time: 28/01/2020

Estimated Cost: Bill to:

OI / TP / FWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBE 4258Y Insured: YN 3148T.

at Workshop n/s Gold Bell Tel: 9739 6433

of BIK 5035 AMK Ind. Park 2 #01-367

Policy No: DTHM110149171603 Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 28/01/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

29/1/2020

I.L.O.D. Endorsement:

Date/Time: 4.53pm @ 28/1/2020 Person Contacted: Ms. Kong Vehicle: IN/OUT

Date/Time	Action/Instruction
	I should ✓
	GBE 4258Y -X
	YN 3148T -X
17/12 11/12 @ 8 For email & confirm CRad 8039.32, H8/M	

ASSIGNMENT

From:

Date:

29/01/2020

Estimated Cost:

OD ☒ TP / ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBE 4258Y

at Workshop m/s

Goldbell

of 10 Amk Ind. park 2 #01-367

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Vehicle is In.

Ms. Kong @ 9739 6433

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.:

Yes or No

Lump Sum:

201.51%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

imp

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBE 4258Y

Yr Regn:

11, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV 350

C.C

2488

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

109P31

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN1MC2E2680004743

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: M / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15XD

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

2

mm

L/Bal.

3

mm

L/Bal.

2

mm

D.O.A.

23/1/20

D.O.I.

29/1/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fr

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 17 FEB 2020

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 17/2 - typist

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Wheel and (\$

Survey Fee:

Transportation:

S + RS \$

Fluorid

Other:

TOTAL

6x25 = 150

250 + 150

60

80

19

559

Report Format:

TP

Lump Sum / L.B.I. (\$

8700k

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 23/01/2020 13:48
 Date Of Accident 23/01/2020 09:45
 Exact Location Of Accident 39 GREENWICH DRIVE
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE4258Y

Insured/Policyholder

Name Of Registered Owner SINGAPORE POST LIMITED
 Co Reg No 1XXXXX623M
 Email Address NOEMAIL
 Mobile Phone No (LOCAL) +65-97875134
 Alternative Phone No OFFICE-68412000

Vehicle Particulars

Manufacturer NISSAN
 Model NV350-2.5 5MT 5DR EURO V (A)
 Exact Purpose for which vehicle was being used at time of accident MAIL DELIVERY

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company GREAT EASTERN GENERAL INSURANCE LIMITED
 Type Of Coverage THIRD PARTY
 Fleet Policy YES
 Policy Number V0107634
 Cover Note Number

Driver

Name of Driver MUHAMMAD AZIZI BIN SHAARI
 Passport No/FIN GXXXX261R
 Date Of Birth 11/03/1993
 Occupation OUTDOOR
 Date Of Driving Pass 10/10/2017
 Driving Experience 2 YEARS AND 3 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-97875134
 Fax Number
 Contact Number
 EMail Address NOEMAIL

Address C/O SINGPOST

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1
NAME: : STAFF
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

ON 23 JAN 2020 AT ABOUT 0945, I PARKED MY VEHICLE ALONG ROAD NEAR TO 39 GREENWICH DR. I INTENDED TO EXIT FROM THERE AND MOVE MY VEHICLE GBE4258Y. WHILE MOVING MY VEHICLE, SUDDENLY THERE WAS A VEHICLE, YN3148T TURNING LEFT IN FRONT OF MY VEHICLE TO 39 GREENWICH DR. WHILE VEHICLE YN3148T TURNING INTO LEFT, ITS BACK PORTION (GARBAGE LORRY) HIT ON MY FRONT RIGHT PORTION, CAUSED SERIOUS DAMAGE FOR MY VEHICLE. NOBODY WAS INJURED.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YN3148T

Vehicle Make/Model/Colour GARBAGE LORRY

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver LIM HOCK LEE

NRIC/Passport Number SXXXX268I

Contact Number +6598979166

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any **willful misrepresentation or withholding of material facts** may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time: 23/1/20-1040H

Reporting Centre Personnel's Signature
Name: Khamey
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23 Jan 2020 at about 0945, I was parked my vehicle along road near to 39 Greenwich Dr. I intended to exit from there and move my vehicle GIBE 4255Y. while I moving my vehicle suddenly there was a vehicle YN 3148T turn left to in front my vehicle to 27 Greenwich Dr. while vehicle YN 3148T turn into left its back portion (garbage bag) was hit on my front right portion cause some damage for my vehicle. NO body was injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time: 23/1/20-1040H

Reporting Centre Personnel's Signature
Name: *Waham*
NIC/FIN No.:



Kennerth Kongs @ 1kkauto.com

ESTIMATE

Date : 29/01/2020 Reg No : GBE4258Y
To : UNITED OVERSEAS INSURANCE Model : OTHERS
Attn. : *Not Authorised* Chassis No : JN1MC2E26Z0004743
Office / Mobile : *Resurvey B4 paint* Engine No : YD25374818A
Email Address : *7 days* Quotation No. : 104307
From : GOLDBELL ENGINEERING PTE LTD Ref. No. : GBE/SVC/SALES-AMK05
Attn. : KONYINSIEW D.O.A. : 23/01/2020
Office / Mobile : +65 6861 0007 Policy No. : V0107634
Email / Fax No. : KonYinSiew@goldbell.com.sg Claim Type : TP CLAIM - UOI
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		WIPER CROWDING	1	0.00	0	0.00	0.00 ?
2		FRONT PANEL	<i>B4</i> 1	0.00	0	0.00	0.00 L
3		FRONT GRILLE	<i>mis</i> 1	0.00	0	0.00	0.00 L
4		FRONT GRILLE CLIPS	<i>mu</i> 1	0.00	0	0.00	0.00 L
5		FRONT EMBLEM - NISSAN	<i>mu</i> 1	0.00	0	0.00	0.00 L
6		FRONT BUMPER	<i>DIT / cam</i> 1	0.00	0	0.00	0.00 L
7		FRONT BUMPER RETAINER LH	1	0.00	0	0.00	0.00 ?
8		FRONT BUMPER RETAINER RH	<i>DIT</i> 1	0.00	0	0.00	0.00 L
9		FRONT BUMPER CLIPS	<i>mu</i> 1	0.00	0	0.00	0.00 L
10		FRONT BUMPER TOWING COVER	<i>mu</i> 1	0.00	0	0.00	0.00 X
11		FRONT BUMPER GRILLE	1	0.00	0	0.00	0.00 ?
12		FRONT CORNER PANEL RH	<i>B4</i> 1	0.00	0	0.00	0.00 L
13		FRONT CORNER PANEL RH SUPPORT BRACKET	2	0.00	0	0.00	0.00 ?
14		HEADLAMP LH	<i>su</i> 1	0.00	0	0.00	0.00 X
15		HEADLAMP RH	<i>CR</i> 1	0.00	0	0.00	0.00 L
16		HEADLAMP BULB RH	1	0.00	0	0.00	0.00 ?
17		SIGNAL BULB RH	1	0.00	0	0.00	0.00 ?
18		SIDE LIGHT BULB RH	2	0.00	0	0.00	0.00 ?
19		INTERCOOLER	<i>B4</i> 1	0.00	0	0.00	0.00 L
20		INTERCOOLER HOSE	1	0.00	0	0.00	0.00 ?
21		INTERCOOLER SUPPORT BRACKET	<i>R</i> 1	0.00	0	0.00	0.00 X
22		FRONT DOOR LH	<i>R</i> 1	0.00	0	0.00	0.00 X
23		FRONT DOOR RH	<i>B4</i> 1	0.00	0	0.00	0.00 L
24		SIDE MIRROR RH	<i>R</i> 1	0.00	0	0.00	0.00 X
25		SIDE MIRROR COVER RH	<i>mu</i> 1	0.00	0	0.00	0.00 X

PARTS TOTAL : 0.00

SPECIAL NETT ITEMS

1 FRONT VEHICLE NUMBER PLATE 1 *B4 20sn* 30.00

PARTS TOTAL: 30.00



ESTIMATE

Date : 29/01/2020
To : UNITED OVERSEAS INSURANCE LIMITED
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

Reg No : GBE4258Y
Model : OTHERS
Chassis No : JN1MC2E26Z0004743
Engine No : YD25374818A
Quotation No. : 104307
Ref. No. : GBE/SVC/SALES-AMK05
D.O.A. : 23/01/2020
Policy No. : V0107634
Claim Type : TP CLAIM - UOI
Workshop : 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK-OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	@600.00	1800.00
2	TO CHECK AND RECONNET ALL NECESSARY WIRING		200 100.00
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	@350	1500.00
4	TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM, ETC		300 350.00
5	TO TEST RUN INTERCOOLER FUNCTIONALITY		600 100.00

LABOUR TOTAL :	3,850.00
SUB-TOTAL :	3,880.00
GST @ 7% for \$ 3,880.00	271.60
GRAND TOTAL (\$\$) :	4,151.60

LKE Auto Consultants hereby notify the Receiver of the following:

- To remove interconnector from parking
- To replace damaged parts during recovery
- Parts price coverage is not available
- Third party liability is "Visual Inspection" basis
- No third party liability is covered
- Scope of work is not to be recovered and replaced by the insurance company

Admitted by Receiver

Signature

Date



ESTIMATE

Date : 29/01/2020
To : UNITED OVERSEAS INSURANCE LIMITED
Attn. :
Office / Mobile :
Email Address :

Reg No : GBE4258Y
Model : OTHERS
Chassis No : JN1MC2E26Z0004743
Engine No : YD25374818A
Quotation No. : 104307
Ref. No. : GBE/SVC/SALES-AMK05
D.O.A. : 23/01/2020
Policy No. : V0107634
Claim Type : TP CLAIM - UOI
Workshop : 8 TUAS AVE 18

From : GOLDBELL ENGINEERING PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

PREPARED BY : KONYINSIEW

DATE / TIME : _____

SURVEYOR : _____

MOBILE NO : _____

OFFICE FAX NO : _____

EMAIL ADDRESS : _____

EXCESS AMOUNT : _____

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : _____

REMARKS : _____



ESTIMATE

Date : 29/01/2020
To : UNITED OVERSEAS INSURANCE LIMITED
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

Reg No : GBE4258Y
Model : OTHERS

Chassis No : JN1MC2E26Z0004743
Engine No : YD25374818A
Quotation No. : 104307
Ref. No. : GBE/SVC/SALES-AMK05
D.O.A. : 23/01/2020
Policy No. : V0107634
Claim Type : TP CLAIM - UOI
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		WIPER CROWDING	1	518.40	-20	414.72X	414.72X
2		FRONT PANEL	1	1,629.35	-20	1,303.48✓	1,303.48✓
3		FRONT GRILLE	1	614.25	-20	491.40✓	491.40✓
4		FRONT GRILLE CLIPS	10	3.00	-20	2.40✓	24.00✓
5		FRONT EMBLEM - NISSAN	1	101.25	-20	81.00✓	81.00✓
6		FRONT BUMPER	1	694.85	-20	555.88✓	555.88✓
7		FRONT BUMPER RETAINER LH	1	198.45	-20	158.76X	158.76X
8		FRONT BUMPER RETAINER RH	1	198.45	-20	158.76✓	158.76✓
9		FRONT BUMPER CLIPS	10	3.00	-20	2.40✓	24.00✓
10		FRONT BUMPER TOWING COVER	1	60.80	-20	48.64✓	48.64X
11		FRONT BUMPER GRILLE	1	378.00	-20	302.40✓	302.40X
12		FRONT CORNER PANEL RH	1	644.90	-20	515.92✓	515.92✓
13		FRONT CORNER PANEL RH SUPPORT BRACKET	3	321.75	-20	257.40✓	772.20X
14		HEADLAMP LH	1	487.10	-20	389.68X	389.68X
15		HEADLAMP RH	1	487.10	-20	389.68✓	389.68✓
16		HEADLAMP BULB RH	1	33.75	-20	27.00X	27.00X
17		SIGNAL BULB RH	1	17.55	-20	14.04X	14.04X
18		SIDE LIGHT BULB RH	2	13.50	-20	10.80X	21.60X
19		INTERCOOLER	1	2,864.20	-20	2,291.36✓	2,291.36✓
20		INTERCOOLER HOSE	1	669.10	-20	535.28✓	535.28✓
21		INTERCOOLER SUPPORT BRACKET	1	202.50	-20	162.00✓	162.00X
22		FRONT DOOR LH	1	1,370.25	-20	1,096.20X	1,096.20X
23		FRONT DOOR RH	1	1,370.25	-20	1,096.20✓	1,096.20✓
24		SIDE MIRROR RH	1	702.45	-20	561.96X	561.96X
25		SIDE MIRROR COVER RH	1	162.45	-20	129.96X	129.96X

PARTS TOTAL : 11,566.12

SPECIAL NETT ITEMS

1 FRONT VEHICLE NUMBER PLATE 1 30.00

PARTS TOTAL: 30.00



ESTIMATE

Date : 29/01/2020
To : UNITED OVERSEAS INSURANCE LIMITED
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

Reg No : GBE4258Y
Model : OTHERS

Chassis No : JN1MC2E26Z0004743
Engine No : YD25374818A
Quotation No. : 104307
Ref. No. : GBE/SVC/SALES-AMK05
D.O.A. : 23/01/2020
Policy No. : V0107634
Claim Type : TP CLAIM - UOI
Workshop : 8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK-OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS	1400.00 1800.00
2	TO CHECK AND RECONNET ALL NECESSARY WIRING	20.00 100.00
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1400.00 1500.00
4	TO TRANSFER DOOR COMPARTMENT / WINDOW GLASS / REGULATOR / LOCK / MECHANISM,ETC	80.00 350.00
5	TO TEST RUN INTERCOOLER FUNCTIONALITY	60.00 100.00

LABOUR TOTAL :	3,850.00
SUB-TOTAL :	15,446.12
GST @ 7% for \$ 15,446.12	1,081.23
GRAND TOTAL (S\$) :	16,527.35

16,739.32



ESTIMATE

Date : 29/01/2020
To : UNITED OVERSEAS INSURANCE LIMITED
Attn. :
Office / Mobile :
Email Address :

From : GOLDBELL ENGINEERING PTE LTD
Attn. : KONYINSIEW
Office / Mobile : +65 6861 0007
Email / Fax No. : KonYinSiew@goldbell.com.sg

Reg No : GBE4258Y
Model : OTHERS

Chassis No : JN1MC2E26Z0004743
Engine No : YD25374818A
Quotation No. : 104307
Ref. No. : GBE/SVC/SALES-AMK05
D.O.A. : 23/01/2020
Policy No. : V0107634
Claim Type : TP CLAIM - UOI
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	%	Net Price	Ext Price
1		FRONT INNER PANEL	1	187.10	-20	149.68	149.68
2		FRONT FOG LAMP LH	1	420.95	-20	336.76	336.76
3		FRONT FOG LAMP RH	1	420.95	-20	336.76	336.76
PARTS TOTAL :							823.20

SPECIAL NETT ITEMS

1	COMPANY SIGNATURE STICKER (SINGPOST)	1	300.00
2	FRONT PANEL WORDING (SPEEDPOST)	1	150.00
3	ROC STICKER	1	20.00
PARTS TOTAL:			470.00

SUB-TOTAL : 1,293.20
GST @ 7% for \$ 1,293.20 90.52
GRAND TOTAL (S\$) : 1,383.72



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI20001498/Kvd3n2	
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 17-02-2020	
		Code : UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	Veh. Inspected	Y/N 3148T GBE 4258Y
	Policy No.	Coverage (\$)	DHOM110149171603 0.00
	Claim No.	Excess (\$)	0.00
	Assign From	Assign Date	FELIS 28/01/2020
2. Vehicle Particulars & Condition			
	Make & Model	c.c	NISSAN NV350 (M) 2488
	Engine No.	Year of Reg.	HIDDEN 2015
	Chassis No.	Colour	JN1MC2E26Z0004743 BLUE
	Odometer	Steering	109931 IN ORDER
	Brakes	Modification	IN ORDER NIL
	General		GOOD
3. Conditions of Tyres			
		Size	Make
	R/H Front Tyre	195 R15X8	BRIDGESTONE
	L/H Front Tyre	195 R15X8	BRIDGESTONE
	R/H Rear Tyre	195 R15X8	BRIDGESTONE
	L/H Rear Tyre	195 R15X8	BRIDGESTONE
			Balance
			3 mm
			3 mm
			8 mm
			8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
	Accident Date	Inspection Date	23/01/2020 29/01/2020
	Survey held at	10 AMK.IND PARK 2 #01-367	
	Repairer	GOLDBELL ENGINEERING PTE LTD	
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.			
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 4258Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	WIPER CROWDING (SN)	SERVICEABLE	414.72	-
1	FRONT PANEL (SN)	BENT	1,303.48	1,303.48
1	FRONT GRILLE (SN)	MISSING	491.40	491.40
10	FRONT GRILLE CLIPS (SN)	NECESSARY	24.00	24.00
1	FRONT EMBLEM-NISSAN (SN)	NECESSARY	81.00	81.00
1	FRONT BUMPER (SN)	DISTORTED / CRACKED	555.88	555.88
1	FRONT BUMPER RETAINER LH (SN)	SERVICEABLE	158.76	-
1	FRONT BUMPER RETAINER RH (SN)	DISTORTED	158.76	158.76
10	FRONT BUMPER CLIPS (SN)	NECESSARY	24.00	24.00
1	FRONT BUMPER TOWING COVER (SN)	SERVICEABLE	48.64	-
1	FRONT BUMPER GRILLE (SN)	SERVICEABLE	302.40	-
1	FRONT CORNER PANEL RH (SN)	BENT	515.92	515.92
3	FRONT CORNER PANEL RH SUPPORT BRACKET (SN)	TO REPAIR SEE LABOUR	772.20	-
1	HEADLAMP LH (SN)	SERVICEABLE	389.68	-
1	HEADLAMP RH (SN)	CRACKED	389.68	389.68
1	HEADLAMP BULB RH (SN)	SERVICEABLE	27.00	-
1	SIGNAL BULB RH (SN)	SERVICEABLE	14.04	-
2	SIDE LIGHT BULB RH (SN)	SERVICEABLE	21.60	-
1	INTERCOOLER (SN)	BENT	2,291.36	2,291.36
1	INTERCOOLER HOSE (SN)	DENTED	535.28	535.28
1	INTERCOOLER SUPPORT BRACKET (SN)	TO REPAIR SEE LABOUR	162.00	-
1	FRONT DOOR LH (SN)	TO REPAIR SEE LABOUR	1,096.20	-
1	FRONT DOOR RH (SN)	BENT	1,096.20	1,096.20
1	SIDE MIRROR RH (SN)	SERVICEABLE	561.96	-
1	SIDE MIRROR COVER RH (SN)	SERVICEABLE	129.96	-
1	FRONT VEHICLE NUMBER PLATE (SN)	BENT	30.00	20.00
1	FRONT INNER PANEL (ADDITIONAL) (SN)	TO REPAIR SEE LABOUR	149.68	-
1	FRONT FOG LAMP LH (ADDITIONAL) (SN)	SERVICEABLE	336.76	-
1	FRONT FOG LAMP RH (ADDITIONAL) (SN)	MISSING	336.76	336.76
1	COMPANY SIGNATURE STICKER (SINGPOST) (ADDITIONAL) (SN)	NECESSARY	300.00	150.00

Report Ref No. CS/UOI20001498/Kvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT PANEL WORDING (SPEEDPOST) (ADDITIONAL) (SN))	NECESSARY	150.00	-
1	ROC STICKER (ADDITIONAL)(SN)	NECESSARY	20.00	20.00
			12,889.32	7,993.72
	LABOUR			
	TO REMOVE,REFIT & REPAIR AFFECTED DAMAGED PARTS.INCLUDING KNOCK-OUT,WELD AND STRAIGHTEN ON THE AFFECTED PARTS.INCLUSIVE OF THE REPAIR OF FRONT CORNER PANEL RH SUPPORT BRACKET,INTERCOOLER SUPPORT BRACKET,FRONT DOOR LH AND FRONT INNER PANEL.		1,800.00	1,400.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRING.		100.00	20.00
	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC.		1,500.00	1,400.00
	TO TRANSFER DOOR COMPARTMENT/WINDOW GLASS/REGULATOR/LOCK/MECHANISM,ETC.		350.00	80.00
	TO TEST RUN INTERCOOLER FUNCTIONALITY.		100.00	60.00
			3,850.00	2,960.00
GRAND TOTAL			16,739.32	10,953.72
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,700.00

Report Ref No. CS/UOI20001498/Kvd3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.