

ASS. REC. BY:

REF:

08/TM120001575/Nsd321

Special Instruction:

Surveyor: NAZ

ASSIGNMENT (Office)

From (Person):

clarah Milah Yeo

of

TMI

Date/Time:

29/01/2020 @ 2:32pm

Estimated Cost:

Bill to:

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SHD8555Y

Insured:

SLK98329

at Workshop m/s

Comfort delgro  
Selayang Drive

Tel:

6214 8300

of

Policy No.:

MK000575

Claim No.:

M2000705

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

27/01/2020

CA / REV / REP. / REV. 24 HRS

H.O.D. Endorsement:

Date/Time:

2:47pm @ 29/1/2020

Person Contacted:

Jumeri

Vehicle  IN  OUT

Date/Time	Action/Instruction	Technician
	SHD8555Y - cc3 / 03FA9004059 / Kleb3g2	
	SLK98329 - X.	
30/01/20	@ 14:58 pm revised PA to clara milah via meimen.	



## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jan 2020 18:20 <a href="#">Sendback Est</a>	28 Jan 2020 18:33 <b>S\$4,689.24</b>	29 Jan 2020 14:32 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)
[Reference](#)
[Claim Details](#)
[Documents](#)
[Show All](#)

### CLAIM SUBFOLDER DETAILS

Insured:	LION CITY RENTALS PTE LTD, Co. Reg. No.: 201504621K		
Main Claimant:	CITYCAB PTE LTD, Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	SHD8555Y	Date of Loss:	27/01/2020 17:00 - :59 [40 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2000705	Policy/Cover Note No.:	MK000575 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	SLK9832G	Policy No. (Claimant):	D-18088937MFSH
		Excess:	S\$1,600.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Clara Milah Yeo]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/02/2020]		

### ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Workshops**

39 Loyang Drive Singapore 508969  
 383 Sin Ming Drive Singapore 575717  
 45 Pandan Road Singapore 608286  
 390 Libby Road Singapore 610198

24 Senoko Loop Singapore 758156  
 7 Sungei Kadut Way Singapore 728791  
 501 Yehun Industrial Park A Singapore 768731

A member of COMFORTDELGRO

Date/Time: 28.01.2020 16:34 Page : 1

Team: ARC Repair TP(CFSO)1

### JOB CARD

Sales Order:

JC NO.: 305377328

TOMER  
 MS  
 TOMER NO.  
 PRESS  
 (R)  
 (P)  
 COUNT CARD NO.

**CITYCAB PTE LTD**  
 7010070  
 383 SIN MING DRIVE  
 Singapore SINGAPORE 575717  
 65551188

VARs


REGN NO.: SHD8555Y	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 28.01.2020 12:35
YR OF MANU 15.09.2016	TARGET DATE
CHASSIS CODE KMHLB41UMGU093716	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 27.01.2020  
 NATURE: 3P 27.01.2020

S/NO                      LABOR CODE                      DESCRIPTION

TOKIO - Right Front



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD8555Y

LARRY

Vehicle No.: SHD8555Y

Larry Ng

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

## Shirley Hiew (LKK Auto)

---

**From:** Naz (LKKAuto)  
**Sent:** Wednesday, 19 February 2020 5:38 pm  
**To:** Ng Nyuk Phin  
**Cc:** Shirley Hiew (LKK Auto); SUR  
**Subject:** Re: SHD8555Y FINALISATION DAO: 27.01.2020  
**Attachments:** FINALIZED.pdf

Dear Mr Ng,

Finalized Lump Sum Repair \$3,050 / 3 Repair Days subject to insurance approval.

Thank you.

Best Regards,

**Naz** | Technical Investigator

**LKK Auto Consultants**

Phone: 6841-2157 | Email: [Naz@lkkauto.com](mailto:Naz@lkkauto.com) | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Nyuk Phin <[ngnp@cdge.com.sg](mailto:ngnp@cdge.com.sg)>  
**Sent:** Wednesday, 19 February 2020 12:26 PM  
**To:** Naz (LKKAuto) <[Naz@lkkauto.com](mailto:Naz@lkkauto.com)>  
**Cc:** Shirley Hiew (LKK Auto) <[ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** Re: SHD8555Y FINALISATION DAO: 27.01.2020

Dear Naz,

Thanks for sharing the photos. Please see attached Supplementary list for the Front Wheel Cover - RH.

The Front Bumper Bracket - RH and Right Headlamp were changed.

Kindly see attached Revised Finalisation.

Regards,  
Larry Ng  
ComfortDelgro Engineering Pte Ltd  
Loyang Taxi Crash Repair  
6214 8316



Think Before Printing

---

**From:** Naz (LKKAuto) <Naz@lkkauto.com>  
**Sent:** Wednesday, 19 February 2020 11:32 AM  
**To:** Ng Nyuk Phin <ngnp@cdge.com.sg>  
**Cc:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; SUR <sur@lkkauto.com>  
**Subject:** Re: SHD8555Y FINALISATION DAO: 27.01.2020

Dear Mr Ng,

Here are the photos of the dismantled parts. My finalization does not tally with yours. Kindly help me mark the checked items that were included in the final figure.

Thank you.

Best Regards,

**Naz** | Technical Investigator

**LKK Auto Consultants**

Phone: 6841-2157 | Email: [Naz@lkkauto.com](mailto:Naz@lkkauto.com) | Fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Ng Nyuk Phin <ngnp@cdge.com.sg>  
**Sent:** Tuesday, 11 February 2020 3:53 PM  
**To:** Naz (LKKAuto) <Naz@lkkauto.com>  
**Subject:** SHD8555Y FINALISATION DAO: 27.01.2020

Hi Naz,

Please see attached Finalisation Form and photos.

Regards,  
Larry Ng  
ComfortDelgro Engineering Pte Ltd  
Loyang Taxi Crash Repair  
6214 8316



Think Before Printing

From: canon@comfortdelgro.com.sg <canon@comfortdelgro.com.sg>

Sent: Tuesday, 11 February 2020 3:51 PM

To: Ng Nyuk Phin

Subject: Scan Image

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

---

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]

---

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Tokio Marine Insurance Singapore Ltd  
20 McCallum Street  
#09-01 Tokio Marine Centre  
Singapore 069046

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Clara Milah Yeo

Date: 30 Jan 2020

**Preliminary Advice**

Insured Vehicle No	: SLK9832G	Accident Date	: 27/01/2020
TP Vehicle No	: SHD8555Y	Assignment Date	: 29/01/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 3 days
Date of Inspection	: 29/01/2020		
Inspection At	: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,689.24
Revised Amount	:S\$	2,555.32
Check Items (Estimated)	:S\$	1,953.92
Total	:S\$	4,509.24
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : TP : WP

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	28/01/2020 14:25
Date Of Accident	27/01/2020 18:00
Exact Location Of Accident	YISHUN CENTRAL TWDS AVE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD8555Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CITYCAB PTE LTD
Co Reg No	1XXXXX839G
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088937MFSH
Cover Note Number	

### Driver

Name of Driver	SIM KIM TIAN
NRIC No	SXXXX195Z
Date Of Birth	11/10/1963
Occupation	OUTDOOR
Date Of Driving Pass	16/05/1985
Driving Experience	34 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94230506
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 862 YISHUN AVENUE 4 #09-63
Postcode	760862
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	DRIZZLING
Road Surface	WET

### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : - GENDER: : FEMALE

### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

### Circumstances of Accident

REFER ATTACHED

### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK9832G
Vehicle Make/Model/Colour	HONDA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TAY SIEN DJIM
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

LH FRONT

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

CITYCAD PTE LTD  
CO. REG. NO. 199502839G


Policyholder's Signature  
Date & Time:



Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27 Jan 2020 @ 1800 hr I, veit A  
 corinhat stop.  
 Slow down B4 Box Junction due Red light  
 once I veit (A) notice vehicle in front  
 make my lane was clear suddenly veit  
 (B) 3rd lane cut across to my lane  
 I veit (A) cannot stop intime all  
 collide with veit (B) @ the point  
 of accident veit (A) ferry ferry  
 a female passenger seat injure.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CITYCAB PTE LTD  
 CO. REG. NO. 199502839G

Policyholder's Signature  
 Date & Time

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No :

SIAS.AC SketchPlanForm\_V3

# ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

**TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)**  
**CITYCAB PTE LTD**

Singapore

**Claimant**  
**Insurer: MS First Capital Insurance Ltd**

## PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/01/2020
Vehicle Reg. No.:	<b>SHD8555Y</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Driver (TP):	SIM KIM TIAN		

Make/Model:	HYUNDAI I40, 1.7 D CRDI (A)	Vehicle Reg. Date:	15/09/2016
Vehicle Colour:	YELLOW	Gen Condition:	GOOD
Engine No:	D4FDGU673783	Chassis No:	KMHLB41UMGU093716
Odometer:	510410 KM		

Paint Type:

List Item Discount: 20.00 %

Total Loss? **NO**

Est. Duration of Repair (day) 3

Description of Accident/Loss: REFER ATTACHED

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS	Amount
Parts	3,418.24
Miscellaneous Items	11.00
Labour	1,260.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>4,689.24</b>

*Larry Ng* 4774.92

**+ GST 7.00% (S\$)** 328.25

**Nett Amount (S\$)** 5,017.49

**This claim is handled by: NG NYUK PHIN**

*Generated using Merimen e-Claims Internet Estimation & Adjusting System*

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Jan 2020)

**Parts:** 143 HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD8555Y/28/01/2020 18:33

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	20.00	0.00	*1,052.20 FL ✓DB
2	10		*FRONT BUMPER CLIPS	20.00	0.00	*22.00 FL ✓DB
3	1		*FRONT BUMPER TOP BRACKET - RH	20.00	0.00	*22.40 FL ✓DB
4	1		*FRONT BUMPER BRACKET - RH	20.00	0.00	*24.60 FL ✓DB
5	1		*FRONT FENDER - RH	20.00	0.00	*556.30 FL ✓DB
6	1		*HEADLAMP - RH	20.00	0.00	*1,388.00 FL ✓DB
7	1		*HEADLAMP SUPPORT PANEL	20.00	0.00	*907.40 FL ✓DB
8	1		*FRONT FENDER SHIELD - RH	20.00	0.00	*174.90 FL ✓DB
9	1		*ADVERTISEMENT - FRONT FENDER - RH	0	0.00	*100.00 FS ✓DB


F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 4,247.80

**- List Item Discount on L Items (\$\$)** 829.56

**Total Parts (\$\$)** 3,418.24

**ComfortDelGro Engineering Pte Ltd/SHD8555Y/28/01/2020 18:33.** Not valid without Reference section.  
Generated using **Merimen e-Claims IEAS**



Handwritten calculations:  
 PARTS L20% 3,325.10  
 L 2,660.08  
 L 1,030.00  
 3,790.08  
 LESS L520% 3,032.06  
3,050.00 / 30 Days

# Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	560 600.00
2	SPRAY PAINTING	New	400 500.00
3	WIRING CHARGE	New	30 ? 80.00 XAX
4	TUFF KOTE	New	40 80.00
<b>Gross Labour Cost (S\$)</b>			<b>1,260.00</b>

ComfortDelGro Engineering Pte Ltd/SHD8555Y/28/01/2020 18:33. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Handwritten notes:*  
 Larry Ng  
 30/1/2020  
 NAZ LKK 29/10/2020 1715  
 (1)  
 3 DAYS  
 CHECK ITEM PHOTOS  
 AFTER REPAIR PHOTOS

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:



Our Job Ref No : 305377328

Date : 19. Feb. 2020

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

**FINALIZATION FORM**

To : LKK

Fax :

Attn : NAZ

Vehicle Reg No. : SHD8555Y

Date of Accident: 27. Jan. 2020

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO SLK9832G

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less: \_\_\_\_\_

**Final Lumpsum Repair cost** \$3,050.00

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Name : Larry Ng

Tel : 6214 8316

Fax : 6546 8156

Signature : 

Name : NAZ LKK

Date : 19/2/2020

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid				
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jan 2020 18:20 <a href="#">Sendback Est</a>	28 Jan 2020 18:33 <b>S\$4,689.24</b>	29 Jan 2020 14:32 <a href="#">Edit Adj Rpt</a>	<b>S\$3,050.00</b> <a href="#">Edit Estimates</a>	<b>S\$3,050.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:	<b>LION CITY RENTALS PTE LTD</b> , Co. Reg. No.: 201504621K		
Main Claimant:	<b>CITYCAB PTE LTD</b> , Co. Reg. No.: 199502839G		
Vehicle Reg. No.:	<b>SHD8555Y</b>	Date of Loss:	27/01/2020 17:00 - :59 [40 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / M2000705</b>	Policy/Cover Note No.:	MK000575 (Third Party Only) Coverage: 25/06/2019 - 24/02/2020
Vehicle Reg. No. (Insured):	<b>SLK9832G</b>	Policy No. (Claimant):	D-18088937MFSH
		Excess:	S\$1,600.00
Repairer:	<b>ComfortDelGro Engineering Pte Ltd (Loyang)</b> 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	<b>Tokio Marine Insurance Singapore Ltd (HQ)</b> - Tel: 6221 6111 ... [Handled by <b>Clara Milah Yeo</b> ]		
Claimant's Insurer:	<b>MS First Capital Insurance Ltd (HQ)</b> - Tel: 62222311		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>Muhammad Nazril Bin Abdullah</b> ] ... [Final Rpt due 07/02/2020]		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

### Claim Documents

**SHD8555Y (M2000705)**  
**[SLK9832G]**  
**TP**  
**CITYCAB PTE LTD**  
**Jan 27 2020 5:00PM**  
**[LION CITY RENTALS PTE LTD]**  
**ComfortDelGro Engineering Pte Ltd**

Upload Documents		Upload Photos		Compose New Letter		<b>View</b> View in Browser <input type="button" value="v"/>	
<b>Assessment Reports</b>						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)			<b>Thumbnail</b>	<b>Print</b>	
1	28/01/20 18:33	<b>Repairer Estimates</b>			Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			<b>Thumbnail</b>	<b>Print</b>	
1	30/01/20 14:58	<b>Adjuster Immediate Advice</b>			Load HTM		
<b>Photos/Images</b>						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			<b>Thumbnail</b>	<b>Print</b>	
1	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
2	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
3	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
4	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
5	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
6	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
7	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
8	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
9	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
10	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
11	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
12	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
13	30/01/20 11:28	<b>General View</b>			Load JPG	<input checked="" type="checkbox"/>	
14	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
15	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
16	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
17	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
18	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
19	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
20	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
21	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
22	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
23	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
24	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
25	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
26	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
27	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
28	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
29	19/02/20 17:50	<b>Dismantled Parts</b>			Load JPG	<input checked="" type="checkbox"/>	
30	19/02/20 17:51	<b>Photo After Spray</b>			Load JPG	<input checked="" type="checkbox"/>	
31	19/02/20 17:51	<b>Photo After Spray</b>			Load JPG	<input checked="" type="checkbox"/>	
32	19/02/20 17:51	<b>Photo After Spray</b>			Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
33	19/02/20 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

### Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	28/01/20 14:35	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	28/01/20 14:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	28/01/20 14:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	28/01/20 14:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	28/01/20 14:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	28/01/20 14:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	28/01/20 14:34	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	28/01/20 14:34	SCENE	 Load JPG	<input checked="" type="checkbox"/>
8	28/01/20 14:34	SCENE	 Load JPG	<input checked="" type="checkbox"/>
9	28/01/20 14:34	SCENE	 Load JPG	<input checked="" type="checkbox"/>
10	28/01/20 14:34	SCENE	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail	Print
1	28/01/20 14:30	Sketch Plan	 Load TIF	

### Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>			
<b>Show Remarks To:</b> <input type="checkbox"/> Repairer <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/TMI20001575/NSD3E2

**Date:** 25/02/2020

#### REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No: MK000575	
<b>Claimant Vehicle No :</b> SHD8555Y	<b>Insured Vehicle No :</b> SLK9832G	
Date of Loss: 27/01/2020	Nature of Claim: TP	Claim No: M2000705

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD8555Y	Engine No:	D4FDGU673783
Make & Model:	HYUNDAI I40, 1.7 D CRDi (A)	Chassis No:	KMHLB41UMGU093716
Reg. Date:	15/09/2016 (Man. Year: 2016)	Odometer:	510410 km
Colour:	Yellow		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Average

#### CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,418.24	2,760.08	658.16	19.25
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,260.00	1,030.00	230.00	18.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,689.24</b>	<b>3,801.08</b>	<b>888.16</b>	<b>18.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,050.00</b>		
(S\$)	4,689.24	3,050.00	1,639.24	34.96
<b>+ GST 7.00/7.00% (S\$)</b>	328.25	213.50	114.75	34.96
<b>Nett Amount (S\$)</b>	<b>5,017.49</b>	<b>3,263.50</b>	<b>1,753.99</b>	<b>34.96</b>

#### INSPECTION

Date of Assignment:	29/01/2020 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	29/01/2020 Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** Muhammad Nazril Bin Abdullah

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 25 Feb 2020)
<b>Parts:</b> 143	HYUNDAI I40 1.7 D CRDi (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD8555Y)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER	Deformed	1,052.20 FL	-	*1,052.20 FL
2	10		*FRONT BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
3	1		*FRONT BUMPER TOP BRACKET - RH	Serviceable	22.40 FL	-	*- FL
4	1		*FRONT BUMPER BRACKET - RH	Cracked	24.60 FL	-	*24.60 FL
5	1		*FRONT FENDER - RH	Deformed	556.30 FL	-	*556.30 FL
6	1		*HEADLAMP - RH	Cracked	1,388.00 FL	-	*1,388.00 FL
7	1		*HEADLAMP SUPPORT PANEL	Serviceable	907.40 FL	-	*- FL
8	1		*FRONT FENDER SHIELD - RH	Torn	174.90 FL	-	*174.90 FL
9	1		*ADVERTISEMENT - FRONT FENDER - RH	Necessary	100.00 FS	-	*100.00 FS
10	1		*FRONT WHEEL COVER - RH	Deformed	-	-	*107.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>4,247.80</b>	<b>3,425.10</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	829.56	665.02
<b>Total Parts (S\$)</b>	<b>3,418.24</b>	<b>2,760.08</b>

Report was unsubmitted during this print-out.

### Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<b>Miscellaneous Items</b>				
1	1	OD/TP Case (Insurer)	11.00	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>	<b>11.00</b>

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	600.00	560.00
2	SPRAY PAINTING	New	500.00	400.00
3	WIRING CHARGE	New	80.00	30.00
4	TUFF KOTE	New	80.00	40.00
<b>Gross Labour Cost (S\$)</b>			<b>1,260.00</b>	<b>1,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >