

AES. REC. BY:

REF: 28/CTI20001608/Q1 d3<sup>32</sup> Special Instruction:

Surveyor:

## ASSIGNMENT (Office)

From (Person): Ben Tang of CTI Date/Time: 30/1/2020 @ 1:35pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: PC 6880G Insured: SFM 5151A

at Workshop m/s The one Holdings Tel: 67558810

of 8 woodlands Ind. Park E3 woodlands Ind. Park E

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 6/1/2020  
(Client's Record) 4/02/2020 @ 10:30am

CA / REV / REP. / REV 24 HRS (wp) H.O.D. Endorsement:

Date/Time: 2:11pm @ 30/1/2020 Person Contacted: Zi Xuan Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate	✓
	SFM 5151A-NA/CTI20000482/h4		
	PC 6880G-NA/CTI20000482/h4		

D.O.A: 06/01/2020

D.O.A: 06/01/2020

REF: CTI

ASS. REC. BY:

## ASSIGNMENT

From: Date: 4/2/2020

Estimated Cost:

OE / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SFM 5151A PC 6880 G

at Workshop m/s The one Holdings

of 8 woodlands Ind. Park E3 woodlands

Insured: Ind. park E.

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: 10:30 am (waiting)

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 1 up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: PC 6880 G. Yr Regn: 22/12/2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volvo B7R Auto. C.C 7146

Colour: Multicolour. A/C: Insured / Std / NI / NA

Sp. Reading: 82449. T/Radio: Insured / Std / NI / NA

Eng/No: -

C/No: YV3R6R624HA186300

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 295 / 80 R 22.5

R: 295 / 80 R 22.5 (V)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm

R/Bal. 5/5 mm

L/Bal. 5 mm

L/Bal. 5/5 mm

D.O.A. 06/01/2020.

D.O.I. 04/02/2020.

Survey held at The One Holding

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 2 MAR 2020

Confirm with Hilmi

Finalize \$750 @ 1 day (L/S) Cred: 750.00%

26/2/2020

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.J. (\$)

## Nivitha (LKK Auto)

---

**From:** Ben Tang <Ben.Tang@sg.cntaiping.com>  
**Sent:** Thursday, 30 January 2020 1:35 PM  
**To:** 'assignments@lkkauto.com'  
**Subject:** FW: PC6880G surveyor appointment request (TP Vehicle SFM5151A)

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SFM5151A.

Thank you.

Best Regards  
Ben Tang  
Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #XX-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6175 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平狮城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Hilmi (TOH) <hilmi@theoneholdings.com.sg>  
**Sent:** Thursday, January 30, 2020 12:22 PM  
**To:** Ben Tang <Ben.Tang@sg.cntaiping.com>  
**Cc:** Susan Teo <susan.teo@sg.cntaiping.com>; Albert Chua <albert.chua@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; accounts@theoneholdings.com.sg  
**Subject:** RE: PC6880G surveyor appointment request (TP Vehicle SFM5151A)

Hi Ben,

We choose Adrian Ling.  
Can we make it on Monday 4th Feb at 10am.  
location-No 8 Woodlands Industrial Park E3 Singapore 757786.

Thanks & regards  
Hilmi (F)

---

**From:** Ben Tang [<mailto:Ben.Tang@sg.cntaiping.com>]  
**Sent:** Wednesday, January 29, 2020 5:31 PM  
**To:** 'hilmi@theoneholdings.com.sg' <hilmi@theoneholdings.com.sg>  
**Cc:** Susan Teo <susan.teo@sg.cntaiping.com>; Albert Chua <albert.chua@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; accounts@theoneholdings.com.sg'

<accounts@theoneholdings.com.sg>

**Subject:** RE: PC6880G surveyor appointment request (TP Vehicle SFM5151A)

**WITHOUT PREJUDICE**

Dear Sir,

We refer to your email dated 29 January 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards  
Ben Tang  
Executive  
Claims Department

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road #XX-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6175 | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG

*Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.*

---

**From:** Hilmi (TOH) <hilmi@theoneholdings.com.sg>  
**Sent:** Wednesday, January 29, 2020 11:35 AM  
**To:** Feedback of China Taiping Insurance <[feedback@sg.cntaiping.com](mailto:feedback@sg.cntaiping.com)>  
**Cc:** [accounts@theoneholdings.com.sg](mailto:accounts@theoneholdings.com.sg)  
**Subject:** PC6880G surveyor appointment request (TP Vehicle SFM5151A)

Dear Sir/Maam,

Kindly see attachment, we would like to make an appointment for a surveyor.

*Regards*

*Muhd.Hilmi Deres*

*The One Holdings Pte Ltd*

*Tel : +65 6755 8810*

*Fax : +65 6755 8809*

*Mobile : +65 97480340*

*Email Add : [hilmi@theoneholdings.com.sg](mailto:hilmi@theoneholdings.com.sg)*

*ROC no:201704052Z*

## Oi Sun Pin (LKK Auto)

---

**From:** Hilmi (TOH) <hilmi@theoneholdings.com.sg>  
**Sent:** Wednesday, 19 February, 2020 10:37 AM  
**To:** Oi Sun Pin (LKK Auto)  
**Cc:** accounts@theoneholdings.com.sg  
**Subject:** RE: PC6880G 6th January 2020 accident case with SFM5151A

Dear Oi

Noted, we will close at \$750 and LOU amount subject to approval? @\$250?

Hilmi

---

**From:** Oi Sun Pin (LKK Auto) [mailto:sunpin@lkkauto.com]  
**Sent:** Wednesday, February 19, 2020 9:45 AM  
**To:** Hilmi (TOH) <hilmi@theoneholdings.com.sg>  
**Subject:** RE: PC6880G 6th January 2020 accident case with SFM5151A

Dear Hilmi,

Kindly refer the finalize amount for COR \$750, (before gst). Repair day 1 days under part by part repair.

Thank you.

Best Regards,

**Oi Sun Pin** | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: [Sunpin@lkkauto.com](mailto:Sunpin@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Hilmi (TOH) [mailto:hilmi@theoneholdings.com.sg]  
**Sent:** Wednesday, 19 February, 2020 9:00 AM  
**To:** Oi Sun Pin (LKK Auto)  
**Cc:** accounts@theoneholdings.com.sg  
**Subject:** RE: PC6880G 6th January 2020 accident case with SFM5151A

Dear Oi Sun Pin

Kindly see attachments for the repair images.

Anything that we need to start from here? Kindly advice.

Thanks

*Regards*

Muhd. Hilmi Deres  
The One Holdings Pte Ltd  
Tel : +65 6755 8810  
Fax : +65 6755 8809  
Mobile : +65 97480340

Pending to booking Surveyor.  
9/1/2020

MSC120003753 / SC Auto Industries (S) Pte Ltd - HQ  
ENTRY DATE & TIME: 09/01/2020 10:48  
SUBMITTED BY: Hamimah Bte Jamaludin

Your NCD will be affected due to late reporting  
Actual e-Filing Submission Date & Time: 09/01/2020 11:01

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/01/2020 10:48
Date Of Accident	06/01/2020 19:40
Exact Location Of Accident	JUNCTION OF DEFU LANE 10 & AVE 1
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC6880G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	REGENCY TRAVEL PTE LTD
Co Reg No	1XXXXX192D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-81112929

### Vehicle Particulars

Manufacturer	VOLVO
Model	B7R-7.1 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	GA426491
Cover Note Number	

### Driver

Name of Driver	ANG POH ENG
NRIC No	SXXXX865G
Date Of Birth	23/06/1964
Occupation	OUTDOOR
Date Of Driving Pass	26/09/1991
Driving Experience	28 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97598492
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 124C RIVERVALE DRIVE #16-219

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions RAINING

Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SFM5151A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LIM KEI HAO PATRICK

NRIC/Passport Number SXXXX137J

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

X  
Policyholder's Signature  
Date & Time:




X  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



X  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 6th January 2020 at 19:40hrs I was driving along Defu Lane 10 junction towards Defu Ave 1. All vehicle is waiting for clearance to turn left. I was on the 2nd lane to turning left. After checking my blindspot and the road is clear to turn I drove slowly and suddenly I felt like something grazed on my front left side of the bus. I looked again and saw a car was there. Not only that car on that lane but also on it's left side also there was a lorry. Both in one lane. Then stopped aside and exchange particulars and took some images.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

x

Policyholder's Signature  
Date & Time:



x

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	192D
<b>Vehicle Details</b>	
Vehicle No.:	PC6880G
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Feb 2020
Vehicle Make:	VOLVO
Vehicle Model:	B7R AUTO
Primary Colour:	Multicolor
Manufacturing Year:	2017
Engine No.:	D7E12027941
Chassis No.:	YV3R6R624HA186300
Maximum Power Output:	-
Open Market Value:	\$138,133.00
Original Registration Date:	22 Dec 2017
First Registration Date:	22 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$6,907.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 Dec 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$58,036.00
COE Rebate Amount:	\$45,679.00
<b>Total Rebate Amount:</b>	<b>\$45,679.00</b>

The information contained herein is correct as at 07 Feb 2020

OK

4/2/2020 10:30am Survey



**THE ONE HOLDINGS**  
PRIVATE LIMITED

(Specializes in commercial vehicle repair works)  
Business and GST Reg No.: 2017040522

**The One Holdings Pte Ltd**

No 8 Woodlands Industrial Park E3 Singapore 757786

Telephone: +65 6755 8810 Facsimile: +65 6755 8809

Email: enquiry@theoneholdings.com.sg

Website: www.facebook.com/theholdings

**QUOTATION**

**To: China Taiping Insurance (Singapore) Pte.**  
**Ltd.**  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

**Our Ref : Q200156**  
**Date : 30/01/2020**  
**Term : COD**  
**In Charge : Hilmi**

**Attn : Ben Tang (63896175)**

Dear Sir / Madam

**RE: Accident Involving PC6880G & SFM5151A on 06/01/2020**

No	Description	Qty	UOM	U/P (S\$)	Amt (S\$)
<b>Ad hoc</b>					
1	To repair and spray paint the LHS side panel.	1.00	UT	750.00	750.00 ✓

Repair — 150

Spray — 600

P/P Repair

After Repair photo

Repair day — 1 days.

Sun Pm (4kk)

04/02/2020.

TP without prejudice

sunpm @ lkk auto .com

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Terms & Conditions:**

Loss of Use 1days X \$250 = \$250.00

Prices are subject to change without prior notice, additional  
parts need to be replaced, subject to final checking and bill  
separately.

**Accepted and Confirmed by :**

**Subtotal:** 750.00  
**GST 7.0% :** 52.50  
**Total Amount:** 802.50

Company Chop & Signature

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Jan 2020		26 Feb 2020 09:57 <a href="#">Edit Adj Rpt</a>	<b>S\$750.00</b> <a href="#">Edit Estimates</a>	<b>S\$750.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	<b>REGENCY TRAVEL PTE LTD</b>	
Vehicle Reg. No.:	<b>PC6880G</b>	Date of Loss: 06/01/2020 19:00 - :59 [24 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / SNM20D200107</b>	Policy/Cover Note No.: DMPCSN30211019000 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SFM5151A</b>	Policy No. (Claimant):
		Excess: S\$0.00
Repairer:	<b>The One Holdings Pte Ltd (HQ)</b> 8 Woodlands Industrial Park E3, 757786 Woodlands - Tel:	
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]	
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>OI SUN PIN</b> ] ... [Final Rpt due 06/03/2020]	

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a> <a href="#">Compose Case Mail</a>
There are no mail for this case.	

ALL ASSOCIATED TASKS <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*PC6880G (SNM20D200107)**  
**[SFM5151A]**






















**TP**

**REGENCY TRAVEL PTE LTD**

**Jan 6 2020 7:00PM**

**[-]**

**The One Holdings Pte Ltd**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
2	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
3	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
4	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
5	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
6	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
7	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
8	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
9	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
10	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
11	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
12	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
13	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
14	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
15	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
16	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
17	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
18	26/02/20 10:13	<b>General View</b>	 Load JPG	<input checked="" type="checkbox"/>
19	26/02/20 10:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
20	26/02/20 10:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>
21	26/02/20 10:13	<b>Reinspection Photo</b>	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a> <a href="#">Save</a> <a href="#">Print</a>
There are no document checklists configured.	
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 100px; margin-top: 5px;"></div>	
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	





## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20001608/QTD3S2  
Date: 03/03/2020

## REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN30211019000  
Claimant Vehicle No: PC6880G Insured Vehicle No: SFM5151A  
Date of Loss: 06/01/2020 Nature of Claim: TP Claim No: SNM20D200107

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: PC6880G  
Make & Model: VOLVO B7R, 7.1 (A) Engine No: D7E12027941  
Reg. Date: 22/12/2017 (Man. Year: 2017) Chassis No: YV3R6R624HA186300  
Colour: Multi-colour Odometer: 82449 km  
Engine Capacity: 7146 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D)  
Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5/5 mm  
Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	750.00	750.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>750.00</b>	<b>750.00</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>52.50</b>	<b>52.50</b>	<b>0.00</b>	<b>0.00</b>
<b>Nett Amount (\$\$)</b>	<b>802.50</b>	<b>802.50</b>	<b>0.00</b>	<b>0.00</b>

## INSPECTION

Date of Assignment: 26/02/2020  
Date Inspected: 04/02/2020 Inspected At: The One Holdings Pte Ltd (HQ)  
8 Woodlands Industrial Park E3  
Singapore 757786  
Estimated Period of Repair: 1.0 days

Adjuster: OI SUN PIN

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 03 Mar 2020)	
<b>Parts:</b>	N/A	VOLVO B7R 7.1 (A) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for PC6880G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR AND SPRAY PAINT THE LHS SIDE PANEL.	New	750.00	750.00
Gross Labour Cost (S\$)			750.00	750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >