



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 07/02/2020

User ID : CatherineLee

### Section A - Accident Details

Registration Number	SMB1590S
Case Reference Number	BUS/01/20/1034
Registration Date	7/1/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Khoo Yan Tik
Type of Accident	Side Swipe
Accident Date and Time	21/1/2020 9:20 AM
Accident Reported Date and Time	21/1/2020 11:45 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105433
Special Instruction to ARC, if any	SMB1590S-RIGHT FRONT PORTION SGN43U ( TP ) INSURED WITH AIG
Prepared Date and Time	22/1/2020 5:24 PM
Chassis Number	WMAA22ZZ8F7002562
Mileage	
Work Shop	
Repair Completion Date and Time	

### Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$708.00	\$616.00
Total Spare Part Cost	\$1,892.16	\$651.17
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,395.16	\$1,797.17
Lump Sum Total	\$3,400.00	\$1,800.00
Number of Repair Days	3.0	2.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	22/01/2020 5:35 PM	23/01/2020 3:12 PM
Signature		
Remarks		

### Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 07/02/2020

User ID : CatherineLee

### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$530.00
Total Labour	\$795.00	\$530.00

#### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	\$616.00
Total Spray Painting & Panel Beating	\$708.00	\$616.00

#### Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

#### Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010152	Body	F01001-CW266	COVER, HEADLAMP, FRT, RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair X R
6010305	VE	81.25101-6540	HEADLAMP, RH (MAN BUS)	0.00	\$1,603.60	0.00	\$0.00	Replace	Not Given X MC
6010307	VE	81.25320-6112	FLASHER, AUX HEADLAMP, RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	Replace / CRA
6009375			LOCK CAM	1.00	\$120.00	100.00	\$0.00	Replace	Repair X R
Total					\$3,602.70		\$813.96		

#### Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

$$\begin{array}{r} 813.96 \\ - 20\% \\ \hline 651.17 \\ 530 \\ 616 \\ \hline 1,797.17 \end{array}$$

$$L/S = 1,800$$

2 days