

ASS. REC. BY:

H. ANN

REF: FCI

ASSIGNMENT

From:

Date: 31/01/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 5616Y

at Workshop m/s

Autolution Industrial

of

19 ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

3pm (waiting)

Hamzah

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (ap)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLE 5616Y

Yr Regn: 27/06/2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN SYLPHY

c.c 1598

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

58200

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MNTBBAB 172 002 7425

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/60/R16

R:

/ /

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

18/1/20

D.O.I.

31/1/20

Survey held at

Autolution Industrial

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* SLE 5616Y No Direct
case, but Repair.* Agent workshop required
need to p/p repair.

3727.28

mv - 53000

pv - 46607

nv - 6300

Hamzah → 96450079

R655

Date/Time, File Pass to?

☐

: Preli. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format:

Lump Sum / L.B.I. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Week end (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	000J
Vehicle Details	
Vehicle No.:	SLE5616Y
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Jan 2020
Vehicle Make:	NISSAN
Vehicle Model:	SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	HR16990409B
Chassis No.:	MNTBBAB17Z0027425
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$16,910.00
Original Registration Date:	27 Jul 2016
First Registration Date:	27 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$16,910.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2026
PARF Rebate Amount:	\$12,682.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$33,925.00
Total Rebate Amount:	\$46,607.00

The information contained herein is correct as at 31 Jan 2020

OK



Michelin
Ultra-high
performance
tyre.



Enhance Car
Interior With
CF Steering
Wheel



Optimise
Your Ride
With Comfort
& Handling



Rainbow
set @
only!
\$1284

Nissan Sylphy 1.6A

Price Range

Depreciation

Year Reg

Vehicle Type

Home » Used Cars » Viking Motor Pte Ltd » Nissan Sylphy 1.6A Premium

Nissan Sylphy 1.6A Premium

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$60,800

Depreciation ⓘ

\$7,590 /yr

View models with similar depre

Reg Date

27-Dec-2016

(6yrs 10mths 25days COE left)

Mileage

52,000 km (16.8k /yr)

Manufactured ⓘ

2016

Road Tax ⓘ

\$742 /yr

Transmission

Auto

Dereg Value ⓘ

\$45,758 as of today (change)

OMV ⓘ

\$16,807

COE ⓘ

\$48,000

ARF ⓘ

\$16,807

Engine Cap

1,598 cc

Power

85.0 kW (113 bhp)

Curb Weight ⓘ

1,205 kg

No. of Owners ⓘ

1

Type of Vehicle

Mid-Sized Sedan

Features

Responsive And Powerful 4 Cylinder Inline DOHC C-VTC Producing 113BHP, Dual SRS Airbags, ABS, Keyless Entry/Push Start Button, Rear Aircon. View specs of the Nissan Sylphy (2013-2016)

Accessories

Leather/Alcantara Seats, 8" Touch Screen Multi Media With GPS, Reverse Camera, Bluetooth, USB, DVD, Multi Function Steering Wheel.

Description

1 Careful Owner! Low Mileage! Nice Elegant Blue! Warranty Up To One Year! Bank And In House Full Loan Available, Interior And Exterior All Well Maintained And In Excellent Condition, View To Believe, Contact Our Name Sales Person For Viewing.

Category

PARF Car

Status

Available

Resources

Compare


tion

? Request to have this car evaluated professionally. Find out more



Location Map

Price Chart



Click on the point to view the vehicle

Shortlist

Compare

Add no

Report Error

More Actions

Seller Information

Viking Motor Pte Ltd

37 vehicles for sale. 72 sold in past 3 mths

210 Turf Club Road Lot B33