



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20001709/Bga3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 27-08-2020



ATTN: PETER WANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 3329T	Veh. Inspected	SGH 9953R
Policy No.	GA521582/1	Coverage (\$)	0.00
Claim No.	S0M02ELZ	Excess (\$)	0.00
Assign From	PETER WANG	Assign Date	29/01/2020

2. Vehicle Particulars & Condition

Make & Model	NISSAN SUNNY 1.6EXA	c.c	1597
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JN1CFAN16Z0102616	Colour	BLACK
Odometer	259293	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	POOR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/50 R16	BRIDGESTONE	5 mm
L/H Front Tyre	205/50 R16	BRIDGESTONE	5 mm
R/H Rear Tyre	205/50 R16	BRIDGESTONE	5 mm
L/H Rear Tyre	205/50 R16	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/01/2020	Inspection Date	29/01/2020
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	-----------------------