

**FDK AUTOMOBILE & LEASING SERVICES PTE LTD**

UEN: 201611065K  
39 WOODLANDS CLOSE MEGA @ WOODLANDS  
#05-12 S (737856)

Fabian Wong: 9191 6590  
Daryl Wong: 9772 9698  
Kenneth Wong: 9755 3198

Date: 29 January 2020

BLK 51 UBI AVENUE 1, #01-25  
PAYA UBI INDUSTRIAL PARK  
SINGAPORE 408933

ATTN: STEVE  
MOTOR CLAIM DEPT  
TEL: 6419 3000  
FAX: 6415 3723

YOUR REF NO:  
CLAIM TYPE: THIRD PARTY CLAIM  
ACCIDENT DATE:

|                   |                                  |
|-------------------|----------------------------------|
| NO                | QUOTATION: 2020/0001             |
| DATE              | 29/01/2020                       |
| POICY NO          | MOMVP000001118-03-000            |
| VEHICLE<br>REG NO | SLF5864S                         |
| MAKE/<br>MODEL    | VOLKSWAGEN POLO 1.4AT<br>6R 13E7 |
| CHASSIS NO        | WVWZZZ6RZAU042078                |
| ENGINE NO         | CGG333817                        |
| REG. DATE         | 31 MAY 2010                      |

**Estimate Repair Cost to SLF5864S**

|   | Description                                                      | Quantity | Unit Price (S\$) | Amount |
|---|------------------------------------------------------------------|----------|------------------|--------|
| 1 | RIGHT FRONT DOOR<br>ASSY                                         | 01       | \$1200           | \$1200 |
| 2 | RIGHT REAR DOOR<br>ASSY                                          | 01       | \$1400           | \$1400 |
| 3 | REAR BUMPER + RIGHT<br>SIDE FENDER PANEL<br>BEATING              | 01       | \$440            | \$440  |
| 4 | WIRING CHECKING<br>LABOUR                                        | 01       | \$120            | \$120  |
| 5 | SPRAY PAINTING (2<br>DOOR + REAR BUMPER<br>+ SIDE STEP + FENDER) | 03       | \$1600           | \$1600 |
| 6 | VOLKSWAGEN RIM<br>REPAIR + SPRAY<br>PAINTING                     | 01       | \$320            | \$320  |
| 7 | DOOR FITTING LABOUR<br>(2 UNIT) + SHIFT PANEL<br>+ REAR BUMPER   | 09       | \$220            | \$1980 |
|   |                                                                  |          |                  |        |

Repair days — 4 days

Lump sum  
After part photo

Sun Pm (4 hrs)

30/01/2020

TP without pmg rider

P = 2,340

L = 1,440

3,780

- 20%

3,024

L/S \$3,000

|  |              |  |  |               |
|--|--------------|--|--|---------------|
|  | <b>TOTAL</b> |  |  | <b>\$7060</b> |
|--|--------------|--|--|---------------|

MAKE ALL CHEQUE PAYABLE TO FDK AUTOMOBILE & LEASING SERVICES PTE LTD



Authorized Signature

2,600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: