*	SUNVAJOV From (Person		(Contract of the Contract of	NMENT (Office)		te/Time: 31.1. 2020	4.550. 5
4	Estimated Cos		of	Bill to:	Da	te/Time:	
	/ /	STTP RES / OD RE	SIEVAIINVIM L 64654		Insured:	SLL 4654	
		m/s Huat Auto b] ub Rd 1	muble #01-404		Tel:	SLL 4654 (7461868	
	Policy No:			Claim No:	19/20/2	0/1100/003	436
	Sum Insured:			Excess:			
	Make of Veh: (Client's Record				D.0	D.A. 15. Jan. 2	020
	CA / REV	/ REP. / REV 24 H	IRS 9. m Person Contac	sted: 70m y		LO.D. Endorsement:	
	Date/Time	Action/Instruction	(V) Esti	nute.		· · ·	
		SL1 64654					
	-	SL1 4654	- X)				
	صدمد ادبا	check with	Marcus, n	o estimate			

(08/11/13) wef	REF:	/		
ASS. REC. BY: March	, nc.	spe/		
From:	ASSI Date:	GNMENT Veh No: SLL6	465- / Yr Regn: 3	.17
Estimated Cost:	Date.		I Van / Lorry / Taxi / Prime Mover	1
OD ITP WS / TP RES / OD RES / To Inspect Vehicle No: at Workshop m/s	SIL6465 /	Truck/Trailer or Make: On or Colour Residence Sp.Reading (#2.)	A/C: Insured / Sto	
Insured:		Eng/No:	(
Policy No. Claims No.		C/No: R Gen. Cond: Good-/Fair / Po	V11207632	
Sum Insured:	Excess:	Steering: Iporder / Jammed	/ Leaked / Burnt or	
(Client's Record)		Brake: Morder / Jammed	/ Leaked / Burnt or	
Make of Veh:		Modi: Nil (SIRim / STD	ARIM OF /6021	6
(Policy Condition)		C R:		
Remark: The veh had commenced repair at the time of insp		BS / DUN EXNOVA / GY /	FS / LIZA / MIC / OHTSU / PIR / SU	MI/
Bal. or Market Value:	4/2.	Front	Rear C	
777	consistent? : Yes or No		nm R/Bal.	mm , mm
Est. Repairs: days	Res.: Yes or No	D.O.A. 15/1/20	D.O.I. 3/2/	201.25
Lum Sum: %	3 Val.: Yes or No	Survey held at		11.24
CA / REV / REP. / 24 HRS	477 43 383 Vehicle: IN/OUT		ar I O/S I N/S I U/C I Rooftop	or
Date: Person Cont		The U/C / Chassis fram	ne / Body Structure affected due	to collision.
Date / Time Action / Instruction	on	-	BOART 1	
				-
	RECEIVED	1 1 FEB 2020	-1100	
	,			
Date/Time, File Pass to?	eli. Report	Days Of Repair:		
11/02/20	TOTAL PROPERTY (1998)	Resurvey No. of Trip:	2 Survey Fee:	
	Add Fee:	: Site Insp (\$)S +RS,SI	
2)	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	: Interview (\$) Photos	***
Report Format :	ks	: Tech. Invs (\$) Others	
Lump Sum / I.B.I: (\$)	:Weekend (\$)	
AND		_	TOTAL	

Shirley Hiew (LKK Auto)

From:

LILY KOH < lilykoh@lonpac.com>

Sent:

Monday, 10 February 2020 6:15 pm

To:

Denise Tay (LKKAuto); Admin-D (LKKAuto); assignments; 'victorfong@toplis.com.sg'

Cc:

NM_Claim_SG; SUR; NM_Claim_SG

Subject:

Claim No 19/20/20/LL00/03436 Policy No Z/19/LL00/015920 Insd : SA Valet Pte Ltd Inspection on t/p veh No SLL 6465Y at Huat Automobile Air Con Service [External

Confidential]

Lonpac External - Confidential

Dear Denis

Kindly note our Claim Ref: 19/20/20/LL00/003436 in this regard.


Thank You

Best Regards Lily Koh

Deputy Claims Manager | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

DID: 62799259 / 62507388 Ext 259 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]

Sent: Wednesday, 5 February 2020 10:46 am

To: LILY KOH < lilykoh@lonpac.com>; Admin-D (LKKAuto) < admin-d@lkkauto.com>; assignments

<assignments@lkkauto.com>; 'victorfong@toplis.com.sg' <victorfong@toplis.com.sg>

Cc: NM_Claim_SG <nm_claim@lonpac.com>; SUR <sur@lkkauto.com>; NM_Claim_SG <nm_claim@lonpac.com>

Subject: RE: Policy No Z/19/LL00/015920 Insd : SA Valet Pte Ltd Inspection on t/p veh No SLL 6465Y at Huat Automobile

Air Con Service [External Confidential]

Dear Lily,

Kindly provide claim no./ref no. for our record purpose

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Nivitha (LKK Auto)

From:

ONG LI LI < llong@lonpac.com>

Sent:

Friday, 31 January 2020 4:55 PM

To:

assignments@lkkauto.com; Summer Lee (LKK Auto)

Cc:

MT_Claim_SG; NM_Claim_SG

Subject:

FW: RE: NOTICE FOR PRE-REPAIR INSPECTION OF SLL 6465Y // OUR REF:

L.20.0131.YP [External Confidential]

Lonpac External - Confidential

Dear Nivitha

Please see below and arrange TP survey on 'WP' basis.


Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road #17-04/07 The Concourse

Singapore 199555

Tel: (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: LILY KOH

Sent: Friday, 31 January 2020 4:53 PM To: ONG LI LI < llong@lonpac.com>

Cc: NM_Claim_SG <nm_claim@lonpac.com>

Subject: FW: RE: NOTICE FOR PRE-REPAIR INSPECTION OF SLL 6465Y // OUR REF: L.20.0131.YP [External

Confidential]

Lonpac External - Confidential

Dear Lili,

Kindly arrange for LKK to survey t/p vehicle SLL 6465Y on 'WP' basis.

Thank You

Best Regards

Lily Koh

Deputy Claims Manager | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

DID: 62799259 / 62507388 Ext 259 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Patrick Ng [mailto:adpat21@hotmail.com]

Sent: Friday, 31 January 2020 4:41 pm To: LILY KOH lilykoh@lonpac.com

Cc: Admin S.A Valet Pte. Ltd. <admin@savalet.sg>

Subject: Fw: RE: NOTICE FOR PRE-REPAIR INSPECTION OF SLL 6465Y // OUR REF: L.20.0131.YP

Hi Lily

As per Third Party claim on SA Valet Pte Ltd

Best Regards, Patrick Ng

Ad-Pat Agency Pte Ltd

From: Admin S.A Valet Pte. Ltd. <admin@savalet.sg>

Sent: Thursday, 30 January 2020 10:46 PM To: Patrick Ng <adpat21@hotmail.com>

Subject: Fwd: RE: NOTICE FOR PRE-REPAIR INSPECTION OF SLL 6465Y // OUR REF: L.20.0131.YP

Sent from Tohsoft.Mail for mobile

----Forwarded Message---- From: <u>kurulegal@yahoo.com.sg</u> To: <u>admin@savalet.sg</u> Date: 13:26 Subject: RE: NOTICE FOR PRE-REPAIR INSPECTION OF SLL 6465Y // OUR REF: L.20.0131.YP

To: S A Valet Private Limited

Attn: Mr Afan

CLAIM AGAINST S A VALET PRIVATE LIMITED FOR DAMAGES AND LOSS CAUSED TO SLL 6465Y ON 15.01.2020 AT KK WOMEN'S & CHILDREN'S HOSPITAL CARPARK

We act for Ms Yong Lee Peng, owner of SLL 465Y, whose vehicle was damaged due to the negligence of your employee, servant and/or agent, while in your company's care.

We are instructed to claim against you for our client's damages and loss in connection with the above incident, including but not limited to the repair cost of her vehicle, loss of use and/or rental cost for a replacement vehicle, surveyor's fees, report fees and legal costs, incidentals and disbursements.

Before our client proceed with the repair of her vehicle, you may inspect the damaged vehicle at the following address:

HUAT AUTOMOBILE AIR CON SERVICE

Blk 3007 Ubi Road 1

#01-404

Singapore 408701

Contact: Mr Tomy Tan 6746 1868

Kindly do so within the next 2 days, failing which our client shall proceed with the repair without further reference to you.

Please note that all negotiations and settlement of the claim is to be done through us as solicitors for our client.

We may be contacted at 6532 2009 (Ms Yean / Ms Anne) and at our address below.

Meanwhile, please advise your mailing address, as well as your insurers' details if you wish for them to handle the claim on your behalf.

Regards, Ms Yean for Mr Kurubalan

Kuru & Co 150 South Bridge Road #04-06 Fook Hai Building Singapore 058727

Tel: 6532 2009 Fax: 6532 2007

CONFIDENTIALITY CAUTION: This message is intended for the addressee(s) only and may contain confidential information and/or may be subjected to legal privilege. If you have received in error, please notify us immediately by return email, delete this message and you shall not disseminate, distribute or copy any information contained herein.

To Tommy lan From: Tan Siew Trong

MBHH20008234 / Ajax Mars Pie Ltd - Bulet Merah ENTRY DATE & TIME: 1801/2020 01:53 SUBMITTED BY: Sabitra Shangri Kanthirajan

Your NCD will be affected due to late reporting Actual e-Filling Submission Date & Time: 18/01/2020 02:14

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy fiability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report

18/01/2020 01:53

Date Of Accident

15/01/2020 17:00

Exact Location Of Accident

ALONG KK WOMEN AND CHILDRENÅ€™S HOSPITAL.

Country/State of Loss

SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SLL6465Y

Insured/Policyholder

Name Of Registered Owner

YONG LEE PENG

NRIC No

SXXXX711Z

Email Address

CHRISYONGLP@GMAIL.COM

Mobile Phone No

(LOCAL) +65-97638111

Alternative Phone No

OFFICE-97638111

Vehicle Particulars

Manufacturer

HONDA

Model

VEZEL 1.5X CVT

Exact Purpose for which vehicle was being used at

PRIVATE

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

THIRD PARTY

If No. Please state action to be taken Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

ERGO INSURANCE PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

Policy Number

DMPG19002214

Cover Note Number

Driver

Name of Driver YONG LEE PENG

NRIC No SXXXX711Z 03/10/1970 Date Of Birth INDOOR Occupation 09/09/1996 **Date Of Driving Pass**

Driving Experience

23 YEARS AND 4 MONTHS

Gender

Mobile Number

FEMALE (LOCAL) +65-97638111

Fax Number

Contact Number

OFFICE-97638111

EMail Address

CHRISYONGLP@GMAIL.COM

Page 1 of 34

Contact Number Address

Postcode

. .

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	711Z
Vehicle No.:	SLL6465Y
Vehicle to be Exported:	No
Intended Deregistration Date:	04 Feb 2020
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Red
Manufacturing Year:	2016
Engine No.:	L15B4407633
Chassis No.:	RU11207632
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,563.00
Original Registration Date:	03 Mar 2017
First Registration Date:	03 Mar 2017
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$12,189.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Mar 2027
PARF Rebate Amount: Intended COE Rebate Details	\$9,141.00
COE Expiry Date:	02 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,401.00
COE Rebate Amount:	\$34,252.00
Total Rebate Amount:	\$43,393.00

The information contained herein is correct as at 04 Feb 2020

OK



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ONDAG INCLIDANGE		PECTION REPORT Ref. CS3/LPC2000175	1/I lef3e2
LONPAC INSURANCE 300 BEACH ROAD #17-04/07 THE CONC	OURSESINGAPORE 199555	Date: 11-02-2020	11031332
		Code: LPC2	
1.		:- (THIRD PARTY CLAIM	SLL 6465Y
Insured Veh.	SLL 465Y	Veh. Inspected	
Policy No.	Z/19/LL00/015920	Coverage (\$)	0.00
Claim No.	19/20/20/LL00/003436	Excess (\$)	0.00
Assign From	LILY KOH	Assign Date	31/01/2020
2.		ticulars & Condition	
Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU11207632	Colour	RED
Odometer	042019 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Condi	tions of Tyres	
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm
4	Descrip	tion of Damages	
THE VEHICLE SU	STAINED DAMAGES AT THE RE	EAR N/S PORTION.	
5.	Gener	al Information	
Accident Date	15/01/2020	Inspect Date / Time	03/02/2020 (11:25 AM)
Survey held at	HUAT AUTOMOBILE - BLK 300	7 UBI RD 1 #01-404	
Repairer	12		
5a.		Remarks	
B) THE REPAIR E	ON WAS CONDUCTED ON A "W STIMATE WAS NOT PRESENTE WAS TOLD TO PREPARE THE ES LEASE FIND DAMAGED VEHICLE	D AT THE TIME OF INSPEC STIMATE.	S. TION.

Report Ref No. CS3/LPC20001751/Usf3s2

Inspected By

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.