

*ASS. REC. BY:

REF: CS/MSG 20001794 / et f30

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Ching myk puiof MSGDate/Time: 3.2.2011 11.58pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMP 7971M

Insured:

SLV 7657at Workshop m/s Auburn AutoTel: 9787 5558of 176 sn ming drive #04-18Policy No: 28795104MEXClaim No: 618706

Sum Insured:

Excess:

Make of Veh:

D.O.A. 28.1.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 3.2.2011 5:28pmPerson Contacted: SamVehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	Inspection: 3 AMK street 62 #04-18 Link @ AMK
	SMP 7971M - X
	SLV 7657 - X
6/2-	Revised preli advice via maximen.

ASS. REC. BY: Steve

REF: msig

ASSIGNMENT

From: _____ Date: 5.2.2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMP 7971M

at Workshop n/s Auburn Auto

at 176 Sn ming Drive #04-18

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____


(Client's Record)

Make of Veh: Sam 97875558

Insuranc. 3 Annk Strms 62 #01-45 Lax @ Ank

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMP 7971M Yr Regn: 1/11/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota PREVIA C.C. 2362

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 286052 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTEG054M60A924855

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/80R17

R: 9

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 5 mm

D.O.A. 28/1/29

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repairer wants to wait till Steve come back from arrange for survey.
	MV- 28000
	PV- 21043
	NV- 6957
	Steve, RECEIVED 17 FEB 2020
	PLS check parts prices.
17/2/20	Final offer \$3550, 2 days (Sam) Cred: 9125, 71%
	17/2/2020

Date/Time, File Pass 107

17/2 Typast

Date/Time, File Return 105

☐ : Prel. Report☒ : Final Report

Days Of Repair: 2

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weld and (\$

Survey Fee: 200

Transportation: 5 + RS. \$4

Fines

Other

TOTAL

211

Rep. Format: TP

Lump Sum: 3550-

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2020		03 Feb 2020 16:58 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N		
Main Claimant:	ALPHA MOTOR PTE LTD, Co. Reg. No.: 201922050H		
Vehicle Reg. No.:	SMP7971M	Date of Loss:	28/01/2020 13:00 - :59 [110 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 618706	Policy/Cover Note No.:	28795104MCX (Comprehensive) Coverage: 19/10/2019 - 07/08/2020
Vehicle Reg. No. (Insured):	SLV765T	Policy No. (Claimant):	
		Excess:	S\$1,000.00
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhla Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 04/02/2020]		
Adj Asg. Remarks:	on WP, Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Samuel @ 9787 5558. * Survey location is at 3 Ang Mo Kio Street 62 # 01-45 Link @ AMK*.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Steve Chen (LKK Auto)

From: Sam Ng <samuel.auburnauto@gmail.com>
Sent: Friday, February 14, 2020 4:22 PM
To: Steve Chen (LKK Auto)
Subject: Re: SMP7971M - Finalize

Hi steve,

Kindly proceed thanks.

with regard
Sam
Auburn Auto Pte Ltd
+65 9787 5558

On Thu, 13 Feb 2020 at 09:49, Steve Chen (LKK Auto) <SteveChen@lkkauto.com> wrote:

Dear Sam,

Kindly refer our finalize \$3550 (L/S, before GST). 2 repair days.

Kindly confirm.

Thanks.

Best Regards,

Steve Chen| Assistant Automotive Assessor

LKK Auto Consultants

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sun@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pul

Date: 06 Feb 2020

Preliminary Advice

Insured Vehicle No	: SLV765T	Accident Date	: 28/01/2020
TP Vehicle No	: SMP7971M	Assignment Date	: 03/02/2020
Make	: TOYOTA PREVIA	Est. Duration of Repair	: 2.00
Date of Inspection	: 05/02/2020		
Inspection At	: AUBURN AUTO PTE LTD (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages O/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,675.00
Revised Amount	:S\$	3,550.00
Check Items (Estimated)	:S\$	5,455.00
Total	:S\$	9,005.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/01/2020 16:30
Date Of Accident	28/01/2020 13:35
Exact Location Of Accident	10 FARRER PARK STATION RD PARK HOTEL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMP7971M
Insured/Policyholder	
Name Of Registered Owner	ALPHA MOTORS PTE LTD
Co Reg No	2XXXXX050H
Email Address	SAMUEL.AUBURNAUTO@GMAIL.COM
Mobile Phone No	(LOCAL) +65-88692498
Alternative Phone No	OFFICE-88692498

Vehicle Particulars

Manufacturer	TOYOTA
Model	PREVIA-2.4 7-SEATER (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	CN075540
Cover Note Number	29/01/2020 - 28/01/2021

Driver

Name of Driver	RAMLAN BIN DOLLAH
NRIC No	SXXXX884E
Date Of Birth	04/04/1962
Occupation	INDOOR
Date Of Driving Pass	14/10/1991
Driving Experience	28 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88692498
Fax Number	
Contact Number	OTHERS-97875558
Email Address	NOEMAIL

Address	907 TAMPINES AVVE 4 #06-284
Postcode	520907
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	4
Passenger 1	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CENTRAL POLICE DIVISIONAL HQ (A DIVISION)
Police Station Address	ROAD: 391 NEW BRIDGE ROAD #03-112 POLICE CANTONMENT COMPLEX BLOCK A , POSTCODE: 088762 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2240000 - FAX NO: 62200877
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO THE POLICE REPORT & SKETCH PLAN BY DRIVER

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV765T
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name RAMLAN BIN DOLLAH

Approximate Age

Injuries Sustain BODY UNWELL

Injured person in which vehicle? SMP7971M

Were seat belts worn? YES

Was this injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]


Reporting Centre Person's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

Date of accident: 20/1/20 Time: 13:55 Location: 10 Ferner Park Station Rd, Park Hotel
My Vehicle A: JMP 3911M Vehicle B: SW7454 Vehicle C: -

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to the police report

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks : Please forward a copy of my efile accident report to :

My workshop :

Email address :

& myself

Email address

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

DECLARATION

(/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature _____

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature _____

PROBATION

1982年12月



**SINGAPORE
POLICE FORCE**



A/20200129/7012

1 of 2

POLICE REPORT (NP299)

Report No. A/20200129/7012

Police Station Of Origin
Central Division HQ
A 391 New Bridge Road #03-112 Police
Cantonment Complex SINGAPORE 088762
Tel No: 1800-2240000

Date/Time Report Made 29/01/2020 12:52	Vide Report No.	Station Diary No.
Name Of Informant RAMLAN BIN DOLLAH	Address APT BLK 907 TAMPINES AVENUE 4 #06-284 SINGAPORE 520907	
ID Type / ID No. NRIC NO / S1569884E	Contact No. Home/Office: Mobile: 88692498	
Nationality SINGAPORE CITIZEN	Email Address ramlandollah@gmail.com	
Occupation Other car and light goods vehicle drivers nec	Sex Male	Age 57
Institution/School Name	Date of Birth 04/04/1962	Race Malay
Date/Time Of Incident 28/01/2020 13:35	Location Of Incident 10 FARRER PARK STATION ROAD PARK HOTEL FARRER PARK SINGAPORE 217564	

Brief details.

On 28 Jan 2020, I was about to park my vehicle on the hotel lobby awaiting drop off of passanger. My vehicle car plate bearing SMP7971M. Suddenly A vehicle bearing car plate SLV765T Toyota Sienta reverse into my right rear side door causing a huge impact and the windscreen shattered. All my passanger was shocked. The whole process is captured by the hotel lobby camera. We came down and exchange contacts and we individually report the case to our insured. The next day i felt unwell from the accident and went to see a doctor and was given mc.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 29/01/2020 12:52
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



A/20200129/7012

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. A/20200129/7012

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 29/01/2020 12:52
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	050H
Vehicle Details	
Vehicle No.:	SMP7971M
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PREVIA 7 SEATER
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	2AZH595321
Chassis No.:	JTEGD54M60A024855
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$35,783.00
Original Registration Date:	01 Nov 2010
First Registration Date:	01 Nov 2010
Transfer Count:	4
Actual ARF Paid:	\$35,783.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Oct 2020
PARF Rebate Amount:	\$17,891.00
Intended COE Rebate Details	
COE Expiry Date:	31 Oct 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$3,152.00
Total Rebate Amount:	\$21,043.00

The information contained herein is correct as at 05 Feb 2020

OK



Free on Advertisements
Get a new Advertiser's Kit
\$58 until it's SOLD!

© 2004 Blackwell Publishing Ltd *Journal of Internal Medicine* 255: 105–112

1000

Page 19	Page 20	Page 21
---------	---------	---------

Journal of Management

[Back to Table of Contents](#)
[Home](#)

1.2. *Method*

Source: *U.S. Census Bureau, Current Population Reports, 1990*

© 2005 Blackwell Publishing Ltd *Journal of Internal Medicine* 258: 103–110

[illegible]

Save the world's critical, to get your party membership a report to report.

For all advertisements, see www.elsevier.com

20 • J. Neurosci., November 11, 2009 • 29(45):11991–12000

[Home](#) [New Cars](#) [Used Cars](#) [Sell My Car](#) [Dealers](#) [Products](#) [Insurance](#) [Article](#) [Events](#) [Resources](#)

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)

sgCARMART CONNECT
Insurance, Loans & Finance

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

BMW 5 Series 523d Sedan



Power by 5.0L Turbo Diesel
Engine: 2000cc 240hp &
Automatic, 8 Speed Auto Trans
Trust Motoring 2010/2



Browse by Category

Sort by Date Posted 20 results/page

2 vehicles

toyota previa

Advanced Search

Price Model Price Depreciation Year Start Eng Cap Mileage Veh Type Status

Search Selection toyota previa Any Any 2011 Any Any Any Available



Toyota Previa 2.4A

\$12,800

\$14,520 /yr

24-Feb-2011

2,362 cc

-

MPV

Available

1 Owner, 8 Seater Model, In Overall Good Condition And Suitable For COE Renewal. This Is A Consignment Car, Please Call Beforehand To Arrange A Viewing. Thank You.

Posted: 21-Jan-2020

Tags: 2011 Toyota Previa, 2011 toyota previa, Toyota Previa, toyota previa, Toyota, Previa, previa, Used Toyota



Toyota Previa 2.4A

\$34,000

\$13,640 /yr

12-Apr-2011

2,362 cc

-

MPV

Available

Premium 7 Seater MPV, Very Well Maintain By Careful And Fussy Owner, 100% Accident Free. Call Us Now For Viewing And Test Drive.

Posted: 10-Feb-2020

Tags: 2011 Toyota Previa, 2011 toyota previa, Toyota Previa, toyota previa, Toyota, Previa, previa, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Price Model Price Depreciation Year Start Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, or COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car imports, carpark rates & car insurance. Find buy used toyota previa, toyota previa Singapore, used toyota previa Singapore, used toyota previa, used toyota previa Singapore or even buy used toyota previa Singapore. We have now car dealers comprising parallel importers, authorised car dealers, and even car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, travel, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All press and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2020 sgCarMart. All rights reserved.

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: samuel.auburnauto@gmail.com

Vehicle No: SMP7971M

Model: Toyota Previa

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Rear R/H Door Panel / <i>DD</i>	\$ 1,100.00 /
1	Rear R/H Door Mechanism ? / <i>joined (glass motor & remote)</i>	600.00 459 /
1	Rear R/H Door Automated Lock system ? / <i>BT (Door lock)</i>	1,200.00 311 /
1	Rear R/H Panel Windscreen Seal ? / <i>cut (glass rubber)</i>	105.00 /
1	Rear R/H windscreen Door (<i>glass</i>) / <i>BR</i>	\$ 1,300.00 385 /
1	Rear R/H Panel Garnish / <i>cut (lower)</i>	\$ 260.00 /
1	Rear R/H Automated door ? X <i>NMI</i>	\$ 3,200.00 X
1	Rear R/H Panel Inner Garnish ? X <i>NMI</i>	350.00 X
1	Rubber Moulding / <i>DD</i>	\$ 120.00 /

Sliding door glass outer moulding / *BT* \$156
 Sliding door glass inner moulding / *BT* \$148
 Sliding door Kicking plate RH / *CRU* \$726.34
 Sliding door trim board RH / *CRU* \$588
 Sliding door weatherstrip RH / *TN* \$247.60
 Sliding door inner handle RH / *joined* \$381
 Sliding door lower hinge RH / *BT* \$191
 Sliding door centre hinge RH / *BT* \$182

\$ 8,235.00

4859.94
 -25%
 3644.95

c/f: \$ 8,235.00

Special Nett Items		AMT \$	
1	Rear R/H Windscreen Sealant	\$ 120.00	X AM
1	Rear R/H Panel bumper clip	\$ 150.00	X AM
		<u>\$ 270.00</u>	

S/N. Labour Charges

1	Panel Beating R/H Door/ Refit R/H door	\$ 1,800.00	300
2	Remove and refit rear R/H Door windscreen	\$ 500.00	60
3	Remove, refit and replaced damage and check up rear electrical wiring	\$ 150.00	30
4	Remove and refit inner garnishes trim to assist repair	\$ 200.00	50
5	To apply undercoating on replaced panel	\$ 120.00	30
6	To Respray Painting.	\$ 1,400.00	300
		<u>\$ 4,170.00</u>	
GRAND TOTAL		<u>\$ 12,675.00</u>	70

P- 3644.95
 L- 770
 4414.95
 L/S - 3531.96
 = 3550

14794.94

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name)

Steve (LKK)

(Contact)

8778813

(Email)

(Signature)

(Date/Time)

5/2/20, 3:30pm

L/S

WHL ML

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)
















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Jan 2020		03 Feb 2020 16:58 Edit Adj Rpt	S\$3,550.00 Edit Estimates	S\$3,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	SKYWAY MOTOR PTE LTD, Co. Reg. No.: 199904194N								
Main Claimant:	ALPHA MOTOR PTE LTD, Co. Reg. No.: 201922050H								
Vehicle Reg. No.:	SMP7971M	Date of Loss:	28/01/2020 13:00 - :59 [110 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 618706	Policy/Cover Note No.:	28795104MCX (Comprehensive) Coverage: 19/10/2019 - 07/08/2020						
Vehicle Reg. No. (Insured):	SLV765T	Policy No. (Claimant):							
		Excess:	S\$1,000.00						
Repairer:	Auburn Auto Pte Ltd (HQ) 176 SIN MING DRIVE, #04-18 SIN MING AUTOCARE, 575721 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pul - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 04/03/2020]								
Adj Asg. Remarks:	on WP. Liab: NR. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd, Contact: Samuel @ 9787 5558. * Survey location is at 3 Ang Mo Kio Street 62 # 01-45 Link @ AMK*.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMP7971M (618706)
[SLV765T]
TP
ALPHA MOTOR PTE LTD
Jan 28 2020 1:00PM
[SKYWAY MOTOR PTE LTD]
Auburn Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/02/20 17:04	Video - Accident	Load AVI	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/02/20 17:02	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
2	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
3	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
4	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
5	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
6	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
7	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
8	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
9	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
10	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
11	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
12	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
13	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
14	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
15	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
16	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
17	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
18	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
19	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
20	05/02/20 18:38	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
21	05/02/20 18:38	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
22	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
23	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
24	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
25	05/02/20 18:38	General View	Load JPG	<input checked="" type="checkbox"/>
26	17/02/20 09:04	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
27	17/02/20 09:04	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
28	17/02/20 09:04	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
29	17/02/20 09:04	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
30	17/02/20 09:04	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
31	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
32	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
33	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
34	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
35	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
36	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	17/02/20 09:04	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
81	17/02/20 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
82	17/02/20 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
83	17/02/20 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
84	17/02/20 09:05	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	30/01/20 16:38	TPD SMP7971M - PRI	 Load PDF	
2	03/02/20 10:28	Agree on SJE	 Load PDF	
3	10/02/20 17:07	Status of driving licence	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20001794/ETF3E2

Date: 18/02/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28795104MCX

Claimant Vehicle No : SMP7971M

Insured Vehicle No : SLV765T

Date of Loss: 28/01/2020

Nature of Claim: TP

Claim No: 618706

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMP7971M

Make & Model: TOYOTA PREVIA, 2.4 7-seater (A)

Engine No: 2AZH595321

Reg. Date: 01/11/2010 (Man. Year: 2010)

Chassis No: JTEGD54M60A024855

Colour: Black

Odometer: 286052 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Continental 5 mm

Rear Left Side: Continental 5 mm

Front Right Side: Continental 5 mm

Rear Right Side: Continental 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,624.94	3,644.95	6,979.99	65.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,170.00	770.00	3,400.00	81.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,794.94	4,414.95	10,379.99	70.16
Approved Total (Overridden) (S\$)		3,550.00		
Nett Amount (S\$)	14,794.94	3,550.00	11,244.94	76.01

INSPECTION

Date of Assignment: 03/02/2020

Date Inspected: 05/02/2020 Inspected At:

3 AMK Street 62 #01-45 Link @ AMK
Repairer : Auburn Auto Pte Ltd (HQ)

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2020)
Parts:	M1-MPV	TOYOTA PREVIA 2.4 7-seater (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP7971M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR R/H DOOR PANEL	Dented	1,100.00 F	*1,100.00 FL
2	1		*REAR R/H DOOR MECHANISM	Jammed	600.00 F	*459.00 FL
3	1		*REAR R/H DOOR AUTOMATED LOCK SYSTEM	Bent	1,200.00 F	*311.00 FL
4	1		*REAR R/H PANEL WINDSCREEN SEAL	Cut	105.00 F	*105.00 FL
5	1		*REAR R/H WINDSCREEN DOOR	Broken	1,300.00 F	*385.00 FL
6	1		*REAR R/H PANEL GARNISH	Cut	260.00 F	*260.00 FL
7	1		*REAR R/H AUTOMATED DOOR	Not Necessary	3,200.00 F	*- FL
8	1		*REAR R/H PANEL INNER GARNISH	Not Necessary	350.00 F	*- FL
9	1		*RUBBER MOULDING	Dented	120.00 F	*120.00 FL
10	1		*SLIDING DOOR GLASS OUTER MOULDING	Bent	156.00 F	*156.00 FL
11	1		*SLIDING DOOR GLASS INNER MOULDING	Bent	148.00 F	*148.00 FL
12	1		*SLIDING DOOR KICKING PLATE RH	Crushed	226.34 F	*226.34 FL
13	1		*SLIDING DOOR TRIM BOARD RH	Crushed	588.00 F	*588.00 FL
14	1		*SLIDING DOOR WEATHERSTRIP RH	Torn	247.60 F	*247.60 FL
15	1		*SLIDING DOOR INNER HANDLE RH	Jammed	381.00 F	*381.00 FL
16	1		*SLIDING DOOR LOWER HINGE RH	Bent	191.00 F	*191.00 FL
17	1		*SLIDING DOOR CENTRE HINGE RH	Bent	182.00 F	*182.00 FL
18	1		*REAR R/H WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
19	1		*REAR R/H PANEL BUMPER CLIP	Not Necessary	150.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (\$\$)	10,624.94	4,859.94
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	1,214.99
Total Parts (\$\$)	10,624.94	3,644.95

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING R/H DOOR / REFIT R/H DOOR	New	1,800.00	300.00
2	REMOVE AND REFIT REAR R/H DOOR WINDSCREEN	New	500.00	60.00
3	REMOVE, REFIT AND REPLACED DAMAGE AND CHECK UP REAR ELECTRICAL WIRING	New	150.00	30.00
4	REMOVE AND REFIT INNER GARNISHES TRIM TO ASSIST REPAIR	New	200.00	50.00
5	TO APPLY UNDERCOATING ON REPLACED PANEL	New	120.00	30.00
6	TO RESPRAY PAINTING	New	1,400.00	300.00
Gross Labour Cost (S\$)			4,170.00	770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >