NATIONAL Assessment Centre			IMA 1200 1		A CONTRACT OF THE	
Date In 3/2/20 17:37	Jeb description		Date & Time Cor		Dune by	
	SAS c-filing		198			
MALALG 2000 1797144.	E-mull (etata sia	s, AIC 2hrs)				
SKN 6059 M.	I-Motor Cinim					
112120 15:05.	I-Motor W/O (Tir thrs)			. 8.
OH TP Reporting Only	f-Photo Uploac					
	Assessment/Surv					
TP luxurer:	Ass't Report by		Owner/Wksp			
The state of the Annual When I DW I	1000		Tul:	Fax:)
Profured West And Assign West / QW: (12 Particulars: Veh No: C	JL 4005 D.	INC ()/Non-INC ()		
Owner / Driver: (1 4003 D.		Tel:)	
	iod: ()	Cover Type: ()	
Confirmed by : (Date:	Time:)	
Insured/Driver Liability: (%) [N	lote-Est. Status (W	O): N: 0-20	%; P: 21-79%.	P: 80-100%		
	Varranty: YES ()/NO()			
Total of Resignation (00 ()/\$2,000 ()				en er somme
THE RESERVE THE PARTY OF THE PROPERTY OF THE P	SAASSESSA NICOTA IN	REPUBLISHED AND AND ADDRESS OF THE PARTY OF	A PROPERTY OF A PARTY	EE BANKS	3,	f.
Goueral Remarks: 3. 2. 1935 63 145 63 147 2 () Walk-In Customer: Customer's Infor	CAMPACAMANANA CAN	idential & St	ictiv NO refer of	repolier.		
() Total Loss Case : to e-mail Insure		T: () C	owing Co: (7	1)
		anni allanti di ili	OLE CONTROL OF THE STREET, STR	学 人艺术的艺术。	esidono by	/ · ·
ttemaris:: - (186 flothin: 6708 6616) 85	治科學的學科	Zini in in	M Directanoised	Mint, merchant	V-1-6-1-2	
1) Apply for Transport Allowance ()/C	ourtesy Car ()		(·+-			
	A STATE OF THE PARTY OF THE PAR			1.5		
2) QC Check / Post Repair Inspection	(·)					
QC Check / Post Reprir Inspection Upload Resurvey Photo [Repair Cost > \$3						
2) QC Check / Post Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Infary:		STEEL PROPERTY OF THE PARTY OF T	PROGRAMMA CORRESTO		Corner	ज्या <u>त</u> ्र हो
2) QC Check / Past Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Infary:						(2)(q ₁ , ₂ , ₂ , ₂ , ₂
2) QC Check / Post Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Infary:					TO STATE	214, 21,
2) QC Check / Past Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:					A Chek's Ker	710, 27.
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:		ATTERIOR AND THE			ger - Leer to	211, 70, 1
2) QC Check / Past Repair Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury:			PROPERTY TO P		10 to	2000
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Distribute Praction Practical Process Process Practical Process Process Practical Process Process Practical Prac	000] ()		The constitution of the second		N. 18 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	YASH (\$)
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Darty Photo Photo [Repair Cost > \$3		はないが、別点に見述いれたとかは、他には、	in ration Chick		Chu Struck	ASIR(C)
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Dante/Photo Prefer in Section 2019 [1985] MARKET COST Prefer i	20009(9	1) AR: Anciden	phration Check than the Check traporting (330); Assessment (5100);	INC (\$3.0)_		
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: DartyPhoto [Arthority 2007] 2007 [1987] 2007 Champon's Particulars:	20009(9	1) AIL: Acciden 2) DA: Damego 3) TF: Towing 4) ET: Follow-	through Survey	INC (550) \$40/\$45 \$120		
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Darty Epinol (Arction) (1988) (1988) (1988) (1988) Champon's Particulars (1988) (1988	20009(9	1) AIL; Anoiden 2) DA: Damego 3) TF: Towing 4) FT; Follow-	Thru(I) i Check thru(I) i Check thru(I) i Short Reporting (330); Resource (5100); Fee	INC (\$3.0) \$40/\$45 \$120 (vay) \$3.0		
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Darty Epinol (Arction) (1988) (1988) (1988) (1988) Champon's Particulars (1988) (1988	20009(9	1) AR: Acciden 2) DA: Damage 3) TF: Towing 4) FT: Follow- 5) FT: Follow- For glaiming 6) TR: Re-lum	Intraffou Check traporting (330); Assurament (5100); Fre Through Survey Through Survey (Resur- taning UNIC Only (we	INC (330) \$40/\$45 \$120 (vey) \$20 (10 Jan 2003) \$75		
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Dante/Photo Prefer in Section Property Property	20009(9	1) AR: Accident 2) DA: Demego 3) TF: Towing 4) FT: Follow- 5) FT: Follow- For galming 6) TR: Re-lum 7) NI: Idao DA	Threafton Check the control (\$30); Assessment (\$100); Fig. (\$300); Through Survey Through Survey (Resurvey Through Survey (Resurvey) the control (\$400); Through Survey (\$400); Through Survey	INC (\$3.0) \$40/\$45 \$120 (vay) \$20 (10 Jan 2005)	70.00	
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Darty Epro Control of Action Research and the second secon	20009(9	1) AR: Acciden 2) DA: Demego 3) TF: Towing 4) FT: Follow- 5) FT: Follow- For usining 6) TR: Re-impo 7) NI: Idae DA 3) NTUC Addit OD.	Through Survey	INC (330) \$40/\$45 \$120 (voy) \$20 (10 Jan 2003) \$75 \$75	70.00	1
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Distribute Particulars and approximately approximately privately approximately	20009(9	1) AR: Acciden 2) DA: Demego 3) TF: Follow- 5) FT: Follow- For galming 6) TR: Re-lum 7) NI: Idae DA 8) NTUC Addit QD* *NS: Courter	Threafton Check the control (\$30); Assessment (\$100); Fig. (\$100); French Survey Through Survey (Results (\$100); We settled (\$100); French Survey (\$100);	INC (330) \$40/\$45 \$120 (vey) \$20 (10 Jan 2003) \$75	70.00	
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Dark Time (Faction) Claimant's Particulars: Driver/Owner: Contact No: Damaged Portion:	20009(9	1) AR: Acciden 2) DA: Denneye 3) TF: Towing 4) FT: Follow- 5) FT: Follow- For glaiming 6) TR: Re-insp 7) NI: Idea DA 3) NTUC Addit OD.* *NS: Courter *NS: Courter *NS: Repair	Through Survey Throug	INC (330) \$40/\$45 \$120 (voy) \$20 \$10 Jan 2000) \$75 \$3160 \$25	70.00	
2) QC Check / Pest Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Date: Enny Cactions Contact No. Date: Owner: Contact No. Damaged Portion: QC Checked by (Engr-In-Charge):	20009(9)	1) All: Anciden 2) DA: Denneye 3) TF: Towing 4) FT: Follow- 5) FT: Follow- For glaiming 6) TR: Re-insp 7) N1: Idea DA 5) NTUC Addit OD.* *N6: Repair *N6: Repair *N7: Fost Re Data DA / C	The control of the city of the	INC (330) \$40/\$45 \$120 (voy) \$10 Jan 2003) \$75 \$5160 \$525 tion \$525	70.00	
2) QC Check / Post Reprir Inspection 3) Upload Resurvey Photo [Repair Cost > \$3 Injury: Darte/Fine / Action Plans Reprir Inspection	20009(9)	1) All: Anciden 2) DA: Denneye 3) TF: Towing 4) FT: Follow- 5) FT: Follow- For glaiming 6) TR: Re-insp 7) N1: Idea DA 5) NTUC Addit OD.* *N6: Repair *N6: Repair *N7: Fost Re Data DA / C	The control of the clips of the	INC (330) \$40/\$45 \$120 (voy) \$10 Jan 2003) \$75 \$5160 \$525 tion \$525	72.00	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	03/02/2020 17:37
Date Of Accident	01/02/2020 15:05
Exact Location Of Accident	NICOLL HWY TWDS KPE TUNNEL
Country/State of Loss	SINGAPORE
The state of the s	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SKN6059M
Insured/Policyholder	
Name Of Registered Owner	TSENG KING JET @ ZENG QINGZHENG
NRIC No	SXXXX935E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96833021
Alternative Phone No	OFFICE-96833021
Vehicle Particulars	
Manufacturer	ТОУОТА
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100377129-05
Cover Note Number	
Driver	
Name of Driver	TSENG JIA YUAN FELIX
NRIC No	SXXXX352G
Date Of Birth	07/09/1996
Occupation	INDOOR
Date Of Driving Pass	08/06/2017
Driving Experience	2 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93229025
Fax Number	
Contact Number	
	NOTHAL

NOEMAIL

66 MEI HWAN DR #10-12 Address

568429 Postcode

Was driver an employee of the Insured's Company NO

CHILDREN If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

CLEAR Weather Conditions DRY Road Surface

Other Information

NO Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

YES Was any body injured in the Accident?

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES NO

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

: MONA CHEW POH GEK Passenger 1 NAME:

2

NO

4

NO

NO

: FEMALE GENDER:

: FELICIA TSENG HUI JUAN Passenger 2 NAME:

> : FEMALE GENDER:

Passenger 3 : TSENG KING JET NAME:

> : MALE GENDER:

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT

Attachment(s)

YES Are accident photos available for attachment? NO Was there any video captured by Car Camera? NO

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

SJL4005D

Vehicle Registration Number

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Page 2 of 13

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TSENG JIA YUAN FELIX

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SKN6059M

Were seat belts worn? YES

Was this injured conveyed to hospital by

ambulance?

NO

Address Postcode

DETAILS OF INJURED PERSON 2

Name FELICIA TSENG HUI JUAN

Approximate Age

Injuries Sustain BODY

Injured person in which vehicle? SKN6059M

Were seat belts worn? YES

Was this injured conveyed to hospital by

ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material racts may allow insurance companies to repudiate policy liability.
- 4 The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

			venicle 18. SILYais
TE DE			
DESCRIBE CIRCUMSTANCE		L time. I,	volsich A wer
traving straight	on the stated	venue. Judden	the I felt an huge
impact from the	ver portion u	t my vehicu	. I, then realise that
Which 8 had	collided on to	nry vehic	h.
5 7 5			

DECLARATION

I/We declare the foregoing particulars are true in every respect.

- Kary

Policyholder's Signature Date & Time: Jus:

Driver's Signature (If driver is not the policyholder) Date & Time: and the

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

ACCIDENT STATEMENT

		ACCIDENT DATE 1 2 203	J(DD/MM/YYY	(Y), TIME: 15 05 (HH:A
		LOCATION: LIGHT LISHWAY	tohals Ep	E Tunn -
		1. DETAILS OF VEHICLE		
		GIVEHICLE NUMBER: SKN	6059M	
		DJINSURANCE COMPANY:_		
		CIPOLICY NUMBER: 2100 3	377129 05	
				20/12/22 21/22
		PIMAKE & MODELL TOUR	INDIVE / IMIKU PA	RTY / THÍRD PARTY FIRE & THE
		ELTYPE IS A FOOD LOOKE	Corolla Altis	<u> </u>
		THE GALOON / COUPE / N	MEV /V AN / LORR	RY / MOTORCYCLE / OTHERS)
		g/VEHICLE CATEGORY: (PRIV	ATE / COMMERC	IAL / MOTORCYCLE)
		HIPURPOSE OF USING AT ACC	CIDENT TIME:	
		I ARE YOU CLAIMING UNDER	YOUR OWN INSU	IRANCE (YES/NO)
		IF NO. PLEASE STATE (THIRD A	PARTY CLAIM / RE	EPORTING ONLY)
		2. INSURED / POLICY HOLDER	_	
		Alname: Tsens king 3	et (0 Zong @:ns	MALE / FEMALE)
		DINKIC/FIN/PASSPORT: SI	6219356	CONTACT. QUESTION
		CLADDRESS: BITH 66 Me.	Here Drive	e #10-12 (S) 56841
		The second secon		A Committee of the Comm
	MILL O	* CONTINUE TO 3.d IF DRIVER	ALSO POLICY HO	LDER
	# No of passon	ga DRIVER		Injury
2000	Clincluding driv	I alname: Isena sa yu	ann tollk	(AAAIE / EEAAAIE)
ind	64)	DINKIC/FIN/PASSPORT: SOL	6313526	_CONTACT: 9312 9025
Mose		CIADONESS DIE No Mai	Hwa Drive	#10-12 (S) 568429
) Thomas	chew Por Gek (F)	TO DATE OF HIRITARY		
Felicia	· Tseny Hui. Juan (*d)DATE OF BIRTH: [07 / 04 F) = JOCCUPATION: (INDOOR / 0	/ [996] [DD/N	(M/YYYY)
	isery Au. Juan (f) YEARS OF DRIVING EXPRERIEN	UDOOK)	
TSON	king Jet (n)	4 WAS DRIVER AN EMPLOYEE	NCE: 1719PC	·
song	ring sea (4. WAS DRIVER AN EMPLOYEE (OF THE INSURE	D'S COMPANY? (YES / NO)
		IF NO, RELATIONSHIP OF TH. 5. a) WEATHER CONDITION: (CLEA	E DRIVER WITH	INSURED:
8: 10		DIROAD SURFACE: (DRY / WET	K/RAINING/O	THERS
	20	6. WAS ANYBODY INJURED (FES)	MA I	
		7. a) REPORTED TO POLICE (YES / N	May 1	
		IF YES, PLEASE STATE WHICH PO	OUGE STATION	5
-	8	TUIDD BADTY LITTLE	DLICE STATION:_	
	# No of passenger	a) VEHICLE NUMBER: SOL 4	FINE D	the state of the s
	Cladudina debut) b) DRIVER'S NAME: MOHam	nod 0:10	MODEL: Honda circ
	/ 13	c) NRIC/FIN/PASSPORT:	100 100 200	
	(THIRD PARTY VEHICLE		_CONTACT:
		THE THEFT		anneath and
	* No of passzanger	al Danvenicking		MODEL:
	(Including drive	O DRIVER 3 NAME:	7	
	()	() f) NRIC/FIN/PASSPORT:	HUSER COTTON TO SERVE	CONTACT:
	()			ATT THE PLANT OF THE REAL PROPERTY OF THE PARTY OF THE PA
	Strate-34-+0			

email = ricoboautosurvices egmail. com fax = 6286 7060



CERTIFICATE OF INSURANCE

AUTOPLUS PRIVATE VEHICLE

Name of Policyholder : Tseng King Jet @ Zeng Qingzheng : 27 Jun 2019 To 26 Jun 2020 Period of Insurance

Engine No. : 1ZRX426018

Chassis No. : MR053REH104511199 Vehicle No. SKN6059M Policy No. : 2100377129-05

Endorsement No.

Issued Date : 28 May 2019

ABOUT THE COVER

Make/Model TOYOTA COROLLA ALTIS 1.6 DUAL

Engine Capacity/Tonnage : 1,598.00 CC Sum Insured : Market Value First Year of Registration : 2014 Driver Restriction Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

a) The Policymology b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") If You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc Optional

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings

EXCESS

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Tseng King Jet @ Zeng Qingzheng - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Approved Reporting Centres/ AIG Authorised Repairers (For claims related repairs)

Any accident repairs to the Vehicle in Singapore, You have the option of having the accident repairs to the Vehicle in Singapore, You have the option of having the accident repairs carried out at the Sole Agent's workshop.

For other Approved Reporting Centres/AIG Authorised Repairers, Please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, You may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189); Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0030210156

AIG - ALITO DIRECT 78 SHENTON WAY #07-16 AIG BUILDING

SINGAPORE 079120

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

20 buile

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

SSPGMM